

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 05/03/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: PC7200M		VIC
MODEL	: MERCEDES BENZ V220		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 2-Mar-18
		TIME	: 14:00HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Repair</i>	1	\$ 1,300.00	\$ 1,300.00
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 199.20	\$ 199.20
3	HEADLAMP LH <i>new</i>	1	\$ 1,350.00	\$ 1,350.00
4	FRONT FENDER LH <i>Dented</i>	1	\$ 880.00	\$ 880.00
5	FRONT FENDER INNER COWLING LH <i>new</i>	1	\$ 203.00	\$ 203.00
6	FRONT FENDER QUARTER GLASS MOULDING LH <i>new</i>	1	\$ 190.00	\$ 190.00
7	FRONT KNUCKLE ARM WITH BEARING LH <i>Best</i>	1	\$ 2,120.00	\$ 2,120.00
10	FRONT DOOR LH <i>Dented</i>	1	\$ 1,800.00	\$ 1,800.00
11	FRONT DOOR OUTER HANDLE LH <i>new</i>	1	\$ 250.00	\$ 250.00
12	FRONT DOOR LOCK LH <i>new</i>	1	\$ 280.00	\$ 280.00
13	FRONT DOOR WEATHERSTRIP LH <i>new</i>	1	\$ 190.00	\$ 190.00
14	FRONT DOOR SIDE MIRROR FRAME <i>new</i>	1	\$ 1,060.00	\$ 1,060.00
15	FRONT DOOR SIDE MIRROR GLASS <i>new</i>	1	\$ 205.00	\$ 205.00
16	FRONT DOOR SIDE MIRROR COVER <i>new</i>	1	\$ 200.00	\$ 200.00
17	FRONT DOOR SIDE MIRROR SIGNAL LAMP <i>new</i>	1	\$ 190.00	\$ 190.00
18	FUEL TANK COVER <i>Dented</i>	1	\$ 290.00	\$ 290.00
19	REAR SLIDING DOOR LH <i>Dented</i>	1	\$ 2,500.00	\$ 2,500.00

*+*  
*+*  
*x*  
*✓*  
*+*  
*+*  
*-*  
*1480*  
*x*  
*+*  
*✓*  
*+*  
*✓*  
*✓*  
*-*  
*2355*

20	REAR FENDER <i>Reps</i>	1	\$ 2,900.00	\$ 2,900.00	<i>+</i>
21	REAR FENDER QUARTER GLASS MOULDING <i>new</i>	1	\$ 190.00	\$ 190.00	<i>+</i>
22	REAR BUMPER <i>Reps</i>	1	\$ 1,450.00	\$ 1,450.00	<i>+</i>
23	REAR BUMPER SIDE RETAINER <i>for new</i>	1	\$ 92.00	\$ 92.00	<i>-</i>
24	REAR WHEEL HUP WITH BEARING DM	2	\$ <del>1,800.00</del> <i>900</i>	\$ 3,600.00	<i>1,800</i>

12107  
10896.30

TOTAL PRICE \$ 21,439.20  
LESS 10% \$ 2,143.92  
SUB TOTAL PRICE \$ 19,295.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	<i>+</i>
3	FRONT WHEEL TYRE <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	<i>+</i>
4	FRONT WHEEL RIM(SET) <i>lt 3 piece</i>	1	\$ 3,500.00	\$ 3,500.00	<i>1200</i>
5	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>+</i>

TOTAL \$ 4,765.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	<del>\$1,800.00</del>	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	<del>\$1,800.00</del>	<i>1300</i>	
3	Tuff Coat	\$150.00	<i>x</i>	
4	WIRING CHECK	<del>\$80.00</del>	<i>30</i>	
5	TO REMOVE AND REFIX FRONT FENDER QUARTER GLASS	\$100.00	<i>x</i>	
6	TO REMOVE AND REFIX FRONT DOOR QUARTER GLASS	\$120.00	<i>x</i>	
7	TO REMOVE AND REFIX FRONT FRONT DOOR <i>Settings</i>	<del>\$200.00</del>	<i>80</i>	
8	TO REMOVE AND REFIX REAR SLIDING DOOR QUARTER GLASS	<del>\$100.00</del>	<i>+ 60</i>	
9	TO REMOVE AND REFIX REAR SLIDING DOOR <i>Settings</i>	<del>\$250.00</del>	<i>80</i>	
10	TO REMOVE AND REFIX REAR FENDER QUARTER GLASS MOULDING	\$80.00	<i>x</i>	
11	FOUR WHEEL ALIGNMNET	<del>\$100.00</del>	<i>80</i>	

12	TO REFIX AND REMOVE UNDERCARRIAGE	\$550.00	300	
<b>TOTAL</b>		<del>\$5,330.00</del>	2730	

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 24,060.28  
 TOTAL LABOUR COST : \$ 5,330.00  
 TOTAL REPAIR COST : \$ 29,390.28

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM

NO OF DAYS :

Adrian L  
 L/S 05/03/18  
 07 Days.

total: 14846.3  
 A/S: 11-87K.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: