

ASS. REC. BY:

REF: CS/MSG/18004210/T1rd3n Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person):

Trene Tan

of

MSG

Date/Time: 5/3/18 09:39 am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV/CS

To Inspect Vehicle No:

GW23185

Insured:

YN2112C

at Workshop m/s

Sng Ah Tee Motor

Tel:

6268 6183

of

Blk 3 Pioneer Rd North #01-18

Policy No:

B29069239 MKF

Claim No:

549001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/02/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

11:55 am 05/3/18

Person Contacted:

joyce

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

GW23185-X

YN2112C-X

6/3/18

Send preli revised by merimen

22/5/18

LS \$2000 confirmed by email (Red 1726.60, 4613)

Signature

Tang

REF:

MSIG

ASSIGNMENT

2018 April

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

93K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

after 3pm

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

check limit
Repair limit \$2000, e-mail workshop

Veh No:

GW23188

Yr Regn:

2003 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi L300

cc

2472

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

194157

T. Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM AJNP1503 A000554

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

5/3/18 01745

Survey held at

Sung Lee Tree

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 22 MAY 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 2015- typist

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

200

10

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

2000/2

210

Survey Department Check List (Case Handler)

Reference No.: CS | MS918004210 | Tivd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 22/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004210/T1vd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2112C	Veh. Inspected	GW 2318S	
Policy No.	B29069239MKF	Coverage (\$)	0.00	
Claim No.	549001	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/02/2018	Inspection Date		
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 06 Mar 2018
Preliminary Advice	

Insured Vehicle No	: YN2112C	Accident Date	: 06/02/2018
TP Vehicle No	: GW2318S	Assignment Date	: 05/03/2018
Make	: MITSUBISHI L300	Est. Duration of Repair	: 5.00
Date of Inspection	: 05/03/2018		
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,726.60
Revised Amount	:S\$	3,125.30
Check Items (Estimated)	:S\$	134.55
Total	:S\$	3,259.85

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is economical/not economical for repair.

☒ The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2018 11:10 Sendback Est	02 Mar 2018 11:25 S\$3,726.60	05 Mar 2018 09:39 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	GARDENIA FOODS (S) PTE LTD, Co. Reg. No.: 197801714R		
Main Claimant:	SATS FOOD SERVICES PTE. LTD., Co. Reg. No.: 197300678G		
Vehicle Reg. No.:	GW2318S	Date of Loss:	06/02/2018 13:00 - :59
Claim Type:	TP / 549001	Policy/Cover Note No.:	B29069239MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	YN2112C	Policy No. (Claimant):	P1490444
		Excess:	S\$1,500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/03/2018]		
Driver/Custodian (Insured):	WONG KIAN WOON (/ Male), NRIC: G2465721W		
Adj Asg. Remarks:	car in at 3pm 05/03/18 to be survey by today		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Taufikh (LKKAuto)
Sent: Tuesday, 6 March 2018 9:19 AM
To: 'Janice Chang'
Cc: 'Sharon Sng'; Veron Chen (LKKAuto)
Subject: GW 2318S REPAIR LIMIT

Hi Janice,

Please take note repair limit for this van is \$2000. COE ends April 2018.

Regards
Taufikh
Lkk Auto

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 22 May 2018 3:25 PM
To: 'Sharon Sng'
Cc: SUR
Subject: RE: GW2318S - FINALISE (LIMIT REPAIR \$2000)

Dear Sharon,

WITHOUT PREJUDICE

Confirmed Lump Sum \$2000 before GST @ 5 working days.

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Tuesday, 22 May 2018 3:03 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: GW2318S - FINALISE (LIMIT REPAIR \$2000)

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>





ANNOUNCING Don Motoring Pte Ltd
as sgCarMart Premium Dealer 2018

DON MOTORING
Private Limited

Mitsubishi L300

Price Range

Depreciation

> 10 year(s) of Vehicle Type

Search

Advanced Search

Home » Used Cars » Hoe Beng Auto Trading » Mitsubishi L300 (COE till 08/2018)

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle



Mitsubishi L300 (COE till 08/2018)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$5,900	
Depreciation	-	?
Reg Date	06-Aug-2003 (4mths 30days COE left)	
Lifespan	05-Aug-2023	
Manufactured	2003	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,477 cc	
Curb Weight	1,390 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Good Conditions. Ideas For Short Terms Use.	
COE	\$29,749	?
OMV	\$13,381	?
ARF	\$670	?
Dereg Value	\$2,478 as of today (change)	?
No. of Owners	3	?
Type of Veh	Van	
Category	COE Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 07-Feb-2018 | Last Updated on: 09-Feb-2018

Tags: Mitsubishi L300, 2003 Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$590 (change)	Maximum 90% Loan ?
1st Instalment	\$1,347	?
Total Upfront Payment	\$1,962 (excluding insurance)	?

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

Items for Mitsubishi L300

» View All

Day Running Light
From \$19020" Rims (With
Continental
Contispo...
\$3,495

Seller Information

Company	Hoe Beng Auto Trading » dealer's pricelist » 12 vehs sold 44 vehs available	
Address	3 Ang Mo Kio Street 62 #01-20 Search cars nearby this location	
Office No	67450138 / 65523003	
Contact Person(s)	Eric	83538778
	Agnes	93680138

Useful Services

Make sure of this car condition
with STA Evaluation.

Vehicle Evaluation

Find out the market value for your car.
Get a free Car Valuation.

Free Valuation

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 0678G

Vehicle Details

Vehicle No.: GW23185

Vehicle to be Exported: No

Intended De-registration Date: 01 Mar 2018

Vehicle Make: MITSUBISHI

Vehicle Model: L300 P/VAN

Primary Colour: White

Manufacturing Year: 2003

Engine No.: 4D56KP1233

Chassis No.: JMAJNP15V3A000554

Maximum Power Output: -

Open Market Value: \$13,327.00

Original Registration Date: 25 Apr 2003

First Registration Date: 25 Apr 2003

Transfer Count: 0

Actual ARF Paid: \$667.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Apr 2018

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$27,795.00

COE Rebate Amount: \$818.00

Total Rebate Amount: \$818.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 07 Feb 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 14:51
Date Of Accident	06/02/2018 13:35
Exact Location Of Accident	ALONG PANDAN LOOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GW2318S
Insured/Policyholder	
Name Of Registered Owner	SATS FOOD SERVICES PTE. LTD.
Co Reg No	197300678G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84327319
Alternative Phone No	OFFICE-90040281

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	L300-1.6 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P1490444
Cover Note Number	

Driver

Name of Driver	KOH KIAN HENG
NRIC No	S1337754E
Date Of Birth	07/11/1958
Occupation	OUTDOOR
Date Of Driving Pass	30/09/1978
Driving Experience	39 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82350348
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 06/02/2018 AT ABOUT 1335 HRS .WHILE I WAS TRAVELLING ALONG PANDAN LOOP. I TRAVELLING SLOWLY AND OPEN RIGHT SIGNAL INTEND GO RIGHT TO 234 PANDAN LOOP. HAVE ONE VEHICLE STATIONARY IN FRONT OF 234 PANDAN LOOP WAITING THE GATE OPEN. I THEN STOP MY VEHICLE . AFTER A WHILE , I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT REAR OF MY VEHICLE COLLIDED BY VEHICLE B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2112C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG KIAN WOON
NRIC/Passport Number	404830953
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

GDPR/CC-BY-SA/CC-BY-SA/CC-BY-SA

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

☐ Claim own policy
☒ Claim third party
☐ Claim OD / TP at other works hop
☐ For record purpose

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

QIAGEN Qiagen SkelchPlatform_V3

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

NIL
NIL
Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
 Policy No:
 Vehicle Reg. No.: GW2318S
 Party At Fault: UNKNOWN
 Driver (TP): KOH KIAN HENG

Ref. No:
 Date of Loss: 06/02/2018
 Driveable?

Make/Model: MITSUBISHI L300, 1.6 (M)
 Vehicle Colour: WHITE
 Engine No: 4D56KP1233
 Odometer: 5 KM

Vehicle Reg. Date: 25/04/2003
 Chassis No: JMAJNP15V3A000554

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 8

Tan Jiah 97445749
5/3/18 1745
5 days
lump sum sure claimant
renew after repair.

Description of Accident/Loss

ON 06/02/2018 AT ABOUT 1335 HRS .WHILE I WAS TRAVELLING ALONG PANDAN LOOP. I TRAVELLING SLOWLY AND OPEN RIGHT SIGNAL INTEND GO RIGHT TO 234 PANDAN LOOP. HAVE ONE VEHICLE STATIONARY IN FRONT OF 234 PANDAN LOOP WAITING THE GATE OPEN. I THEN STOP MY VEHICLE . AFTER A WHILE , I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT REAR OF MY VEHICLE COLLIDED BY VEHICLE B.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	2,176.60
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,726.60
+ GST 7.00% (S\$)	260.86
Nett Amount (S\$)	3,987.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display () during resurvey
- To provide confirmation
- To provide "Warranty" basis
- To provide "Legal" basis
- To provide "Supplement" basis
- To provide "Subject to" basis

Acknowledged by Repairer
 Signature:
 Date:

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 02 Mar 2018)**Parts:** N/A MITSUBISHI L300 1.6 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GW2318S)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT	0.00	0.00	bt ✓ *540.00 F
2	1		*REAR BOOT TRIMBOARD	0.00	0.00	7x ✓ *77.00 F NN
3	1		*REAR BOOT WIPER ARM	0.00	0.00	x ✓ *40.00 F NN
4	1		*REAR BOOT GARNISH	0.00	0.00	de ✓ *75.00 F
5	1		*REAR BUMPER	0.00	0.00	de ✓ *135.00 F
6	6		*REAR BUMPER CLIPS	0.00	0.00	all ✓ *21.00 F
7	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	all ✓ *56.00 F
8	2		*REAR BUMPER BRACKET	0.00	0.00	x? ✓ *40.00 F R
9	1		*REAR END PANEL	0.00	0.00	bt ✓ *210.00 F
10	1		*REAR BUMPER SIDE (LH)	0.00	0.00	de ✓ *95.00 F
11	1		*REAR TAIL LAMP (LH)	0.00	0.00	all ✓ *140.00 F
12	1		*REAR WINDSCREEN RUBBER	0.00	0.00	all ✓ *350.00 F
13	1		*REAR SPARE TYRE HOLDER	0.00	0.00	Rx ✓ *105.00 F
14	1		*REAR BOOT 70 KM/M STICKER	0	0.00	all ✓ *10.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	1,894.00
+ Margin on L,N Items 15.00% (S\$)	282.60
Total Parts (S\$)	2,176.60

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK,WELD,REMOVE & FIX ABOVE PARTS	New	7 600 800.00
2	TO PUTTY ,RESPRAY PAINTING ON AFFECTING AREAS	New	500 600.00
3	TO REMOVE & REFIX ABOVE REAR WINDSCREEN	New	✓ 120.00
4	TO CHECK WIRING	New	✓ 30.00
Gross Labour Cost (S\$)			1,550.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

NIL

NIL

Singapore

Claimant Insurer: AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

Claim Type: THIRD PARTY

Ref. No:

Policy No:

Date of Loss: 06/02/2018

Vehicle Reg. No.: GW2318S

Driveable?

Party At Fault: UNKNOWN

Driver (TP): KOH KIAN HENG

Make/Model: MITSUBISHI L300, 1.6 (M)

Vehicle Reg. Date: 25/04/2003

Vehicle Colour: WHITE

Engine No: 4D56KP1233

Chassis No: JMAJNP15V3A000554

Odometer: 5 KM

Paint Type:

Total Loss? NO

Est. Duration of
Repair (day)

8

Description of
Accident/Loss

ON 06/02/2018 AT ABOUT 1335 HRS .WHILE I WAS TRAVELLING ALONG PANDAN LOOP. I TRAVELLING SLOWLY AND OPEN RIGHT SIGNAL INTEND GO RIGHT TO 234 PANDAN LOOP. HAVE ONE VEHICLE STATIONARY IN FRONT OF 234 PANDAN LOOP WAITING THE GATE OPEN. I THEN STOP MY VEHICLE . AFTER A WHILE , I FEEL AN IMPACT FROM MY REAR. I NOTICED THAT REAR OF MY VEHICLE COLLIDED BY VEHICLE B.

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	2,176.60
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	3,726.60
+ GST 7.00% (\$\$)	260.86
Nett Amount (\$\$)	3,987.46

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 02 Mar 2018) Unit Repair \$7000
Parts: N/A MITSUBISHI L300 1.6 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GW2318S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT	0.00	0.00	bt ✓ *540.00 F
2	1		*REAR BOOT TRIMBOARD	0.00	0.00	? *77.00 F
3	1		*REAR BOOT WIPER ARM	0.00	0.00	x *40.00 F
4	1		*REAR BOOT GARNISH	0.00	0.00	de ✓ *75.00 F
5	1		*REAR BUMPER	0.00	0.00	de ✓ 135.00 F
6	6		*REAR BUMPER CLIPS	0.00	0.00	all ✓ *21.00 F
7	2		*REAR BUMPER SIDE RETAINER	0.00	0.00	all ✓ *56.00 F
8	2		*REAR BUMPER BRACKET	0.00	0.00	? *40.00 F
9	1		*REAR END PANEL	0.00	0.00	bt ✓ *210.00 F
10	1		*REAR BUMPER SIDE (LH)	0.00	0.00	de ✓ *95.00 F
11	1		*REAR TAIL LAMP (LH)	0.00	0.00	all ✓ *140.00 F
12	1		*REAR WINDSCREEN RUBBER	0.00	0.00	all ✓ *350.00 F
13	1		*REAR SPARE TYRE HOLDER	0.00	0.00	Rv ✓ *105.00 F
14	1		*REAR BOOT 70 KM/M STICKER	0	0.00	all ✓ *10.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	\$1622.00	1,894.00
+ Margin on L,N Items 15.00% (\$\$)	Spett \$101	282.60
Total Parts (\$\$)		2,176.60

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimate Report

There are no new miscellaneous items selected.

No Particulars

Labour Items		Lab.Type	Amount
1	TO KNOCK,WELD,REMOVE & FIX ABOVE PARTS	New	800.00
2	TO PUTTY ,RESPRAY PAINTING ON AFFECTING AREAS	New	500 600.00
3	TO REMOVE & REFIX ABOVE REAR WINDSCREEN	New	✓ 120.00
4	TO CHECK WIRING	New	✓ 30.00
Gross Labour Cost (\$\$)		(750)	1,550.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

total \$2882
 under \$2000 Chapman
 ok Mrs. Revett.
 ok 2/15/88

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004210/T1VD3N2

Date: 23/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29069239MKF
Claimant Vehicle No :	GW2318S	Insured Vehicle No :	YN2112C
Date of Loss:	06/02/2018	Nature of Claim:	TP
		Claim No:	549001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW2318S	Engine No:	4D56KP1233
Make & Model:	MITSUBISHI L300, 1.6 (M)	Chassis No:	JMAJNP15V3A000554
Reg. Date:	25/04/2003 (Man. Year: 2003)	Odometer:	194157 km
Colour:	White		
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185R14	Rear Tyre Size:	185R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,176.60	1,875.30	301.30	13.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,250.00	300.00	19.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,726.60	3,125.30	601.30	16.14
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	3,726.60	2,000.00	1,726.60	46.33
+ GST 7.00/7.00% (S\$)	260.86	140.00	120.86	46.33
Nett Amount (S\$)	3,987.46	2,140.00	1,847.46	46.33

INSPECTION

Date of Assignment:	05/03/2018	Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	05/03/2018	Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 May 2018)	
Parts:	N/A	mitsubishi L300 1.6 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW2318S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT (WCP)	Bent	540.00 F	*540.00 F
2	1		*REAR BOOT TRIMBOARD (WCP)	Not Necessary	77.00 F	*- F
3	1		*REAR BOOT WIPER ARM (WCP)	Not Necessary	40.00 F	*- F
4	1		*REAR BOOT GARNISH (WCP)	Deformed	75.00 F	*75.00 F
5	1		*REAR BUMPER (WCP)	Bent	135.00 F	*135.00 F
6	6		*REAR BUMPER CLIPS (WCP)	Necessary	21.00 F	*21.00 F
7	2		*REAR BUMPER SIDE RETAINER (WCP)	Necessary	56.00 F	*56.00 F
8	2		*REAR BUMPER BRACKET (WCP)	Repair	40.00 F	*- F
9	1		*REAR END PANEL (WCP)	Bent	210.00 F	*210.00 F
10	1		*REAR BUMPER SIDE (LH) (WCP)	Deformed	95.00 F	*95.00 F
11	1		*REAR TAIL LAMP (LH) (WCP)	Cracked	140.00 F	*140.00 F
12	1		*REAR WINDSCREEN RUBBER (WCP)	Cracked	350.00 F	*350.00 F
13	1		*REAR SPARE TYRE HOLDER (WCP)	Repair	105.00 F	*- F
14	1		*REAR BOOT 70 KM/M STICKER	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	1,894.00	1,632.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	282.60	243.30
Total Parts (\$\$)	2,176.60	1,875.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD,REMOVE & FIX ABOVE PARTS	New	800.00	600.00
2	TO PUTTY ,RESPRAY PAINTING ON AFFECTING AREAS	New	600.00	500.00
3	TO REMOVE & REFIX ABOVE REAR WINDSCREEN	New	120.00	120.00
4	TO CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,550.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >