

INSURER

INS. CASE OWNER: Joyce

CC 3 / QBE18004224 / KES

LKK:  
IDAC:

KEA3

Surveyor: KENNETH

DOI: 02/05/18

Date / Time: 02/05/18

Registered in Meritmen: \_\_\_\_\_

Pre-assign / CCU / FTE



Insured Vehicle No. : XD 9317Y

Claim No. : VC011224

Name of Insured : POH WAH MACHINERY & TRADING PTE LTD

Policy No. : 8-V0010603-MVA-R002

Insured Tel No. : \_\_\_\_\_ HP: 8259 7428

Make / Model : ISUZU

Excess Sec II :SS \_\_\_\_\_ D.O.A: 24/02/18

Place of Accident : WOODLANDS AVE 2 TO SLE AFT TRAFFIC LIGHT JUNCTION

Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age : TAN ENG HOCK

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Driver Tel No. : 82997428 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHC 59042



INSRS:  
WSP: Trans-Tab (Amic)  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
<u>06/02/18 (Shc)</u>	Call OI: <u>34.04.18</u>	
<u>24-04-18</u>	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 05/05/18 Sent By: shirley new

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: WNC

Repair Cost: 45 \$5,800 ( 5 days) Reduction: 89 % Email  Call

FINAL SETTLEMENT Date/Time: 10.01.20 Confirm with: WNC Email  Call

Final Liability: 100 % 50 (Agreed / Assessed) BOLA S/N No. : Nil  
 Repair Cost: with 15% (30%) \$5,568.00  
 Loss of Rental (LOR): 100% \$5,355.11 ( 7 days) = \*101.96  
 Loss of Use (LOU): - \$5 - (5 x days)  
 Loss of Income (LOI): 330.00 (\$50 x 7 days)  
 LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]  
 GIA/LTA Search - \$5 -  
 Medical: - \$5 -  
 Disbursement: - \$5 - (e.g. Tow/Independent)  
 Legal Cost: - \$5 -

Total: 16,196.22 \$5,098.11 Global Sum \$5: 3,100

FINAL PAYMENT Date/Time: 10.01.20 Confirm with: WNC Email  Call

Payee 1: \$5,100.00 Name 1: Trans-Tab Auto Services Pte Ltd.

Payee 2: (Strike if N.A.) \$5 Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$5 Name 3: \_\_\_\_\_

**COPY SENT**  
21/1/2020





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Exports En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE18004224/Kys3	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 05-03-2018	
		Code : QBE	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XD 9317Y	Veh. Inspected	SHC 5904Z
Policy No.	8-V0010603-MVA-R002	Coverage (\$)	0.00
Claim No.	VC011224	Excess (\$)	0.00
Assign From		Assign Date	05/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	24/02/2018	Inspection Date	02/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5904Z - QBE***Not Authored**Li Peng & Good*

Vehicle No.:	SHC5904Z - JHOW
Chassis No.:	VF1ABL15AUC280978
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	24.02.2018
Third Party Insurer :	QBE

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>Per</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Per</i> 768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	<i>Per</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Per</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Per</i> 44.99 ✓
6	1	BUMPER REFLECTOR RH	\$	<i>Per</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Per</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Per</i> 44.99 X
9	1	ROCKER PANEL OUTER RH	\$	<i>Per</i> 987.49 X
10	1	SILL PANEL OUTER RH	\$	<i>Per</i> 3,663.62 X
11	1	FENDER PANEL REAR RH	\$	<i>Per</i> 3,299.13 ✓
12	1	FENDER PANEL INNER TRIM REAR	\$	<i>Per</i> 671.45
13	1	WHEELARCH REAR RH	\$	<i>Per</i> 543.47
14	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	<i>Per</i> 3,039.04
15	1	KUCKLE ARM REAR RH	\$	<i>Per</i> 736.67
16	1	LOWER ARM REAR RH	\$	<i>Per</i> 905.99
17	1	ABSORBER REAR RH	\$	<i>Per</i> 389.75
18	1	TAILLAMP RH	\$	<i>Per</i> 552.55
19	1	TAILLAMP PANEL RH	\$	<i>Per</i> 986.70
20	1	EXHAUST REAR	\$	<i>Per</i> 7,489.05 X
21	1	EXHAUST CAP REAR	\$	<i>Per</i> 230.49
22	1	DOOR PANEL REAR RH	\$	<i>Per</i> 2,844.66
23	1	DOOR GUIDE REAR RH	\$	<i>Per</i> 176.82
24	1	DOOR HINGE UPPER RH	\$	<i>Per</i> 274.50
25	1	DOOR HINGE LOWER RH	\$	<i>Per</i> 300.55
26	1	DOOR CHECK REAR RH	\$	<i>Per</i> 203.06
27	1	DOOR LOCK REAR RH	\$	<i>Per</i> 908.75
28	1	DOOR GRAB HANDLE REAR RH	\$	<i>Per</i> 210.96
29	1	DOOR HANDLE OUTER REAR RH	\$	<i>Per</i> 126.49
30	1	DOOR HANDLE CAP REAR RH	\$	<i>Per</i> 35.52
31	1	DOOR HANDLE SEAL REAR RH	\$	<i>Per</i> 7.89
32	1	DOOR HANDLE COVER REAR RH	\$	<i>Per</i> 13.22
33	1	DOOR HANDLE MODULE REAR RH	\$	<i>Per</i> 133.60
34	1	DOOR FINISHER REAR RH	\$	<i>Per</i> 423.10

**TRANS-CAB AUTO SERVICES PTE LTD**

**AAD1802-237**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5904Z - QBE**

35	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>Sm</i>	410.66	X
36	1	DOOR SEAL REAR RH	\$	<i>Sm</i>	162.02	X
37	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sm</i>	334.69	X
38	1	DOOR MOULDING REAR RH	\$	<i>Sm</i>	176.82	X
39	1	DOOR PANEL FRT RH	\$	<i>A</i>	2,844.66	X

<b>TOTAL</b>	<b>\$</b>	<b>35,479.66</b>
10%	<b>\$</b>	<b>3,547.97</b>
	<b>\$</b>	<b>31,931.70</b>

**Special Nett**

1	1SET	PARKING AID	\$	<i>Sm</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>nr</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nr</i>	33.00	✓
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>nr</i>	10.00	X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>nr</i>	20.00	X
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nr</i>	22.00	X
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nr</i>	66.00	X
8	1	EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	X
9	1	TAILLAMP CLIP RH	\$	<i>nr</i>	5.00	X
10	1SET	WHEELARCH CLIP RR RH	\$	<i>nr</i>	66.00	X
11	2	REAR WINDSCREEN SELANT	\$	<i>nr</i>	80.00	<i>40sm</i>
12	1	WINDSCREEN MOULDING	\$	<i>nr</i>	100.00	✓
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nr</i>	100.00	<i>30sm</i>
14	1	CAP HUB RH RR	\$	<i>Sm</i>	35.00	X
15	1	RIM RH RR	\$	<i>Sm</i>	385.00	X
16	1	TYRE RH RR	\$	<i>Sm</i>	330.00	X
17	1	DOOR STICKER "Trans-cab"	\$	<i>nr Sm</i>	80.00	X
18	1	DOOR STICKER "Classic"	\$	<i>nr</i>	30.00	X
19	1	DOOR STICKER "6555-3333"	\$	<i>nr</i>	80.00	<i>60sm</i>

<b>TOTAL</b>	<b>\$</b>	<b>2,225.82</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>34,157.52</b>

Putty And Spray Painting Of The Affected Portion. \$ 4,500.00 *66d*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 4,200.00 *Foot*

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5904Z - QBE**

To reinstall rear bumper parking sensor.	\$	170.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	~ 170.00 X
To repair and realign rear exhaust pipe.	\$	170.00	~ 170.00 X
Towing Fees	\$	120.00	~ 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	101
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	121
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	~ 380.00 X

**TOTAL \$ 10,990.00****Over All Total \$ 45,147.52****(PARTS BY PARTS)  
Repair Days****15 Days  
5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/QBE18004224/Kys3

Date: 05.03.2018

The Motor Claims Department  
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 5904Z**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/03/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	45,147.52
Revised Estimate Amount	: S\$	6,006.32
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
O/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5904Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002374
Chassis No.:	VF1ABL15AUC280978
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$31,044.00
<b>Total Rebate Amount:</b>	<b>\$40,417.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Feb 2018

OK

## Shirley Hiew (LKK Auto)

---

**From:** Joyce Foo <joyce.foo@qbe.com>  
**Sent:** Tuesday, 6 March 2018 9:05 AM  
**To:** Thin Thin (LKKAuto); Admin A; Jas Khine (LKKAuto); Shirley Hiew (LKK Auto)  
**Subject:** FW: Direct Settlement - Accident Involving XD9317Y (OI : QBE - TBA) AND SHC5904Z (TP : LKK REF - CC3/QBE18004224/Kys3) on 24/02/2018  
**Attachments:** TP GIA REPORT.pdf; TP ESTIMATE- MARKED.pdf; Preliminary Advice.pdf; LKK SURVEYOR PHOTO.pdf; XD9317Y-18.pdf

Our Ref. VC011224

Dear Shirley

Attached is OI GIA report for your retention.

Thank You & Best Regards

---

Joyce Foo  
Senior Assistant - Claims  
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd  
Phone: +65 6477 1184  
Email: joyce.foo@qbe.com  
Visit us on the web at [www.qbe.com.sg](http://www.qbe.com.sg)



**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Monday, 5 March, 2018 7:37 PM  
**To:** Joyce Foo <joyce.foo@qbe.com>; Jas Khine (LKKAuto) <jaskhine@lkkauto.com>  
**Cc:** Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving XD9317Y (OI : QBE - TBA) AND SHC5904Z (TP : LKK REF - CC3/QBE18004224/Kys3) on 24/02/2018

### **WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5904Z at M/s Trans-Cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/QBE18004224/Kea3q2

1 RAFFLES QUAY #29-10 SOUTH  
TOWERSINGAPORE 048583

Date : 20-01-2020



Code : QBE

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 9317Y	Veh. Inspected	SHC 5904Z
Policy No.	8-V0010603-MVA-R002	Coverage (\$)	0.00
Claim No.	VC011224	Excess (\$)	0.00
Assign From		Assign Date	02/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC280978	Colour	METALLIC WHITE / RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	7 mm
L/H Front Tyre	215/60 R16	FALKEN	7 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	24/02/2018	Inspection Date	02/03/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS,  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5904Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	987.49	-
1	SILL PANEL OUTER RH	TO REPAIR SEE LABOUR	3,663.62	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	TO REPAIR SEE LABOUR	543.47	-
1	FENDER WHEEL HOUSE PANEL REAR RH	TO REPAIR SEE LABOUR	3,039.04	-
1	KNUCKLE ARM REAR RH	SERVICEABLE	736.67	-
1	LOWER ARM REAR RH	SERVICEABLE	905.99	-
1	ABSORBER REAR RH	SERVICEABLE	389.75	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-

Report Ref No. CC3/QBE18004224/Kea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-3,547.97	-445.26
			31,931.70	4,007.32
	<b>SPECIAL NETT ITEMS</b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR RH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00

Report Ref No. CC3/QBE18004224/Kea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	SERVICEABLE	385.00	-
1	TYRE RH RR (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER 'CLASSIC' (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
			2,225.82	329.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		4,500.00	660.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER RH,SILL PANEL OUTER RH,WHEELARCH REAR RH,FENDER WHEEL HOUSE PANEL REAR RH,TAILLAMP PANEL RH,EXHAUST REAR,EXHAUST CAP REAR,DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK REAR RH AND DOOR PANEL FRT RH .		4,200.00	700.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-

Report Ref No. CC3/QBE18004224/Kea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			10,990.00	1,670.00
<b>GRAND TOTAL</b>			<b>45,147.52</b>	<b>6,006.32</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,800.00</b>

Report Ref No. CC3/QBE18004224/Kea3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.