

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHC5904Z - QBE**

AAD1802-237

*Not Notion*  
*Li Ling @ 4 food*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHC5904Z - JHOW**  
**VF1ABL15AUC280978**  
**RENAULT**  
**LATITUDE**  
**24.02.2018**  
**QBE**

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Pr</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Sm</i> 768.84 X
3	1 BUMPER BRACKET CTR REAR	\$ <i>Sm</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$ <i>Sm</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$ <i>Pr</i> 44.99 ✓
6	1 BUMPER REFLECTOR RH	\$ <i>Sm</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$ <i>Sm</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$ <i>Sm</i> 44.99 X
9	1 ROCKER PANEL OUTER RH	\$ <i>R</i> 987.49 X
10	1 SILL PANEL OUTER RH	\$ <i>R</i> 3,663.62 X
11	1 FENDER PANEL REAR RH	\$ <i>Pr</i> 3,299.13 ✓
12	1 FENDER PANEL INNER TRIM REAR	\$ <i>Sm</i> 671.45
13	1 WHEELARCH REAR RH	\$ <i>R</i> 543.47
14	1 FENDER WHEEL HOUSE PANEL REAR RH	\$ <i>R</i> 3,039.04
15	1 KUCKLE ARM REAR RH	\$ <i>Sm</i> 736.67
16	1 LOWER ARM REAR RH	\$ <i>Sm</i> 905.99
17	1 ABSORBER REAR RH	\$ <i>Sm</i> 389.75
18	1 TAILLAMP RH	\$ <i>Sm</i> 552.55
19	1 TAILLAMP PANEL RH	\$ <i>R</i> 986.70
20	1 EXHAUST REAR	\$ <i>R</i> 7,489.05 X
21	1 EXHAUST CAP REAR	\$ <i>R</i> 230.49
22	1 DOOR PANEL REAR RH	\$ <i>R</i> 2,844.66
23	1 DOOR GUIDE REAR RH	\$ <i>Sm</i> 176.82
24	1 DOOR HINGE UPPER RH	\$ <i>R</i> 274.50
25	1 DOOR HINGE LOWER RH	\$ <i>R</i> 300.55
26	1 DOOR CHECK REAR RH	\$ <i>Sm</i> 203.06
27	1 DOOR LOCK REAR RH	\$ <i>R</i> 908.75
28	1 DOOR GRAB HANDLE REAR RH	\$ <i>Sm</i> 210.96
29	1 DOOR HANDLE OUTER REAR RH	\$ <i>Sm</i> 126.49
30	1 DOOR HANDLE CAP REAR RH	\$ <i>Sm</i> 35.52
31	1 DOOR HANDLE SEAL REAR RH	\$ <i>Sm</i> 7.89
32	1 DOOR HANDLE COVER REAR RH	\$ <i>Sm</i> 13.22
33	1 DOOR HANDLE MODULE REAR RH	\$ <i>Sm</i> 133.60
34	1 DOOR FINISHER REAR RH	\$ <i>Sm</i> 423.10

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1802-237

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5904Z - QBE

35	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>Sm</i>	410.66	X
36	1	DOOR SEAL REAR RH	\$	<i>Sm</i>	162.02	X
37	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sm</i>	334.69	X
38	1	DOOR MOULDING REAR RH	\$	<i>Sm</i>	176.82	X
39	1	DOOR PANEL FRT RH	\$	<i>R</i>	2,844.66	X

<b>TOTAL</b>	\$	<b>35,479.66</b>
<b>10%</b>	\$	<b>3,547.97</b>
	\$	<b>31,931.70</b>

**Specical Nett**

1	1SET	PARKING AID	\$	<i>Sm</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>Nu</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>Nu</i>	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>Nu</i>	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>Nu</i>	20.00	X
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>Nu</i>	22.00	X
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>Nu</i>	66.00	X
8	1	EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	X
9	1	TAILLAMP CLIP RH	\$	<i>Nu</i>	5.00	X
10	1SET	WHEELARCH CLIP RR RH	\$	<i>Nu</i>	66.00	X
11	2	REAR WINDSCREEN SELANT	\$	<i>Nu</i>	80.00	<i>40sm</i>
12	1	WINDSCREEN MOULDING	\$	<i>Nu</i>	100.00	✓
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>Nu</i>	100.00	<i>30sm</i>
14	1	CAP HUB RH RR	\$	<i>Sm</i>	35.00	X
15	1	RIM RH RR	\$	<i>Sm</i>	385.00	X
16	1	TYRE RH RR	\$	<i>Sm</i>	330.00	X
17	1	DOOR STICKER "Trans-cab"	\$	<i>Nu Sm</i>	80.00	X
18	1	DOOR STICKER "Classic"	\$	<i>Nu</i>	30.00	X
19	1	DOOR STICKER "6555-3333"	\$	<i>Nu</i>	80.00	<i>60sm</i>

<b>TOTAL</b>	\$	<b>2,225.82</b>
<b>TOTAL PARTS</b>	\$	<b>34,157.52</b>

Putty And Spray Painting Of The Affected Portion. \$ 4,500.00 *600*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 4,200.00 *700*

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.2 ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G  
**SHC5904Z - QBE**

**AAD1802-237**

To reinstall rear bumper parking sensor.	\$	170.00	<i>60d</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>30d</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nr</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nr</i> 170.00	<i>X</i>
Towing Fees	\$	<i>nr</i> 120.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	<i>100d</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>120d</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00	<i>X</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nr</i> 380.00	<i>X</i>

<b>TOTAL</b>	<b>\$</b>	<b>10,990.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>45,147.52</b>

**(PARTS BY PARTS)**  
**Repair Days**

*15 Days*  
*50d*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: