

A14

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7134B

DATE 1/3/2018 16:58

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover X			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
				\$ 135.70
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00 180
	Wiring Charge			\$ 50.00 X
	Tuff Kote			\$ 50.00 X
	R/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 2,461.58

Kelvin LKK
 2/3/18 1105hrs
 2 Pys
 PIP
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.