

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20180302/0499		LOCATION OF FIRE:	
		Along Changi North Crescent	
TIME OF CALL: 13:59:12 hrs		Near Lamp Post No. 47 Singapore	
STATION COVERAGE: Tampines Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: Front left tyre of an Isuzu truck (XD1815D).			
METHOD OF EXTINGUISHMENT: By SCDF crew using two 38mm hose line jets from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Frictional heat at front left tyre)			
DAMAGE SUSTAINED: As a result of the fire, the truck was damaged. The skip container and its contents sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
DANNIES ANG WEITONG			

This is a computer generated Fire Report. No signature is required.

for COMMISSIONER

SINGAPORE CIVIL DEFENCE FORCE