

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6887C

DATE 5/3/2018 10:37

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>X repair</i>			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips X			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover X			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat X			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 380.00	
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	X
	R/Refix Reverse Sensor			\$ 120.00	X
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,461.58	
	<i>Kalin 11/11/18</i>				
	<i>5/3/18 11.00 L</i>				
	<i>2 Days</i>				
	<i>PIP</i>				
	<i>After Repair photo</i>				
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party surveys on a "No Win No Fee" basis • No illegal modification(s) is allowed • Supplementary item(s) must be approved and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				