

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST065/18/TP
Your Ref: TP claim against SKA9197X

5-Mar-18

AXA Insurance Singapore Pte Ltd
#01-01 GB Building
Singapore 069542

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Mitsubishi Lancer no: SJP475K

Date of accident: 01-01-2018

Parts supply:

- 1 pc Front bumper
- 2 pcs Front bumper retainers @\$40.00
- 2 pcs Front bumper brackets @\$65.00
- 8 pcs Front bumper clips @\$3.50
- 1 pc Headlamp L/h
- 1 pc Headlamp clip L/h
- 1 pc Front L/h fender
- 1 pc Front L/h fender inner shield
- 1 pc Rear L/h door
- 1 pc Rear l/h door weatherstrip
- 1 pc Rear L/h door inner lock
- 1 pc Rear L/h door outer moulding
- 1 pc Rear L/h door outer handle
- 1 pc Rear L/h fender
- 1 pc Rear L/h fender inner shield
- 5 pcs Rear L/h fender inner shield clips @\$3.50
- 1 pc Taillamp L/h
- 1 pc Taillamp clip L/h
- 1 pc Rear bumper
- 2 pcs Rear bumper retainers @\$40.00
- 2 pcs Rear bumper brackets @\$65.00
- 8 pcs Rear bumper clips @\$3.50
- 1 pc Rear bumper lip
- 1 pc Rear windscreen moulding

Labour charges:

- To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.
- To respray affected part.
- To remove & refit rear windscreen.
- To remove & refit rear L/h door glass
- To apply underseal.
- To check wirings.

ESTIMATE

- KK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

deepcut, SS	622.00	✓
MS set	80.00	100
11	130.00	X
101	28.00	—
CRQ	480.00	—
11	10.00	X
10/101	420.00	—
101	85.00	—
11	780.00	X
11	112.00	X
11	220.00	X
11	105.00	X
11	95.00	0
10/101	641.00	X
11	65.00	X
11	17.50	X
11	404.00	X
11	10.00	X
11	653.00	X
11	80.00	X
11	130.00	X
11	28.00	X
11	661.00	X
11	89.00	X
	5,945.50	
Less 10%:	(594.55)	

1,500.00	600
1,800.00	1000
11 100.00	X
11 40.00	X
60.00	50
30.00	✓
SS	8,880.95
	3,187.5
	28

no f. Allowed
L/h
a/s 2500/-
42.
before plus after
repair
6/3/18