



UNIQUE MOTORSPORTS PTE LTD

11 Tannery Lane Singapore 207930 (Head Office)

1007/1009 Serangoon Road Singapore 328168 (Show Room)

1 Kaki Bukit Ave 6 #02-54/55 Autobay @ Kaki Bukit Singapore 417883

48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586

280 Woodlands Industrial Park E5 #01-43 Harvest Singapore 757322

Tel: 6292 5578 (3 lines) Fax: 6295 5579

Tel: 6341 5378 (3 lines) Fax: 6341 7379

Tel: 6844 6378 (3 lines) Fax: 6844 6379

Tel: 6515 4978 (3 lines) Fax: 6515 4979

Tel: 6339 2178 (3 lines) Fax: 6339 3379

Date: 03/03/2018

Make / Model: Honda GLH 125

Registration No: FBH9597U

Damage Assessment

S/N	Description	Condition	Qty	Unit Price	Total Price
1	CUSTOMIZED CRASHBAR	✓	1	\$320.00	\$320.00
2	HANDLEBAR	✓	1	\$109.00	\$109.00
3	MIRROR - RIGHT	✓	1	\$84.00	\$84.00
4	BRAKE LEVER	✓	1	\$62.00	\$62.00
5	REAR FENDER ASSY	✓	1	\$181.00	\$181.00
6	NUMBER PLATE LIGHT ASSY	✓	1	\$113.00	\$113.00
7	EXHAUST PROTECTOR	✓	1	\$95.00	\$95.00
8	REAR BOX	✓	1	\$192.00	\$192.00
9	PERFORM ELECTRICAL CHECK	✗	1	\$30.00	\$30.00
10	TOWING FROM ACCIDENT SCENE TO WORKSHOP		1	\$35.00	\$35.00
11	LABOUR TO REPLACE PARTS DUE TO ACCIDENT		1	\$150.00	\$150.00

Number plate \$25 ✓ 15 (SN)

Sub Total \$1,371.00
GST 7% \$95.97
Grand Total \$1,466.97

UNIQUE MOTORSPORTS PTE LTD
GST Reg. No. 200907910H
11 Tannery Lane
Singapore 207930
Tel / Fax: 6292 5578 / 6295 5579

Prepared By: Alvin Koh

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 900

lumpsum repair

After repair photos

2 Days

07/3/18

Chen Qiqi 82880282