

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0294/2018/CCS
Date : 7-Mar-18

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle no: SLP 274 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Audrey Lim Sock Ju
Address : 46 Jalan Bukit Ho Swee
#02-884
Singapore 160046
Telephone : HP +65 81265337
Type of Claim : Third Party Claims
Policy No. : 2100401339-03000
Vehicle No : **SJG 8607 S**
Model Code : Audi A3 SB 1.4 TFSI
Model / Year : Jan-15
Engine No : CZC 229417
Chassis No : WAUZZZ8V6FA092894
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Mar-18
Place of Accident : Upper Changi Road East slip rd towards TPE / SLE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle S1G 8607 S.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper with lower spoiler, inspect for damages and reinforcement and end panelling. Repair and re-align rear lid. Re-install all parts removed.	\$ 1,200.00	500
3	To respray paint on rear bumper and rear lid.	\$ 1,200.00	1100
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>2,872.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJG 8607 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>del d</i>	\$ 1,619.00	✓
2	REAR BUMPER FIXING PARTS <i>me c</i>	\$ 166.00	X
3	REAR BUMPER SPOILER <i>me c</i>	\$ 206.00	X
4	REAR PARKING AID SENSOR <i>me c</i>	\$ 421.00	X
5	REAR LID AUDI LOGO <i>2</i>	\$ 108.00	✓
6	REAR LID 'A3' INSCRIPTION <i>me</i>	\$ 83.00	✓
7	REAR LID 'TFSI' INSCRIPTION <i>me</i>	\$ 83.00	✓
8	SUNDRIES ?	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		: \$ 2,886.00	
TOTAL LABOUR CHARGES		: \$ 2,872.00	
GRAND TOTAL		: \$ 5,758.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian Lj
23/09/08

Not Authorised, or Repairs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant