

INS. CASE OWNER:

Ung Jee

cc3, LK 1800 4286, PLWA39

LKK:

IDAC:

Surveyor:

Ang

DOI:

ASSIGNMENT

9/3/18

Date / Time:

9/3/18

Registered in Merimen:

6/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 7243B

Name of Insured:

LCRF PLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

3/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Loong Chee Kan

Driver Tel No.:

90106639

(V/L: YES / NO)

Claim No.:

635 991008456

Policy No.:

0909994756

Make / Model:

7. Rienta

Place of Accident:

9 Loyang way

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final? Yes / No

SHA 3801 K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chutong



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

14/3

SHA 3801 K, cc3/AXA 1109306/Hylis/12, 18/10/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

16/3/18

Email letter to OI.

1/1/AN

Need to get video from TP.

07/10/18

19/3/18

Email workshop liability unclear.

18/6/18

Receive TP video RECEIVED 9 OCT 2018

24/8/18

Email to ALG. TP video. Lett advise.

28/8/18

Email from ALG to reject TP claim.

Email to workshop reject claim. Base on TP video TP was straddling in between both lane before encroached into OI's lane.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

50

(

Agreed / Assessed)

BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

reject

A320.00

9/10/18

Surge No: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate # and Cost: _____

OD / T / F / WS / TP RES / OD RES / EVA / INV / MV

To Insp # and Vehicle No: _____

at Work stop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: 2.82 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 3801K

Yr Regn: 15 Jan 27

Type: M.Car / M.Cycle / Bus / Van / Lorry / T / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

C.C.

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 108542

T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: 5TD1CB3F4003558802

Gen. Cond: Good / 6 / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: 195/65R15

R: _____

SS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm

R/Bal: 7 mm

L/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 3 p/8

D.O.I: 5 p/8

Survey held at

CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s R4

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/3/8

ALL PIP \$2217.10 / 18/5/8.

AZ4

PIP

(Red-A 2148.43 49%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

\$ + RS \$ _____

☐ : Inter/ew (\$ _____)

Phone: _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/LCR18004286/K1wa3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 06-03-2018	
			Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 7243B	Veh. Inspected	SHA 3801K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/03/2018	Inspection Date	05/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305121854

Date : 09/03/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHA3801K

Date of Accident : 03-Mar-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG ASIA --- SLE7243B

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,207.10

(b) Labour Charges \$1,010.00

Total for Part-By-Part Repair Cost \$2,217.10

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : KALVIN

Tel : 62148398


Date : 9/3/18

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	*****			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305121854
 REGN NO : SHA3801K
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 15.06.2017
 DATE/TIME IN : 04.03.2018 09:10
 ACCIDENT DATE : 03.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0592-G	FRT DOOR RH**	1	1,227.00	25.00	920.25
0002 28-01-0103-0003-A	Frt Door COMFORTDELGRO RH	1	75.00		75.00
0003 03-01-0302-2057-G	REAR WHEEL CAP RH	1	175.80	25.00	131.85
0004 28-01-0103-2013-A	Rear Door APPS Sticker RH	1	80.00		80.00

SUB-TOTAL : 1,207.10

JOB NATURE

0000 L	PANEL BEATING	400.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	540.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0003 L	TRANSFER OF DOOR	50.00

SUB-TOTAL : 1,010.00


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305121854
REGN NO : SHA3801K
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 15.06.2017
DATE/TIME IN : 04.03.2018 09:10
ACCIDENT DATE : 03.03.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,217.10


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

VEHICLE NO : SHA 3801K

MAKE :

MODEL : TOYOTA PRIUS

Agasia-CP(P)

5/3/2018 12:24

IS

LKK - Kalvin

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER, RH <i>X repair</i>			\$ 817.50	
REAR FENDER SHEILD (RH) <i>X repair</i>			\$ 134.20	
PANEL SUB-ASSY, REAR DOOR, RH <i>X repair</i>			\$ 1,227.00	
FRONT DOOR BAR FRONT (RH) <i>X repair</i>			\$ 140.20	
REAR WHEEL HUB CAP (RH) <i>hand</i>			\$ 175.80	
<i>Front Door (RH) / Part \$ 1127.00</i>				
SUB TOTAL			\$ 2,494.70	
LESS 25%			\$ 623.68	
DISCOUNTED TOTAL			\$ 1,871.03	
FRONT DOOR COMFORT LOGO, RH <i>u</i>			\$ 75.00	NETT
REAR DOOR COMFORT & APPS STICKER, RH <i>u</i>			\$ 80.00	NETT
			\$ 155.00	
Labour Charge			\$ 850.00	<i>400</i>
Panel Beating			\$ 600.00	<i>500</i>
Spray Painting Charge			\$ 50.00	<i>100</i>
Wiring Charge			\$ 50.00	<i>20</i>
Tuff Kote			\$ 400.00	<i>X 100</i>
Front Chassis Alignment Charge			\$ 150.00	<i>X 100</i>
Remove/Refix Cushion & Upholstery Rear			\$ 120.00	<i>X 100</i>
Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>50</i>
Transfer of Door				
TOTAL LABOUR			\$ 2,340.00	
ESTIMATE TOTAL			\$ 4,366.03	

Kalvin (1/1/18)

5/3/18 13.00

3 Rys

P/P

Before Paint p/LH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

REPAIR ESTIMATE

VEHICLE NO : SHA 3801K

MAKE :

MODEL : TOYOTA PRIUS

5/3/2018 12:24

IS

Aig Asia-CP(P)

LKK-Kalvin

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER, RH <i>X</i>			\$ 817.50	
REAR FENDER SHEILD (RH) <i>X</i>			\$ 134.20	
PANEL SUB-ASSY, REAR DOOR, RH <i>X</i>			\$ 1,227.00	
FRONT DOOR BAR FRONT (RH) <i>X</i>			\$ 140.20	
REAR WHEEL HUB CAP (RH) <i>-</i>			\$ 175.80	
<i>Front Door (RH) -</i>				
SUB TOTAL			\$ 2,494.70	
LESS 25%			\$ 623.68	
DISCOUNTED TOTAL			\$ 1,871.03	
FRONT DOOR COMFORT LOGO, RH <i>-</i>			\$ 75.00	NETT
REAR DOOR COMFORT & APPS STICKER ,RH <i>-</i>			\$ 80.00	NETT
			\$ 155.00	
Labour Charge				
Panel Beating			\$ 850.00	<i>400</i>
Spray Painting Charge			\$ 600.00	<i>540</i>
Wiring Charge			\$ 50.00	<i>0</i>
Tuff Kote			\$ 50.00	<i>20</i>
Front Chassis Alignment Charge			\$ 400.00	<i>X</i>
Remove/Refix Cushion & Upholstery Rear			\$ 150.00	<i>X</i>
Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>X</i>
Transfer of Door			\$ 120.00	<i>50</i>
TOTAL LABOUR			\$ 2,340.00	
ESTIMATE TOTAL			\$ 4,366.03	
<i>Kalvin</i> <i>5/3/18 13.30</i> <i>3 Rys</i> <i>PIP</i> <i>Before Paint pht</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary request must be reviewed and is subject to final approval from insurance company Acknowledged by Repairer Signature:				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Friday, 16 March, 2018 2:25 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLE 7243B AND SHA 3801K ON 03/03/2018

Our Ref: CC3/LCR18004286/K1wa3

16 March 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 7243B AND SHA 3801K ON 03/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within 7 days i.e. by **27/03/2018**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref : T 0318 / SHA3801K /CL(st)
Your Ref:
Date : 14-Mar-18

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHA3801K YOUR INSURED SLE7243B
AND OTHER _____ ON 03.03.18

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHA3801K which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving SLE7243B we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 2,372.30
2	5 days Loss of Rental @ \$ 125.40 per day	\$ 627.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation	\$ -
Sub Total :		\$ 3,006.79

HIRER'S CLAIM

7	5 days Loss of Income @ \$ 80.00 per days	\$ 400.00
Total Claims :		\$ 3,406.79

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 8 pcs.
- b) LTA search slip/s of : SLE7243B
- c) GIA / Police report/s of : SHA3801K
- d) Letter of authority from owner / hirer / operator
 - (X) Photograph/s of Accident Scene () Certificate of Insurance
 - () Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

CDGE Taxi Claims Dept

59 Loyang Drive 4th Floor

Singapore 508969

Mainline +65 6383 6280

Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199900001V

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 608286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 1

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO
SHA3801K

MAKE
TOYOTA

MODEL
PRIUS HYBRID(G4)

DATE OF REG
15.06.2017

CHASSIS CODE
JTDKB3FU003558802

INV. NO/DATE
91361837 13.03.2018

JOB NO.
305121854

ODOMETER READING

DATE/TIME IN
04.03.2018 09:10

Description : 3P 03.03.18

S/No Part No.

Qty Unit Price \$Disc Net

PART REQUISITION

0001	04-01-0302-0592	FRIG4 PANEL SUB-ASSY FRON	1	1,227.00	25.00	920.25
0002	28-01-0103-0003	(I40)FRT DOOR LOGO SONATA	1	75.00	0.00	75.00
0003	03-01-0302-2057	FRIG4 CAP WHEEL	1	175.80	25.00	131.85
0004	28-01-0103-2013	I40V3 APP LOGO REAR DOOR	1	80.00	0.00	80.00
SUB-TOTAL :						1,207.10

JOB NATURE

0001	L	PANEL BEATING	400.00	400.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	540.00	540.00
0003	20-00	TUFF COAT ON AFFECTED PARTS.	20.00	20.00
0004	L	TRANSFER OF DOOR	50.00	50.00

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

ACCOUNT No.

INVOICE No.

AMOUNT

BANK/CHQ No.

8010004

91361837

2,372.30

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 2

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO
SHA3801K

MAKE
TOYOTA

MODEL
PRIUS HYBRID(G4)

DATE OF REG
15.06.2017

CHASSIS CODE
JTDEKB3FU003558802

INV. NO/DATE
91361837 13.03.2018

JOB NO.
305121854

ODOMETER READING

DATE/TIME IN
04.03.2018 09:10

S/No Part No.

Qty Unit Price %Disc Net

SUB-TOTAL : 1,010.00

Items total	2,217.10
Add GST @ 7.000 %	155.20
Invoice amount	2,372.30

Issued by : CHEWBEELING 13.03.2018 11:02:35
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91361837	2,372.30	

Our Ref: CT18030105

Date: 13 March 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	03/03/2018 @ 15:30 hrs
ALONG	LOYANG WAY
INVOLVING	SLE7243B

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA3801K** (the "Taxi"). The Taxi was hired to **WAN FOOK LOY IC NO S1110974H** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.40** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

ERATED (TIME)		DATE	NAME OF DRIVER	MILEAGE READING			MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
TO				10	6	4		FROM	TO
		28/2	3 ³ / ₄	10	6	4	87	17.15	4.55
		1/3	Wan	10	6	7	41	06.45	16.45
		1/3	3 ³ / ₄	10	7	1	58	17.15	04.45
		2/3	Wan	10	7	3	82	06.45	16.45
		2/3	3 ³ / ₄	10	7	7	05	17.15	04.00
		3/3	Tay	10	8	0	78	05.00	16.45
		3/3	3 ³ / ₄	10	8	4	15	17.15	04.50
		4/3							
		4/3	Accident					0910	—
		8/3	repar					—	1330

for

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****TOYOTA PRIUS SHA3801K , SLE7243B
LOYANG WAY****ON 03-Mar-18 15:30**

I / We

WAN FOOK LOY(Hirer) NRIC No.: **S1110974H**

and/or

TAY JIT SANG(Relief) NRIC No.: **S0185278Z**

Taxi Number

SHA3801K

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

04-Mar-2018

Name of Hirer

WAN FOOK LOY

Hirer NRIC

S1110974H

Signature :



Address

**184 JELEBU ROAD #08-30
670184**

Contact No.

96352042

Name of Relief

TAY JIT SANG

Relief NRIC

S0185278Z

Signature :



Address

**404 FAJAR RD #07-275
670404**

Contact No.

93889946

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SLE7243B	03 Mar 2018 / 15:30:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Previous](#)[OK](#)

SHAZ801K

Vivian Lau (LKKAUTO)

From: Mavis, Chew <Chew.Mavis@aig.com>
Sent: Tuesday, 28 August, 2018 11:49 AM
To: Vivian Lau (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: RE: Your ref: #6359910084SG003#023# ,Our Ref: CC3/LCR18004286/K1wa3,Accident involving Vehicle SLE 7243B & SHA 3801K on 03/03/2018

Dear Vivian

Thank you for the TP's AVF.

Based on the video, our insured was within his lane while TP was straddling in between both lanes therefore encroached into our insured's lane.

Furthermore, there is no reason for our insured to change to the last lane at that point of time due to roadwork. Kindly proceed to reject third party claim and keep us updated, thank you.

Best Regards,
Ms. Mavis Chew
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +(65) 6419 1970 | Fax +(65) 6835 7416
chew.mavis@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vivian Lau (LKKAUTO) [mailto:vivianlau@lkkauto.com]
Sent: Friday, 24 August, 2018 9:32 AM
To: Mavis, Chew
Cc: Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO)
Subject: Your ref: 6359910084SG,Our Ref: CC3/LCR18004286/K1wa3,Accident involving Vehicle SLE 7243B & SHA 3801K on 03/03/2018

Your ref: 6359910084SG
Our Ref: CC3/LCR18004286/K1wa3

Dear Joee,

Accident involving Vehicle SLE 7243B & SHA 3801K on 03/03/2018

We refer to the above matter.

Enclosed is TP video for your perusal.(video upload in merimen)

Based on the circumstances of both parties and available information in hand. Base on TP video. We are in the opinion that TP was travel in between lane.

Kindly advice on your view/opinion/instruction for this claim.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 28 August 2018 12:09 PM
To: 'richard'; mandy@ltm.sg
Cc: Admin A
Subject: TP Claim for SLF 3623 J ***LKK REF:CC4/AXA17012058/Kja3
Attachments: GBE 3563 Y SIGNED DV.pdf; GBE 3563 7.mp4

WITHOUT PREJUDICE

Dear Richard/Mandy,

We refer to our e-mail on 03/08/2018.

Our principal have reviewed the matter and based on the video evidence and successful claim of our insured against your client's insurer, we regret to inform you that we are unable to look into your claim.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Joy Irene (LKKAuto)
Sent: Friday, 3 August 2018 5:57 PM
To: 'richard' <richard@ltm.sg>; 'Mandy' <mandy@ltm.sg>
Cc: Admin A <admin-a@lkkauto.com>; mandy@ltm.sg
Subject: RE: TP Claim for SLF 3623 J ***LKK REF:CC4/AXA17012058/Kja3

WITHOUT PREJUDICE

Dear Richard,

Attached settlement on our insured's claim against your client's insurer. Claim successful at 90%.

Also attached video for your viewing.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Tuesday, 28 August, 2018 12:14 PM
To: Cecilia Lee Peng Geok
Cc: Thin Thin (LKKAUTO)
Subject: RE: Your Ref: T0318/ SHA 3801K / CL(st), Our Ref: CC3/LCR18004286/K1wa3, Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018
Attachments: Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: T0318/ SHA 3801K / CL(st)
Our Ref: CC3/LCR18004286/K1wa3

Dear Sir/Madam,

Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Based on your client video footage our insured was within his lane while your client was straddling in between both lanes therefore encroached into our insured's lane.

Furthermore, there is no reason for our insured to change to the last lane at that point of time due to roadwork.

We attached herewith our insured's accident report for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cecilia Lee Peng Geok [mailto:cecilialee@sparkcarcare.com]

Sent: Friday, 24 August, 2018 9:04 AM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Re: Your Ref: T0318/ SHA 3801K / CL(st),Our Ref: CC3/LCR18004286/K1wa3,Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018

Importance: High

Without Prejudice

Dear Vivian

Please look into the matter and revert with your offer soon. Our client is chasing.

Thank you.

Best Regards

Cecilia Lee

Claims Department | ComfortDelGro Engineering Pte Ltd

Off: 6214 8354 | Fax: 6214 1843

From: Cecilia Lee Peng Geok

Sent: Wednesday, 25 July 2018 4:28 PM

To: Vivian Lau LKK

Subject: Re: Your Ref: T0318/ SHA 3801K / CL(st),Our Ref: CC3/LCR18004286/K1wa3,Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018

Without Prejudice

Dear Vivian

Our client is chasing for settlement. Please assist to expedite.

Thank you.

Best Regards

Cecilia Lee

Claims Department | ComfortDelGro Engineering Pte Ltd

Off: 6214 8354 | Fax: 6214 1843

From: Cecilia Lee Peng Geok/sparkcarcare/cdge/delgronotes

To: "Vivian Lau (LKKAuto)" <vivianlau@lkkauto.com>

Date: 18/06/2018 02:40 PM

Subject: Re: Your Ref: T0318/ SHA 3801K / CL(st),Our Ref: CC3/LCR18004286/K1wa3,Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018

Without Prejudice

Dear Sir/Madam

Attached video footage. Please note that the video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

[attachment "SHA3801K VC (TS)(1).avi" deleted by Cecilia Lee Peng Geok/sparkcarcare/cdge/delgronotes]

Thank you.

Best Regards

Cecilia Lee

Claims Department | ComfortDelGro Engineering Pte Ltd

Off: 6214 8354 | Fax: 6214 1843

From: "Vivian Lau (LKKAUTO)" <vivianlau@lkkauto.com>

To: Cecilia Lee Peng Geok <cecilialee@sparkcarcare.com>

Cc: "Joy Irene (LKKAUTO)" <joylrene@lkkauto.com>, "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>

Date: 19/03/2018 10:06 AM

Subject: Your Ref: T0318/ SHA 3801K / CL(st), Our Ref: CC3/LCR18004286/K1wa3, Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018

WITHOUT PREJUDICE

Your Ref: T0318/ SHA 3801K / CL(st)

Our Ref: CC3/LCR18004286/K1wa3

Dear Sir/Madam,

Accident involving Vehicle SHA 3801K & SLE 7243B ON 03/03/2018

We refer to the above matter

We are of the opinion that this is a case of conflicting versions. There is no conclusive evidence to substantiate either's parties version. Enclosed herewith a copy of our insured's accident report for your perusal.

Meanwhile, we would like to request the CCTV footage as stated in your client's accident report in order to seek further instruction from our principal.

Our insured reported no Collision.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at her DID 6841 8625.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[attachment "Sketch Plan .pdf" deleted by Cecilia Lee Peng Geok/sparkcarcare/cdge/delgronotes]

...CLAIM SUBFOLDER...(Pending for Survey Report)

































Revoked / No settlement















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Mar 2018 Edit Reg		05 Mar 2018 00:00 Edit Adj Rpt	S\$2,217.10 Edit Estimates	S\$2,217.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Main Claimant: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Vehicle Reg. No.: SHA3801K		Date of Loss: 03/03/2018 15:00 - :59 [8 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6359910084SG		Policy/Cover Note No.: 0999994756							
Vehicle Reg. No. (Insured): SLE7243B		Policy No. (Claimant): MCOM0015							
		Excess:							
Repairer: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chong, Joee]									
Claimant's Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 15/03/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA3801K (6359910084SG)
 [SLE7243B]
 TP
 COMFORT TRANSPORTATION PTE LTD
 Mar 3 2018 3:00PM
 [LCRF PTE LTD]
 ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/08/18 09:25	Video - Accident	 Load AVI	
Assessment Reports				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/03/18 09:54	Accident Statement <small>From: SC - Reg. No: SLE7243B, Claimant: LCRF PTE LTD</small>	 Load HTM	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/03/18 17:54	General View	 Load JPG	<input checked="" type="checkbox"/>
29	07/03/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	07/03/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	07/03/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	07/03/18 17:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	09/03/18 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	09/03/18 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	09/03/18 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	09/03/18 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	09/03/18 08:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 09:29	TP ESTIMATE - MARKED	 Load PDF	
2	09/03/18 09:29	TP GIA REPORT	 Load PDF	
3	16/03/18 14:26	Email letter to ACCIDENT INVOLVING SLE 72438 AND SHA 3801K ON 03.03.2018	 Load PDF	
4	09/10/18 11:21	Email from AIG to maintain rejection 5.10.18	 Load PDF	
5	09/10/18 11:21	Click here & type to add comment... Email from AIG to reject TP claim 28.8.18	 Load PDF	
6	09/10/18 11:21	Click here & type to add comment... Email to wkshop AIG maintain rejection 9.10.18.	 Load PDF	
7	09/10/18 11:21	Email to wkshop reject TP claim 28.8.18.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18004286/K1WA3Q2

Date: 10/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994756

Claimant Vehicle No: SHA3801K

Insured Vehicle No: SLE7243B

Date of Loss: 03/03/2018

Nature of Claim: TP

Claim No: 6359910084SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA3801K

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS048436

Reg. Date: 15/06/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU003558802

Colour: Blue

Odometer: 108542 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Bridgestone 7 mm

Rear Left Side:

Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side:

Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,946.27	1,207.10	1,739.17	59.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,010.00	1,330.00	56.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,286.27	2,217.10	3,069.17	58.06
+ GST 7.00/7.00% (S\$)	370.04	155.20	214.84	58.06
Nett Amount (S\$)	5,656.31	2,372.30	3,284.01	58.06
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/03/2018

Date Inspected: 05/03/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER ,RH	Repair	817.50 FL	*- FL
2	1		*REAR FENDER SHIELD (RH)	Serviceable	134.20 FL	*- FL
3	1		*PANEL SUB -ASSY ,REAR DOOR ,RH	Repair	1,227.00 FL	*- FL
4	1		*FRONT DOOR BAR FRONT (RH)	Serviceable	140.20 FL	*- FL
5	1		*REAR WHEEL HUB CAP (RH)	Grazed	175.80 FL	*175.80 FL
6	1		*FRONT DOOR (RH)	Dented	1,227.00 FL	*1,227.00 FL
7	1		*FRONT DOOR COMFORT LOGO ,RH	Necessary	75.00 FS	*75.00 FS
8	1		*REAR DOOR COMFORT & APPS STICKER ,RH	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,876.70	1,557.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	930.43	350.70
Total Parts (\$\$)	2,946.27	1,207.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	850.00	400.00
2	SPRAY PAINTING CHARGE	New	600.00	540.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	50.00	20.00
5	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	0.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
8	TRANSFER OF DOOR	New	120.00	50.00
Gross Labour Cost (\$\$)			2,340.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >