

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 9083J

DATE 5/3/2018 10:41

MAKE :

MODEL : HYUNDAI i40

DOA: 01.03.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket			\$ 49.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	
	Rear Bumper Reflector Lamp (LH/RH)		\$ 32.00	\$ 64.00	
	<b>SUB TOTAL</b>			<b>\$ 1,971.35</b>	
	<b>LESS 20%</b>			<b>\$ 394.27</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,577.08</b>	
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
				<b>\$ 435.70</b>	
	<b>Labour Charge</b>			<b>200</b>	
	Panel Beating			\$ 380.00	
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	X 27
	R/Refix Reverse Sensor			\$ 120.00	20
	<b>TOTAL LABOUR</b>			<b>\$ 750.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,762.78</b>	
KK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Larry Ng

K/La 11/11/18

5/3/18 1120h

2027

PIP

Before Part 1 of 1