

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0655/2018
DATE : 01-MAR-2018

EQ INSURANCE COMPANY LTD
22 GEMMILL LANE

S(069257)
TEL : 62239433
FAX : 62243903

OWNER'S NAME : LEOW SWEE CHENG, ANCEL
ADDRESS : APT BLK 199A PUNGGOL FIELD
#04-409
S(821199)
TELEPHONE NO : 90885590

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P28921071DMA
VEHICLE NO : SLM190Z
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y557687
CHASSIS NO : JF1SJ5KC5HG084197
MILEAGE : 1 KM
DATE IN : 01/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 28/02/2018

Print Date : 01/03/2018
Print Time : 16:17:33

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM190Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM EQ LOCATION:SERANGOON ROAD DATE:28/02/2018 TIME:2300H		
3	ZZ/002	REMOVE/REPLACE REAR BUMPER,REAR PANEL	1120.00	2801
4	ZZ/003	RESPRAY REAR BUMPER,REAR PANEL	840.00	4201
5	ZZ/004	DISMENTLE & REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	nn 300.00	X
6	ZZ/005	TO CONDUCT(REAR)LIGHTING TEST	50.00	201
7	ZZ/006	TO CONDUCT(REAR)ANTI-RUST COATING	nn 580.00	X
8	ZZ/007	TO SUPPLY&INSTALL REVERSE SENSOR-2 EYES	300.00	?
9	ZZ/008	SUNDRIES	100.00	201
TOTAL LABOUR CHARGES			3290.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM190Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	SKIRT COMPL R	5.2F 52401SG0109P	288.00	X			
2	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	✓			
3	BRKT CORNER R RH	57707SG060	18.00	X			
4	BRKT CORNER R LH	57707SG070	18.00	X			
5	BRKT SD R RH	(1) 57707SG080	43.20	X			
6	BRKT SD R LH	57707SG090	14.40	7			
7	COVER HOOK R	57731SG010NN	12.60	X			
8	REFLEC AY RH	84281SC000	20.40	X			
9	REFLEX AY LH	84281SC010	20.40	X			
10	TRIM PNL AY SKIRTR	94026SG000VH	36.00	X			
11	CARGO STEP PANEL (RESIN)FORESTER	E775ESG000	420.00	✓			
SUB TOTAL			1431.00	0.00	0.00		0.00
LESS DISCOUNT (NETT-20 %)			286.20	0.00	0.00		0.00
GRAND TOTAL			1144.80	0.00	0.00		0.00
OVERALL TOTAL			1144.80				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM190Z

TOTAL LABOUR CHARGES	3290.00
TOTAL SPARE PARTS CHARGES	1144.80
GRAND TOTAL	4434.80 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Authorized
1-21
Repair B4 pain
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: