



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFY1018R

Mdm Teo Yee Cheng

40 Yunnan Drive 1
Singapore 638265

Mobile: 81017669

Vehicle & Document Information

WIP No **21732**
Reg No/Reg Date **SFY1018R / 31/07/2013**
Date In/Mileage **/ 0**
Chassis No **WDD2120342A804405**
Engine No **27492030064007**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212)**
Colour/Trim **025 526 Dolomite Br/ 042 274 Leather Jav**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	05/03/2018/ 16:34	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNUN POLICY NO/ACC DATE : GA052160/1// 04.03.18 DRIVE IN/EXCESS : 05.03.18 // TP CAR NO. SKA2266B= AXA INS DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPAIR ON RHF DOOR, RHR DOOR, RIGHT WING MIRROR				1920 2880.00
A BPIRES RESPRAY ON RHF DOOR, RHR DOOR, RIGHT WING MIRROR				1200 1800.00
M RHF DOOR BOTTOM INSULATION	1.00	26.48	00.00	2 26.48
M RHF DOOR TOP INSULATION	1.00	4.67	00.00	NA 4.67
M RHF DOOR WEATHERSTRIP	1.00	280.72	00.00	NA 280.72
M RIGHT DRIVER'S DOOR	1.00	2069.88	00.00	NA 2069.88
M RIGHT WING MIRROR PANELING	1.00	174.33	00.00	NA 174.33
M RH COVER MIRROR HOUSING	1.00	356.98	00.00	NA 356.98
M RIGHT MIRROR FRAME	1.00	949.95	00.00	NA 949.95
M RHF DOOR WINDOW RUN	1.00	129.57	00.00	NA 129.57
M RIVET	20.00	2.96	00.00	NA 59.20
M RHR DOOR INSULATION	1.00	29.18	00.00	NA 29.18
M RHR ABSORBING DOOR	1.00	4.26	00.00	NA 4.26
M RHR DOOR WEATHERSTRIP	1.00	280.72	00.00	NA 280.72
M RIGHT REAR DOOR	1.00	2127.98	00.00	NA 2127.98
M RIGHT ORNAMENTAL TRIM ROOF	1.00	404.12	00.00	NA 404.12

Not Authorized
PIP Repair
Before paint photo
LKK Auto
4w/ days
28/3/2018

Confirmed & accepted by

Signature of the following:
resurvey before after spray painting
display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Validity of this estimate, including any modification(s) is allowed. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We warrant that the above estimate is based on our inspection and does not include any additional parts or labour which may be required after repair work has commenced. If any damaged parts are discovered after work has started and needed for repairs or replacement, however, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Nett 11,958.04
7% GST on 11958.04 837.06
Total Payable 12,795.10

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany