



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFY1018R

Mdm Teo Yee Cheng

40 Yunnan Drive 1
Singapore 638265

Mobile: 81017669

Vehicle & Document Information

WIP No **21732**
Reg No/Reg Date **SFY1018R / 31/07/2013**
Date In/Mileage **0**
Chassis No **WDD2120342A804405**
Engine No **27492030064007**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212**
Colour/Trim **025 526 Dolomite Br/ 042 274 Leather Jav**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	05/03/2018/ 16:34	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : GA052160/1// 04.03.18 DRIVE IN/EXCESS : 05.03.18 // TP CAR NO. SKA2266B= AXA INS DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPAIR ON RHF DOOR, RHR DOOR, RIGHT WING MIRROR				2880.00
A BPIRES RESPRAY ON RHF DOOR, RHR DOOR, RIGHT WING MIRROR				1800.00
M RHF DOOR BOTTOM INSULATION	1.00	26.48	00.00	26.48
M RHF DOOR TOP INSULATION	1.00	4.67	00.00	4.67
M RHF DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M RIGHT DRIVER'S DOOR	1.00	2069.88	00.00	2069.88
M RIGHT WING MIRROR PANELING	1.00	174.33	00.00	174.33
M RH COVER MIRROR HOUSING	1.00	356.98	00.00	356.98
M RIGHT MIRROR FRAME	1.00	949.95	00.00	949.95
M RHF DOOR WINDOW RUN	1.00	129.57	00.00	129.57
M RIVET	20.00	2.96	00.00	59.20
M RHR DOOR INSULATION	1.00	29.18	00.00	29.18
M RHR ABSORBING DOOR	1.00	4.26	00.00	4.26
M RHR DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M RIGHT REAR DOOR	1.00	2127.98	00.00	2127.98
M RIGHT ORNAMENTAL TRIM ROOF	1.00	404.12	00.00	404.12

Confirmed & accepted by

7% GST on **Nett 11,958.04**
837.06

Authorized signatory and company stamp

Total Payable 12,795.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg