



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18004297/R1pa3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 06-03-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9988X	Veh. Inspected	FBJ 3203K	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M009YD	Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/03/2018	Inspection Date	06/03/2018	
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722

Email: support@hklimmotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291

Website: www.hklimmotorsport.com.sg

FBJ3203K

- 1 TOWING
- 2 FRONT FORK ASSY LH/RH
- 3 FRONT FORK UNDER BRACKET
- 4 STEERING ONE BEARING
- 5 FRONT FENDER
- 6 FRONT WHEEL RIM
- 7 FRONT WHEEL SHALF
- 8 FRONT WHEEL BEARING 2PCS
- 9 FRONT WHEEL BEARING OIL SEAL 2PCS
- 10 FRONT BRAKE DISC LH
- 11 METER ASSY
- 12 HEADLIGHT ASSY
- 13 HEADLIGHT BRACKET LH/RH
- 14 HANDLEBAR
- 15 HANDLEBAR GRIP LH/RH
- 16 HANDE BAR GRIP RUBBER LH/RH
- 17 HANDLEBAR BALANCER LH
- 18 SIDE MIRROR LH
- 19 IU UNIT
- 20 IU UNIT BRACKET
- 21 CLUTCH LEVER
- 22 FRAME SLIDER
- 23 PULSER OIL COVER / GASKET
- 24 ENGINE OIL 4 LITRE
- 25 GEAR PEDAL / RUBBER
- 26 GEAR PEDAL ROD
- 27 FRONT FOOT REST LH
- 28 FRONT FOOT REST BRACKET LH
- 29 TOPBOX GIVI 47L (MADE IN ITALY)
- 30 TOP BOX RACK
- 31 REAR TYRE
- 32 REAR WHEEL RIM
- 33 REAR WHEEL SHALF
- 34 FUEL TANK
- 35 LABOUR

\$35.00 ? receipt → 12600
 \$2,400.00 ~~3200~~ → SN
 \$250.00 X
 \$150.00 X
 \$220.00 X
 \$750.00 X
 \$120.00 X
 \$50.00 X
 \$30.00 X
 \$520.00 X
 \$1,200.00 X
 \$480.00 X
 \$240.00 X
 \$195.00 X
 \$180.00 X
 \$45.00 X
 \$45.00 X
 \$120.00 X
 \$180.00 X
 \$35.00 X
 \$60.00 X
 \$180.00 X
 \$240.00 X
 \$100.00 X
 \$160.00 X
 \$80.00 X
 \$85.00 X
 \$250.00 X
 \$400.00 X
 \$160.00 X
 \$220.00 X
 \$900.00 X
 \$130.00 X
 \$1,200.00 X
 \$750.00 X
 \$12,210.00

Rasul
Hp 90010068

3 days
4/5 p/p

06/03/18 @ 1450

Resy after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before final spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



HKL LIM TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklilmotorsport.com.sg

Tel: 6275 6656, 6275 6566. 62727292 Fax: 6272 9291
Website: www.hklilmotorsport.com.sg

FBJ3203K

- 1 TOWING
- 2 FRONT FORK ASSY LH/RH
- 3 FRONT FORK UNDER BRACKET
- 4 STEERING ONE BEARING
- 5 FRONT FENDER
- 6 FRONT WHEEL RIM
- 7 FRONT WHEEL SHALF
- 8 FRONT WHEEL BEARING 2PCS
- 9 FRONT WHEEL BEARING OIL SEAL 2PCS
- 10 FRONT BRAKE DISC LH
- 11 METER ASSY
- 12 HEADLIGHT ASSY
- 13 HEADLIGHT BRACKET LH/RH
- 14 HANDLEBAR
- 15 HANDLEBAR GRIP LH/RH
- 16 HANDE BAR GRIP RUBBER LH/RH
- 17 HANDLEBAR BALANCER LH
- 18 SIDE MIRROR LH
- 19 IU UNIT
- 20 IU UNIT BRACKET
- 21 CLUTCH LEVER
- 22 FRAME SLIDER
- 23 PULSER OIL COVER / GASKET
- 24 ENGINE OIL 4 LITRE
- 25 GEAR PEDAL / RUBBER
- 26 GEAR PEDAL ROD
- 27 FRONT FOOT REST LH
- 28 FRONT FOOT REST BRACKET LH
- 29 TOPBOX GIVI 47L (MADE IN ITALY)
- 30 TOP BOX RACK
- 31 REAR TYRE
- 32 REAR WHEEL RIM
- 33 REAR WHEEL SHALF
- 34 FUEL TANK

1521
495
550
2566
3 days
P/P

\$35.00 ? receipt ✓ labour
\$2,400.00 ~~200~~ 200 - SN
\$250.00 ~~200~~ 200 - SN
\$150.00 ~~200~~ 200 - SN
\$220.00 ~~200~~ 200 - SN
\$750.00 ~~200~~ 200 - SN
\$120.00 ~~200~~ 200 - SN
\$50.00 ~~200~~ 200 - SN
\$30.00 ~~200~~ 200 - SN
\$520.00 ~~200~~ 200 - SN
\$1,200.00 ~~200~~ 200 - SN
\$480.00 ~~200~~ 200 - SN
\$240.00 ~~200~~ 200 - SN
\$195.00 ~~200~~ 200 - SN
\$180.00 ~~200~~ 200 - SN
\$45.00 ~~200~~ 200 - SN
\$45.00 ~~200~~ 200 - SN
\$120.00 ~~200~~ 200 - SN
\$180.00 ~~200~~ 200 - SN
\$35.00 ~~200~~ 200 - SN
\$60.00 ~~200~~ 200 - SN
\$180.00 ~~200~~ 200 - SN
\$240.00 ~~200~~ 200 - SN
\$100.00 ~~200~~ 200 - SN
\$160.00 ~~200~~ 200 - SN
\$80.00 ~~200~~ 200 - SN
\$85.00 ~~200~~ 200 - SN
\$250.00 ~~200~~ 200 - SN
\$400.00 ~~200~~ 200 - SN
\$160.00 ~~200~~ 200 - SN
\$220.00 ~~200~~ 200 - SN
\$900.00 ~~200~~ 200 - SN
\$130.00 ~~200~~ 200 - SN
\$1,200.00 ~~200~~ 200 - SN
\$750.00 ~~200~~ 200 - SN
\$12,210.00

1690
10%
1521
S/N - 495
350
+
200
550

Rasul
Hp 9000068

3 days
P/P

06/03/18 @ 1450
Resy after repair

Resurvey 8/3/18
Lyn

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



BIKEBULANCE

9D, Yuan Ching Road #03-38 S(518546)
Tel: 6425-5333 95880928
Email: bikebulance@yahoo.com
MOTORCYCLE/SCOOTER Haulage Company

☐ DELIVERY ORDER
☒ CASH SALE
☐ INVOICE

NO: 115926

RE:

DATE:

2-3-18

ITEM	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1		FBT 3203 K	\$	\$ 35
2			\$	\$
3		Ayer Rajah Air	\$	\$
4		HKL	\$	\$
5			\$	\$
Total				\$ 35

50% of quoted Price or min \$20 (whichever is higher) is liable for cancellation of booking (Not For Contract Basis)

注意: 本公司對所拖的電單車, 在拖運中如有任何損壞, 一概由車主自行負責

E & O E

NOTE: Vehicle is hauled at owner's risk. The Company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed.

YM 2E ☐ YM3C ☒ GY 2E ☐ GBB 2K ☐ GZ 2320T ☐ GBB4376E ☐ Other ☐

Issued By

Customer's Signature & Chop

Bikebulance Is The Solution To Your Motorcycle / Scooter Conveying Needs (Local & West Malaysia)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M009YD

Our ref: CC4/ASM18004297/R1pa3

Date: 07.03.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

FBJ 3203K

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.03.2018 at the premises of M/s HKL Lim Team Motorsport - Bukit Merah and have the following to report:-

Workshop Estimate Amount	: S\$	12,210.00
Revised Estimate Amount	: S\$	2,540.00
"Check" Items Amount	: S\$	195.00
Total (Including Check Items)	: S\$	2,735.00

Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion & N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 4 May 2018 11:16 AM
To: 'HKL Lim Team Motorsport'
Subject: RE: FBJ3203K /YN9988X ON:02/03/2018 DISCHARGE VOUCHER

Without Prejudice

Hi,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and we shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

We are seeking mandate approval on quantum from AXA and will get back to you asap.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: HKL Lim Team Motorsport [mailto:hklteam@gmail.com]
Sent: Thursday, 3 May 2018 4:24 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: FBJ3203K /YN9988X ON:02/03/2018 DISCHARGE VOUCHER

hi Hsiao Tong,

Do refer to the attached and send us the DV.

Thank You.

Best Regards

James Lim (Keong)

Tel:+65 9242 3895



BLK 1008 #01-24 Bukit Merah Lane 3, Singapore 159722

Tel:+65 6275-6656, 6275-6566 Fax: 6272-9291



**Re:<URGENT> RE:<SEEK MANDATE> - Claim no
S8M009YD; ACCIDENT INVOLVING YN 9988X (OI) & FBJ
3203K (TP) ON 02/03/2018]**

Type

Question

Message

Mandate approved 14/2/2018

Reply



RE: <SEEK MANDATE> - Claim no S8M009YD; ACCIDENT INVOLVING YN 9988X (OI) & FBJ 3203K (TP) ON 02/03/2018]

Type

🔗 Question

Message

Hi, we refer to the e-mail on 23/05/2018 and 11/06/2018, we appreciate if you could let us have your mandate approval/ instruction. thank you. pohkin by today -12.07.2018. RE: Liability: Insured collided to rear of third party. Front to rear collision. Send letter to OI via E-mail on 4th May 2018. We seek your approval to offer Third Party repairer "HKL Lim Team Motorsport" is as follows: - 1)COR(w/GST): \$2,566.00 + 2) Loss of Use (3daysx\$25.00): \$75.00 =Total: \$2,641.00. **03days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 23/05/2018

Reply



RE: <SEEK MANDATE> - Claim no S8M009YD; ACCIDENT INVOLVING YN 9988X (OI) & FBJ 3203K (TP) ON 02/03/2018]

Type

Question

Message

Hi, we refer to the e-mail below, we appreciate if you could let us have your mandate approval/ instruction.
thank you. pohkin

Reply



<SEEK MANDATE> - Claim no S8M009YD; ACCIDENT INVOLVING YN 9988X (OI) & FBJ 3203K (TP) ON 02/03/2018]

Type

Question

Message

Liability: Insured collided to rear of third party. Front to rear collision. Send letter to OI via E-mail on 4th May 2018. We seek your approval to offer Third Party repairer "HKL Lim Team Motorsport" is as follows: -
1)COR(w/GST): \$2,566.00 + 2) Loss of Use (3daysx\$25.00): \$75.00 =Total: \$2,641.00. **03days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 23/05/2018

Reply



**Re:RE: Re:RE: Re:RE: Direct Settlement - Accident
Involving YN 9988X (OI : AXA - S8M009YD) and FBJ
3203K (TP : LKK REF - CC4/ASM18004297/R1pa3) on
02.03.2018**

Type

🔗 Question

Message

Please proceed DS

Reply



Re:RE: Re:RE: Direct Settlement - Accident Involving YN 9988X (OI : AXA - S8M009YD) and FBJ 3203K (TP : LKK REF - CC4/ASM18004297/R1pa3) on 02.03.2018

Type

 Question

Message

Please check validity of ID's D/L - refer to attached CI & policy schedule

Reply



**RE: Re:RE: Re:RE: Direct Settlement - Accident Involving
YN 9988X (OI : AXA - S8M009YD) and FBJ 3203K (TP :
LKK REF - CC4/ASM18004297/R1pa3) on 02.03.2018**

Type

🔔 Question

Message

Hi Cynthia, OID has valid D/L. We have uploaded a copy of OID driving licence status in SMART Claim for your easy reference. Kindly advise if we may proceed DS. Thanks. Hsiao Tong - 03/05/2018.

Reply

HKL LIM TEAM MOTORSPORT (53347346B)
BLK 1008 #01-24 Bukit Merah Lane 3 Singapore 159722
Tel: 6275 6566, 6275 6656 Fax: 6272 9291

I GOH KOK HIN HENRY NRIC No: S 8208572 F Am very

satisfied with **HKL LIM TEAM MOTORSPORT** workshop for their
repair and the claiming of insurance that they had done for my

motorcycle FBT3203K



Signature

Name : _____

NRIC: _____

HKL LIM TEAM MOTORSPORT (53347346B)
BLK 1008 #01-24 Bukit Merah Lane 3 Singapore 159722
Tel: 6275 6566, 6275 6656 Fax: 6272 9291

I Goh Kok Hin HENRY NRIC No: S 8208572 F Am very
satisfied with **HKL LIM TEAM MOTORSPORT** workshop for their
repair and the claiming of insurance that they had done for my
motorcycle FBJ3203K



Signature

Name : _____

NRIC: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8572F
Vehicle Details	
Vehicle No.:	FBJ3203K
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 May 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400A
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	NC42E1125394
Chassis No.:	JH2NC4291CK400018
Maximum Power Output:	-
Open Market Value:	\$7,382.00
Original Registration Date:	20 Mar 2014
First Registration Date:	20 Mar 2014
Transfer Count:	1
Actual ARF Paid:	\$1,108.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Mar 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,782.00
COE Rebate Amount:	\$1,036.00
Total Rebate Amount:	\$1,036.00

The information contained herein is correct as at 23 May 2018

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 23.05.2018

Survey Details:

Date of loss	2-Mar-18
Date of appointment	5-Mar-18
Date of survey	6-Mar-18
Location of survey	HKL Lim Team Motorsport

Vehicle Details:

Claim Type:	Third party
Vehicle number	FBJ 3203K
Make and Model	HONDA CB400A
Date of registration	20/3/2014
Excess	
Market Value	
Part Rebate	
Nett Loss	

Repair details:

Initial Estimate	\$12,210.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$2,016.00
Check items (estimate)	Nil
Labour	\$550.00
Total	\$2,566.00
Lump Sum(if applicable)	

Number of days for repair	<u>3</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 23.05.2018

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$2,566.00	
Loss of use	\$75.00	\$25.00 x 3 days
Loss of rental	Nil	
Loss of income	Nil	
LTA search fees	Nil	
Others	Nil	
Proposed Total	\$2,641.00	

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YN 9988X (Insd veh)	Model:	HONDA
	FBJ 3203K (TP veh)		CB400A
Date of Accident:	02/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$		12,210.00
Final Repair Cost	:	\$		2,566.00
Loss of Use	:	\$		75.00
Rental (if any)	:	\$		3 days at \$25.00 per day
LTA / GIA Search Fee	:	\$		days

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	2,641.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:	Agreed Liability	_____	100 (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	HKL LIM TEAM MOTORSPORT	:	\$ 2,641.00

NUR SHAQILAH BTE ABDOL
WAHAB

04/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim

S8M009YD

Reference

CC4/ASM18004297/R1pa3s2 

Loss Date

March 2, 2018

Request Date

March 5, 2018

Due Date

March 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

None

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #

FBJ3203K

Make

TPVD HONDA

Model

Service Address

CB400

Primary Contact/Insured

CHIP HONG FARM PRODUCT
14 WOODLANDS TERRACE, 738439, Singapore
67584554
chyehoon@chiphong.com.sg

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

NAME	TYPE	SUB-TYPE	AUTHOR	Messages	Invoices	History	Documents	Assessment	Metrics	Notes	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen								

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
EMAIL WITH TP GIA.msg	Forms / Claim Documents	Others	KUMAR Shalendra	March 5, 2018

<< Service Request Details

Claim	S8M009YD	Actions		Adjust		
Reference	CC4/ASM18004297/R1pa3s2 	Loss Date	Next Step	Finish the work	Complete Work	
March 2, 2018		Request Date			None	
March 5, 2018		Due Date				
March 5, 2019		Vendor Name				
LKK AUTO CONSULTANTS PTE LTD (TP)		Type of Loss	Vehicle Information			
Third Party Vehicle Damage		Services	Incident Vehicle Registration #	FBJ3203K	Make	
Pending verification - Direct Settlement			Make		Service Address	
			TPVD HONDA	Model		
			CB400	Primary Contact/Insured		
			CHIP HONG FARM PRODUCT 14 WOODLANDS TERRACE, 738439, Singapore 67584554 chiyephoon@chiphong.com.sg			
Additional Instructions			Claim Handler			
			LOH Cynthia 6568804843 cynthia.loh@axa.com.sg			
			Messages	Invoices	History	Documents
			Assessment	Metrics	Notes	
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
KUMAR Shailendra	3/5/18 8:58 AM	2566	2566	Open	Share	Clone



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	FBJ3203K	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	03/20/2014
Mileage	54741	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	PHOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year		2013	Driver Name	GOH KOK HIN HENRY	
Make	TPVD HONDA	HONDA	Date of Birth	March 21, 1982	mm/dd/yyyy
Model	CB400	CB400A	Age	36	
Type			Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No		JH2NC4291CK400018	Driving Experience	0	
Engine No		NC42E1125394	Driver License #		
Engine Capacity		399 cc	License Type		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *

03/06/2018

General condition

Fair

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Spare wheel

Age of Tyres

Front Tyre Size

120/60ZR17

Rear Tyre Size

160/60ZR17

Front left side

ROADTEC 4mm

Rear left side

ROADTEC 4mm

Front right side

Rear right side

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsTaxes & RatioParts & LabourMiscellaneousSummaryParts

Add

Approve

Deny

Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTRN%	DISC CUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			STEERING ON E BEARING			Necessary	150		10		135	Reviewing	
	2	1			FRONT FENDER			Serviceable	0		10		0	Reviewing	
	3	1			FRONT WHEEL RIM			Repair	0		10		0	Reviewing	
	4	1			FRONT WHEEL SHALF			Serviceable	0		10		0	Reviewing	
	5	2			FRONT WHEEL BEARING			Serviceable	0		10		0	Reviewing	
	6	2			FRONT WHEEL BEARING OIL SEAL			Serviceable	0		10		0	Reviewing	
	7	1			FRONT BRAKE DISC LH			Serviceable	0		10		0	Reviewing	
	8	1			METER ASSY			Serviceable	0		10		0	Reviewing	
	9	1			HEADLIGHT ASSY			Serviceable	0		10		0	Reviewing	
	10	1			HEADLIGHT BRACKET L/HRH			Serviceable	0		10		0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC QUAN%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	26	1			REAR TYRE			Serviceable	0		10		0	Reviewing	
	27	1			REAR WHEEL RIM			Serviceable	0		10		0	Reviewing	
	28	1			REAR WHEEL SHALF			Serviceable	0		10		0	Reviewing	
	29	1			FUEL TANK			Serviceable	0		10		0	Reviewing	

Labour

Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TOWING.	35	0	0	Reviewing		
	2		LABOUR.	350	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SIR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		3	
	2	ENGINE OIL 4 LITRE	Reviewing	60	NECESSARY	
	3	TOPBOX GIVI 47L (MADE IN ITALY)	Reviewing	400	SCRATCHED	
	4	FRONT FORK ASSY L/H/R/H }	Reviewing	200	DAMAGED	
	5	FRONT FORK UNDER BRACKET }	Reviewing	0		

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$2,566.00

Claim Amount

\$2,566.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$385.00	\$385.00
Miscellaneous	\$660.00	\$660.00
Spare Parts	\$1,521.00	\$1,521.00

Submit for Review