



HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722

Tel: 6275 6656, 6275 6566, 62727292

Fax: 6272 9291

Email: support@hklimmotorsport.com.sg

Website: www.hklimmotorsport.com.sg

FBJ3203K

- 1 TOWING
- 2 FRONT FORK ASSY LH/RH
- 3 FRONT FORK UNDER BRACKET
- 4 STEERING ONE BEARING
- 5 FRONT FENDER
- 6 FRONT WHEEL RIM
- 7 FRONT WHEEL SHALF
- 8 FRONT WHEEL BEARING 2PCS
- 9 FRONT WHEEL BEARING OIL SEAL 2PCS
- 10 FRONT BRAKE DISC LH
- 11 METER ASSY
- 12 HEADLIGHT ASSY
- 13 HEADLIGHT BRACKET LH/RH
- 14 HANDLEBAR
- 15 HANDLEBAR GRIP LH/RH
- 16 HANDE BAR GRIP RUBBER LH/RH
- 17 HANDLEBAR BALANCER LH
- 18 SIDE MIRROR LH
- 19 IU UNIT
- 20 IU UNIT BRACKET
- 21 CLUTCH LEVER
- 22 FRAME SLIDER
- 23 PULSER OIL COVER / GASKET
- 24 ENGINE OIL 4 LITRE
- 25 GEAR PEDAL / RUBBER
- 26 GEAR PEDAL ROD
- 27 FRONT FOOT REST LH
- 28 FRONT FOOT REST BRACKET LH
- 29 TOPBOX GIVI 47L (MADE IN ITALY)
- 30 TOP BOX RACK
- 31 REAR TYRE
- 32 REAR WHEEL RIM
- 33 REAR WHEEL SHALF
- 34 FUEL TANK

35 LABOUR

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$35.00 *1 receipt*
\$2,400.00 *200*
\$250.00 *X*
\$150.00 *X*
\$220.00 *X*
\$750.00 *X*
\$120.00 *X*
\$50.00 *X*
\$30.00 *X*
\$520.00 *X*
\$1,200.00 *X*
\$480.00 *X*
\$240.00 *X*
\$195.00 *X*
\$180.00 *X*
\$45.00 *X*
\$45.00 *sea*
\$120.00 *sea*
\$180.00 *sea*
\$35.00 *BT*
\$60.00 *sea*
\$180.00 *sea*
\$240.00 *sea*
\$100.00 *60 sea*
\$160.00 *BT*
\$80.00 *BT*
\$85.00 *sea*
\$250.00 *X*
\$450.00 *400 sea*
\$160.00 *X*
\$220.00 *X*
\$900.00 *X*
\$130.00 *X*
\$1,200.00 *X*
\$750.00 *200 350*
\$12,210.00

Rasul
Hp 90010068

3 days
4/8 p/p

06/03/18 @ 1450

Resy after repair