

ASS. REC. BY:

REF: CS/FCI18004298/Mlqd3ez

Special Instruction

SURVANT

MA

ASSIGNMENT (Office)

From (Person):

Schene Ler

of

FCI

Date/Time

6/3/18 @ 2:28pm

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SLN 2373U

Insured:

SHD 4709Y

at Workshop m/s

Lett Huatt (Meng Kee)

Tel:

G 4538110

of

160 Sin Ming Drive # 04-01/02

Policy No:

Claim No:

D18001858MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A

03/03/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

2:31pm 06/3/18

Person Contacted:

jenny

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 2373U - X

SHD 4709Y - NA/TMI/16011024/13

D.O.A. 14/6/16

08/3/18 @

10.11am revised to Schene by email.


Now finalized final fig @ 7000, 9 days.

Chkd @ 1038, 13/6/18

## ASSIGNMENT

APR 2017

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: **CAI HUNT (MG)**  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Sal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs: **9** days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Yr: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SLN 2373U**  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover  
 Truck / Trailer or  
 Make: **Bmw** or **1998**  
 Colour: **Beige** A/C Insured / Std / Nil / NA  
 So. Reading: **2312** T-Radio Insured / Std / Nil / NA  
 Eng No: \_\_\_\_\_  
 C No: **WBA8A16030NU74506**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: **225/50/27**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI  
 TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R Bal: **7** mm R Bal: **7** mm  
 L Bal: **7** mm L Bal: **7** mm  
 D/OA: **03/03/2018** D/O: **6/3/2018**  
 Survey held at: \_\_\_\_\_  
 Des. of Damages: Fnt / Rear / OS / NS / UIC / Rooftop or  
**NS Body**  
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

*Signature*  
 14/6/2018

RECEIVED

Date/Time File Page 107

14/6/2018

Date/Time File Return 107

☐ Prel. Report  
☐ Final Report

Days Of Repair: **9**

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transport: \_\_\_\_\_

Fuel: \_\_\_\_\_

Toll: \_\_\_\_\_

Other: \_\_\_\_\_

Total: \_\_\_\_\_

Add Fee: ☐ Site Insp: \$☐ Interim: \$☐ Test: \$☐ Workshop: \$Report Format: **7P**

Lump Sum / I.B.R. \$

**7048**

160

50

27

237



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004298/M1qd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-03-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4709Y	Veh. Inspected	SLN 2373U
Policy No.		Coverage (\$)	0.00
Claim No.	D18001858MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	06/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	03/03/2018	Inspection Date	06/03/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### MOTOR SURVEY ASSIGNMENT

<b>Date</b>	06-03-2018	<b>Our Ref No.</b> D18001858MFSH
<b>Accident Date</b>	03-03-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD4709Y	<b>Third Party Vehicle.</b> SLN2373U
<b>Survey Location</b>	160 Sin Ming Drive #04-01/02 and #07-03 Sin Ming Autocity	
<b>Contact Person.</b>	JENNY LIM	
<b>Contact No.</b>	64538110/ 0	<b>Fax No.</b> 64596267
<b>Survey Type</b>	DIRECT SETTLEMENT: EST. COR - \$8,545.02	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	LAI HUAT (MENG KEE) MOTOR PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235631)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18001858MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & LAI HUAT LTD
<b>Workshop Name</b>	LAI HUAT (MENG KEE) MOTOR PTE LTD (Contact Person : JENNY LIM)	<b>Survey Location &amp; Contact Details</b>	160 Sin Ming Drive #04-01/02 and #07-03 Sin Ming Auto <b>Mobile:</b> 0 , <b>Phone:</b> 64538110 , <b>Fax:</b> 64596267 <b>EmailId:</b> JENNY.LIM@LAIHUAT.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT: EST. COR - \$8,545.02		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHD4709Y	<b>TP Vehicle No</b>	SLN2373U
<b>PRI Recieved Date</b>	06-03-2018 03:40:02 PM	<b>Surveyor Appointed Date</b>	06-03-2018 02:26:57 PM	<b>Surveyor Accept Date</b>	06-03-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>		<b>Surveyor Report Date</b>	06-03-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	Please Select Make ▾	<b>Model</b>	Please Select Model ▾	<b>Year</b>	Select Year ▾
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAUTO)

---

**From:** Jenny Lim <jenny.lim@laihuat.com.sg>  
**Sent:** Thursday, 3 May 2018 3:56 PM  
**To:** Ma C.F (LKKAUTO)  
**Cc:** SUR  
**Subject:** Finalisation - SLN 2373U / BMW 320i  
**Attachments:** SLN 2373U.pdf; IMG\_5558.jpg; IMG\_5559.jpg; IMG\_5560.jpg; IMG\_5561.jpg; IMG\_5562.jpg; IMG\_5699.jpg; IMG\_5700.jpg; IMG\_5701.jpg

Dear Sir

For your confirmation, please:

- Parts: \$4,858.00
- L&P: \$2,190.00 (include supplementary)
- Sub-total: \$7,048.00 / 9 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 8 March 2018 10:11 AM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18001858MFSH/1  
**Attachments:** CSFCI18004298M1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLN 2373U.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 6 March 2018 2:35 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18001858MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 6 March 2018 2:27 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SERENELER@MSFIRSTCAPITAL.COM.SG](mailto:SERENELER@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001858MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001858MFSH

Date: 08 March 2018

Our Ref: CS/FCI18004298/M1qd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 2373U**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/03/2018 at the premises of M/s LAI HUAT MENG KEE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,986.00</u>
Revised Estimate Amount	: S\$ <u>6,948.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the n/s body.



Yours faithfully

Ma C.F.  
Automotive Assessor



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/03/2018 09:04
Date Of Accident	03/03/2018 16:50
Exact Location Of Accident	COSTA RHU CONDOMINIUM CAR PARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2373U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEO HIAN HENG GILLIAN
NRIC No	S1317180G
Email Address	GILLHHYEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94887692
Alternative Phone No	OTHERS-94887692

### Vehicle Particulars

Manufacturer	BMW
Model	320i LED NAV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	C0070766

### Driver

Name of Driver	YEO HIAN HENG GILLIAN
NRIC No	S1317180G
Date Of Birth	03/09/1958
Occupation	INDOOR
Date Of Driving Pass	15/11/1977
Driving Experience	40 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94887692
Fax Number	
Contact Number	OTHERS-94887692
Email Address	GILLHHYEO@GMAIL.COM

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: - 5 MAR 2018

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: Deborah Lai  
NRIC/FIN No.: S7332811Z

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Vehicle Number: **S1317180G**

**YEO HIAN HENG GILLIAN**

Birth Date: 03 Sep 1958  
Issue Date: 16 Dec 2002

000004855J



**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. **S1317180G**



Name

**YEO HIAN HENG GILLIAN**

**杨 贤 卿**

Race

**CHINESE**

Date of birth:

**03-09-1958**

Country/Place of birth:

**SINGAPORE**

Sex

**F**

**S1317180G**



**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

PASS DATE

**Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

**15 Nov 1977**



NP 438A

**5863818**



ID No: **S1317180G**



Date of issue

**01-02-2018**

Address

**25 CHUAN DRIVE  
SINGAPORE 554805**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7180G

### Vehicle Details

Vehicle No.: SLN2373U

Vehicle to be Exported: No

Intended De-registration Date: 05 Mar 2018

Vehicle Make: B.M.W.

Vehicle Model: 320i LED NAV

Primary Colour: Silver

Manufacturing Year: 2017

Engine No.: F2901642B48B20A

Chassis No.: WBA8A16030NU74506

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$38,197.00

Original Registration Date: 27 Apr 2017

First Registration Date: 27 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$40,476.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Apr 2027

PARF Rebate Amount: \$30,357.00

### Intended COE Rebate Details

COE Expiry Date: 26 Apr 2027

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$54,501.00

COE Rebate Amount: \$49,365.00

**Total Rebate Amount: \$79,722.00**

The information contained herein is correct as at 05 Mar 2018

OK

Thank you!



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 05 Mar 2018, 09:06:51.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

#### Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(\$\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SHD4709Y	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	05 Mar 2018 / 09:07:19

# 来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679. Tel: 6453 8110 Fax: 6459 6267  
RCB No: 199407592C

## ESTIMATE

EST No EST0018703  
Yeo Hian Heng Gillian

Page 1 of 2  
Your ref TP-SHD 4709Y FG  
Job No. 69288  
Our ref 18.03.09  
Payment  
Date 8/3/2018

Attn

Vehicle No SLN 2373U  
Vehicle Model BMW 320i  
Accident on 3/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front door LH	1,210.00	dt ✓	1,210.00
1.00	Pc	Front door weatherstrip LH	135.00	he ✓	135.00
1.00	Pc	Front door glass outer moulding LH	125.00	dt ✓	125.00
1.00	Pc	Front door glass LH	255.00	cut ✓	255.00
1.00	Pc	Front door wing mirror LH	640.00	cut ✓	640.00
1.00	Pc	Front door wing mirror frame LH	930.00	dis ✓	930.00
1.00	Pc	Front door wing mirror cover LH	115.00	mir ✓	115.00
1.00	Pc	Front Sport Line emblem LH	48.00	cut x	48.00
1.00	Pc	Front fender LH	670.00	NIN x	670.00
1.00	Pc	Rear door LH	1,238.00	dt ✓	1,238.00
1.00	Pc	Rear door weatherstrip LH	135.00	he ✓	135.00
1.00	Pc	Rear door outer handle LH	75.00	cut ✓	75.00
Labour & Misc					
1.00		To remove + refix door frame mouldings LH (black)	100.00		100.00

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267  
RCB No: 199407592C

## ESTIMATE

EST No: EST0018703  
Yeo Hian Heng Gillian

Page: 2 of 2  
Your ref: TP-SHD 4709Y FC  
Job No: 69288  
Our ref: 18.03.08  
Payment:  
Date: 6/3/2018

Attn:

Vehicle No: SLN 2373U  
Vehicle Model: BMW 320i  
Accident on: 3/3/2018

Quantity	Unit	Description	Unit price	Disc. pot	Amount
1.00		To check + erase fault code + reset	90.00		90.00
1.00		Tuff coat	120.00	100	120.00
1.00		To knock dents on rear fender LH and renew of parts	900.00	800	100.00
1.00		To spray paint (include blending front fender LH)	1,200.00	1000	200.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Not Authorised  
PIP Repair  
Before Paint Plan  
LKK Auto Consultants  
6/3/2018  
6w days

*[Signature]*  
6/3/18

Sub-Total: 7,986.00 2086  
GST 7.00%: 559.02  
Total: S\$ 8,545.02

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

\$7048.12

9w days

# 来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267  
RCH No: 199407592C

## ESTIMATE

EST. No EST0018703  
Yeo Hian Heng Gillian

Page 1 of 2  
Your ref TP-SHD 4709Y FC  
Job No 69288  
Our ref 18.03.09  
Payment  
Date 6/3/2018

Attn

Vehicle No SLN 2373U  
Vehicle Model BMW 320i  
Accident on 3/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item					
1.00	Pc	Front door LH	1,210.00		dt ✓ 1,210.00
1.00	Pc	Front door weatherstrip LH	135.00		uc ✓ 135.00
1.00	Pc	Front door glass outer moulding LH	125.00		dt ✓ 125.00
1.00	Pc	Front door glass LH	255.00		cut ✓ 255.00
1.00	Pc	Front door wing mirror LH	640.00		cut ✓ 640.00
1.00	Pc	Front door wing mirror frame LH	930.00		dis ✓ 930.00
1.00	Pc	Front door wing mirror cover LH	115.00		misc ✓ 115.00
<del>1.00</del>	<del>Pc</del>	<del>Front Sport Line emblem LH</del>	<del>46.00</del>		<del>cut X 46.00</del>
<del>1.00</del>	<del>Pc</del>	<del>Front fender LH</del>	<del>670.00</del>		<del>cut X 670.00</del>
1.00	Pc	Rear door LH	1,238.00		dt ✓ 1,238.00
1.00	Pc	Rear door weatherstrip LH	135.00		uc ✓ 135.00
1.00	Pc	Rear door outer handle LH	75.00		cut ✓ 75.00
Labour & Misc					(4858)
1.00		To remove + refix door frame mouldings LH (black)	100.00		✓ 100.00

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理, 除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



# 来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267  
RCB No: 199407592C

## ESTIMATE

EST No EST0018703  
Yeo Hian Heng Gillian

Page 2 of 2  
Your ref TP-SHD 4709Y FC  
Job No 69288  
Our ref 18.03.09  
Payment  
Date 6/3/2018

Attn

Vehicle No SLN 2373U  
Vehicle Model BMW 320i  
Accident on 3/3/2018

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00		To check + erase fault code + reset	90.00		90.00
1.00		Tuff coat	120.00		<del>120.00</del>
1.00		To knock dents on rear fender LH and renew of parts	900.00		<del>900.00</del>
1.00		To spray paint (include blending front fender LH)	1,200.00		<del>1,200.00</del>

Not Authorized  
P/P Repair  
Before Paint Plan  
LHK (with)  
6/3/2018  
Qwday

2090

Sub-Total 7,986.00  
GST 7.00% 559.02  
Total S\$ 8,545.02

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司  
**LAI HUAT (MENG KEE) MOTOR PTE LTD**

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267  
RCB No: 199407592C

**SUPPLEMENTARY**

**ESTIMATE**

EST. No EST0018703  
Yeo Hian Heng Gillian

Page 1 of 1  
Your ref TP-SHD 4709Y FC  
Job No 89288  
Our ref 18.03.09  
Payment  
Date 9/3/2018

Attn

Vehicle No SLN 2373U  
Vehicle Model BMW 320i  
Accident on 3/3/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
SUPPLEMENTARY ITEM					
1.00		To remove + refix rear door quarter glass + supply sealant	100.00		✓ 100.00

Sub-Total 100.00  
GST 7.00% 7.00  
Total S\$ 107.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理，除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004298/M1qd3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-06-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4709Y	Veh. Inspected	SLN 2373U
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001858MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	06/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	B.M.W. 320i	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA8A16030NU74506	Colour	BEIGE
Odometer	23112	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	03/03/2018	Inspection Date	06/03/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2373U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT DOOR LH	DENTED	1,210.00	1,210.00
1	FRONT DOOR WEATHERSTRIP LH	NECESSARY	135.00	135.00
1	FRONT DOOR GLASS OUTER MOULDING LH	DENTED	125.00	125.00
1	FRONT DOOR GLASS LH	CUT	255.00	255.00
1	FRONT DOOR WING MIRROR LH	CRACKED	640.00	640.00
1	FRONT DOOR WING MIRROR FRAME LH	DISTORTED	930.00	930.00
1	FRONT DOOR WING MIRROR COVER LH	MISSING	115.00	115.00
1	FRONT SPORT LINE EMBLEM LH	SERVICEABLE	48.00	-
1	FRONT FENDER LH	NOT NECESSARY	670.00	-
1	REAR DOOR LH	DENTED	1,238.00	1,238.00
1	REAR DOOR WEATHERSTRIP LH	NECESSARY	135.00	135.00
1	REAR DOOR OUTER HANDLE LH	CUT	75.00	75.00
			5,576.00	4,858.00
<b><u>LABOUR</u></b>				
	TO REMOVE + REFIX DOOR FRAME MOULDINGS LH (BLACK).		100.00	100.00
	TO CHECK + ERASE FAULT CODE + RESET.		90.00	90.00
	TUFF COAT.		120.00	100.00
	TO KNOCK DENTS ON REAR FENDER LH AND RENEW OF PARTS.		900.00	800.00
	TO SPRAY PAINT (INCLUDE BLENDING FRONT FENDER LH).		1,200.00	1,000.00
	TO REMOVE + REFIX REAR DOOR QUARTER GLASS + SUPPLY SEALANT.		100.00	100.00
			2,510.00	2,190.00
<b>GRAND TOTAL</b>			<b>8,086.00</b>	<b>7,048.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>7,048.00</b>

Report Ref No. CS/FCI18004298/M1qd3e2

**MA CHIN FOOK**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.