

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR SGY2668X

Mdm Leong Wan Sing

C/O AXA INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 8 SHENTON WAY #24-01 SINGAPORE 068811

Vehicle & Document Information

WIP No 21755

SGY2668X / 14/11/2012 Reg No/Reg Date

Date In/Mileage

07/03/2018/-48254 WDD2043312G011087 Chassis No

Engine No

27491030023243

1.00 .

Make/Model

MB/C 180 CGI (B/E) COUPE C20

Colour/Trim

027 775 Iridium sil/ 041 131 MB Lex Anth

	7 2	ait 3			Colour/Trim	027	//5 Iri	alum Sii/ O	41 131	MB Lex Anth
Account No	Terms	Date/Time Print	ed, C	SE	Operator					
CSI00001	Cash	20/03/2018/	14:54	10 No. 1254	350 / Eric	Lee Ming N	lui	ALESSE CONTRACTOR OF THE SECOND CONTRACTOR OF		*0
		Description	of Goods / Se	rvices			Qty	Unit Price	Disc%	Amount
X RIVETED X RETAINER X RIVET	WEDGE	NOT	AN	O	FIG		4.00 2.00 8.00	3.66 14.87 2.48	00.00	14 64 28 74 19 84
X SEAM SEA							1.00	97.68	00.00	97.68
X SPARE WH	EEL RECESS						1.00	and 270.13	00.00	270.13
X SURFACE	GASKET						1.00	32.74	00.00	32.74
X SURFACE	GASKET						1.00	32.74	00.00	32.74
X CENTRAL	REAR BUMPER	REINFORCEMEN	IT			The state of	1.00	135.13	00.00	135.13
X MOUNTING	PLATE					my har I	2.00	5.94	00.00	11.88
X BASIC MO	UNTING FOR	BUMPER				K.	100 6	67.58	00.00	67.58
X BASIC MO	UNTING FOR	BUMPER			. (1)	13.8	1.00	67.58	00.00	67.58
X [STR] LO	СК			- N	INI	150	1.00	285.68	00.00	285,68
	EDGE PANELL	ING		175	MUSIC		1.00	115.52	00.00	115.52
X TREENAIL			The state of the s	1	WIND	\$	4.00	2,67	00.00	10.68
	EEL RECESS	Repeated		11 /	1170		1.00	270.13	00.00	270.13

SUPPLEMENTARY

Confirmed & accepted by

REAR LAMP COMBINATION

Nett

2,138.75

678.06

7% GST on

2138.75

149.71

Total Payable

678.06 00.00

2,288.46

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

