

ASS. REC. BY:

REF: CS/FCI18004310/R1td3⁰²

Special Instruction:

Surveyor:

Rahul

ASSIGNMENT (Office)

From (Person):

Sithera

of

FCI

Date/Time:

5/3/18 1:39pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGD 7070Y

Insured:

SHC 7802X

at Workshop m/s

Performance Motor

Tel:

G3190174

of

303 Alexandra Rd

Policy No:

Claim No:

D18001785MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/2/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

/wp

H.O.D. Endorsement:

Date/Time:

10:36am 6/3/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time

Action/Instruction

() Estimate

SGD 7070Y-X

SHC 7802X-

Part by Part \$2062.75 (red. 270.30 @ 9%)

2/2

Surveyor

Rohan

REF: FCL

59583

ASSIGNMENT

From: _____ Date: 19/03/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGD 7070Y

at Workshop m/s: Performance

of: 303 Alexandra Rd

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: SGD 7070Y Yr Regn: 2016 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 218 I Comp c.c. 1499

Colour: RGD A/C: Insured / Std / NI / NA

Sp.Reading: 35607 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 2F 12060V758-175

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>28/02/18</u>	D.O.I. <u>19/03/18</u>

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 03 MAY 2018

Date/Time: File Pass to?

1) 2/6 Typist

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$) 2062.75

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

_____ S + RS. _____

Photos

Others

TOTAL

110
50
30
180



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004310/R1td3

36 ROBINSON ROAD

#16-01 CITY HOUSES SINGAPORE 068877

Date : 06-03-2018

Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7802X	Veh. Inspected	SGD 7070Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18001785MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	06/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/02/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MOTOR SURVEY ASSIGNMENT

Date	02-03-2018	Our Ref No. D18001785MFSH
Accident Date	28-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7802X	Third Party Vehicle. SGD7070Y
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE: PLS SHARE VIDEO	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235545)



PRI Documents



Close X

PRI Header Details

Claim No	D18001785MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEI Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: PLS SHARE VIDEO		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7802X	TP Vehicle No	SGD7070Y
PRI Recieved Date	05-03-2018 03:47:40 PM	Surveyor Appointed Date	05-03-2018 04:38:25 PM	Surveyor Accept Date	05-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159941
Tel. 63190888 (AfterSales)
63190833 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Supplementary item(s) must be resurveyed and approved by LKK approval from Insurance Company

Acknowledged by Repairer

Signature:

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

01 MAR 2018

Estimate No. : b1 46090
Date Estimated : 01/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -Hu Su Cheng
1 Springleaf View

Singapore 787907

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGD7070Y	V758175	11/05/2016	218iA/2	0

DESCRIPTIONTo making good on rear bumper including remove and install
attachments to facilitate with repair work.VALUE

850.00

Painting on rear bumper assembly

934 1038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

net 40.00

Total Labour 1: 2,105.00

DESCRIPTION

REAR GUIDE CENTRE
RH SIDE GUIDE FOR BUMPER
REAR BUMPER TRIM STRIP (LINE SPORT)

QTY	PRIC
1	41.45
1	47.85
1	88.75

VALUE

41.45
47.85
88.75

Total Parts : 178.05

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 19/03/18 @ 11:15 Excess \$5
Surveyor's Name R Kaul Sign _____
Surveyor's Tel 96010688 Authorized Yes / No

Signature
20/3/18

2283.05

Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail _____
No. of Working Days Recommend 3 days

Labour 1	:	2,105.00
Parts	:	178.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	159.81
Grand Total	:	2,442.86

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46090
Date Estimated : 01/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Hu Su Cheng
1 Springleaf View

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 787907

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SGD7070Y	V758175	11/05/2016	218iA/2	0		
DESCRIPTION			ORIGINAL PRICE		DISC. %	NETT
To make good the rear bumper include replacement of damaged parts and knocking out dents caused by the accident			850.00			850.00
To spray paint rear bumper			934.00			934.00
To check electrical wiring systems and lightings at the rear section for proper function.			150.00			150.00
Sundries.			40.00			40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (LINE SPORT)	88.75	1.00		88.75

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	88.75
Total Labour & Parts :	2,062.75
Deduction for Excess :	
Total Repair Costs less Excess:	2,062.75
GST @7%:	144.39
Grand Total :	2,207.14



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004310/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7802X	Veh. Inspected	SGD 7070Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001785MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 218I COUPE	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA2F12060V758175	Colour	RED	
Odometer	35607	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	19/03/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 7070Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	40.00	40.00
1	REAR GUIDE CENTRE (SN)	SERVICEABLE	41.45	-
1	RH SIDE GUIDE FOR BUMPER (SN)	SERVICEABLE	47.85	-
1	REAR BUMPER TRIM STRIP (LINE SPORT)(SN)	SCRATCHED	88.75	88.75
			218.05	128.75
	LABOUR			
	TO MAKING GOOD ON REAR BUMPER INCLUDING REMOVE AND INSTALL ATTACHMENTS TO FACILITATE WITH REPAIR WORK.		850.00	850.00
	PAINTING ON REAR BUMPER ASSEMBLY.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,065.00	1,934.00
	GRAND TOTAL		2,283.05	2,062.75
RECOMMENDED COST OF REPAIRS				2,062.75

Report Ref No. CS/FCI18004310/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.