

ASS. REC. BY:

REF: CS/FCI18004316/R1+d3

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Raisul
Lurene Juw

of

PEI

Date/Time:

6/3/18 @ 2:32pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 2211R

Insured:

SHA8007D

at Workshop n/s

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

Claim No:

D18001868MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

2:35pm 6/3/

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJU 2211R-X

SHA 8007D-CC3/CTI16617775/Gub3q2

D.O.A: 17/4/16

13/3-

Revert predi via email

Part by Part \$3247.40, 3days. (Red: 1377.50 : 36%)

Signature Poon

REF:

78672

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S3U 2211Rat Workshop m/s: PERFORMANCE

of _____

Insured: PCI/TP

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: S3U 2211R Yr Regn: 2012 / MAYType: C Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B-M-W 320 I A C.C. 1997Colour: Black A/C: Insured / Std / NI / NASp. Reading: 78105 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 3812060E983471Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 05/03/18 D.O.I. 12/03/18Survey held at PERFORMANCEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 JUN 2018

Date/Time: File Pass to?

1) 21/6 Typist

Date/Time: File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Offers

TOTAL:

Add Fee: ☐ : Site Insp \$☐ : Interview \$☐ : Tech. Invs \$☐ : Weekend \$

Report Format:

Lump Sum / I.B.I: \$ 3247.40

140

50

50

33

273



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001866MFSH

Date: 13/3/2018

Our Ref: CS/FC18004316/R1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJU 2211R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/3/2018 at the premises of M/s Performance, and have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,991.75</u>
Revised Estimate Amount	: S\$ <u>2,952.15</u>
"Check" Items Amount	: S\$ <u>745.40</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u></u>
Nett Value	: S\$ <u></u>

Description of Damage:
The vehicle sustained damages
at the rear.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-03-2018	Our Ref No. D18001868MFSH
Accident Date	05-03-2018	Claim Type. Third Party
Insured Vehicle	SHA8007D	Third Party Vehicle. SJU2211R
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235642)



PRI Documents



Close



PRI Header Details

Claim No	D18001868MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEI Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8007D	TP Vehicle No	SJU2211R
PRI Recieved Date	06-03-2018 04:00:40 PM	Surveyor Appointed Date	06-03-2018 02:31:46 PM	Surveyor Accept Date	06-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-03-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004316/R1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8007D	Veh. Inspected	SJU 2211R
Policy No.		Coverage (\$)	0.00
Claim No.	D18001866MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	06/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/03/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 13 March 2018 5:46 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001868MFSH/1
Attachments: PRELI ADVISED SJU 2211R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SJU 2211R**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 6 March 2018 3:07 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001868MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 March 2018 2:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001868MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190880 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64756601 (AfterSales)
64756624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

06 MAR 2018

Estimate No. : b1 46125
Date Estimated : 06/03/2018
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

May Cheok Geok Min (May Shi Yumin)
15 Riviera Drive
#05-19

Singapore 467205

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.
SJU2211R

CHASSIS NO.
E983471

REGN. DATE
11/05/2012

MODEL
320iA/4

MILEAGE
0

DESCRIPTION

To replace rear bumper including attachments etc and
to knock out dented area caused by accident

To paint rear bumper

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries.

VALUE

850 1,700.00

934 1,038.00

WAX 271.00

150 177.00

80.00

Total Labour 1: 3,266.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
RR BUMPER TRIM PANEL PRIMED (LINES/
RR BUMPER FLAP TOWING EYE PRIMED
GUIDE FOR BUMPER SIDE LH
GUIDE FOR BUMPER SIDE RH
DECOUPLING RING PDC TORQUE CONVERTE

QTY PRIC

1	66.10
1	32.10
1	432.90
1	1,018.15
1	42.20
1	57.05
1	57.05
4	5.05

VALUE

66.10

32.10

432.90

1,018.15

42.20

57.05

57.05

20.20

Total Parts : 1,725.75

Performance Motors Limited

A member of the Sime Darby Group
 A member of the Sime Darby Group
 CO. Reg. No. 97401559W GST Reg. No M2-0020081-X



115, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Tel. 63190100 (Sales & Admin)
 63190111 (AfterSales)
 Fax. 64797770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Tel. 63190555 (AfterSales)
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Tel. 63190528 (AfterSales)
 63190533/530 (Motorrad)
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46125
 Date Estimated : 06/03/2018
 Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJU2211R	E983471	11/05/2012	320iA/4	0

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured Insured / Direct Solidwork

Regn No. _____

Date & Time 12/03/18 9:11:15

Surveyor's Name RABU

Surveyor's Tel 90010068

Authorised Date _____

RESURVEY PARTS PHOTO BY CURVE - ON Yes / No

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

5207- 4/13/18

Labour 1	:	3,266.00
Parts	:	1,725.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	349.42
Grand Total	:	5,341.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X.



FINAL REPORT

Estimate No. : b1 46125
Date Estimated : 06/03/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
May Cheek Geok Min (May Shi Yumin)
15 Riviera Drive
#05-19

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 467205

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SJU2211R	E983471	11/05/2012	320iA/4	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include knocking out dented areas caused by the accident	850.00		850.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# REAR DECORATIVE STRIP (SPORT LINE) *	57.00	1.00		57.00
REAR BUMPER PANEL PRIMED (LINES)	1,100.25	1.00		1,100.25
# REAR PDC HOLDER SET *	23.10	1.00		23.10
# (DG) ADHESIVE SET K6 *	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,233.40
Total Labour & Parts :	3,247.40
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,247.40
GST @7%:	227.32
Grand Total :	3,474.72

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg No. 197401599W GST Reg No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46125
Date Estimated : 06/03/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
May Cheek Geok Min (May Shi Yumin)
15 Riviera Drive
#05-19

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 467205

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SJU2211R	B983471	11/05/2012	320iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# REAR DECORATIVE STRIP (SPORT LINE) *	57.00	1.00		57.00
# REAR PDC HOLDER SET *	23.10	1.00		23.10
# (DG) ADHESIVE SET K6 *	53.05	1.00		53.05

Total Labour :	
Total Parts :	133.15
Total Labour & Parts :	133.15



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18004316/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8007D	Veh. Inspected	SJU 2211R	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001868MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 320I A	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBA3B12060E983471	Colour	BLACK	
Odometer	78105	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/03/2018	Inspection Date	12/03/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 2211R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RR BUMPER BOTTOM REINFORCEMENT (SN)	SERVICEABLE	66.10	-
1	REAR BUMPER CENTRE GUIDE (SN)	SERVICEABLE	32.10	-
1	REAR BUMPER CARRIER (ECE)(SN)	SERVICEABLE	432.90	-
1	RR BUMPER TRIM PANEL PRIMED (LINES)(SN)	DEFORMED	1,100.25	1,100.25
1	RR BUMPER FLAP TOWING EYE PRIMED (SN)	SERVICEABLE	42.20	-
1	GUIDE FOR BUMPER SIDE LH (SN)	SERVICEABLE	57.05	-
1	GUIDE FOR BUMPER SIDE RH (SN)	SERVICEABLE	57.05	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	SERVICEABLE	20.20	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	REAR DECORATIVE STRIP (SPORT LINE)(ADDITIONAL) (SN)	NECESSARY	57.00	57.00
1	REAR PDC HOLDER SET (ADDITIONAL)(SN)	NECESSARY	23.10	23.10
1	(DG) ADHESIVE SET K6 (ADDITIONAL)(SN)	NECESSARY	53.05	53.05
			2,021.00	1,313.40
LABOUR				
TO REPLACE REAR BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT.			1,700.00	850.00
TO PAINT REAR BUMPER.			1,038.00	934.00
TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.			271.00	-
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	150.00
			3,186.00	1,934.00
GRAND TOTAL			5,207.00	3,247.40
RECOMMENDED COST OF REPAIRS				3,247.40

Report Ref No. CS/FCI18004316/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.