

INS. CASE OWNER:

CC 3 / LPC18004326 / KLF3n2

LKK:

IDAC:

Surveyor:

KALVIN

DOI:


06/03/18

Date / Time:

06/03/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBA 71749

Name of Insured:

Esth Duthers Building & Const  
Contract

Insured Tel No.:

HP:

02/02/18

Excess Sec II :SS

D.O.A.:

02/02/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Sekar Karthikeyan

Driver Tel No.:

85430165

(V/L: YES / NO)

Claim No.:

17/18/18/1000/020449

Policy No.:

21/17/1000/100057

Make / Model:

MUF.

Place of Accident:

X-Junction of Thas Ave 2 /  
Pinner Rd

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SHD 415K



INSRS:

WSP: COGE (Layang)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

314  
AcherSHD 415K - N3A/ENC16016+85/4 DOA: 5/10/16  
GBA 71749 - CS/ENC09016062/1851 DOA: 15/07/19  
- N3A/ENC09016350/161 DOA: 15/07/19  
To check as certain if there is any damage  
to the rear bumper.

16/4/18 FILE PASS TO TYPIST TO PREPARE REPORT.

RECEIVED 19 JUL 2018

RECEIVED 17 APR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

17/03/18

Sent By:

Shirley Hews

FINALIZATION

Date/Time: 9/3/18

Confirm with: JUMAH

Confirm by: AUC

Repair Cost:

45

SS 2,050.00

( 3 )

days) Reduction:

68

%

Email

Call

FINAL SETTLEMENT

Date/Time: 2.7.18

Confirm with: WAZAL

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass, Lia:

Repair Cost:

w/1651

SS 2,193.50

010 CHARGED WARE HIR 70.

Loss of Rental (LOR):

SS 340.38

( 3.5 )

days) x

98.25

Loss of Use (LOU):

SS

( 5 )

x

days)

Loss of Income (LOI):

SS 215.00

( 5.5 )

x

5.5 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS 7.49

Medical:

SS -

Disbursement:

SS -

(e.g. Tow / Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+ 450

Total:

SS 3,016.37

Global Sum SS:

FINAL PAYMENT

Date/Time: 2.7.18

Confirm with: WAZAL

Email

Call

Payee 1:

SS 3,016.37

Name 1:

COMFORTDELGRO ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

106/1113

Survey Vlt: Kelvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate Cost: \_\_\_\_\_

OD / T / E / WS / TP RES / OD RES / EVA / INV / MV

To Insp. at Vehicle No: \_\_\_\_\_

at Workshop: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHD 4115 K Yr Regn: 27 Apr 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/O / Prime Mover /

Truck / Traller or

Make: Hyundai Santa c.c. 1891

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 165242 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KAHET41VACAB2J64

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 2/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/3/18	WH 4/5 \$450/ 3 Pr, Longac 4/5
	(RBD: 74,391.20 68%)

Date/Time, File Pass to?

☐: Prell. Report

Days Of Repair: \_\_\_\_\_

1)

☐: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: \_\_\_\_\_

2)

Transportation: \_\_\_\_\_

Add Fee: ☐: Site Insp (\$ \_\_\_\_\_)

S + RS. \$ \_\_\_\_\_

☐: Interview (\$ \_\_\_\_\_)

Phone: \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC3/LPC18004326/K1ea3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 06-03-2018	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBA 7174G		Veh. Inspected	SHD 4115K
Policy No.			Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020449		Excess (\$)	0.00
Assign From			Assign Date	06/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	02/03/2018		Inspection Date	06/03/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

511-BLAVUE L #02-25 PAYA LEBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VC00/020449  
Our ref: CC3/LPC18004326/K1es3

Date: 08/03/2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHD 4115K**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.03.2018 at the M/s ComfortDelGro Engineering Pte Ltd (Loyang) have the following to report:-

Workshop Estimate Amount	: S\$	6,491.20
Revised Estimate Amount	: S\$	2,541.76
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
O/S Body



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

**Catherine Chong (LKK Auto)**

---

**From:** ERIC WOO JUN KIAT <ericwoo@lonpac.com>  
**Sent:** Tuesday, 6 March, 2018 9:27 AM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K  
along Tuas Ave 2 on 2/3/18  
**Attachments:** 06032018092230.pdf

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SHD 4115K on without Prejudice Basis.

We look forward to receiving your report soon.

*Kevin*

Thank you.

Best Regards,  
Eric Woo  
Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

## Mei Kwan (LKKAuto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 2 April, 2018 2:34 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

**Categories:** AGNES

Dear Shirley,

Kindly verify with the surveyor and ascertain if there is any damage to the rear bumper.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Wednesday, 21 March, 2018 2:29 PM  
**To:** GERALD POH WEE BIN; Asher Sng (LKKAuto)  
**Cc:** MT\_Claim\_SG; ONG LI LI; ERIC WOO JUN KIAT; Vic (LKKAuto); Admin A  
**Subject:** RE: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

Dear Gerald,

Thanks and noted.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]  
**Sent:** Wednesday, 21 March 2018 2:07 PM  
**To:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** RE: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

Dear Shirley,

Our insured has yet to lodge a report and we are making enquiries.

The premium for the policy has been settled.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Wednesday, 21 March, 2018 1:30 PM

**To:** MT\_Claim\_SG; GERALD POH WEE BIN; Asher Sng (LKKAuto)

**Cc:** ONG LI LI; ERIC WOO JUN KIAT; Vic (LKKAuto); Admin A

**Subject:** FW: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

**Your ref: 17/18/18/VC00/020449**

**LKK ref: CC3/LPC18004326/K1es3**

**WITHOUT PREJUDICE**

Dear Sir/Madam,

We refer to the above matter.

Meanwhile, please advise whether insured has reported.

If so, kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto)

**Sent:** Thursday, 8 March 2018 10:05 AM

**To:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Cc:** [llong@lonpac.com](mailto:llong@lonpac.com); [ericwoo@lonpac.com](mailto:ericwoo@lonpac.com); Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

**Your ref: 17/18/18/VC00/020449**

**LKK ref: CC3/LPC18004326/K1es3**

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SHD 4115K

Date of survey: 06/03/2018

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

**Sent:** Wednesday, 7 March 2018 9:11 AM

**To:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** RE: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

Dear Shirley,

Our insured has yet to lodge a report and we are making enquiries.

The premium for the policy has been settled.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Wednesday, 7 March, 2018 9:09 AM

**To:** MT\_Claim\_SG; Asher Sng (LKKAuto)

**Cc:** ONG LI LI; ERIC WOO JUN KIAT; GERALD POH WEE BIN; Admin A

**Subject:** FW: Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

**Your ref: 17/18/18/VC00/020449**



**LKK ref : CC3/LPC18004326/es3**

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s ComfortDelGro Engineering Pte Ltd - Loyang.

We have not authorized repairs.

We will revert preliminary advice in due course.

Meanwhile, Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

***To check availability of the case handler , you may contact the undersigned.***

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

**Sent:** Tuesday, 6 March, 2018 9:27 AM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** Our Ref: 17/18/18/VC00/020449 Accident involving GBA7174G & SHD4115K along Tuas Ave 2 on 2/3/18

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SHD 4115K on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Team: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order:

JC NO. 305121788

OWNER AS COMFORT TRANSPORTATION PTE LTD 7010045 OWNER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (O) (P)		REGN NO. SHD4115K MAKE: HYUNDAI MODEL SONATA YR OF MANU 27.04.2012 CHASSIS CODE RMHET41VMCA823611	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 03.03.2018 11:10 TARGET DATE COMPLETION DATE/TIME:
OUNT CARD NO.			

ccident Date: 02.03.2018  
 ATURE: 3P 02.03.18

JOB DESCRIPTION

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

ICKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vo.: SHD4115K

JU LONPAC

Vehicle No.:

SHD4115K

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

## COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHD 4115K

DATE 5/3/2018 13:45

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 578.40
	Rear Bumper Protector (RH) X			\$ 38.00
	Rear Fender (RH) X Repair			\$ 1,935.90
	Rear Fender Inner Lining (RH) X			\$ 74.10
	Rear Windscreen Moulding X			\$ 60.00
	Rear Door (RH)			\$ 1,294.70
	Rear Door Protector(RH) X Repair			\$ 54.50
	Rocker Panel Outer Garnish (RH) X Repair			\$ 463.40
	Rear Wheel Hub-Cap (RH)			\$ 145.00
	<b>SUB TOTAL</b>			<b>\$ 4,644.00</b>
	<b>LESS 20%</b>			<b>\$ 928.80</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,715.20</b>
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Windscreen Sealant X			\$ 46.00
	Rear Door Advertisement Logo (RH)			\$ 100.00
				<b>\$ 196.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	<b>TOWING</b>			<b>\$ 50.00</b>
	<b>TOTAL LABOUR</b>			<b>\$ 2,530.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 6,441.20</b>
	<p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p>			
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			

K9kin 10KRW  
 6/3/18 1030hr  
 3 hrs  
 45  
 After Repair photo

Acknowledged by Repairer

Signature  
Date:

## COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHD 4115K

DATE 5/3/2018 13:45

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 578.40
	Rear Bumper Protector (RH) X Repair			\$ 38.00
	Rear Fender (RH) X Repair			\$ 1,935.90
	Rear Fender Inner Lining (RH) X S-			\$ 74.10
	Rear Windscreen Moulding X M			\$ 60.00
	Rear Door (RH) — Part			\$ 1,294.70
	Rear Door Protector (RH) X Repair			\$ 54.50
	Rocker Panel Outer Garnish (RH) X Repair			\$ 463.40
	Rear Wheel Hub-Cap (RH) — Wheel			\$ 145.00
	<b>SUB TOTAL</b>			<b>\$ 4,644.00</b>
	<b>LESS 20%</b>			<b>\$ 928.80</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,715.20</b>
	Rear Bumper Advertisement Logo — M			\$ 50.00
	Rear Windscreen Sealant X M			\$ 46.00
	Rear Door Advertisement Logo (RH) — M			\$ 100.00
				<b>\$ 196.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door			\$ 120.00
	Rear Wheel Alignment			\$ 120.00
	<b>TOWING</b>			<del>\$ 50.00</del>
	<b>TOTAL LABOUR</b>			<b>\$ 2,530.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 6,445.20</b>
	<b>K9 km (C/KR)</b>			
	<b>6/3/18 1030 hr</b>			
	<b>3 hrs</b>			
	<b>45</b>			
	<b>After Repair photo</b>			
	<b>LKK Auto Consultants</b> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modifications is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Lampac -

Jumani

6491.20

## COMFORTDELGRO ENGINEERING

Our Job Ref No : 305121788

Date : 08/03/18

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHD4115K

Date of Accident : 02/03/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: LONPAC --- GBA7174G  
###
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges ###
  - Total for Part-By-Part Repair Cost
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$2,050.00  
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 3 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : KALVIN

Date : 9/3/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC18004326/K1ea3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 20-07-2018		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBA 7174G	Veh. Inspected	SHD 4115K	
Policy No.	Z/17/VC00/100057	Coverage (\$)	0.00	
Claim No.	17/18/18/VC00/020449	Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHET41VMCA823611	Colour	BLUE	
Odometer	165242	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	215/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	215/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	215/60 R16	WEST LAKE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/03/2018	Inspection Date	06/03/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4115K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	578.40	-
1	REAR BUMPER PROTECTOR (RH)	TO REPAIR SEE LABOUR	38.00	-
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	1,935.90	-
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	74.10	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.00	-
1	REAR DOOR (RH)	DENTED	1,294.70	1,294.70
1	REAR DOOR PROTECTOR (RH)	TO REPAIR SEE LABOUR	54.50	-
1	ROCKER PANEL OUTER GARNISH (RH)	TO REPAIR SEE LABOUR	463.40	-
1	REAR WHEEL HUP-CAP (RH)	GRAZED	145.00	145.00
	LESS 20% DISCOUNT		-928.80	-287.94
			3,715.20	1,151.76
<b>SPECIAL NETT ITEMS</b>				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	REAR DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			196.00	150.00
<b>LABOUR</b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR BUMPER PROTECTOR (RH),REAR FENDER (RH),REAR DOOR PROTECTOR (RH) AND ROCKER PANEL OUTER GARNISH (RH).		1,000.00	400.00
	SPRAY PAINTING CHARGE.		800.00	720.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	30.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TRANSFER OF DOOR.		120.00	50.00

Report Ref No. CC3/LPC18004326/K1ea3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REAR WHEEL ALIGNMENT,	NOT NECESSARY	120.00	-
	TOWING.	NOT NECESSARY	50.00	-
			2,580.00	1,250.00
GRAND TOTAL			6,491.20	2,551.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CC3/LPC18004326/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.