

Surveyor:

REF: CS3 / ALH17014526 / U 96:1

Special Instruction:

US: \$ 4050.00

ASSIGNMENT (Office)

From (Person): Norsiah of ALH Date/Time: 05/03/2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Kelvin Automotive Appraising

Workshop: MCS Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: FBJ 5866J Insured: SDA 6898J

at Workshop m/s MCS Auto Tel: 6296 9939

of No. 1100 Sarangoon Rd

Policy No: Claim No: 4221266761867 (003)

Sum Insured: Excess:

Make of Veh: D.O.A. 23072017

(Client's Record)

07-03-2018 (Wednesday) @ 12pm - 3pm

04-04-2018 @ 11:30am - 12pm H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red S / %; Original 5 days)

Date/Time: 07/5/18 Submit Final Fig 2100 3 days (Red S 1950 / 48%; Original 5 days)

Date/Time	Action/Instruction
	FBJ 5866J - CS3 / ALH17014526 / Jbe2
	SDA 6898J - x
08/03/2018	Owner did not tune up (by ALH)
05/04/2018	"
"	Received email from Norsiah to conduct Paper survey
	3 by \$ 2100
	During Disassemble PMS Exhaust near D-smooth rim

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 02 MAY 2018

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:


1) Date/Time 07/5/18 File Pass to trisr

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17014526/qb-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-03-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SDA 6898J	Veh. Inspected	FBJ 5866J
Policy No.		Coverage (\$)	0.00
Claim No.	4221266761SG (003)	Excess (\$)	0.00
Assign From	NORSIAH	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/07/2017	Inspection Date	07/03/2018
Survey held at	MCS AUTO NO. 1100 SERANGOON ROAD SINGAPORE 328195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Catherine Chong (LKK Auto)

---

**From:** Md Noor, Norsiah <Norsiah.MdNoor@aig.com>  
**Sent:** Thursday, 5 April, 2018 11:33 AM  
**To:** info@catherinelimllc.com; Catherine Chong (LKK Auto)  
**Cc:** 'assignments'  
**Subject:** RE: Re-inspection - Our Ref : 4221266761SG (003) Yoyr Ref: CL/170794/T/MCS.sg

WITHOUT PREJUDICE

Dear Sally,

As per our telephone conversation, we will conduct paper survey for this matter.

Dear Catherine,

Please assist to conduct paper survey and submit the report urgently.

Thank you

Norsiah Md Noor  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606 | Fax +(65) 6835-7417  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, April 05, 2018 8:57 AM  
**To:** info@catherinelimllc.com; Md Noor, Norsiah  
**Cc:** 'assignments'  
**Subject:** RE: Re-inspection - Our Ref : 4221266761SG (003) Yoyr Ref: CL/170794/T/MCS.sg

Dear Sally,

Please be informed that our surveyor went down for the Re-Inspection yesterday, but the owner still did not turn up at the prescribed time and place.

Kindly re-arrange.

Best Regards,

**Catherine Chong** | Admin

## Catherine Chong (LKK Auto)

---

**From:** Md Noor, Norsiah <Norsiah.MdNoor@aig.com>  
**Sent:** Monday, 5 March, 2018 4:34 PM  
**To:** 'SUR'; Catherine Chong (LKK Auto)  
**Subject:** FW: Re-inspection - Our Ref : 4221266761SG (003) Yoyr Ref: CL/170794/T/MCS.sg

Dear Catherine,

Refer to the above.

Please assist to conduct physical re-inspection on third-party's vehicle.

FBJ 5866J

Thank you

Norsiah Md Noor  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606 | Fax +(65) 6835-7417  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Sally [mailto:info@catherinelimllc.com]  
**Sent:** Thursday, March 01, 2018 4:32 PM  
**To:** Md Noor, Norsiah  
**Subject:** RE: Re-inspection - Our Ref : 4221266761SG (003) Yoyr Ref: CL/170794/T/MCS.sg

Dear Norsiah (Without Prejudice)

We refer to your email.

We arrange re-inspection as follows:

Date : 07 March 2018 ( Wednesday)

Venue : MCS Auto (1100 Serangoon Road Singapore 328196)

Time: 12noon - 3pm

Contact: 6296 9939

Please confirm and let us know your appointed surveyor.

Regards  
Sally Goh  
Catherine Lim LLC  
20 Havelock Road #03-01  
Central Square  
Singapore 059765  
Email: [info@catherinelimllc.com](mailto:info@catherinelimllc.com)

---

**From:** Md Noor, Norsiah [<mailto:Norsiah.MdNoor@aig.com>]  
**Sent:** Monday, February 12, 2018 8:57 AM  
**To:** Sally  
**Subject:** RE: Re-inspection - Our Ref : 4221266761SG (003) Yoyr Ref: CL/170794/T/MCS.sg

WITHOUT PREJUDICE

Dear Sally,

We refer to your letter dated 26/6/18.

As we are not able to reach settlement, we request to conduct re-inspection on your client's vehicle.

Please revert.

Thank you

Norsiah Md Noor  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606 | Fax +(65) 6835-7417  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	25/07/2017 14:56
Date Of Accident	23/07/2017 17:30
Exact Location Of Accident	CARPARK BESIDE A.M.K. BUS INTERCHANGE
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ5866J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	QUI YUAN JIUNN CHERVIN
NRIC No	S9406168G
Email Address	CHERVINQUIYUANJIUNN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91806954
Alternative Phone No	OTHERS-91806954
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	WAVE 125
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5087982880
Cover Note Number	
<b>Driver</b>	
Name of Driver	QUI YUAN JIUNN CHERVIN
NRIC No	S9406168G
Date Of Birth	23/02/1994
Occupation	OUTDOOR
Date Of Driving Pass	20/10/2014
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91806954
Fax Number	
Contact Number	OTHERS-91806954
E Mail Address	CHERVINQUIYUANJIUNN@GMAIL.COM

Address. BLK 220 ANG MO KIO AVENUE 1  
#06-813

Postcode 560220

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLIDED INTO PARKED VEHICLE

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name KEBUN BARU NEIGHBOURHOOD POLICE POST

Police Station Address ROAD: BLK 111 ANG MO KIO AVENUE 4 , POSTCODE: 560111 ,  
COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4589999 - FAX NO: 64574454

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SDA6898J

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver JOSHUA MAH JING ZHI

NRIC/Passport Number S9203370H

Contact Number 91708838

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

\_\_\_\_\_  
Policyholder's Signature / Date & Time

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

**Sketch Plan**







**SINGAPORE  
POLICE FORCE**



F/20170725/2092

1 of 2

POLICE REPORT (NP299)

Report No. F/20170725/2092

Police Station Of Origin  
Kebun Baru NPP  
111 Ang Mo Kio Avenue 4 SINGAPORE  
560111  
Tel No: 1800-4589999

Date/Time Report Made 25/07/2017 14:26		Vide Report No.		Station Diary No. 18	
Name Of Informant QUI YUAN JIUNN CHERVIN		Address APT BLK 220 ANG MO KIO AVENUE 1 #06-813 SINGAPORE 560220			
ID Type / ID No. NRIC NO / S9406168G		Contact No. Home/Office		Mobile 91806954	
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Delivery driver		Sex Male	Age 23	Date of Birth 23/02/1994	Race Chinese
Institution/School Name		Language			
Date/Time Of Incident 23/07/2017 17:30		Location Of Incident C/O 53 ANG MO KIO AVENUE 3 AMK HUB SINGAPORE 569933 Carpark beside AMK bus interchange			

**Brief details.**

On 23/07/17 at about 1710hrs, I had parked my motorbike behind one of the motorbikes that was parked at the motorbike lots. I then left to run some errands.

On 23/07/17 at about 1730hs, when I came back to retrieve my motorbike, FBJ5866J, I noticed that my motorbike had fallen and there were a few people trying to pick my motorbike up. I then approached the

Signature Of Officer Recording The Report: F / Sgt MUHAMMAD KHAIR BIN SAHARUDDIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 25/07/2017 14:26
Officer In-Charge Of Case: F / Ang Mo Kio North N.P.C / Staff Sgt MUHAMMAD AZRI BIN MASRAN Contact No.: 64849999	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



F/20170725/2092

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20170725/2092

group of people and one of the male subject, Joshua Mah Jing Zhi S9203370H Hp: 91708838 admitted that he had earlier hit onto my motorbike whilst he was reversing his car, white Nissan Slyphy SDA6898J in the parking area. I noticed that there were some damages on my motorbike due to the accident. Joshua then agreed to settle the matter privately and he told me to give him a quotation so that he could pay for the damages done to my motorbike. On 25/07/17, I gave Joshua a quotation for the damages however he refused to pay me for the damages as he says that I have repaired some of the areas on my motorbike. I am lodging this report for insurance claim.

Signature Of Officer Recording The Report: F / Sgt MUHAMMAD KHAIR BIN SAHARUDDIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 25/07/2017 14:26
Officer In-Charge Of Case: F / Ang Mo Kio North N.P.C / Staff Sgt MUHAMMAD AZRI BIN MASRAN Contact No.: 64849999	Classification Of Case:

Authentication Stamp





### Claim Documents

\*FBJ5866J (4221266761SG)  
 [SDA6898J]  
 TP  
 QUI YUAN JIUNN CHERVIN  
 Jul 23 2017 5:20PM  
 [Mah Joseph]  
 Mcs Auto

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	
Photos/Images										Use Viewer	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		3 per page		Thumbnail		Print			
1	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
2	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
3	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
4	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
5	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
6	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
7	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
8	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
9	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
10	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
11	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
12	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
13	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
14	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
15	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
16	05/09/17 19:23	Odometer Reading			Load JPG		<input checked="" type="checkbox"/>				
17	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
18	05/09/17 19:23	General View			Load JPG		<input checked="" type="checkbox"/>				
19	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
20	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
21	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
22	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
23	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
24	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
25	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
26	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
27	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
28	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
29	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
30	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
31	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
32	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
33	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
34	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
35	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
36	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				
37	05/09/17 19:24	Photographs of Damaged Parts			Load JPG		<input checked="" type="checkbox"/>				

38	05/09/17 19:24	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	05/09/17 19:24	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	05/09/17 19:24	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
42	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
43	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
44	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
45	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
46	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
47	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
48	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
49	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
50	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
51	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
52	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
53	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
54	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
55	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
56	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
57	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
58	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
59	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
60	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
61	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
62	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
63	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
64	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
65	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
66	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
67	05/09/17 19:24	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

**DOCUMENTS CHECKLIST** Reset Save Print

There are no document checklists configured.

---

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17014526/JBE2  
Date: 19/09/2017

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100349730-03000
Claimant Vehicle No :	FBJ5866J	Insured Vehicle No :	SDA6898J
Date of Loss:	23/07/2017	Nature of Claim:	TP
		Claim No:	4221266761SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ5866J	Engine No:	NF125MDE0014728
Make & Model:	HONDA WAVE 125, 125cc	Chassis No:	NF125MD0014728
Reg. Date:	04/06/2002 (Man. Year: 2002)	Odometer:	34585 km
Colour:	Blue		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth.*

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	27/07/2017	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Date Inspected:	28/07/2017		
Estimated Period of Repair:	3.0 days		

Adjuster: Richard Harjanto

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F	
2	1		*FRONT HEADLAMP FAIRING	Broken	0.00 F	*- F	
3	1		*HANDLE BAR	Bent	0.00 F	*- F	
4	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F	
5	1		*SIDE FAIRING	Broken	0.00 F	*- F	
6	1		*FAIRING FRONT	Broken	0.00 F	*- F	
7	2		*CENTER FAIRING + BUCKET	Broken	0.00 F	*- F	
8	1		*FRONT FOOT REST LH	Damaged	0.00 F	*- F	
9	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F	
10	1		*REAR FOOT REST LH	Damaged	0.00 F	*- F	
					<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

# MCS AUTO

120264

1100 Serangoon Road Singapore 328195  
Company Registration No. 53126812L  
Email : mcs.auto@yahoo.com.sg

Date: 21 Aug 2017

Qui Yuan Jiunn Chervin  
1100 Serangoon Road Singapore 328195


FINAL REPAIR COSTS

VEHICLE NO: FBJ5866J (HONDA WAVE125S)

Repair costs of vehicle no. FBJ5866J as per the surveyor's  
report KELVIN AUTOMOTIVE APPRAISING SERVICES (attached herewith)  
dated 14 Aug 2017 ..... \$4,050.00  
(Lump Sum)

SINGAPORE DOLLARS : FOUR THOUSAND FIFTY ONLY





kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825  
tel: 6746 2118 fax: 6746 1148  
reg no: 53058468m

Insured : -  
Policy No. : -  
Sum Insured : -  
Excess : -  
Our Reference : KAAS/TA/4712/5866/TP/07.17  
Date : 14 August 2017

To: Qui Yuan Jiunn Chervin  
c/o 1100 Serangoon Road  
Singapore 328195

### VEHICLE APPRAISAL REPORT

Name of Workshop : MCS Auto  
Place of inspection : 1100 Serangoon Road, Singapore 328195  
Date of Assignment : 03 August 2017  
Date of Accident : 23 July 2017  
Date of Inspection : 03 August 2017

#### PARTICULARS OF INSPECTED VEHICLE

Registration No.	: FBJ 5866J	Engine No.	: HIDDEN FROM VIEW
Make/Model	: Honda Wave 125s	Chassis Frame No.	: NF125MD0014728
Year of Manufacture/Reg	: 2002	Colour	: Blue
Class/Type	: Motorcycle	Odometer Reading	: 35,207 KM

#### CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition	: Good	Undercarriage (Front)	: Serviceable
Paintwork	: Good	Undercarriage (Rear)	: Serviceable
Footbrakes	: Serviceable	Market Value	: -
Steering	: Serviceable	Scrap Value (PARF/OMV)	: -

#### CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front	MAXXIS 70 / 90 - 17	8mm
Rear	MAXXIS 70 / 90 - 17	8mm

\*The above is an estimate of the remaining life of the tyre thread in millimeters

*The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.*



6 tampines st 73, #01-03, singapore 528825  
 tel: 6746 2118 fax: 6746 1148  
 reg no: 53058468m

Our Reference : KAAS/TA/4712/5866/TP/07.17  
 Vehicle Number : FBJ 5866J

### APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
-----	-----	--------------	-------------------------	------------------------	-------------------

LIST ITEMS:-

1	1 pc	Front fender	Deformed	\$ 75.00	\$ 75.00 ✓
2	1 pc	Headlamp	Cracked	\$ 120.00	\$ 120.00 X
3	2 pcs	Front signal lamp @S\$45.00	Cracked	\$ 90.00	\$ 90.00 X
4	1 pc	Head fairing	Broken	\$ 195.00	\$ 195.00 ✓
5	1 pc	Front ctr fairing	Broken	\$ 125.00	\$ 125.00 ✓
6	1 pc	Handlebar	Buckled	\$ 68.00	\$ 68.00 ✓
7	1 pair	Handlebar balancer	Scratched	\$ 30.00	\$ 30.00 ✓
8	1 pair	Handlebar grip	Intact	\$ 36.00	Reuse X
9	1 pc	Handlebar stay	Buckled	\$ 79.00	\$ 79.00 ✓
10	1 pc	Brake fluid reservoir	Leaked	\$ 120.00	\$ 120.00 X
11	1 pc	RH brake lever	Scratched	\$ 27.00	\$ 27.00 X
12	1 pc	RH side mirror	Buckled	\$ 50.00	\$ 50.00 X
13	1 pc	Front rest bar with rubber pad	Buckled	\$ 98.00	\$ 98.00 ✓
14	1 pc	LH pillion rider foot rest bracket w/ pad	Buckled	\$ 112.00	\$ 112.00 ✓
15	2 pcs	Side ( front ) fairing @S\$195.00	Broken	\$ 390.00	\$ 390.00 ✓
16	2 pcs	Side ( rear ) fairing @S\$145.00	Broken	\$ 290.00	\$ 290.00 ✓
17	1 pc	Ctr ( rear ) fairing	Broken	\$ 350.00	\$ 350.00 ✓
18	1 pc	Seat assy	Cut	\$ 270.00	\$ 270.00 X
19	1 pc	Rear exhaust muffler	Buckled	\$ 500.00	\$ 500.00 ✓
20	1 pc	Rear exhaust muffler heat shield	Buckled	\$ 105.00	\$ 105.00 ✓
				\$ 3,130.00	\$ 3,094.00
Less 10%					\$ 309.40
				\$ 3,130.00	\$ 2,784.60

SPECIAL NETT ITEMS:-

21	1 pc	Front wheel rim	Distorted	\$ 450.00	\$ 450.00 X
22	1 pc	Front tyre @50% depreciation	Scratched	\$ 320.00	\$ 160.00 X
23	1 pc	Front storage tray	Scratched	\$ 125.00	\$ 125.00 ✓
24	1 pc	Rear box assy	Scratched	\$ 250.00	\$ 250.00 ✓
25	1 pc	Rear box support bracket	Buckled	\$ 45.00	\$ 45.00 ✓
				\$ 1,190.00	\$ 1,030.00

Sub - Total

4 0.



6 tampines st 73, #01-03, singapore 528825  
 tel: 6746 2118 fax: 6746 1148  
 reg no: 53058468m

Our Reference : KAAS/TA/4712/5866/TP/07.17  
 Vehicle Number : FBJ 5866J

**APPRAISEMENT SCHEDULE**

S/N	Qty	Descriptions	Comments/ Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 4,320.00	\$ 3,814.60
<b>LABOUR &amp; OTHER CHARGES:-</b>					
1		To dismantle and repair damaged parts		\$ 700.00	\$ 600.00 300
2		To check wiring		\$ 60.00	\$ 11 50.00 X
3		To realign front fork		\$ 200.00	\$ 17 180.00 X
4		To perform body frame alignment		\$ 180.00	\$ 17 150.00 X
5		To putty and spray-paint of affected areas		\$ 350.00	\$ 300.00
				\$ 1,490.00	\$ 1,280.00

**Sub - Total \$ 5,810.00 \$ 5,094.60**




6 tampines st 73, #01-03, singapore 528825  
tel: 6746 2118 fax: 6746 1148  
reg no: 53058468m

Our Reference : KAAS/TA/4712/5866/TP/07.17  
Vehicle Number : FBJ 5866J

### ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered to the Rear portion of the vehicle.



(Please refer to the parts list and photographs as attached for more information)

### ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs MCS Auto is \$ 5,810.00 .  
We have adjusted the cost to \$ 5,094.60 and the repairer has agreed to undertake the repairs at a Contract Lump Sum of \$ 4,050.00 to a acceptable quality and standards.  
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of 5 working days.

76 photographs were taken at the time of static inspection.

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. 4712 for our services rendered and we thank you for engaging our services.

Kelvin Automotive Appraising Services

KELVIN TEO  
Licensed Automotive Appraiser  
Nitec in Automotive Technology  
Dip MS  
MSAAA

col 2022

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17014526/Uqbs2-1	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 ATTN: NORSIAH		Date : 04-05-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDA 6898J	Veh. Inspected	FBJ 5866J
Policy No.	2100349730-03000	Coverage (\$)	0.00
Claim No.	4221266761SG	Excess (\$)	0.00
Assign From	NORSIAH	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA WAVE125	c.c	125
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	NF125MD0014728	Colour	BLUE
Odometer	34585	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	70/90-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MAXXIS	3 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/07/2017	Inspection Date	28/07/2017
Survey held at	MCS AUTO NO. 1100 SERANGOON ROAD SINGAPORE 328195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBJ 5866J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT FENDER	CRACKED	75.00	75.00
1	HEADLAMP	NOT NECESSARY	120.00	-
2	FRONT SIGNAL LAMP @ \$45.00	NOT NECESSARY	90.00	-
1	HEAD FAIRING	BROKEN	195.00	195.00
1	FRONT CTR FAIRING	BROKEN	125.00	125.00
1	HANDLEBAR	BENT	68.00	68.00
1	PAIR HANDLEBAR BALANCER	SCRATCHED	30.00	30.00
1	PAIR HANDLEBAR GRIP	NOT NECESSARY	36.00	-
1	HANDLEBAR STAY	BENT	79.00	79.00
1	BRAKE FLUID RESERVOIR	NOT NECESSARY	120.00	-
1	RH BRAKE LEVER	SERVICEABLE	27.00	-
1	RH SIDE MIRROR	SERVICEABLE	50.00	-
1	FRONT REST BAR WITH RUBBER PAD	BENT	98.00	98.00
1	LH PILLION RIDER FOOT REST BRACKET W/PAD	DAMAGED	112.00	112.00
2	SIDE (FRONT) FAIRING @ \$195.00	BROKEN	390.00	390.00
2	SIDE (REAR) FAIRING @ \$145.00	BROKEN	290.00	290.00
1	CTR (REAR) FAIRING	BROKEN	350.00	350.00
1	SEAT ASSY	TO REPAIR SEE LABOUR	270.00	-
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	500.00	-
1	REAR EXHAUST MUFFLER HEAT SHIELD	SERVICEABLE	105.00	-
	LESS 10% DISCOUNT		-	-181.20
			3,130.00	1,630.80
<b>SPECIAL NETT ITEMS</b>				
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	450.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	320.00	-
1	FRONT STORAGE TRAY (SN)	SCRATCHED	125.00	125.00
1	REAR BOX ASSY (SN)	SCRATCHED	250.00	250.00
1	REAR BOX SUPPORT BRACKET (SN)	BENT	45.00	45.00
			1,190.00	420.00

Report Ref No. CS3/AIG17014526/Uqbs2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO DISMANTLE AND REPAIR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF SEAT ASSY AND REAR EXHAUST MUFFLER.		700.00	300.00
	TO CHECK WIRING.	NOT NECESSARY	60.00	-
	TO REALIGN FRONT FORK.	NOT NECESSARY	200.00	-
	TO PERFORM BODY FRAME ALIGNMENT.	NOT NECESSARY	180.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		350.00	300.00
			1,490.00	600.00
	<b>GRAND TOTAL</b>		<b>5,810.00</b>	<b>2,650.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,100.00</b>

Report Ref No. CS3/AIG17014526/Uqbs2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.