

INS. CASE OWNER:

Salina

CC3, ALH18004335, R10039

LKK:

IDAC:

Surveyor:

DANU

DOI:

ASSIGNMENT

19/3/2018

Date / Time:

6/3/18

Registered in Merimen:

6/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 4727L

Name of Insured:

DAIMLER FLEET MANAGEMENT CSB/PLC

Claim No.:

032651681856

Policy No.:

099994742

Insured Tel No.:

HP:

Make / Model:

T-Harrier

Excess Sec II :SS

D.O.A.:

6/3/18

Place of Accident:

Ganges Rd to Havelock Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN ENH HUIEE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

83189816

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SJH 881m



INSRS:

WSP:

Tel:

Liability:

RMKS:

p.m.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

13/3

ADW

SJH 881m - X; SLF 4727L - X

FILE REVIEW: DID REAR ENDED TP.

13/3/18 EMAIL WSP LIABILITY CLEAR.

24.5.18 FILE PASS TO TPMS TO PREPARE REPORT.

RECEIVED 24 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

Email 23/3/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: TP NVAL.

PRELIMINARY ADVICE Date/Time: -

Sent By: -

FINALIZATION

Date/Time: 17.5.18

Confirm with: (AGREE)

Confirm by: MEB

Repair Cost:

P/S \$8,645

(5 days)

Reduction:

61 %

Email

Call

FINAL SETTLEMENT

Date/Time: 30.7.18

Confirm with: (AGREE)

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 21

If NO or B 28, Ass. Lin:

Repair Cost:

m/k/s

\$9,350.15

DID REAR ENDED TP.

Loss of Rental (LOR):

\$750.00

(5 days)

+150

Loss of Use (LOU):

\$ -

(\$

x

days)

Loss of Income (LOI):

\$ -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$7.45

Medical:

\$ -

Disbursement:

\$ -

(e.g. Tow/Independent)

Legal Cost

\$ -

Total:

\$16,001.60

Global Sum SS:

FINAL PAYMENT

Date/Time: 30.7.18

Confirm with: (AGREE)

Email

Call

Payee 1:

\$

9,351.60

Name 1:

PERFORMANCE MOTORS LIMITED

Payee 2: (Strike if N.A.)

\$

750.00

Name 2:

TAN KHIAN BOON (CHEN JIANWEN)

Payee 3: (Strike if N.A.)

\$

Name 3:

Singapore *Pasam*

REF: ALG

4335 / Meas - (2) 0648A

ASSIGNMENT

From: _____ Date: 19032018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJH 881M

at Workshop m/s Performance

of 303 Alexander Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Chuan

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJH 881M Yr Regn: 2016 / 05

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 320i c.c. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 23229 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB98X320509443888

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm L/Bal. 6 mm

L/Bal. 6 mm D.O.I. 19/03/18

D.O.A. 06/03/18

Survey held at Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP 28.645.00 (PBD: +13,716.85 61%)

Date/Time: File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

1)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

_____ \$ + RS. _____ \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18004335/ea3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-03-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 4727L	Veh. Inspected	SJH 881M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/03/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

06 MAR 2018

Estimate No. : b1 46137
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Tan Khien Boon (Chen Jianwen)
60 Lakeside Drive
#09-39

Singapore 648320

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJH881M	G443858	27/10/2016	320iA GT	0

DESCRIPTION

Replace rear boot lid, rear bumper and remove attachment
etc include knock on accident dent

VALUE
~~2550~~ 4,250.00

Spray painting rear bumper, boot lid and tail panel

2537 ~~2,819.00~~

To replace rear windscreen glass

photo ~~574.00~~

To supply and install or rear windscreen solar film.

~~531.00~~

To replace exhaust manifold and gasket including checks
for leak.

807 ~~950.00~~

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~171.00~~

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 ~~271.00~~

To carry out body cavity preservation.
(Per panel).

100 ~~118.00~~

Sundries.

? 150.00

Total Labour 1: 9,840.00

DESCRIPTION

Velcro
TAILPIPE TRIM CHROME
Rear muffler
BOOTLID
LH TRUNK LID HINGE
RH TRUNK LID HINGE
GUIDE CENTRE REAR
RR BUMPER CARRIER
LEFT PROTECT foil

QTY	PRIC	VALUE
4	9.25	37.00
2	118.65	237.30
1	1,017.40	1,017.40
1	1,204.80	1,204.80
1	125.00	125.00
1	125.00	125.00
1	34.90	34.90
1	432.90	432.90
1	11.00	11.00

VALUE
37.00
237.30
1,017.40
1,204.80
125.00
125.00
34.90
432.90
11.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 157401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190531/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46137
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJH881M	G443858	27/10/2016	320iA GT	0

DESCRIPTION	QTY	PRIC	VALUE
RIGHT PROTECT foil	1	11.00	11.00
REINFORCEMENT BUMPER REAR BOTTOM (M	1	80.25	80.25
REINFORCEMENT BUMPER REAR BOTTOM (M	1	80.25	80.25
TRIM PANEL BUMPER REAR BOTTOM (PDC)	1	294.65	294.65
REAR BUMPER PANEL PRIMED (M/PDC)	1	1,178.40	1,178.40
SET MOUNTS PDC SENSOR REAR (M)	1	62.95	62.95
REAR PLAQUE	1	69.50	69.50
MODEL LETTERING 320i	1	62.55	62.55
MODEL LETTERING GT	1	62.55	62.55
GROMMET	2	0.75	1.50
TRUNK LID POWER LOCK DRIVE	1	526.05	526.05
SPINDLE DRIVE LH	1	318.70	318.70
SPINDLE DRIVE RH	1	318.70	318.70
LOCK TRUNK LID	1	211.85	211.85
BOOTLID/TAILOATE PUSH BUTTON	1	47.20	47.20
BUMP STOP	10	3.25	32.50
REAR WINDOW	1	749.55	749.55
Velcro	4	1.10	4.40
HOOK AND LOOP FASTENER	6	2.80	16.80
Trim cover, left	1	106.15	106.15
Trim cover, right	1	106.15	106.15
Cover for lock loading panel	1	9.75	9.75
SPOILER MODULE	1	1,249.70	1,249.70
SPOILER BLADE	1	443.70	443.70
FINISHER ROOF GAP REAR	1	81.85	81.85
FINISHER ROOF GAP REAR	1	81.85	81.85
TRUNK LID SEALING	2	40.25	80.50
TRUNK LID SEALING	2	40.25	80.50
TRUNK LID GASKET	1	118.15	118.15
GUTTER STRIP	2	66.85	133.70
R. reflector	1	35.20	35.20
Rear light i	1	497.60	497.60
Rear light i	1	293.90	293.90
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
PDC SENSOR ALPINWEISS (300)	4	368.80	1,475.20
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : 12,483.55

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 187401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Easpong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46137
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJH881M	G443858	27/10/2016	320iA GT	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 19/03/18 @ 1145 Excess S\$ _____
Surveyor's Name Raul Sign _____
Surveyor's Tel 90010068 Authorised Yes / No _____
Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 5-6 days

Repair by paint

Labour 1	:	9,840.00
Parts	:	12,483.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,562.65
Grand Total	:	23,886.20

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46137
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan Khien Boon (Chen Jianwen)
60 Lakeside Drive
#09-39

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 648320

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SJH881M	G443858	27/10/2016	320iA GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
# SEAL REAR SPOILER LH *	19.15	1.00		19.15
# SEAL REAR SPOILER RH *	19.15	1.00		19.15

Total Labour :	
Total Parts :	38.30
Total Labour & Parts :	38.30



FINAL REPORT

Estimate No. : b1 46137
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan Khien Boon (Chen Jianwen)
60 Lakeside Drive
#09-39

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 648320

REGN NO	CHASSI S NO	REGN DATE	MODEL	MILEAGE
SJH881M	G443858	27/10/2016	320iA GT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments include knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper and boot lid	2537.00		2,537.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	80.00		80.00	

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,204.80	1.00		1,204.80
REAR BUMPER PANEL PRIMED (M/PDC)	1,121.60	1.00		1,121.60
TRIM PANEL BUMPER REAR BOTTOM (PDC)	294.65	1.00		294.65
SET MOUNTS PDC SENSOR REAR (M)	62.05	1.00		62.05
REAR PLAQUE	69.50	1.00		69.50
MODEL LETTERING 320i	62.55	1.00		62.55
MODEL LETTERING GT	62.55	1.00		62.55
GROMMET	0.75	2.00		1.50
TRUNK LID SEALING	40.25	1.00		40.25
TRUNK LID SEALING	40.25	1.00		40.25
# SEAL REAR SPOILER LH *	19.15	1.00		19.15
# SEAL REAR SPOILER RH *	19.15	1.00		19.15

SUPPLEMENTARY ITEMS

Total Labour :	5,647.00
Total Parts :	2,998.00
Total Labour & Parts :	8,645.00
Deduction for Excess :	
Total Repair Costs less Excess:	8,645.00
GST @7%:	605.15
Grand Total :	9,250.15

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 8 June 2018 2:51 PM
To: Syed-Yusoff, Saliha
Subject: Your ref : 0326566868SG, ACCIDENT ON 06/03/2018 INVOLVING SLF 4727L (OI) & SJH 881M (TP)

Your ref : **0326566868SG**
Our ref : CC3/AIG18004335/R1ea3

Dear Sirs,

ACCIDENT ON 06/03/2018 INVOLVING SLF 4727L (OI) & SJH 881M (TP)

We refer to the above matter.

The accident occurred when our insured hit onto third party parked vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **PERFORMANCE MOTORS LTD**" at **\$ 10,007.60 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 23,927.18	\$ 9,250.15
2. Loss of Rental (5days x \$150)	\$ 750.00	\$ 750.00 (5days x \$150)
3. LTA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 24,684.63	<u>\$ 10,007.60</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SJH881M (0326566868SG)**
[SLF4727L]

TP

TAN KHIEH BOON

Mar 6 2018 7:00AM

[DAIMLER FLEET MANAGEMENT]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/06/2018 09:50 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9957.60) - SJH881M - Claim Handler: Syed-Yusoff, Saliha

Approved:9957.60:mandate for settlement up to \$9957.60 [COR- \$9250.15 LOR- \$130-140 x 5 DAYS)

Claim Audit

AUDIT TRAIL				
No	On	Audit	Remarks	By
1	06 Mar 2018 18:37	Cim Veh Model Changed	(205430) BMW 320I 2.0 (A).	[A] HOW MEI KWAN
2	06 Mar 2018 18:37	Cim Created	Reg No: SJH881M, Acct Date: 2018/03/06, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Performance Motors Limited (Alexandra)	[A] HOW MEI KWAN
3	06 Mar 2018 18:37	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	06 Mar 2018 18:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/15	[A] HOW MEI KWAN
5	06 Mar 2018 18:37	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
6	06 Mar 2018 18:37	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
7	06 Mar 2018 18:38	Label Added	(23):Express,	[A] HOW MEI KWAN
8	06 Mar 2018 18:38	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] HOW MEI KWAN
9	20 Mar 2018 19:28	Adj Adjuster Assigned	MOHD TAUFIKH BIN HAMID -> MOHD RASUL	[A] HOW MEI KWAN
10	05 Jun 2018 11:18	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	05 Jun 2018 11:18	Cim Dtl Modified	Claimant's ID: -> -,	[A] JOANNE LEE KHANG MIN
12	05 Jun 2018 11:18	Cim Dtl Modified	JPJ Reg. Date: -> 2016/10/27.	[A] JOANNE LEE KHANG MIN
13	05 Jun 2018 11:18	Cim Details Notified		[A] JOANNE LEE KHANG MIN
14	08 Jun 2018 14:50	Adj Mandate Request	Cur.Req:10007.60:10,007.60	[A] Asher Sng Rong Yi
15	11 Jun 2018 09:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/15, Mandate Remarks: mandate for settlement up to \$9957.60 [COR- \$9250.15 LOR- \$130-140 x 5 DAYS]	[I] Syed-Yusoff, Saliha
16	11 Jun 2018 09:50	Adj Mandate Set	Approved:9957.60:mandate for settlement up to \$9957.60 [COR- \$9250.15 LOR- \$130-140 x 5 DAYS]	[I] Syed-Yusoff, Saliha
17	03 Jul 2018 15:50	Adj Mandate Request	Cur.Req:10007.60:TP DISAGREED WITH OUR OFFER AND REQUEST TO SETTLE THE RENTAL IN FULL, PLS REFER TO THE EMAIL FROM TP. TQ	[A] Asher Sng Rong Yi

Date From Date To Audit Type None Go

ACTIVITY

[13/03/2018 09:59] Asher Sng Rong Yi:
FILE REVIEW: 100% B:27 OID REAR ENDED TP

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Brand)	Ref 1	Ref 2	Amount
1823922	05/06/2018 11:18	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJH881M	SLF4727L	10.70

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SJH 881M	Model:	
Date of Accident:	6-3-2018		

Global Sum Settlement	: ☐ Yes ☐ No	
Repair Estimate	: \$	23886.20
Final Repair Cost	: \$	9250.15
Loss of Use	: \$	
Rental (if any)	: \$	750.00
LTA / GIA Search Fee	: \$	7.45
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	

Is Third Party Workshop GIA Registered? ☐ YES ☐ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 9250.15
2)	Performance Motors Ltd	: \$ 7.45
3)	Tan Khien Boon	: \$ 750.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

Print Received Message

This mail is associated with :

***SJH881M (0326566868SG)**
[SLF4727L]

TP
TAN KHIEN BOON
Mar 6 2018 7:00AM
[DAIMLER FLEET MANAGEMENT]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 17/07/2018 14:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10007.60) - SJH881M - Claim Handler: Syed-Yusoff, Saliha

Approved:10007.60:approved settlement @ \$10,007.60 [LOR @ \$150/day]

From: Asher Sng (LKKAUTO)
Sent: Friday, 23 March 2018 11:32 AM
To: 'benny.chong@daimler.com'
Subject: ACCIDENT INVOLVING SLF 4727L AND SJH 881M ON 06/03/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18004335/R1ea3

23 MAR 2018

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 4727L AND SJH 881M ON 06/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Tan Khuen Boon (the third party claimant) of 60 Lakeside Drive #09-39 SL 648720 (address), owner of SJH881m (vehicle no.) hereby authorize Performance Motors Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SJH881m that was damaged pursuant to the accident which occurred on 06.03.18 (date) along Ganges Ave Towards Hawelock Rd Junction (location) involving vehicle no/s SLF 4727L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 14 (day) of 04 (month) 2018 (year)

1 PL
Signed by "the third party claimant"
(with chop if applicable)

CHUA KEE SIN
Performance Motors Limited
300 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

[Signature]
Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$9250.15 (Repair Cost), S\$750.00 (Loss of rental/~~use~~), S\$7.45 (Disbursement), for vehicle no. SH 881M that was damaged pursuant to the accident which occurred on 6.3.18 (date) along GANGES AVE TOWARDS HAWLOCK RD JUNCTION (location) involving vehicle no/s SLF 4727L. This is pursuant to the inspection conducted on 19.3.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tan Khien Boon ("the third party claimant") of vehicle no. SH 881M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SH 881M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 30 (day) of 01 (month) 20 18 (year)



MRB

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 155941
Tel. 63190100 (Sales & Admin)
63190115 (AfterSales)
Fax. 64747770

286, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

(A)

SERVICE TAX INVOICE

Repair Order No. : B1 1252033

Date IN : 19/03/2018

Cust. Svc. Advisor: Chua Kee Sin

Page No. : 1 of 2

Invoice Number : 1966764 / WSB

Invoice Date : 21/05/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Tan Khien Boon (Chen Jianwen)
60 Lakeside Drive
#09-39

Singapore 648320

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJH881M	G443858	27/10/2016	320IA GT	24729

- - - - LABOUR 1 - - - -

NETT

To replace rear bumper and attachments, rear boot lid and attachments including to remove and install body parts in order to carry out painting job.	2,550.00
To respray rear bumper and rear boot lid.	2,537.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00
To carry out body cavity preservation.	100.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 6.3.2018. 3RD PARTY CAR : SLF4727L.	
YOUR REF NO. : NIL.	
VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 19.3.2018 AT 11.45 AM. AUTHORISED REPAIR BY MS ASHER SNG FROM LKK ON 13.3.2018 VIA E-MAIL.	
PROPOSE CAR RENTAL = \$750.00. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
LTA SEARCH FEE = \$7.45.	0.00

Total Labour 1: **5,647.00**

- - - - PARTS - - - -

	Qty	Retail Price	NETT
BOOTLID	1	1,204.80	1,204.80
REAR BUMPER PANEL PRIMED (M/PDC)	1	1,121.60	1,121.60
GROMMET	2	0.75	1.50
SET MOUNTS PDC SENSOR REAR (M)	1	62.05	62.05
REAR PLAQUE	1	69.50	69.50
MODEL LETTERING 320I	1	62.55	62.55
MODEL LETTERING GT	1	62.55	62.55
TRUNK LID SEALING	1	40.25	40.25
TRIM PANEL BUMPER REAR BOTTOM (PDC)	1	294.65	294.65
SEAL REAR SPOILER LH	1	19.15	19.15
TRUNK LID SEALING	1	40.25	40.25

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0028081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

285, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1252033

Date IN : 19/03/2018

Cust. Svc. Advisor: Chua Kee Sin

Page No. : 2 of 2

Invoice Number : 1966764 / WSB

Invoice Date : 21/05/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

SEAL REAR SPOILER RH

1 19.15 19.15

Total Parts : 2,998.00

Labour Charges : 5,567.00
Parts Charges : 2,998.00
Lubricant/Misc : 80.00

Total Labour & Parts Charges : S\$ 8,645.00
Less Insurance Excess : S\$ 0.00
Invoice Total Amount Exclude GST : S\$ 8,645.00
GST @ 7% : S\$ 605.15
Invoice Total Amount Include GST : S\$ 9,250.15

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 9,250.15

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



CHANS & SONS ENTERPRISE

363 Sembawang Road, Goodlink Park,
Singapore 758379
Tel: 67532536 Fax: 67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

Hirer:

TAN KHIEH BOON

OFFICIAL RECEIPT

DESCRIPTION		AMOUNT (SGD)	
Official Receipt No	: 201804-0163		
Account of	: TAN KHIEH BOON		
Date Issued	: 14/04/2018		
Vehicle Reg No.	: SDU363U		
Rental Dates	: 09/04/2018		
Amount Received	: S\$ 750.00		
Payment Type:	: VISA	V127246	S\$ 750.00
Payment for Invoice	: AR1804-0295		
Comments	:		
TOTAL AMOUNT RECEIVED		S\$	750.00

* This is a computer generated document. No signature is required.

Member of
VRA & ARTAS



ARTAS

363 Sembawang Road Goodlink Park Singapore 758379 T 67532536 F 67567565 E sales@chans.com.sg

CHAN'S & SONS ENTERPRISE

363 Sembawang Road
Singapore 758379
Tel 67532536 Fax:67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

TAX INVOICE

TAN KHIEH BOON

NO. 60 #09-39
LAKESIDE DRIVE
SINGAPORE 648320

ATTN: TAN KHIEH BOON

INVOICE : AR1804-0295
DATE : 14/04/2018
TERMS : C.O.D
STAFF ID : AMIRA
AGREEMENT NO. : HA201804-0099

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

Vehicle Reg No : SDU363U 700.93
Make / Model : TOYOTA CAMRY 2.0 AUTO
Rental Dates : Rental Billing From 09/04/2018 To 14/04/2018
Period : 5 days
Rental Rate : S\$ 150.00 Per Day (Including GST)
Reference No : SJH188M

AMOUNT : S\$
SEVEN HUNDRED FIFTY DOLLARS ONLY

NON-TAXABLE VALUE : 0.00
TAXABLE VALUE : 700.93
GST 7% : 49.07

TOTAL S\$:	750.00
-------------	--------

Please make your cheques payable to : CHAN'S & SONS ENTERPRISE



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	

RENTAL AGREEMENT

201804-0099

Hirer's Name MR. TAN KHIEH BOON		Date of Birth S7620648A	Passport/ Nric No. 15-01-1976	Nationality
Address 60 LAKESIDE #09-39		Occupation	Driving Licence No.	Date of Expiry
Postal Code 648320		Contact No.	Mobile Phone No. 918236466	
Joint Hirer's / Guarantor's Name		Date of Birth	Passport/ Nric No.	Nationality
Address		Occupation	Driving Licence No.	Date of Expiry
Postal Code		Contact No.	Mobile Phone No.	

CHECK OUT

Date 09.04.2018	Time 1030	Mileage KM	E 1/4 1/2 3/4 F
Date 14.4.18	Time 11 am	Mileage KM	Remarks

CHECK IN

IMPORTANT NOTES:-

- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
- No refund will be given for vehicle that returns early.
- Own Damage Liability - First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability - First \$2000 for any Third Party Accident Claim.
- Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
- Hirer is responsible for all parking fines & traffic summons.
- Extension:- One day's advance notice is required otherwise no extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension is charged at 1/5 of the daily rate.
- As preventive maintenance, please check water & engine oil daily.
- Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
- For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
- Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

	UNIT	RATE (\$)	TOTAL (\$)
RATE	5 @	\$150	750
DISCOUNT			
GST @ 7%			
TOTAL			750
EXTENSION			1109246
201804-0163			
CHUA/PML			
SJH188M			
DEPOSIT (refundable) S\$			
CHANGED OVER FROM VEH.			DATE

I/We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.
I/We declare that all information given on this form is true and accurate.

Hirer's Signature 

Joint Hirer's/ Guarantor's Signature


for CHAN'S & SONS ENTERPRISE

VEHICLE NO. SDU 363U	MODEL Camry 2.0
FROM 09.04.2018	RETURN 14.04.2018

*Estimate Date. For actual return see CHECK IN

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 06 Mar 2018 / 15:21:44

Receipt Date/Time : 06 Mar 2018 / 15:21:44

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180306-001760

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLF4727L				
As at 06 Mar 2018/07:06:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLF4727L Enquiry Fee 20180306151922726520	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx5164	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

REPUBLIC OF SINGAPORE

DRIVING LICENCE

Licence Number: **S7620648A**

Name:

TAN KHIEEN BOON
(CHEN JIANWEN)

Birth Date: **15 Jul 1976**

Issue Date: **25 Jun 2003**

000595170H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
25 Jun 2003

1122244972

NF 428A



3967710



SPC No. S7620648A

56407

12-01-2007

60 LAKESIDE DR #00-39
CASPIAN SINGAPORE 848320
S7620648A

30/05/2013

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018 Edit Reg		19 Mar 2018 00:00 Edit Adj Rpt	S\$8,645.00 Edit Estimates	S\$8,645.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z		
Main Claimant:	TAN KHEN BOON, ID: S7620648A		
Vehicle Reg. No.:	SJH881M	Date of Loss:	06/03/2018 07:00 - :59 [16 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0326566868SG	Policy/Cover Note No.:	0999994742
Vehicle Reg. No. (Insured):	SLF4727L	Policy No. (Claimant):	P1924384
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (17/07/2018): Alert - Adj Mandate Approved (S\$10007.60) - SJH881M - Claim Handler: Syed-Yusoff,...
- AIG_SG_EXPRESS (11/06/2018): Alert - Adj Mandate Approved (S\$9957.60) - SJH881M - Claim Handler: Syed-Yusoff,...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJH881M (0326566868SG)

[SLF4727L]

TP

TAN KHIEH BOON

Mar 6 2018 7:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page ☐ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports			1 per page ☐ ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/03/18 09:30	Accident Statement From: SC - Reg. No: SLF4727L, Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.		Load HTM
Photos/Images			3 per page ☐ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/05/18 14:18	Odometer Reading		Load JPG ☒
2	17/05/18 14:18	Chassis Number		Load JPG ☒
3	17/05/18 14:18	General View		Load JPG ☒
4	17/05/18 14:18	General View		Load JPG ☒
5	17/05/18 14:18	General View		Load JPG ☒
6	17/05/18 14:18	General View		Load JPG ☒
7	17/05/18 14:18	General View		Load JPG ☒
8	17/05/18 14:18	General View		Load JPG ☒
9	17/05/18 14:18	General View		Load JPG ☒
10	17/05/18 14:18	General View		Load JPG ☒
11	17/05/18 14:18	General View		Load JPG ☒
12	17/05/18 14:18	General View		Load JPG ☒
13	17/05/18 14:18	General View		Load JPG ☒
14	17/05/18 14:18	General View		Load JPG ☒
15	17/05/18 14:18	General View		Load JPG ☒
16	17/05/18 14:18	General View		Load JPG ☒
17	17/05/18 14:18	General View		Load JPG ☒
18	17/05/18 14:18	General View		Load JPG ☒
19	17/05/18 14:18	General View		Load JPG ☒
20	17/05/18 14:18	General View		Load JPG ☒
21	17/05/18 14:18	General View		Load JPG ☒
22	17/05/18 14:18	General View		Load JPG ☒
23	17/05/18 14:18	General View		Load JPG ☒
24	17/05/18 14:18	General View		Load JPG ☒
25	17/05/18 14:18	General View		Load JPG ☒
26	17/05/18 14:18	General View		Load JPG ☒
27	17/05/18 14:18	General View		Load JPG ☒
28	17/05/18 14:18	General View		Load JPG ☒
29	17/05/18 14:18	General View		Load JPG ☒
30	17/05/18 14:18	General View		Load JPG ☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	17/05/18 14:18	General View	 Load JPG	☒
32	17/05/18 14:18	General View	 Load JPG	☒
33	17/05/18 14:18	General View	 Load JPG	☒
34	17/05/18 14:18	General View	 Load JPG	☒
35	17/05/18 14:18	General View	 Load JPG	☒
36	17/05/18 14:18	General View	 Load JPG	☒
37	17/05/18 14:18	General View	 Load JPG	☒
38	17/05/18 14:18	General View	 Load JPG	☒
39	17/05/18 14:18	General View	 Load JPG	☒
40	17/05/18 14:18	General View	 Load JPG	☒
41	17/05/18 14:18	General View	 Load JPG	☒
42	17/05/18 14:18	General View	 Load JPG	☒
43	17/05/18 14:18	General View	 Load JPG	☒
44	17/05/18 14:18	General View	 Load JPG	☒
45	17/05/18 14:18	General View	 Load JPG	☒
46	17/05/18 14:18	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/18 18:38	TP GIA REPORT	 Load PDF	
2	06/03/18 18:38	TP ESTIMATE	 Load TIF	
3	21/03/18 11:50	TP ESTIMATE - MARKED	 Load PDF	
4	23/03/18 11:44	LETTER TO OI	 Load PDF	
5	05/06/18 11:31	RENTAL RECEIPT	 Load PDF	
6	05/06/18 11:31	LTA SEARCH	 Load PDF	
7	03/07/18 15:49	EMAIL FROM WSP DD 030718	 Load PDF	
8	07/08/18 10:36	WORKSHOP INVOICE	 Load PDF	
9	07/08/18 10:36	AUTHORISATION TO ACT FORM	 Load PDF	
10	07/08/18 10:36	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF4727L (Insd veh)	Model:	BMW 320I 2.0 (A)
	SJH881M (TP veh)		
Date of Accident:	06/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	23,927.18
Final Repair Cost	:	\$	9,250.15
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	750.00 5 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,007.60

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 9,257.60
2)	Tan Khien Boon (Chen Jianwen)	:	\$ 750.00
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

07 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18004335/R1EA3Q2

Date: 07/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 09999994742
Claimant Vehicle No : SJH881M **Insured Vehicle No :** SLF4727L
 Date of Loss: 06/03/2018 Nature of Claim: TP Claim No: 0326566868SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH881M**
 Make & Model: BMW 320i, 2.0 (A) Engine No: F2021513B48B20A
 Reg. Date: 27/10/2016 (Man. Year: 2016) Chassis No: WBA8X32050G443858
 Colour: White Odometer: 23229 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R19 Rear Tyre Size: 225/45 R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,671.85	3,078.00	9,593.85	75.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,690.00	5,567.00	4,123.00	42.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,361.85	8,645.00	13,716.85	61.34
+ GST 7.00/7.00% (S\$)	1,565.33	605.15	960.18	61.34
Nett Amount (S\$)	23,927.18	9,250.15	14,677.03	61.34
+ Car Rental (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,007.60		

INSPECTION

Date of Assignment: 19/03/2018
 Date Inspected: 19/03/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	4		*VELCRO	Not Necessary	37.00 FS	*- FS
3	2		*TAILPIPE TRIM CHROME	Not Necessary	237.30 FS	*- FS
4	1		*REAR MUFFLER	Not Necessary	1,017.40 FS	*- FS
5	1		*BOOTLID	Bent	1,204.80 FS	*1,204.80 FS
6	1		*LH TRUNK LID HINGE	Not Necessary	125.00 FS	*- FS
7	1		*RH TRUNK LID HINGE	Not Necessary	125.00 FS	*- FS
8	1		*GUIDE CENTRE REAR	Not Necessary	34.90 FS	*- FS
9	1		*RR BUMPER CARRIER	Not Necessary	432.90 FS	*- FS
10	1		*LEFT RPROTECT FOIL	Not Necessary	11.00 FS	*- FS
11	1		*RIGHT PROTECT FOIL	Not Necessary	11.00 FS	*- FS
12	1		*REINFORCEMENT BUMPER REAR BOTTOM (M)	Not Necessary	80.25 FS	*- FS
13	1		*REINFORCEMENT BUMPER REAR BOTTOM (M)	Not Necessary	80.25 FS	*- FS
14	1		*TRIM PANEL BUMPER REAR BOTTOM (PDC)	Deformed	294.65 FS	*294.65 FS
15	1		*REAR BUMPER PANEL PRIMED (M/PDC)	Deformed	1,178.40 FS	*1,121.60 FS
16	1		*SET MOUNT PDC SENSOR REAR (M)	Necessary	62.95 FS	*62.05 FS
17	1		*REAR PLAQUE	Necessary	69.50 FS	*69.50 FS
18	1		*MODEL LETTERING 320I	Necessary	62.55 FS	*62.55 FS
19	1		*MODEL LETTERING GT	Necessary	62.55 FS	*62.55 FS
20	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
21	1		*TRUNK LID POWER LOCK DRIVE	Not Necessary	526.05 FS	*- FS
22	1		*SPINDLE DRIVE LH	Not Necessary	318.70 FS	*- FS
23	1		*SPINDLE DRIVE RH	Not Necessary	318.70 FS	*- FS
24	1		*LOCK TRUNK LID	Not Necessary	211.85 FS	*- FS
25	1		*BOOTLID /TAILGATE PUSH BUTTON	Not Necessary	47.20 FS	*- FS
26	10		*BUMP STOP	Not Necessary	32.50 FS	*- FS
27	1		*REAR WINDOW	Not Necessary	749.55 FS	*- FS
28	4		*VELCRO	Not Necessary	4.40 FS	*- FS
29	6		*HOOK AND LOOP FASTENER	Not Necessary	16.80 FS	*- FS
30	1		*TRIM COVER ,LEFT	Not Necessary	106.15 FS	*- FS
31	1		*TRIM COVER ,RIGHT	Not Necessary	106.15 FS	*- FS
32	1		*COVER FOR LOCK LOADING PANEL	Not Necessary	9.75 FS	*- FS
33	1		*SPOILER MODULE	Not Necessary	1,249.70 FS	*- FS
34	1		*SPOILER BLADE	Not Necessary	443.70 FS	*- FS
35	1		*FINISHER ROOF GAP REAR	Not Necessary	81.85 FS	*- FS
36	1		*FINISHER ROOF GAP REAR	Not Necessary	81.85 FS	*- FS
37	1		*TRUNK LID SEALING (2PCS)	Necessary	80.50 FS	*40.25 FS
38	1		*TRUNK LID SEALING (2PCS)	Necessary	80.50 FS	*40.25 FS
39	1		*TRUNK LID GASKET	Not Necessary	118.15 FS	*- FS
40	2		*GUTTER STRIP	Not Necessary	133.70 FS	*- FS
41	1		*R.REFLECTOR	Not Necessary	35.20 FS	*- FS
42	1		*REAR LIGHT I	Not Necessary	497.60 FS	*- FS
43	1		*REAR LIGHT I	Not Necessary	293.90 FS	*- FS
44	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
45	4		*PDC SENSOR ALPINWEISS (300)	Not Necessary	1,475.20 FS	*- FS
46	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
47	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
49	1		*SEAL REAR SPOILER LH	Necessary	19.15 FS	*19.15 FS
50	1		*SEAL REAR SPOILER RH	Necessary	19.15 FS	*19.15 FS
Total Parts (S\$)					12,671.85	3,078.00

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BOOT LID ,REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	4,250.00	2,550.00
2	SPRAY PAINTING REAR BUMPER,BOOT LID AND TAIL PANEL	New	2,819.00	2,537.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	0.00
4	TO SUPPLY AND INSTALL OF REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
5	TO REPLACE EXHAUST MANIFOLD AND GASKET INCLUDING CHECKS FOR LEAK	New	950.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
7	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			9,690.00	5,567.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >