

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

EQ/LKK.
 DATE 5-3-18

Fz
 Fauzy

VEHICLE NO : SHA 904S
 MAKE :
 MODEL : HYUNDAI SONATA RIGHT FRONT

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Sponge X			\$ 136.30
	Front Bumper Reinforcement X			\$ 504.10
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) xpr			\$ 29.20
	Front Bumper Bracket (RH) ✓			\$ 20.10
	Front Bumper Side Bracket ?			\$ 14.30
	Headlamp (RH) ✓			\$ 797.90
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) ?			\$ 86.00
	Front Fender Retainer X			\$ 9.20
	Radiator Grille ✓			
	Radiator Grille U' Moulding ✓			
	SUB TOTAL		\$ 282.10 \$ 108.90	\$ 2,751.30
	LESS 20%			\$ 550.26
	DISCOUNTED TOTAL			\$ 2,201.04
	Front Number Plate X			\$ 25.00
	Front No Plate Trim Cover X			\$ 30.00
	Front RH Fender Advertisement ✓	\$ 100		\$ 55.00
	Labour Charge			
	Panel Beating			\$ 400
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 1,000.00
	Tuff Kote			\$ 50.00
				\$ 50.00
	TOTAL LABOUR			\$ 2,100.00
	ESTIMATE TOTAL			\$ 4,356.04

Kalme / LKK
 11 5/3/18 14604-
 3 Bpr
 4/5
 After Repair pld

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party services on a "With" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: <u>3/3/18</u> Time Received:		3. Vehicle Type:	
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>MR LEE</u> Contact No. : <u>SHA 9048</u> Vehicle No. : <u>91551386</u> Make / Model / Colour : <u>Sonata</u> Email :		☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	
		4. Type of Towing:	
		☒ Normal Tow ☒ King Dolly ☐ Flat Bed ☐ Crane-up	
		5. Nature of Service:	
		☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery	
7. Location: <u>JLN Bukit Ho Swee</u>		6. Parts Replaced/Remarks:	
9. Preferred Workshop:		8. Vehicle Tow - In Workshop:	
☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:		☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
10. Odometer Reading : _____		11. Radio / CD Player	
Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E		☐ OK ☐ Faulty ☐ Not tested	
Job Attended			
12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ TZ ☐ YISHUN ☐ OTHERS		 # : Cracked X : Dented / : Scatched O : Missing Signature of Customer	
Name of Driver : <u>Edie</u>			
Vehicle No. : <u>YN6230T</u>			
Time Dispatch : <u>2000</u>			
Time of Arrival : <u>2025</u>			
Time Completed :			
Cash In Details (if applicable)			
13. Cash Invoice No. :			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupon, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
<u>3/3/18</u> Date		<u>2025</u> Time	
Signature of Customer			
14. WORKSHOP			
Name of Attending Staff/Guard		Date & Time of Arrival	
		Signature of Attending Staff/Guard	