


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5935P  
 Ref. No : TAX/03/18/2012  
 Reg. Date : 06/06/2013  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : LEE ENG CHUAN  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 02/03/2018 03:05:00 PM  
 Accident Reported Date / Time : 02/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094853  
 Special Instruction to ARC,if any :  
 SKV5637J  
 Prepared Date : 02/03/2018 04:23:46 PM



Sebastian  
 5/3/18.  
 - Lump Sum Repair.  
 - Question Mark Item Photo  
 - Photo After Paint.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB136630

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,494.00	0.00
Total Material Charges :	6,854.89	7,911.13
Other Charges :	960.00	0.00
<b>TOTAL</b> :	<b>10,322.89</b>	<b>0.00</b>
<b>Lum Sum Total</b> :	<b>10,300.00</b>	<b>0.00</b>
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sing Off Date :	03/03/2018 09:10:02 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/03/2018 09:08:52 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	<del>0.00</del> 500
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY REAR BOOT LID	378.00	<del>0.00</del> 200
TO RESPRAY REAR PANEL	180.00 ?	0.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00 ?	0.00
TO RESPRAY REAR FENDER RH	378.00	<del>0.00</del> 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,494.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 ?	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	<del>0.00</del> 50
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	<del>0.00</del> 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	<del>0.00</del> 50
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	<del>0.00</del> 30
TO REPLACE SUNDRY PARTS	100.00	<del>0.00</del> 20
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>960.00</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace / 01	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ?	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ?	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace ?	No
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace x	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace / 0mg	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ?	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ?	No
96647117	COMMON		W/HARNES RR BPR	1	227.34	10.00	204.61	Replace	Replace x	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace / 01	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace x	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace x	No ✓ SCR
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace x	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace x	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace x	No
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace ✓ SCR	No
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace ✓ LRC	No
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Replace x	No
	COMMON		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace x	No
	COMMON		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace x	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓ NRC	No
96634035	REAR	6504564	LETTERING:"CHEVROLET"	1	29.00	10.00	26.10	Replace	Replace ✓ NRC	No
96634897	REAR	6504565	LETTERING:"EPICALT"	1	28.00	10.00	25.20	Replace	Replace ✓ NRC	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NRC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NRC	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ?	No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ?	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ?	No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace ?	No
	COMMON		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Replace x	No
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace x	No
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace x	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace ?	No
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace ?	No
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Repair	Replace X	No
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace X	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓	No NEC
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓	No NEC
<b>TOTAL MATERIALS</b>								<b>8,568.61</b>	<b>9,888.91</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>6,854.89</b>	<b>7,911.13</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									