

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cynthia Loh

Date: 09 Mar 2018

Preliminary Advice

Insured Vehicle No	: SHD9722A		
TP Vehicle No	: GBC6856T	Accident Date	: 26/02/2018
Make	: TOYOTA DYNA 150	Assignment Date	: 05/03/2018
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 5 days
Inspection At	: Ban Choon Motor Works (HQ) Blk 3 Pioneer Road North #01-15 Singapore 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,795.30
Revised Amount	:S\$	3,390.11
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,390.11

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.