



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

EST/QUOTE NO. SQ000118

AXA Insurance Singapore Pte Ltd

8 Shenton Way

B1-01 AXA Tower

Singapore 068811

ATTENTION :

CONTACT : -

FAX NO:

DATE : 05/03/2018
ACCIDENT DATE : 26/02/2018
VEHICLE NO : GBC 6856 T
CHASSIS/ENG.NO : 67766633
VEHICLE MODEL : TOYOTA DYNA
CLAIM NO : TP
POLICY NO : -
REMARK : TP - SHD 9722 A

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** LIST PRICE **							
1	1		Taillamps	240.20	25	180.15 <i>RH-30A</i>	360.30 <i>LH</i>

SUB-TOTAL: 360.30

** SPECIAL NETT PRICE **							
1	2		Tail boards	1,200.00	<i>price?</i>	1,200.00 <i>PH</i>	2,400.00
2	1		70 km/h sticker	20.00		20.00 <i>PH</i>	20.00
3	1		Rear number plate	35.00		35.00 <i>PH</i>	35.00
SUB-TOTAL							2,455.00

** WORK LABOUR **

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

0.00		0.00
480.00	400	480.00
500.00	400	500.00
SUB-TOTAL		980.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

PAGE: 1 of 1

SUB-TOTAL : S\$ 3,795.30

ON BEHALF OF BAN CHOON MOTOR WORKSHOP

E & O E

ALL PRICES SUBJECT TO 7% GST