

ASS. REC. BY:

REF:

CS/SMO180064353/Svd3n2

Special Instruction:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 6/3/18 @ 2.20pm

Estimated Cost:

Bill to:

OD (TP) WS TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SHB 1885B

Insured:

FX 8225 T

at Workshop m/s

SMRT

Tel: 6866 2672

of

60 woodlands Rd Ind. Prk E4

Policy No:

Claim No:

CMTD1801002/AGG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4/3/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time: 2.20pm @ 6/3/18

Person Contacted:

shank

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 1885B - CS/EGI17008116/Klgh3e2

D.O.A: 22/4/17

FX 8225 T - X

7/3/18

Email preli revised to Grace Teo

13/3/18

Sebastian confirmed LS \$1100 Cred 4233.60 79%

REF:

Signature

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time | Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 14/3 - typist

Report Format:

Lump Sum / I.B.I. (\$

TP

1100h

Veh No:

545 1885B

Yr Regn:

3/10/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c. 1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

302/77

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364705757089

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Faller

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

4/3/18

D.O.I.

6/3/18

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 14/11/2018

TAX 10/3/18/2010

LKR

Sampo

FX 8257

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Planks

Others

TOTAL

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

250

# Survey Department Check List (Case Handler)

Reference No.: CS | SMO | 800 4353 | Srd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON | 14/3/18  
Case Handler | Date

\*C: Critical \*N: Non-Critical

21/05/2014



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004353/Svd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 07-03-2018



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FX 8225T	Veh. Inspected	SHB 1885B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801002/AGG	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	07/03/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	04/03/2018	Inspection Date	06/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1801002/AGG

Our ref: CS/SMO18004353/Svd3

DATE :7/3/2018

The Motor Claims Department  
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SHB 1885B**


We thank you for your instruction on 6/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 6/3/2018 at the premises of M/s SMRT AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,333.60
Revised Estimate Amount	: S\$1,214.84
"Check" Items Amount	: S\$1,770.38
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion.



Comments/Present Status:  
Damages Consistent

Yours faithfully,

**SEBASTIAN YEANG**  
Automotive Assessor

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 7 March 2018 4:17 PM  
**To:** 'Teo, Grace'  
**Cc:** 'Ngo, Sau Wei Shawn'; 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD1801002/AGC - ACCIDENT INVLG FX8225T & SHB1885B ON 04.03.18  
**Attachments:** SHB 1885B PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SHB 1885B  
Date of survey: 6/3/2017  
Number of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 6 March 2018 2:22 PM  
**To:** 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: CMTD1801002/AGC - ACCIDENT INVLG FX8225T & SHB1885B ON 04.03.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Tuesday, 6 March 2018 2:20 PM  
**To:** Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <[BThaiyalN@smrt.com.sg](mailto:BThaiyalN@smrt.com.sg)>; [assignments@lkkauto.com](mailto:assignments@lkkauto.com); [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)  
**Cc:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[YeoPohsuan@smrt.com.sg](mailto:YeoPohsuan@smrt.com.sg)>; Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <[TuckFoo@smrt.com.sg](mailto:TuckFoo@smrt.com.sg)>; Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <[YewChung@smrt.com.sg](mailto:YewChung@smrt.com.sg)>; Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <[ZhiYang.Phua@smrt.com.sg](mailto:ZhiYang.Phua@smrt.com.sg)>; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <[ngsiuching@smrt.com.sg](mailto:ngsiuching@smrt.com.sg)>; Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <[limkhachiew@smrtlan.com.sg](mailto:limkhachiew@smrtlan.com.sg)>; Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <[weisiong@smrt.com.sg](mailto:weisiong@smrt.com.sg)>; Ngo, Sau Wei Shawn <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** CMTD1801002/AGC - ACCIDENT INVLG FX8225T & SHB1885B ON 04.03.18



Our Claim Reference: CMTD1801002/AGC

Your Reference: SHB1885B

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK,

Please make arrangement to conduct the survey for SHB1885B.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [<mailto:BThaiyalN@smrt.com.sg>]

**Sent:** Tuesday, March 06, 2018 9:07 AM

**To:** 'motorsurvey@sompo.com.sg'

**Cc:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

**Subject:** RE: SHB1885B - Survey (Sompo Insurance)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB1885B** within 48 hours according to GIA guide line, involving your insured **FX8225T**

Vehicle in Woodlands Depot

Regards  
Shanti

SMRT Automotive Services PTE LTD  
Accident Reporting Center (Claims Dept)  
6866 2671/2 | [bthaiyaln@smrt.com.sg](mailto:bthaiyaln@smrt.com.sg)





**Nivitha (LKK Auto)**

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Tuesday, 6 March 2018 2:20 PM  
**To:** Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Ngo, Sau Wei Shawn; Henry, Irene James  
**Subject:** CMTD1801002/AGC - ACCIDENT INVLG FX8225T & SHB1885B ON 04.03.18  
**Attachments:** SHB1885B.PDF; 2020 - 1885.pdf

Our Claim Reference: CMTD1801002/AGC  
Your Reference: SHB1885B

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that Agnes Chan is the handler of this case.

We have appointed LKK AUTO to conduct the survey.

Aside to LKK,

Please make arrangement to conduct the survey for SHB1885B.

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [mailto:BThaiyalN@smrt.com.sg]

**Sent:** Tuesday, March 06, 2018 9:07 AM

**To:** 'motorsurvey@sompo.com.sg'

**Cc:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

**Subject:** RE: SHB1885B - Survey (Sompo Insurance)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB1885B** within 48 hours according to GIA guide line, involving your insured **FX8225T**

Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | [bthaiyaln@smrt.com.sg](mailto:bthaiyaln@smrt.com.sg)



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1885B
Vehicle to be Exported:	No
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1444088
Chassis No.:	JTDKN36U705752089
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	03 Oct 2014
First Registration Date:	03 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Oct 2022

PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	02 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$29,093.00
<b>Total Rebate Amount:</b>	<b>\$35,159.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Mar 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/03/2018 10:48
Date Of Accident	04/03/2018 22:20
Exact Location Of Accident	PIE TOWARDS JURONG (BEFORE STEVEN RD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1885B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	CHEE JOO POH
NRIC No	S1483611Z
Date Of Birth	06/04/1961
Occupation	OUTDOOR
Date Of Driving Pass	25/05/1982
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 11-77  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : UNKNOWN  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING ALONG PIE TOWARDS JURONG (BEFORE STEVEN RD) WITH ONE PASSENGER (MALE INDIAN) ON BOARD. A VEHICLE IN FRONT OF MY TAXI JAMMED BRAKE. I APPLIED MY BRAKE TO STOP AND MANAGED TO STOP IN TIME. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI. A MOTORCYCLE FX8225T HAD COLLIDED ONTO THE REAR OF MY TAXI. POLICE AND AMBULANCE WERE AT THE SCENE BUT NO ONE WAS CONVEYED TO HOSPITAL

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE TOO BIG  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FX8225T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category MOTORCYCLE  
 Name of Driver MOHAMMAD SHAFEE MUSTAKIM BIN MAHAD  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



A hand-drawn map on lined paper showing a road layout. At the top, a horizontal line represents a road, with several diagonal lines branching off it. To the right of this road is the label "Jalan Road." with an arrow pointing to it. Below this road, there are two more horizontal lines. Between these two lines, there are two arrows pointing to the right. Below the second horizontal line, there is a small rectangular area containing the text "Fx 825 T" and "A" with a small circle around it. To the right of this area, there is a larger rectangular area containing the text "1005" and "1006" with a small circle around it. To the right of these areas, there is a label "Found Jiong." with an arrow pointing to it. Below this label, there is another arrow pointing to the right. At the bottom, there is a horizontal line with several diagonal lines branching off it, similar to the top of the map.

5/3/18  
C. Ph

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.

15 JUL 1964

*[Signature]* 05/3/18

5/3/2018

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SMRT Accident Vehicle Repair Estimates

Sampo 618

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1885B  
 Ref. No : TAX/03/18/2020  
 Reg. Date : 03/10/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : CHEE JOO POH  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 04/03/2018 10:20:00 PM  
 Accident Reported Date / Time : 05/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094869  
 Special Instruction to ARC, if any :  
 TOWED \$40 /FX8225T  
 Prepared Date : 05/03/2018 11:51:32 AM



Sebastian  
 6/3/18

- Lump Sum Repair  
 - Question Mark Item  
 Photo  
 - Photo After Paint

*[Signature]*  
 6/3/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U705752089

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 738.00	0.00
Total Material Charges	: 2,070.46	2,112.72
Other Charges	: 560.00	0.00
<b>TOTAL</b>	<b>: 4,044.46</b> <i>5333.60</i>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 4,050.00</b>	<b>0.00</b>
No. of Repair Days	: 5.00	<del>0.00</del>
Prepared / Adjusted By	:	<i>3 days.</i>
Arc / Surveyor Sign Off Date	: 06/03/2018 08:48:39 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/03/2018 08:47:41 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/6/2018 8:47:55 AM

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	676.00	0.00 <del>300</del>
<b>Total Labour</b>	<b>676.00</b>	<b>0.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 <del>200</del>
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY REAR PANEL	180.00	0.00 ?
<b>Total Spray Painting &amp; Panel Beating</b>	<b>738.00</b>	<b>0.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 <del>60</del>
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 <del>50</del>
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 <del>30</del>
TO REPLACE SUNDRY PARTS	100.00	0.00 <del>20</del>
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>560.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>K</i>	No
52161-16010			BUMPER CLIPS	10	1.61 <i>16.10</i>	25.00	12.07	Replace	Replace <i>✓ NEX</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>?</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>✓ DMG</i>	No
			PIXEL STICKER	2	60.00 <i>120</i>	0.00	120.00	Replace	Replace <i>✓ NEX</i>	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>✓ Defect</i>	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace <i>X</i>	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace <i>X</i>	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace <i>?</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>?</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>✓ CRK</i>	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace <i>?</i>	No
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace <i>X</i>	No
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace <i>X</i>	No
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace <i>X</i>	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace <i>?</i>	No
58336-12090			REINFORCEMENT, RR	2	34.60 <i>69.20</i>	25.00	51.90	Replace	Replace <i>?</i>	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>?</i>	No
<b>TOTAL MATERIALS</b>				<i>3359.60</i>			<b>2,603.95</b>	<b>2,603.90</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>2,070.46</b>	<b>2,112.72</b>		


**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

# SMRT Accident Vehicle Repair Estimates

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1885B  
 Ref. No : TAX/03/18/2020  
 Reg. Date : 03/10/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : CHEE JOO POH  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 04/03/2018 10:20:00 PM  
 Accident Reported Date / Time : 05/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sebastian  
 Vehicle is Towed Back? : No Yes  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094869  
 Special Instruction to ARC, if any :  
 TOWED \$40 / FX8225T - SOMPO INSURANCE  
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121  
 LUMP SUM REPAIR  
 Prepared Date : 05/03/2018 11:51:32 AM



16:50 8-3-18 pass  
 Recording Camera ☐ ☒  
 Radio Antenna ☐ ☒  
 1st witness ☐ Date 6-3-18  
 2nd witness ☐ Date 8-3-18

302260  
 30499  
 1/4 1/2 3/4 1

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 8/3/18

Vehicle Return Time: 14:25

SMRT staff sign:



Chassis No : JTDKN36U705752089

Mileage


0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	300.00
Total Spray Painting Charges	: 738.00	200.00
Total Material Charges	: 1,572.19	443.87
Other Charges	: 560.00	160.00
<b>TOTAL</b>	<b>: 3,546.19</b>	<b>1,103.87</b>
	5333.60	
<b>Lum Sum Total</b>	<b>: 3,550.00</b>	<b>1,100.00</b>
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 06/03/2018 08:48:39 AM	06/03/2018 03:41:18 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/03/2018 08:47:41 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1803-0200

Invoice No :

Quotation Date : 10/3

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/6/2018 8:47:55 AM

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION ✓	676.00	300.00 /
<b>Total Labour</b>	<b>676.00</b>	<b>300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER ✓	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>738.00</b>	<b>200.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	60.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>560.00</b>	<b>160.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	21	458.60	100.00	0.00	Replace	Repair	No R
52161-16010			BUMPER CLIPS	10	1.61 16.10	25.00	12.07	Replace	Replace	No ✓ NEC
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Check	No X
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No X
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No X
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓ DMG
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ✓ NEC
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ✓ Defect
76088-47020		6505617	BUMPER LIP COVER RR/LH	0	72.20	25.00	0.00	Replace	Not given	No X
76087-47020		6505618	BUMPER LIP COVER RR/RH	0	118.10	25.00	0.00	Replace	Not given	No X
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No X
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No X
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ✓ CR
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No X
52563-47010			TAIL LAMP BRACKET, LH	0	30.70	25.00	0.00	Replace	Not given	No X
52562-47010			TAIL LAMP BRACKET, RH	0	30.70	25.00	0.00	Replace	Not given	No X
65637-47021		6505480	FENDER LINER RR/RH	0	141.30	25.00	0.00	Replace	Not given	No X
58307-47060		6505522	END PANEL	1	602.10	25.00	451.58	Replace	Check	No X
58336-12090			REINFORCEMENT, RR	2	34.60 69.20	25.00	51.90	Replace	Check	No X
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
TOTAL MATERIALS				3359.60			1,965.25	554.84		
TOTAL MATERIALS(Discounted)							1,572.19	443.87		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

554.84 /  
- 20%

45 \$1100/-

443.87 /  
+ 300.00 /  
+ 360.00 /

Sebastian  
13/3/18

1103.87 /



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004353/Svd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 15-03-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FX 8225T	Veh. Inspected	SHB 1885B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801002/AGG	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U705752089	Colour	MAROON
Odometer	302199	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	04/03/2018	Inspection Date	06/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1885B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	CRACKED	94.80	71.10
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY,RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY,RR BUMPER RH	NOT NECESSARY	139.60	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SEAL,RR RH	NOT NECESSARY	65.70	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	UNDER COVER SUB-ASSY,RR FLOOR	NOT NECESSARY	514.50	-
1	TAIL LAMP BRACKET,LH	NOT NECESSARY	30.70	-
1	TAIL LAMP BRACKET,RH	NOT NECESSARY	30.70	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	END PANEL	NOT NECESSARY	602.10	-
2	REINFORCEMENT,RR @\$34.60	NOT NECESSARY	69.20	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			<b>3,359.60</b>	<b>554.84</b>
<b>LABOUR</b>				
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF BUMPER REAR.		676.00	300.00
	SPRAY PAINT.		738.00	200.00
	TOWING CHARGE.		80.00	60.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	50.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			<b>1,974.00</b>	<b>660.00</b>

Report Ref No. CS/SMO18004353/Svd3n2



GRAND TOTAL		5,333.60	1,214.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00

Report Ref No. CS/SMO18004353/Svd3n2

YEANG WAI KEEN  
Automotive Assessor

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.