

REF:

CC3/MSG18004356 / Stb 96

Surrey

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJZ 1286E

Policy No. A90300112AMY

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time | Action / Instruction

7/3/18 Sent EST and GA to Catherine

Confirm L/s \$1750, 3 days
Red: \$3756.80, 68%

RECEIVED 05 APR 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

typist

☒

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / E.B.I. (\$) 7P 1750

Veh No:

SUC 4284K

Yr Regn:

22/11/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

cc 1798

Colour

Maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

412313

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN364X05705428

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/45R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pallan

Front

Rear

F/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/3/18

D.O.I.

6/3/18

Survey held at

SPART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt R/L

The U/C / Chassis frame / Body Structure affected due to collision.

7/3/18 18/2018

LKE

MSIG

SJZ 1286E

Date/Time, File Pass to?

☐

Prel. Report

1)

typist

☒

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / E.B.I. (\$) 7P 1750

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

\$ + RS 30

☐

Interview (\$

Phone

☐

Tech. Insp (\$

Expans

☐

Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/MSG18004356/Srb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 07-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJZ 1286E	Veh. Inspected	SHC 4284K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/03/2018	Inspection Date	06/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, March 07, 2018 6:00 PM
To: Catherine Thia; 'Lee Chee Hwee'
Cc: KKLau; 'Christopher Chionh'; Accounts (LKKAUTO); SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD, DOA: 06/03/2018, SHC 4284K (TP VEHICLE), SJZ 1286E (OI VEHICLE)
Attachments: SHC 4284K GIA AND EST.pdf

Dear Catherine/Dan,

Please be informed that we had inspected the vehicle SHC 4284K at M/s: SMRT AUTOMOTIVE SERVICES PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 on 06/03/2018.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4284K
Vehicle to be Exported:	No
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5906183
Chassis No.:	JTDKN36UX05705428
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	22 Nov 2013
First Registration Date:	22 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2021

PARF Rebate Amount: \$6,276.00

Intended COE Rebate Details

COE Expiry Date: 21 Nov 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid: \$63,297.00

COE Rebate Amount: \$29,318.00

Total Rebate Amount: \$35,594.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 17:41
Date Of Accident	03/03/2018 12:45
Exact Location Of Accident	STILL ROAD SOUTH TOWARDS ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4284K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	NEO YEW SING
NRIC No	S1715075H
Date Of Birth	02/12/1965
Occupation	OUTDOOR
Date Of Driving Pass	22/04/1983
Driving Experience	34 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	23
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG STILL ROAD SOUTH TOWARDS ECP IN THE CENTRE LANE WITH ONE PASSENGER (FEMALE CHINESE ON BORD). SUDDENLY A VEHICLE SJZ1286E CUT TOWARDS MY LANE ABRUPTLY FROM THE LEFT AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ1286E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN YEW LEE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me; -
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

msk G117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4284K
 Ref. No : TAX/03/18/2021
 Reg. Date : 22/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : NEO YEW SING
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 03/03/2018 12:43:00 PM
 Accident Reported Date / Time : 05/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094870
 Special Instruction to ARC, if any :
 TSS / TOWED \$ 40
 Prepared Date : 05/03/2018 11:54:33 AM



Sebastian
 4/3/18
 - Lamp Sun Repair
 - Question Mark Iron
 Photo
 - Photo After Paint

[Signature]
 8/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX0-5705428

Mileage

:

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 936.00	400.00
Total Material Charges	: 1,217.04	805.76
Other Charges	: 540.00	160.00
TOTAL	: 3,538.04 - 5506.50	1,765.76
Lum Sum Total	: 3,550.00	1,750.00
No. of Repair Days	: 5.00	3.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 06/03/2018 09:08:12 AM	06/03/2018 03:50:10 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/03/2018 09:07:39 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0194

Quotation Date : 10/3

Invoice Amount : 0.00

Invoice No :

Invoice Date :

Prepared Date : 3/6/2018 9:09:33 AM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	845.00	400.00 /
Total Labour	845.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00 /
RESPRAY WHEEL CAP	180.00	0.00
Total Spray Painting & Panel Beating	936.00	400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	80.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	540.00	160.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	100.00	0.00	Replace	Repair	No <i>R</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	30.00	53.48	Replace	Check	No <i>X</i>
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Check	No <i>X</i>
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No <i>/</i>
53802-47050		6505558	FENDER FRT/LH	1	723.40	100.00	0.00	Replace	Repair	No <i>R</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	30.00	36.33	Replace	Replace	No <i>/</i>
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	30.00	120.19	Replace	Replace	No <i>/</i>
53852-47020			FENDER LINER PAD, FR WHEEL. LH	0	49.30	30.00	0.00	Replace	Not given	No <i>X</i>
42602-47060		6505676	CAP SUB-ASSY, WHEEL	0	174.10	30.00	0.00	Replace	Not given	No <i>X</i>
TOTAL MATERIALS							1,521.30	1,007.20		
TOTAL MATERIALS(Discounted)							1,217.04	805.76		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1007.20 /
 - 202
 805.76 /
 + 400.00 /
 + 560.00 /

 1765.76 /
 45 \$1750/- /

Sebastian
 13/3/18.

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4284K

Ref. No : TAX/03/18/2021

Reg. Date : 22/11/2013

Vehicle Type : TAXI

Make : TOYOTA PRIUS

Model : PRIUS

Name of Driver : NEO YEW SING

Type of Accident : SIDE SWIPE

Date / Time of Accident : 03/03/2018 12:43:00 PM

Accident Reported Date / Time : 05/03/2018 12:00:00 AM

Surveyor is Required? : Yes

Survey by : Sebastian

Vehicle is Towed Back? : No Yes

Towed Back Date/Time :

Replacement Vehicle issued? : No

Accident Repair Job Card No : 000024094870

Special Instruction to ARC, if any :

TSS / TOWED \$ 40 INSLA LIS

BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121

LUMPSUM REPAIR

Prepared Date : 05/03/2018 11:54:33 AM



Recording Camera

☐
☒

Radio Antenna

☐
☒

1st witness

Date

6-3-18

2nd witness

Date

Vehicle to Wega Date In: 07/3

Towing:

Time In: 12:00

Driver:

TAT.

Wega Job No: 03/0177

Vehicle sent to SMRT Date In: 9-3-2018

Towing:

Time In: 1:20

Driver:

Received by (SMRT):

QC 9/5/18 14:58 pass

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX0-5705428

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 2,086.30	2,086.30
Other Charges	: 540.00	0.00
TOTAL	: 4,407.30	0.00
Lum Sum Total	: 4,400.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 06/03/2018 09:08:12 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date

Remarks

Prepared Date : 06/03/2018 09:07:39 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 3/6/2018 9:09:33 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
RESPRAY WHEEL CAP	180.00	0.00 X
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	540.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2119-7930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>R</i>	No
2116-7040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>?</i>	No
1521-7050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace <i>?</i>	No
1170-7500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>✓</i>	No <i>cut</i>
3802-7050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>R</i>	No
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>✓ NC</i>	No
3876-7030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>✓ TN</i>	No
3852-7020			FENDER LINER PAD, FR WHEEL LH	1	49.30	25.00	36.97	Replace	Replace <i>✓</i>	No
2602-7060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								2,607.90	2,607.88	
TOTAL MATERIALS(Discounted)							2,086.30	2,086.30		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									


...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018		05 Apr 2018 10:50 Edit Adj Rpt	S\$1,750.00 Edit Estimates	S\$1,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN YEW LEE, ID: S1330659A, Tel: +6597773933, Email: NOEMAIL								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4284K	Date of Loss:	03/03/2018 12:00 - :59 [51 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 551234	Policy/Cover Note No.:	A29030011QMY (Comprehensive) Coverage: 27/10/2017 - 26/10/2018						
Vehicle Reg. No. (Insured):	SJZ1286E	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Imm.Advice due 06/04/2018]								
Driver/Custodian (Insured):	TAN YEE LEE (), NRIC: S1330659A, Tel: +6597773933								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4284K (551234)
[SJZ1286E]
TP
SMRT TAXIS PTE LTD
Mar 3 2018 12:00PM
[TAN YEW LEE]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/04/18 10:40	Accident Statement <small>From: SC - Reg. No: SJZ1286E, Claimant: TAN YEW LEE</small>	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
2	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/04/18 11:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/04/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
17	05/04/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
18	05/04/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/04/18 10:40	SHC4284K e-file report <small>From: SC - Reg. No: SJZ1286E, Claimant: TAN YEW LEE</small>	 Load PDF	
2	05/04/18 10:50	direct survey done	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18004356/SRBQ2

Date: 09/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29030011QMY

Claimant Vehicle No : SHC4284K

Insured Vehicle No : SJZ1285E

Date of Loss: 03/03/2018

Nature of Claim: TP

Claim No: 551234

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4284K

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR5906183

Reg. Date: 22/11/2013 (Man. Year: 2013)

Chassis No: JTDKN36UX05705428

Colour: Maroon

Odometer: 412313 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,185.80	1,007.20	2,178.60	68.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,321.00	960.00	1,361.00	58.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,506.80	1,967.20	3,539.60	64.28
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	5,506.80	1,750.00	3,756.80	68.22

INSPECTION

Date of Assignment: 05/04/2018

Date Inspected: 06/03/2018 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2018)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC4284K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH (DISC 10%)	Cut	945.20 F	*850.68 F
2	1		*NAME PLATE (HYBRID) (DISC 30%)	Necessary	51.90 F	*36.33 F
3	1		*FENDER LINER FRT/LH (DISC 30%)	Torn	171.70 F	*120.19 F
4	1		*BUMPER FRT	Repair	482.00 F	*- F
5	1		*FENDER FRT/LH	Repair	723.40 F	*- F
6	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
7	1		*LENS & BODY ,FR TURN LH	Not Necessary	511.80 F	*- F
8	1		*FENDER LINER PAD,FR WHEEL ,LH	Not Necessary	49.30 F	*- F
9	1		*CAP SUB-ASSY ,WHEEL	Not Necessary	174.10 F	*- F

F=Franchise part.

Total Parts (\$\$)	3,185.80	1,007.20
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	936.00	400.00
3	TOWING CHARGE	New	80.00	80.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			2,321.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >