

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB7989X - TOKIO****AAD1803-037***Not Authored*  
*6/1 Sep 886000*

Vehicle No.:

**SHB7989X - CANDY**

Chassis No.:

**KL1LA69RJBB123324**

Vehicle Make:

**CHEVROLET**

Vehicle Model:

**EPICA 2.0**

Date of Accident :

**05.03.2018**

Third Party Insurer :

**TOKIO****PART****LIST**

|    |   |                                     |    |                                |
|----|---|-------------------------------------|----|--------------------------------|
| 1  | 1 | Rear Bumper                         | \$ | <i>B1</i> 1,202.00 ✓           |
| 2  | 1 | Rear Bumper Beam                    | \$ | <i>B1</i> 239.94 ✓             |
| 3  | 1 | Rear Bumper Centre Absorber         | \$ | <i>C11</i> 260.00 ✓            |
| 4  | 1 | Rear Bumper Side Retainer RH        | \$ | <i>C11</i> 68.76 ✓             |
| 5  | 1 | Rear Bumper Side Retainer LH        | \$ | <i>Sm</i> 68.76 X              |
| 6  | 1 | Rear Bumper Reflectors RH           | \$ | <i>B1</i> 119.74 ✓             |
| 7  | 1 | Rear Bumper Reflectors LH           | \$ | <i>Sm</i> 119.74 X             |
| 8  | 1 | Rear Bumper Tow Hook Cover          | \$ | <i>Sm</i> 93.00 X              |
| 9  | 1 | Rear Luggage Floor Panel            | \$ | <i>R</i> 973.00 X              |
| 10 | 1 | Rear Luggage Floor Panel Insulator  | \$ | <i>Rn</i> 63.50 X              |
| 11 | 1 | Rear Luggage Floor Panel Trim Board | \$ | <i>Sm</i> 378.00 X             |
| 12 | 1 | Rear End Panel Outer                | \$ | <i>B1</i> 623.76 ✓             |
| 13 | 1 | Rear End Panel Inner Trim           | \$ | <i>D11</i> 263.84 ✓            |
| 14 | 1 | Bootlid                             | \$ | <i>B1</i> 973.00 ✓             |
| 15 | 1 | Bootlid inner trim board            | \$ | <i>C11</i> 400.00 ✓            |
| 16 | 1 | Bootlid Weatherstrip                | \$ | <i>C11</i> 344.28 <i>508mm</i> |
| 17 | 1 | Bootlid Lock - Top                  | \$ | <i>R1</i> 466.56 ✓             |
| 18 | 1 | Bootlid 'CHEVROLET' Badge           | \$ | <i>Rn</i> 120.62 ✓             |
| 19 | 1 | Bootlid Logo                        | \$ | <i>Rn</i> 138.84 ✓             |
| 20 | 1 | Bootlid 'EPICA LT' Badge            | \$ | <i>Rn</i> 119.84 ✓             |
| 21 | 1 | Bootlid Reflector Centre            | \$ | <i>C11</i> 217.97 ✓            |
| 22 | 1 | Bootlid Reflector RH                | \$ | <i>C11</i> 128.40 ✓            |
| 23 | 1 | Bootlid Reflector LH                | \$ | <i>C11</i> 128.40 ✓            |
| 24 | 1 | Bootlid Hinge RH                    | \$ | <i>R</i> 120.00 X              |
| 25 | 1 | Bootlid Hinge LH                    | \$ | <i>R</i> 120.00 X              |
| 26 | 1 | Rear Tail Lamp RH                   | \$ | <i>B1</i> 479.30 ✓             |
| 27 | 1 | Rear Tail Lamp Panel RH             | \$ | <i>B1</i> 359.00 ✓             |
| 28 | 1 | Rear Tail Lamp LH                   | \$ | <i>C11</i> 479.30 ✓            |
| 29 | 1 | Rear Tail Lamp Panel LH             | \$ | <i>R</i> 359.00 X              |
| 30 | 1 | Rear Exhaust Box (Muffler A-EXH,RR) | \$ | <i>R</i> 1,110.00 X            |

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1803-037**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB7989X - TOKIO**

|    |   |                           |    |                |
|----|---|---------------------------|----|----------------|
| 31 | 1 | Rear Fender RH            | \$ | Buz 1,145.00 ✓ |
| 32 | 1 | Rear Fender Inner Trim RH | \$ | CM 418.44 ✓    |
| 33 | 1 | Rear Fender LH            | \$ | R 1,145.00 X   |
| 34 | 1 | Rear Fender Inner Trim LH | \$ | in 418.44 X    |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>13,665.43</b> |
| 10%          | <b>\$</b> | <b>1,366.54</b>  |
|              | <b>\$</b> | <b>12,298.89</b> |

**Special Nett**

|    |      |                                   |    |                |
|----|------|-----------------------------------|----|----------------|
| 1  | 1Set | Licence Plate With Holder         | \$ | Sm 60.00 X     |
| 2  | 1Set | Bootlid inner trim board Clip     | \$ | Me 40.00 ✓     |
| 3  | 1Set | Rear Bumper Parking Sensor        | \$ | nd 300.00 ✓    |
| 4  | 1Set | Rear Bumper Fastener Clip         | \$ | Me 44.00 ✓     |
| 5  | 1Set | Rear Fender Inner Trim Clip LH    | \$ | na 30.00 X     |
| 6  | 1Set | Rear Fender Inner Trim Clip RH    | \$ | na 30.00 ✓     |
| 7  | 1Set | Rear Bumper End Dust Cover Clip   | \$ | na 30.00 X     |
| 8  | 1    | Rear Boot Sticker 'Trans-cab'     | \$ | na 30.00 ✓     |
| 9  | 1    | Rear Boot Sticker '6555-3333'     | \$ | na 30.00 ✓     |
| 10 | 1    | Rear Exhaust Mounting             | \$ | Sm 10.00 X     |
| 11 | 2    | Rear Windscreen Sealant           | \$ | na 80.00 80sm  |
| 12 | 1    | Rear Windscreen Inner Sponge Seal | \$ | na 100.00 30sm |
| 13 | 1    | Spare Tyre                        | \$ | Sm 180.00 X    |
| 14 | 1    | Spare Wheel Rim                   | \$ | Sm 126.74 X    |

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL</b>       | <b>\$</b> | <b>1,090.74</b>  |
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>13,389.63</b> |

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of  
Parts, Adjust And Realign The Same

\$ 5,400.00 1200

To Check Electrical Lighting Concerned.

\$ 170.00 200

To Rust-Proofing Of The Affected Areas.

\$ 170.00 900

Putty And Spray Painting Of The Affected  
Portion.

\$ 5,350.00 1000

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHB7989X - TOKIO****AAD1803-037**

|                                                                                                 |           |                     |        |
|-------------------------------------------------------------------------------------------------|-----------|---------------------|--------|
| To reinstall rear bumper parking sensor.                                                        | \$        | 170.00              | 601    |
| To transfer of end panel fittings and conduct water seepage test.                               | \$        | 170.00              | } 1001 |
| To transfer of luggage floor panel fittings and conduct water seepage test.                     | \$        | 170.00              |        |
| To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.                          | \$        | 170.00              | 1201   |
| To transfer of boot fittings and conduct water seepage test.                                    | \$        | 170.00              | 601    |
| Towing fees                                                                                     | \$        | 120.00              | 501    |
| To transfer of Fender fittings, attachments and perform water seepage test.                     | \$        | Repair 170.00       | X      |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$        | 380.00              | X      |
| To check steering geometry and computer wheel alignment                                         | \$        | 220.00              | X      |
|                                                                                                 |           | <b>\$ 12,830.00</b> |        |
| <b>TOTAL</b>                                                                                    | <b>\$</b> | <b>26,219.63</b>    |        |

**Repair Days****20 Days***8 days*