

ASS. REC. BY:

REF:

Tml

CC3/TML180011358/Kvb/12

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 7889X

Yr Regn: 01, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica c.c. 1991

Colour

White 1Pw A/C: Insured / Std / NI / NA

Sp. Reading

690478 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/13 Ph report to Customer, set injury
618p 886000 (Recd 17.6.19.63, 679)

7/13/18 Email GIA to Shirley

RECEIVED 03 MAR 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

7/13 - typist

Days Of Repair:

8

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

S + RS. \$

10

Photos

Others

TOTAL

260

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

8600/2

Survey Department Check List (Case Handler)

Reference No.: CC3 TMI/800 4358 Kvb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 7/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI18004358/Kvb		
20 MCCALLUM STREET #09-01		Date : 07-03-2018		
TOKIO MARINE CENTRESINGAPORE 069046		Code : TMI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 5590M	Veh. Inspected	SHB 7989X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/03/2018	Inspection Date	07/03/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		07 Mar 2018 15:05 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	COMFORT LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 201508380W		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB7989X	Date of Loss:	05/03/2018 09:00 - :59
Claim Type:	TP / M1801216	Policy/Cover Note No.:	MG000572 (Comprehensive) Coverage: 29/06/2017 - 28/06/2018
Vehicle Reg. No. (Insured):	SKZ5590M	Policy No. (Claimant):	VPX/P1680520
		Excess:	S\$1,500.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 7 March 2018 2:14 PM
To: 'Too Joon Hwa'
Cc: priscilla@tokiomarine.com.sg; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 5/3/2018, SHB 7989X (TP VEHICLE), SKZ 5590M (OI VEHICLE)
Attachments: EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHB 7989X M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 6/3/2018

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB7989X
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1462164K
Chassis No.:	KL1LA69RJBB123324
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,971.00
Original Registration Date:	29 Jan 2013
First Registration Date:	29 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$13,971.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2021
PARF Rebate Amount:	\$9,779.00
Intended COE Rebate Details	

COE Expiry Date:	28 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,655.00
COE Rebate Amount:	\$21,950.00
Total Rebate Amount:	\$31,729.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 15:23
Date Of Accident	05/03/2018 08:40
Exact Location Of Accident	SLE TOWARDS WOODLANDS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7989X
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM LEONG HOCK
NRIC No	S1287544D
Date Of Birth	12/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	08/11/1977
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97930540
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 256 SERANGOON CENTRAL DRIVE #05-40
Postcode	550256
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180305/2056

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ5590M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEE YEONG WAH
NRIC/Passport Number	S1768464G
Contact Number	92471588
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKG3636D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

SIM BAO CUN

NRIC/Passport Number

S8513809Z

Contact Number

96859957

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LIM LEONG HOCK

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHB7989X

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180305/2056

1 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20180305/2056

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/03/2018 13:09		Vide Report No.:		Station Diary No.: 55	
Informant's Particulars					
Name of Informant: LIM LEONG HOCK			Address: APT BLK 256 SERANGOON CENTRAL DRIVE #05-40 SINGAPORE 550256		
ID Type / ID No.: NRIC NO / S1287544D			Contact No.: Home/Office: Mobile: 97930540		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 59	Date of Birth: 12/05/1958	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3,4		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/03/2018 08:40	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SELETAR EXPRESSWAY				
TOWARDS WOODLANDS BEFORE MANDAI EXIT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB7989X	Car	CHEVROLET	EPICA	Red	Seriously Damaged	1
SKG3636D	Car	AUDI	A5	Black		0
SKZ5590M	Car	TOYOTA	HARRIER	White		0



**SINGAPORE
POLICE FORCE**



T/20180305/2056

2 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20180305/2056

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM LEONG HOCK	ID No.	S1287544D
Related Vehicle	SHB7989X (Car)	Contact No.	97930540
Hospital/Clinic	Intermedical 24 Hr Clinic	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	05/03/2018	Date Discharge	05/03/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	SIM BAO CUN	ID No.	S8513809Z
Related Vehicle	SKG3636D (Car)	Contact No.	96859957
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YEE YEONG WAH	ID No.	S1768464G
Related Vehicle	SKZ5590M (Car)	Contact No.	92471588
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05.03.2018 at about 0840hrs, I was driving my taxi (SHB7989X) along lane 1 of SLE towards Woodlands. The vehicle in front of me stopped just before Mandai exit as such I came to a stop too. Moments later, I suddenly felt an impact from the rear. I exited from my taxi to make a check and discovered serious damages to the rear portion of the vehicle. I wish to state that I had noted the vehicle behind me (SKX5590M) was also stationery behind me before the impact. I then discovered that a third vehicle had hit the vehicle behind me, causing it to be pushed forward and hitting into my vehicle.

There was one passenger in my taxi and neither she nor me required medical attention at that time. I



**SINGAPORE
POLICE FORCE**



T/20180305/2056

3 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20180305/2056

CONTINUATION OF REPORT

later visited the clinic where I was given 5 days of MC.



**SINGAPORE
POLICE FORCE**



T/20180305/2056

4 of 4

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20180305/2056

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 REEMA KAUR SANDHU

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/03/2018 13:09

Officer In Charge Of Case:

TP / AEIT /

SI DZUL HAIRIE BIN RAMLI

Contact No.: 65476220

Classification Of Case:

Authentication Stamp

NP168

SINGAPORE
POLICE FORCE

SN 061

SIGNATURE

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7989X - TOKIO**AAD1803-037***Not Authored
6/1/2018 88600*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB7989X - CANDY

KL1LA69RJB123324

CHEVROLET

EPICA 2.0

05.03.2018

TOKIO**PART****LIST**

1	1	Rear Bumper	\$	B ₁ 1,202.00 ✓
2	1	Rear Bumper Beam	\$	B ₁ 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	CM 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	CM 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$	Sm 68.76 X
6	1	Rear Bumper Reflectors RH	\$	B ₁ 119.74 ✓
7	1	Rear Bumper Reflectors LH	\$	Sm 119.74 X
8	1	Rear Bumper Tow Hook Cover	\$	Sm 93.00 X
9	1	Rear Luggage Floor Panel	\$	R 973.00 X
10	1	Rear Luggage Floor Panel Insulator	\$	R 63.50 X
11	1	Rear Luggage Floor Panel Trim Board	\$	Sm 378.00 X
12	1	Rear End Panel Outer	\$	B ₁ 623.76 ✓
13	1	Rear End Panel Inner Trim	\$	D ₁ 263.84 ✓
14	1	Bootlid	\$	B ₁ 973.00 ✓
15	1	Bootlid inner trim board	\$	CM 400.00 ✓
16	1	Bootlid Weatherstrip	\$	CM 344.28 50% ✓
17	1	Bootlid Lock - Top	\$	R 466.56 ✓
18	1	Bootlid 'CHEVROLET' Badge	\$	R 120.62 ✓
19	1	Bootlid Logo	\$	R 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	R 119.84 ✓
21	1	Bootlid Reflector Centre	\$	CM 217.97 ✓
22	1	Bootlid Reflector RH	\$	CM 128.40 ✓
23	1	Bootlid Reflector LH	\$	CM 128.40 ✓
24	1	Bootlid Hinge RH	\$	R 120.00 X
25	1	Bootlid Hinge LH	\$	R 120.00 X
26	1	Rear Tail Lamp RH	\$	B ₁ 479.30 ✓
27	1	Rear Tail Lamp Panel RH	\$	B ₁ 359.00 ✓
28	1	Rear Tail Lamp LH	\$	CM 479.30 ✓
29	1	Rear Tail Lamp Panel LH	\$	R 359.00 X
30	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-037**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7989X - TOKIO

31	1	Rear Fender RH
32	1	Rear Fender Inner Trim RH
33	1	Rear Fender LH
34	1	Rear Fender Inner Trim LH

Bu 1,145.00 ✓
CM 418.44 —
R 1,145.00 X
in 418.44 X

TOTAL	\$	13,665.43
10%	\$	1,366.54
	\$	12,298.89

Special Nett

1	1Set	Licence Plate With Holder
2	1Set	Bootlid inner trim board Clip
3	1Set	Rear Bumper Parking Sensor
4	1Set	Rear Bumper Fastener Clip
5	1Set	Rear Fender Inner Trim Clip LH
6	1Set	Rear Fender Inner Trim Clip RH
7	1Set	Rear Bumper End Dust Cover Clip
8	1	Rear Boot Sticker 'Trans-cab'
9	1	Rear Boot Sticker '6555-3333'
10	1	Rear Exhaust Mounting
11	2	Rear Windscreen Sealant
12	1	Rear Windscreen Inner Sponge Seal
13	1	Spare Tyre
14	1	Spare Wheel Rim

Sm 60.00 X
na 40.00 —
na 300.00 —
na 44.00 —
na 30.00 X
na 30.00 —
na 30.00 X
na 30.00 —
na 30.00 —
Sm 10.00 X
na 80.00 80sm
na 100.00 30sm
Sm 180.00 X
Sm 126.74 X

TOTAL	\$	1,090.74
TOTAL PARTS	\$	13,389.63

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 5,400.00 *1200d*

To Check Electrical Lighting Concerned.

\$ 170.00 *20d*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *90d*

Putty And Spray Painting Of The Affected
Portion.

\$ 5,350.00 *1000d*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1803-037**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7989X - TOKIO

To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	} 100
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	120
To transfer of boot fittings and conduct water seepage test.	\$	170.00	60
Towing fees	\$	120.00	50
To transfer of Fender fittings, attachments and perform water seepage test.	\$	Repair 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
		\$	12,830.00
TOTAL	\$	26,219.63	

Repair Days**20 Days***8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18004358/KVBN2

Date: 12/03/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MG000572
Claimant Vehicle No :	SHB7989X	Insured Vehicle No :	SKZ5590M
Date of Loss:	05/03/2018	Nature of Claim:	TP
		Claim No:	M1801216

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7989X	Engine No:	Z20S1462164K
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Chassis No:	KL1LA69RJB123324
Reg. Date:	29/01/2013 (Man. Year: 2011)	Odometer:	690478 km
Colour:	Red/White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,389.63	8,233.58	5,156.05	38.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,830.00	2,700.00	10,130.00	78.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,219.63	10,933.58	15,286.05	58.30
Approved Total (Overridden) (S\$)		8,600.00		
(S\$)	26,219.63	8,600.00	17,619.63	67.20
+ GST 7.00/7.00% (S\$)	1,835.37	602.00	1,233.37	67.20
Nett Amount (S\$)	28,055.00	9,202.00	18,853.00	67.20

INSPECTION

Date of Assignment:	07/03/2018	
Date Inspected:	06/03/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2018)	
Parts: 143	CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHB7989X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,202.00 FL	*1,202.00 FL
2	1		*REAR BUMPER BEAM	Bent	239.94 FL	*239.94 FL
3	1		*REAR BUMPER CENTRE ABSORBER	Cracked	260.00 FL	*260.00 FL
4	1		*REAR BUMPER SIDE RETAINER RH	Cracked	68.76 FL	*68.76 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	68.76 FL	*- FL
6	1		*REAR BUMPER REFLECTORS RH	Bent	119.74 FL	*119.74 FL
7	1		*REAR BUMPER REFLECTORS LH	Serviceable	119.74 FL	*- FL
8	1		*REAR BUMPER TOW HOOK COVER	Serviceable	93.00 FL	*- FL
9	1		*REAR LUGGAGE FLOOR PANEL	Repair	973.00 FL	*- FL
10	1		*REAR LUGGAGE FLOOR PANEL INSULATOR	Not Necessary	63.50 FL	*- FL
11	1		*REAR LUGGAGE FLOOR PANEL TRIM BOARD	Serviceable	378.00 FL	*- FL
12	1		*REAR END PANEL OUTER	Bent	623.76 FL	*623.76 FL
13	1		*REAR END PANEL INNER TRIM	Distorted	263.84 FL	*263.84 FL
14	1		*BOOTLID	Bent	973.00 FL	*973.00 FL
15	1		*BOOTLID INNER TRIM BOARD	Cracked	400.00 FL	*400.00 FL
16	1		*BOOTLID LOCK-TOP	Dented	466.56 FL	*466.56 FL
17	1		*BOOTLID CHEVROLET BADGE	Necessary	120.62 FL	*120.62 FL
18	1		*BOOTLID LOGO	Necessary	138.84 FL	*138.84 FL
19	1		*BOOTLID EPICA LT BADGE	Necessary	119.84 FL	*119.84 FL
20	1		*BOOTLID REFLECTOR CENTRE	Cracked	217.97 FL	*217.97 FL
21	1		*BOOTLID REFLECTOR RH	Cracked	128.40 FL	*128.40 FL
22	1		*BOOTLID REFLECTOR LH	Cracked	128.40 FL	*128.40 FL
23	1		*BOOTLID HINGE RH	Repair	120.00 FL	*- FL
24	1		*BOOTLID HINGE LH	Repair	120.00 FL	*- FL
25	1		*REAR TAIL LAMP RH	Broken	479.30 FL	*479.30 FL
26	1		*REAR TAIL LAMP PANEL RH	Bent	359.00 FL	*359.00 FL
27	1		*REAR TAIL LAMP LH	Cut	479.30 FL	*479.30 FL
28	1		*REAR TAIL LAMP PANEL LH	Repair	359.00 FL	*- FL
29	1		*REAR EXHAUST BOX (MUFFLER A-EXH,RR)	Repair	1,110.00 FL	*- FL
30	1		*REAR FENDER RH	Buckled	1,145.00 FL	*1,145.00 FL
31	1		*REAR FENDER INNER TRIM RH	Cracked	418.44 FL	*418.44 FL
32	1		*REAR FENDER LH	Repair	1,145.00 FL	*- FL
33	1		*REAR FENDER INNER TRIM LH	Serviceable	418.44 FL	*- FL
34	1		*SET LICENCE PLATE WITH HOLDER	Serviceable	60.00 FS	*- FS
35	1		*SET BOOTLID INNER TRIM BOARD CLIP	Necessary	40.00 FS	*40.00 FS
36	1		*SET REAR BUMPER PARKING SENSOR	Dented	300.00 FS	*300.00 FS
37	1		*SET REAR BUMPER FASTENER CLIP	Necessary	44.00 FS	*44.00 FS
38	1		*SET REAR FENDER INNER TRIM CLIP LH	Not Necessary	30.00 FS	*- FS
39	1		*SET REAR FENDER INNER TRIM CLIP RH	Necessary	30.00 FS	*30.00 FS
40	1		*SET REAR BUMPER END DUST COVER CLIP	Not Necessary	30.00 FS	*- FS
41	1		*REAR BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
42	1		*REAR BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
43	1		*REAR EXHAUST MOUNTING	Serviceable	10.00 FS	*- FS
44	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR WINDSCREEN INER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
46	1		*SPARE TYRE	Serviceable	180.00 FS	*- FS
47	1		*SPARE WHEEL RIM	Serviceable	126.74 FS	*- FS
48	1		*BOOT LID WEATHERSTRIP (50%)	Cut	309.86 FS	*172.14 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					14,721.75	9,068.85
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,332.12	835.27
Total Parts (\$\$)					13,389.63	8,233.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	5,400.00	1,200.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	5,350.00	1,000.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST }	New	170.00	100.00
7	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST }	New	170.00	-
8	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
9	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	60.00
10	TOWING FEES	New	120.00	50.00
11	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
12	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (\$\$)			12,830.00	2,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >