SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

mehicle Repair Estimates

and claims Advisor/Duty officer at Accident Reporting Centre

SMB108J

BUS/02/18/5028

01/03/2018

BUS -12M

MBOC500 (MERCEDES)

: MERCEDES MBOC500

: Mohd Haszreen Bin Razali

: SIDE SWIPE

me of Accident : 23/02/2018 09:00:00 AM

Reported Date / Time: 26/02/2018 12:00:00 AM

Surveyor is Required? : Yes

· IDAC

Survey by : IDAC

Vehicle is Towed Back? : No

Towed Back Date/Time

Replacement Vehicle issued? : No

Accident Repair Job Card No :


Special Instruction to ARC, if any :

SMB108J - RIGHT FRONT PORTION

SHD2286M (TP) - PRIME TAXI. INSURED WITH NTUC

Prepared Date

01/03/2018 09:40:40 AM





LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: