

ASS. REC. BY:

REF: CS/CTI 18004369/Kqd302

Special Instruction:

Surveyor: Kenneth MenmenASSIGNMENT (Office)

From (Person):

Adeline Chng

of

CTI

Date/Time:

6/3/18 @ 3pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 1552B

Insured:

at Workshop n/s

K Kim Hin Auto

Tel:

64527018

of

160 Sin Ming Drive #02-20

Policy No:

DMCVSN3010991800

Claim No:

8NM18D01069C01

Sum Insured:

Excess:

\$550.00

Make of Veh:

(Client's Record)

D.O.A.

23/2/2018CA / ☒ REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:50am 7/3/18

Person Contacted:

ShumanVehicle: ☒ IN ☐ OUT

Date/Time

Action/Instruction

() EstimateGBH 1552B - X08/3/18 @ 9.00am revert to Adeline Chng via Menmen.08/3/18 @ 4.50pm Susan too informed C/A via Menmen.09/3/18 @ 10.45am informed Wang Hui & Simon C/A & ex: \$550 by email.09/3/18 @ 11.00am checked with Adeline, the freeze is under insured policy but no sum insured. (Sum insured: \$NIL)

Summit
Machmen

REF:

CTI CS/CTI18004369/Kqd3

ASSIGNMENT

From: Date: 07/03/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBH 1552B

at Workshop no: K Kim Hin Auto

of 160 Sin Ming Drive #02-20

Insured:

Policy No:

Claims No:


Sum Insured: Excess: \$550.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$78 without free box

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res: Yes or No

Lum Sum: 1-B4 % 3 Val: Yes or No

CA / REP / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Van No: GBH1552B Vr Regn: 02 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota cc: 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 646 T-Radio: Insured / Std / NI / NA

Eng No:

C/No: JTFAT35410K209660

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/75R15

R: 155R12x8(10)

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: Rear: 9 9 mm

R/Bal: 9 9 mm

L/Bal: 9 9 mm

D.O.A: 23/2/18 D.O.I: 7/3/18

Survey held at: ☒

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S & O/S body

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

12/3 Mr. pass to Customer

To check re. free insured or not??

20/3/19 @ 4.28pm confirmed with Mary Hunt foral Prg #11062.25, 14 days (red \$48628.25, 81%)

RECEIVED 21 MAR 2019

Date/Time File Pass to:

☐

Preli. Report

12/3 tyaga

☐

Final Report

Date/Time File Return to:

2.

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee:

Transporter

1-B-#1.5

Price

Scan

17%

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Ins: \$

☐

Weekend: \$

Report Format:

MER-09

Lump Sum / I.B. / \$

11062.25

220
220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18004369/Kqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-03-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBH 1552B
Policy No.	DMCVSN3010991800	Coverage (\$)	0.00
Claim No.	SNM18D01069C01	Excess (\$)	550.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	23/02/2018	Inspection Date	07/03/2018
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018 Sendback Est	06 Mar 2018 10:17 S\$59,690.50	06 Mar 2018 15:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TREEDOTS ENTERPRISE (PRIVATE LIMITED), Co. Reg. No.: 201724120K, Tel: +6596986909									
Vehicle Reg. No.: GBH1552B		Date of Loss: 23/02/2018 22:00 - :59							
Claim Type: OD / SNM18D01069C01		Policy/Cover Note No.: DMCVSN3010991800 (Comprehensive) Coverage: 06/02/2018 - 05/02/2019							
		Excess: S\$550.00							
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/03/2018]									
Driver/Custodian: LAU JIA CAI (25 / Male), NRIC: S9214772Z, Tel: +6596986909									
Adj Asg. Remarks: SURVEY REVERT									
ASSOCIATED MAIL RECEIVED									
				View All					
There are no mail for this case.				Compose Case Mail					
ALL ASSOCIATED TASKS									
		View All							
		Search Tasks							
		Create New Task							
		Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Approval)

CLAIM SUBFOLDER TRACKING

Case	Refined	Estimates	Est Submitted	Adj Assigned	Ins Audited	Status
Main	05 Mar 2018 18:01		06 Mar 2018 10:17 S\$59,690.50			Pending for Approval

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TREEDOTS ENTERPRISE (PRIVATE LIMITED), Co. Reg. No.: 201724120K, Tel: +6596986909		
Vehicle Reg. No.:	GBH1552B	Date of Loss:	23/02/2018 22:00 - :59
Claim Type:	OD	Policy/Cover Note No.:	DMCVSN3010991800 (Comprehensive) Coverage: 06/02/2018 - 05/02/2019
		Excess:	
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Driver/Custodian:	LAU JIA CAI (25 / Male), NRIC: S9214772Z, Tel: +6596986909		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

Shiau Chan (LKKAUTO)

From: survey@kkimhin.com.sg
Sent: Wednesday, 20 March 2019 4:28 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: VEHICLE GBH 1552B (DOA: 23/02/2018) FINALISATION

Hi Shiau Chan,

Confirm you figure \$11,062.25
Thank you.

Regard
Meng Huat
K.Kim Hin Auto

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, 14 March 2019 4:22 PM
To: survey@kkimhin.com.sg
Subject: RE: VEHICLE GBH 1552B (DOA: 23/02/2018) FINALISATION

Dear Meng Huat,

WITHOUT PREJUDICE

Offer final fig \$11,062.25 before excess \$550.00 & GST and 14 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: survey@kkimhin.com.sg <survey@kkimhin.com.sg>
Sent: Wednesday, 13 March 2019 12:21 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: VEHICLE GBH 1552B (DOA: 23/02/2018) FINALISATION

Hi Ms Shiau Chan,

Enclosed your attention.
Please adjust REAR FREEZER BOX PRICE.
Thank you.

Regard
Meng Huat
K.Kim Hin Auto

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 12 March 2019 4:10 PM

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Mar 2018 17:56	Cim Veh Model Changed	(204821) TOYOTA DYNA 150 3.0 D (M).	[R] Wong Shu Man
2	05 Mar 2018 17:56	Cim Created	Reg No: GBH1552B, Policy No: DMCVSN3010991800, Acct Date: 2018/02/23. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: K Kim Hin Auto Pte Ltd (HQ). Created from SAS:MKKH18028010	[R] Wong Shu Man
3	06 Mar 2018 10:17	Cim Submitted	59690.50.	[R] Wong Shu Man
4	06 Mar 2018 15:00	Cim Registration Modified	Excess: -> 550.00.	[I] Adeline Chng Pel Wen
5	06 Mar 2018 15:00	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Adeline Chng Pel Wen
6	06 Mar 2018 15:00	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/15	[I] Adeline Chng Pel Wen
7	06 Mar 2018 15:00	Adj Mandate Set	Approved:0.00.	[I] Adeline Chng Pel Wen
8	06 Mar 2018 18:56	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
9	07 Mar 2018 14:02	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
10	07 Mar 2018 16:55	Adj Rpt Initiated		[A] SHIAU CHAN
11	08 Mar 2018 09:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/15	[A] SHIAU CHAN
12	08 Mar 2018 09:02	Adj Mandate Request	Cur.Reg:54109.75:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY ADVISE THE FREEZE IS UNDER INSURED POLICY. IF YES, HOW MUCH OF SUM INSURED. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
13	08 Mar 2018 16:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/15	[I] Susan Teo
14	08 Mar 2018 16:52	Adj Mandate Set	Approved:54109.75.	[I] Susan Teo

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1739662	05/03/2018 17:56	Motor	K Kim Hin Auto Pte Ltd (HQ)	K Kim Hin Auto Pte Ltd (HQ)	GBH1552B		xx.xx
1742273	07/03/2018 16:55	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBH1552B		10.70

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 9 March 2018 10:47 AM
To: Survey KKH; Simon
Cc: SUR
Subject: VEHICLE GBH 1552B (DOA: 23/02/2018)

Dear Meng Huat and Simon,

As instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle **GBH 1552B (excess \$550/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 07 Mar 2018

Preliminary Advice

Vehicle No	: GBH1552B	Accident Date	: 23/02/2018
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSN3010991800
Assignment Date	: 06/03/2018	Excess	: S\$550.00
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 14.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,690.50
Revised Amount	:S\$	6,120.00
Check Items (Estimated)	:S\$	47,989.75
Total	:S\$	54,109.75

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value (without freeze)	:S\$	78,000.00
COE / PARF Rebate	:S\$	17,034.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,966.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ADVISE THE FREEZE IS UNDER INSURED POLICY. IF YES, HOW MUCH OF SUM INSURED.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4120K
Vehicle Details	
Vehicle No.:	GBH1552B
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2769200
Chassis No.:	JTFAT35Y10K209660
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	06 Feb 2018
First Registration Date:	06 Feb 2018
Transfer Count:	1
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Feb 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$17,134.00
COE Rebate Amount:	\$17,034.00
Total Rebate Amount:	\$17,034.00

The information contained herein is correct as at 27 Feb 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/02/2018 16:02
Date Of Accident	23/02/2018 22:30
Exact Location Of Accident	JUNC. BETWEEN HENDERSON RD & TELOK BLANGAH HEIGHTS
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBH1552B
Insured/Policyholder	
Name Of Registered Owner	TREEDOTS ENTERPRISE (PRIVIAE LIMITED)
Co Reg No	201724120K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96986909
Alternative Phone No	OFFICE-96986909
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3010991800
Cover Note Number	
Driver	
Name of Driver	LAU JIA CAI
NRIC No	S9214772Z
Date Of Birth	03/05/1992
Occupation	INDOOR
Date Of Driving Pass	28/06/2013
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96986909
Fax Number	
Contact Number	
Email Address	JIACAI@THETREEDOTS.COM

Address BLK 122 BISHAN STREET 12
#09-47

Postcode 570122

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TANGLIN POLICE DIVISIONAL HQ ('E' DIVISION)

Police Station Address ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-3910000 - FAX NO: 63964900

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD6472T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

27/1/18 @
3.10pm



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A is making a right turn towards Telok Blangah Height when suddenly vehicle A was hit by vehicle B from the left & thus vehicle A overturn to the right side.

Enclosed police report.

DECLARATION

I/We hereby declare the foregoing particulars are true

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



E20180224V7002

1 of 2

POLICE REPORT (NP299)

Report No. E/20180224/7003

Police Station Of Origin
Tanglin Police Divisional HQ
21 Kampong Java Road SINGAPORE
228892
Tel No:1800-3910000

Date/Time Report Made 24/02/2018 14:47	Vide Report No.	Station Diary No.
Name Of Informant LAU JIA CAI	Address APT BLK 122 BISHAN STREET 12 #09-47 SINGAPORE 570122	
ID Type / ID No. NRIC NO / S9214772Z	Contact No. Home/Office:	Mobile: 96986909
Nationality SINGAPORE CITIZEN	Email Address jiacai@thetreedots.com	
Occupation Chief operating officer/General Manager	Sex Male	Age 25
Institution/School Name	Date of Birth 03/05/1992	Race Chinese
Date/Time Of Incident 23/02/2018 22:30 - 23/02/2018 23:28	Location Of Incident TELOK BLANGAH HEIGHTS	

Brief details.

I am driving at freezer truck turning right from henderson road towards telok blangah heights. I was not sure if it was red lights but all the incoming traffic from the other direction was stopped. As i was turning right, a lexus car carplateSLD 6472T hit the back of my truck, causing my truck to fall to its side.

Subjects Involved	
Victim	
Person Name	LAU JIA CAI

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 24/02/2018 14:47
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



E/20180224/7003

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20180224/7003

ID Type	NRIC NO	ID No	S9214772Z
Gender	Male	Age	25
Race	Chinese	Language	English
Occupation	Chief operating officer/General Manager	Address Type	
Address	APT BLK 122 BISHAN STREET 12 #09-47 SINGAPORE 570122	Mobile No	96986909
Is Informant A Victim?	Yes		
Person Name	LAU JIA CAI (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

24/02/2018 14:47

Classification Of Case:



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3010991800	Date of Loss:	23/02/2018
Vehicle Reg. No.:	GBH1552B	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TREEDOTS ENTERPRISE (PRIVATE LIMITED)	Contact No:	+6596986909
Driver:	LAU JIA CAI		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	06/02/2018
Vehicle Colour:	SILVER	Chassis No:	JTFAT35Y10K209660
Engine No:	1KD2769200		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	24 / 4 days		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN. KINDLY ARRANGE FOR SURVEY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

Not Authorized
Recovery By paint
E x 855d

COST OF CLAIMS

	Amount
Parts	55,200.50
Miscellaneous Items	0.00
Labour	4,490.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	59,690.50
+ GST 7.00% (\$\$)	4,178.34
Nett Amount (\$\$)	63,868.84

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify below/for entry painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No (legal) implications is allowed
- Supplementary work(s) might be required and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature: _____

This claim is handled by: **WONG SHU MAN**

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Mar 2018)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: K Kim Hin Auto Pte Ltd/GBH1552B/06/03/2018 10:17

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*350.00 F	✓
2	1		*O/S FRONT BUMPER BRACKET	0.00	0.00	*110.00 F	X
3	1		*O/S FRONT BUMPER FOG COVER	0.00	0.00	*35.00 F	X
4	1		*O/S HEADLAMP ASSY	0.00	0.00	*500.00 F	✓
5	1		*FRONT GRILLE	0.00	0.00	*320.00 F	X
6	1		*O/S FRONT CORNER PANEL	0.00	0.00	*110.00 F	✓
7	1		*O/S FRONT CORNER PANEL BRACKET	0.00	0.00	*40.00 F	X
8	1		*FRONT WINDSCREEN GLASS	0.00	0.00	*480.00 F	X
9	1		*FRONT WINDSCREEN GLASS RUBBER	0.00	0.00	*115.00 F	✓
10	1		*O/S FRONT DOOR	0.00	0.00	*630.00 F	✓
11	1		*O/S FRONT DOOR GLASS	0.00	0.00	*175.00 F	X
12	1		*O/S FRONT DOOR GLASS RUN CHANNEL	0.00	0.00	*85.00 F	X
13	1		*O/S FRONT DOOR GLASS OUTER MOULDING	0.00	0.00	*55.00 F	X
14	1		*O/S FRONT DOOR GLASS REGULATOR	0.00	0.00	*100.00 F	X
15	1		*O/S FRONT DOOR GLASS REGULATOR MOTOR	0.00	0.00	*195.00 F	X
16	1		*O/S FRONT DOOR OUTER HANDLE	0.00	0.00	*75.00 F	✓
17	1		*O/S FRONT DOOR WEATHERSTRIP	0.00	0.00	*75.00 F	X
18	1		*O/S FRONT DOOR LOCK	0.00	0.00	*125.00 F	X
19	1		*O/S FRONT DOOR LOCK CATCH	0.00	0.00	*35.00 F	X
20	1		*O/S FRONT DOOR LOWER RUBBER LID	0.00	0.00	*55.00 F	✓
21	1		*O/S FRONT DOOR LOWER INNER SEAL	0.00	0.00	*35.00 F	X
22	1		*O/S FRONT DOOR STEP GARNISH	0.00	0.00	*125.00 F	✓
23	1		*O/S FRONT DOOR FRAME	0.00	0.00	*380.00 F	X
24	1		*O/S FRONT DOOR FRAME TOYOTA D-4D EMBLEM	0.00	0.00	*30.00 F	X
25	1		*O/S WINGMIRROR ASSY	0.00	0.00	*85.00 F	✓
26	1		*O/S FRONT MUDGUARD	0.00	0.00	*165.00 F	✓
27	1		*O/S FRONT MUDFLAP	0.00	0.00	*85.00 F	X
28	1		*N/S REAR MUDGUARD-FRONT	0.00	0.00	*165.00 F	✓
29	1		*N/S REAR MUDGUARD-REAR	0.00	0.00	*165.00 F	✓
30	1		*N/S REAR MUDFLAP	0.00	0.00	*85.00 F	X
31	1		*N/S REAR WHEEL BEARING-INNER	0.00	0.00	*45.00 F	✓
32	1		*N/S REAR WHEEL BEARING-OUTER	0.00	0.00	*45.00 F	✓
33	1		*N/S REAR WHEEL BEARING OIL SEAL-INNER	0.00	0.00	*35.00 F	✓
34	1		*N/S REAR WHEEL BEARING OIL SEAL-OUTER	0.00	0.00	*35.00 F	✓
35	1		*N/S REAR AXLE SHAFT	0.00	0.00	*695.00 F	✓
36	2		*REAR SHOCK ABSORBER (LH/RH)	0.00	0.00	*100.00 F	✓
37	1		*REAR AXLE HOUSING	0.00	0.00	*2,850.00 F	✓
38	1		*O/S FRONT SHOCK ABSORBER	0.00	0.00	*60.00 F	✓
39	1		*O/S FRONT UPPER ARM	0.00	0.00	*380.00 F	✓
40	1		*O/S KNUCKLE ARM	0.00	0.00	*280.00 F	X
41	1		*O/S FRONT LOWER ARM	0.00	0.00	*225.00 F	✓
42	1		*O/S FRONT LOWER ARM BALL JOINT	0.00	0.00	*85.00 F	✓
43	1		*O/S FRONT WHEEL BEARING	0.00	0.00	*85.00 F	X
44	1		*O/S FRONT BEARING HUB	0.00	0.00	*185.00 F	X
45	4		*FUEL INJECTOR	0.00	0.00	*1,920.00 F	✓
46	1		*COMMON RAIL	0.00	0.00	*750.00 F	✓
47	1		*AIR FILTER	0.00	0.00	*45.00 F	✓
48	1		*AIR FLOW SENSOR	0.00	0.00	*120.00 F	✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
49	1		*TURBO ASSY	0.00	0.00	*2,200.00 F	7
50	1		*TURBO INTER COOLER	0.00	0.00	*780.00 F	7
51	1		*EGR VALVE	0.00	0.00	*220.00 F	7
52	1		*EGR COOLER	0.00	0.00	*285.00 F	7
53	2		*ENGINE MOUNTING (LH/RH)	0.00	0.00	*120.00 F	X
54	1		*GEAR BOX MOUNTING	0.00	0.00	*60.00 F	X
55	1		*FRONT EXHAUST MUFFLER	0.00	0.00	*880.00 F	7
56	1		*CENTRE EXHAUST MUFFLER	0.00	0.00	*650.00 F	7
57	2		*FRONT EXHAUST MUFFLER TEMPERATURE SENSOR	0.00	0.00	*450.00 F	7
58	1		*REAR FREEZER BOX <i>Insured ??</i>	0.00	0.00	*32,000.00 F	500
59	1		*ERP BRACKET	0	0.00	*26.00 FS	X
60	1		*O/S FRONT DOOR COMPANY REGISTRATION STICKER	0	0.00	*25.00 FS	✓
61	1		*N/S REAR TYRE-OUTER	0	0.00	*320.00 FS	✓
62	1		*N/S REAR RIM-OUTER	0	0.00	*280.00 FS	✓
63	1		*O/S REAR TYRE-OUTER	0	0.00	*320.00 FS	X
64	1		*O/S REAR RIM-OUTER	0	0.00	*280.00 FS	X
65	1		*O/S FRONT TYRE	0	0.00	*370.00 FS	X
66	1		*O/S FRONT RIM	0	0.00	*280.00 FS	X
67	1		*ENGINE OIL	0	0.00	*88.00 FS	✓
68	1		*POWER STEERING OIL	0	0.00	*65.00 FS	X
69	1		*RADIATOR COOLANT	0	0.00	*48.00 FS	X

F=Franchise part. S=SpocNett.

Sub Total (\$\$)	52,672.00
+ Margin on L,N Items 5.00% (\$\$)	2,528.50
Total Parts (\$\$)	55,200.50

K Kim Hin Auto Pte Ltd/GBH1552B/06/03/2018 10:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	600 800.00
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	200 50.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	600 120.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS.	New	800 150.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	100.00 ✓
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	240 280.00
7	TO REMOVE DOORS FITTINGS.	New	600 120.00
8	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	200 280.00 X
9	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	200 240.00 X
10	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	200 240.00
11	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	600 100.00
12	TO REMOVE AND RENEW EXHAUST SILENCER BOX.	New	200 280.00 ?
13	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	720 1,000.00
14	TO REMOVE AND RENEW FUEL INJECTOR AND COMMON RAIL. TO REWIRING AND RE-SETTING PROGRAM.	New	200 380.00 ?
15	TO REMOVE AND RENEW FRONT EXHAUST MUFFLER. TO REWIRING, RE-SETTING PROGRAM, REGENERATION DPF SYSTEM.	New	200 350.00 ?
Gross Labour Cost (S\$)			4,490.00

K Kim Hin Auto Pte Ltd/GBH1552B/06/03/2018 10:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Shiau Chan (LKKAuto)

From: survey@kkimhin.com.sg
Sent: Wednesday, 13 March 2019 12:21 PM
To: Shiau Chan (LKKAuto)
Subject: RE: VEHICLE GBH 1552B (DOA: 23/02/2018) FINALISATION
Attachments: P3135970.jpg; P3135960.jpg; P3135962.jpg; P3135963.jpg; P3135964.jpg; P3135965.jpg; P3135967.jpg; P3135968.jpg; P3135969.jpg; 20190316111406.pdf

Hi Ms Shiau Chan,

Enclosed your attention.
Please adjust REAR FREEZER BOX PRICE. ▲
Thank you.

Regard
Meng Huat
K.Kim Hin Auto

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 12 March 2019 4:10 PM
To: Simon <simon@kkimhin.com.sg>; Survey KKH <survey@kkimhin.com.sg>
Cc: KKH <service@kkimhin.com.sg>
Subject: RE: VEHICLE GBH 1552B (DOA: 23/02/2018)

Dear Simon & Meng Huat,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 23 January 2019 11:15 AM
To: Simon <simon@kkimhin.com.sg>; Survey KKH <survey@kkimhin.com.sg>
Cc: KKH <service@kkimhin.com.sg>
Subject: RE: VEHICLE GBH 1552B (DOA: 23/02/2018)

Dear Simon & Meng Huat,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

金興(龔)汽車私人有限公司160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3010991800	Date of Loss:	23/02/2018
Vehicle Reg. No.:	GBH1552B	Driveable?	
Driver Age/Info:	25 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TREEDOTS ENTERPRISE (PRIVATE LIMITED)	Contact No:	+6596986909
Driver:	LAU JIA CAI		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	06/02/2018
Vehicle Colour:	SILVER	Chassis No:	JTFAT35Y10K209660
Engine No:	1KD2769200		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	2+1/4		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

Not Authored
Repair B4 paint
*Ex 85501***COST OF CLAIMS**

	Amount
Parts	55,200.50
Miscellaneous Items	0.00
Labour	4,490.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	59,690.50
+ GST 7.00% (S\$)	4,178.34
Nett Amount (S\$)	63,868.84

This claim is handled by: WONG SHU MAN

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Mar 2018)
 Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: K Kim Hin Auto Pte Ltd/GBH1552B/06/03/2018 10:17
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	Bu/cu 0.00	0.00	*350.00 F ✓
2	1		*O/S FRONT BUMPER BRACKET	R 0.00	0.00	*110.00 F X
3	1		*O/S FRONT BUMPER FOG COVER	Sn 0.00	0.00	*35.00 F X
4	1		*O/S HEADLAMP ASSY	cm 0.00	0.00	*500.00 F ✓
5	1		*FRONT GRILLE	Sn 0.00	0.00	*320.00 F X
6	1		*O/S FRONT CORNER PANEL	cm 0.00	0.00	*110.00 F ✓
7	1		*O/S FRONT CORNER PANEL BRACKET	0.00	0.00	*40.00 F ?
8	1		*FRONT WINDSCREEN GLASS	Sn 0.00	0.00	*480.00 F X
9	1		*FRONT WINDSCREEN GLASS RUBBER	cu 0.00	0.00	*115.00 F ✓
10	1		*O/S FRONT DOOR	R 0.00	0.00	*630.00 F ✓
11	1		*O/S FRONT DOOR GLASS	Sn 0.00	0.00	*175.00 F X
12	1		*O/S FRONT DOOR GLASS RUN CHANNEL	Sn 0.00	0.00	*85.00 F X
13	1		*O/S FRONT DOOR GLASS OUTER MOULDING	Sn 0.00	0.00	*55.00 F X
14	1		*O/S FRONT DOOR GLASS REGULATOR	R 0.00	0.00	*100.00 F X
15	1		*O/S FRONT DOOR GLASS REGULATOR MOTOR	R 0.00	0.00	*195.00 F X
16	1		*O/S FRONT DOOR OUTER HANDLE	cu 0.00	0.00	*75.00 F ✓
17	1		*O/S FRONT DOOR WEATHERSTRIP	0.00	0.00	*75.00 F ?
18	1		*O/S FRONT DOOR LOCK	R 0.00	0.00	*125.00 F X
19	1		*O/S FRONT DOOR LOCK CATCH	R 0.00	0.00	*35.00 F X
20	1		*O/S FRONT DOOR LOWER RUBBER LID	cu 0.00	0.00	*55.00 F ✓
21	1		*O/S FRONT DOOR LOWER INNER SEAL	0.00	0.00	*35.00 F ?
22	1		*O/S FRONT DOOR STEP GARNISH	Bu/cu 0.00	0.00	*125.00 F ✓
23	1		*O/S FRONT DOOR FRAME	0.00	0.00	*380.00 F ?
24	1		*O/S FRONT DOOR FRAME TOYOTA D-4D EMBLEM	cu 0.00	0.00	*30.00 F X
25	1		*O/S WINGMIRROR ASSY	cm 0.00	0.00	*85.00 F ✓
26	1		*O/S FRONT MUDGUARD	cu 0.00	0.00	*165.00 F ✓
27	1		*O/S FRONT MUDFLAP	Sn 0.00	0.00	*85.00 F X
28	1		*N/S REAR MUDGUARD-FRONT	R 0.00	0.00	*165.00 F ✓
29	1		*N/S REAR MUDGUARD-REAR	R 0.00	0.00	*165.00 F ✓
30	1		*N/S REAR MUDFLAP	Sn 0.00	0.00	*85.00 F X
31	1		*N/S REAR WHEEL BEARING-INNER	0.00	0.00	*45.00 F ?
32	1		*N/S REAR WHEEL BEARING-OUTER	0.00	0.00	*45.00 F ?
33	1		*N/S REAR WHEEL BEARING OIL SEAL-INNER	0.00	0.00	*35.00 F ?
34	1		*N/S REAR WHEEL BEARING OIL SEAL-OUTER	0.00	0.00	*35.00 F ?
35	1		*N/S REAR AXLE SHAFT	0.00	0.00	*695.00 F ?
36	2		*REAR SHOCK ABSORBER (LH/RH)	0.00	0.00	*100.00 F ?
37	1		*REAR AXLE HOUSING	0.00	0.00	*2,850.00 F ?
38	1		*O/S FRONT SHOCK ABSORBER	Sn 0.00	0.00	*60.00 F X
39	1		*O/S FRONT UPPER ARM	Sn 0.00	0.00	*380.00 F ✓
40	1		*O/S KNUCKLE ARM	Sn 0.00	0.00	*280.00 F X
41	1		*O/S FRONT LOWER ARM	Sn 0.00	0.00	*225.00 F X
42	1		*O/S FRONT LOWER ARM BALL JOINT	Sn 0.00	0.00	*85.00 F X
43	1		*O/S FRONT WHEEL BEARING	Sn 0.00	0.00	*85.00 F X
44	1		*O/S FRONT BEARING HUB	Sn 0.00	0.00	*185.00 F X
45	4		*FUEL INJECTOR	0.00	0.00	*1,920.00 F ?
46	1		*COMMON RAIL	0.00	0.00	*750.00 F ?
47	1		*AIR FILTER	0.00	0.00	*45.00 F ?
48	1		*AIR FLOW SENSOR	0.00	0.00	*120.00 F ?

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
49	1		*TURBO ASSY	0.00	0.00	*2,200.00 F	7
50	1		*TURBO INTER COOLER	0.00	0.00	*780.00 F	7
51	1		*EGR VALVE	0.00	0.00	*220.00 F	7
52	1		*EGR COOLER	0.00	0.00	*285.00 F	7
53	2		*ENGINE MOUNTING (LH/RH)	0.00	0.00	<i>Sn</i> *120.00 F	X
54	1		*GEAR BOX MOUNTING	0.00	0.00	<i>Sn</i> *60.00 F	X
55	1		*FRONT EXHAUST MUFFLER	0.00	0.00	*880.00 F	7
56	1		*CENTRE EXHAUST MUFFLER	0.00	0.00	*650.00 F	7
57	2		*FRONT EXHAUST MUFFLER TEMPERATURE SENSOR	0.00	0.00	*450.00 F	7
58	1		*REAR FREEZER BOX <i>Injured ??</i> <i>Butler</i>	0.00	0.00	*32,000.00 F	7
59	1		*ERP BRACKET	0	0.00	<i>nn</i> *25.00 FS	X
60	1		*O/S FRONT DOOR COMPANY REGISTRATION STICKER	0	0.00	<i>nn</i> *25.00 FS	✓
61	1		*N/S REAR TYRE-OUTER	<i>nn</i> 0	0.00	*320.00 FS	✓
62	1		*N/S REAR RIM-OUTER	<i>nn</i> 0	0.00	*280.00 FS	✓
63	1		*O/S REAR TYRE-OUTER	<i>nn</i> 0	0.00	<i>Bz</i> *320.00 FS	X
64	1		*O/S REAR RIM-OUTER	<i>nn</i> 0	0.00	<i>nn</i> *280.00 FS	X
65	1		*O/S FRONT TYRE	0	0.00	<i>nn</i> *370.00 FS	X
66	1		*O/S FRONT RIM	0	0.00	<i>nn</i> *280.00 FS	X
67	1		*ENGINE OIL	0	0.00	<i>nn</i> *88.00 FS	✓
68	1		*POWER STEERING OIL	0	0.00	*65.00 FS	7
69	1		*RADIATOR COOLANT	0	0.00	*48.00 FS	7

F=Franchise part. S=SpecVett.

Sub Total (S\$)	52,672.00
+ Margin on L,N Items 5.00% (S\$)	2,528.50
Total Parts (S\$)	55,200.50

K Kim Hin Auto Pte Ltd/GBH1552B/06/03/2018 10:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

$\$2,485.00 - \text{Prof.}$
 $+ 5\%$
 $\$2,609.25$
 $\text{From } \$5000/\text{hr}$
 $\$2,140.00 - \text{Labour}$
 $\underline{\hspace{1cm}}$
 4

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	600 800.00
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	200 50.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	600 120.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS.	New	800 150.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	100.00 ✓
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	2800 280.00
7	TO REMOVE DOORS FITTINGS.	New	600 120.00
8	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	280.00 X
9	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES, TO REPLACE AFFECTED PORTIONS.	New	240.00 X
10	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	200 240.00
11	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	600 100.00
12	TO REMOVE AND RENEW EXHAUST SILENCER BOX.	New	280.00 ?
13	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	720 1,000.00
14	TO REMOVE AND RENEW FUEL INJECTOR AND COMMON RAIL. TO REWIRING AND RE-SETTING PROGRAM.	New	380.00 ?
15	TO REMOVE AND RENEW FRONT EXHAUST MUFFLER. TO REWIRING, RE-SETTING PROGRAM, REGENERATION DPF SYSTEM.	New	350.00 ?
Gross Labour Cost (S\$)			4,490.00

K Kim Hin Auto Pte Ltd/GBH1552B/06/03/2018 10:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTOCITY

SINGAPORE 575722

GBH1552B

SIMON

NO: DLI9200656

PAGE: 1

DATE: 12/03/2018

A/C CODE: LDKK241

TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 ✓ T52101-37985	FR BUMPER	DB2N	1	350.00	350.00
2 ✓ T81110-37660	HEADLAMP ASSY RH	DR2BB	1	500.00	500.00
3 ✓ T53813-37170-B0	FR SIDE PANEL	DBS	1	110.00	110.00
4 ✓ T55121-25040	W/S RUBBER FR	DBHOP	1	115.00	115.00
5 ✓ T67001-25051	DOOR FR RH	DBS	1	630.00	630.00
6 ✓ T69210-37020	OUTER HANDLE FR RH	DBH180	1	75.00	75.00
7 ✓ T51771-25020	STEP GARNISH RH	DBTAR15	1	125.00	125.00
8 ✓ T87910-25040	MIRROR RH	DBGN145	1	85.00	85.00
9 ✓ T66010-25040	FR MUDGUARD LH	DBHOP	1	165.00	165.00
10 ✓ T66010-95A04	RR MUDGUARD LH	DBHOP	1	165.00	165.00
11 ✓ T66010-95A04	RR MUDGUARD LH	DBHOP	1	165.00	165.00

TOTAL QUANTITY: 11 TOTAL: SIN 2,485.00

AED GST @ 7%: 173.95

GRAND TOTAL: SIN 2,658.95


#02-21

Print / MT / 12/03/2018 10:35:54 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



EC & OULET
PARTS





HWEE JAN (S) PTE LTD

Head Office: 82 Joo Koon Circle, Jurong Ind. Est., Singapore 629101. Tel: 6897 339 Fax: 6897 7337(Accs), 6863 4836(Sales), 6863 4632(Service)
Co. Reg. No.: 199201209N GST Reg. No.: 19-9201209-N Website: <http://www.hweejan.com.sg>
North Link Service Center: No. 10 Admiralty Street, #02-82 North Link Building, Singapore 757695. Tel/Fax: 6752 9339 Hotliner: 8139-8778

TAX INVOICE ORIGINAL

Customer Name / Address	
K0115	K.KIM HIN AUTO PTE LTD
	160 SIN MING DRIVE
	SIN MING AUTO CITY
	#02 20
	SINGAPORE 575722
	TEL:

Invoice No.
81513-0

Date
27-03-2018

Currency
SGD

Terms
NET DUE

P.O. / Work Order

Vehicle No.
GBH1552B

Vehicle Mileage

Running Hour

Confirmed By
MR KHONG

Serviced By
JOHNSON LIM C A

S/N	Item	Description	UoM	Qty	U/Price	Disc.	Amount
1	67960	DOOR GASKET 85MM	PC	8.00	0.00	0.00	0.00
2	MISEDE	NEW R.H SIDE STEEL FRAME	PC	1.00	0.00	0.00	0.00
3	DSP-06	DOOR SPRING OD 11.3 X W 1.3 SUS	PC	3.00	0.00	0.00	0.00
4	LAB-OTH	LABOUR CHARGE	NOS	1.00	4,300.00	0.00	4,300.00
~ TO CARRY OUT BOX REPAIR							
~ TO SUPPLY LABOUR, MATERIAL AND EQUIPMENT							
~ TO DISMANTLE ALL DOOR PANEL FOR REPLACE DOOR RUBBER GASKETS							
~ TO ENFORCE REAR RIGHT & LEFT DOOR PANEL WITH ALUMI. CHECKER PLATE.							
TIGHTENING WITH BOLTS AND NUTS							
~ TO CUT AND REPLACE DAMAGE FIBER BOARD (DRIVER & PASSENGER SIDE)							
~ TO PATCHING FIBER GLASS ON DAMAGE AREA , SMOOTHENING SURFACE							
~ TO CUT AND REPLACE DAMAGE ALUMI. CORNER GUARD							
~ TO CONCEAL INTERIOR AND EXTERIOR ON BOX							
~ TO CHECK DOOR ALIGNMENT							
~ TO CHECK AIR CON SYSTEM							
~ TO FINAL CLEANING							

UNDER BOX REPAIR							



Sub Total 4,300.00
GST(7%) 301.00
Total 4,601.00

- * Cheque should be crossed and made payable to HWEE JAN (S) PTE LTD.
- * Interest of 1% per month is chargeable for late payment.
- * I certified that the above service & price has been carried out to my entire satisfaction, unless notify within 3days, all work done will be deemed agreed.
- * Goods sold are not refundable or commodities exchange.

HWEE JAN (S) PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018 Sendback Est	06 Mar 2018 10:17 S\$59,690.50	06 Mar 2018 15:00 Edit Adj Rpt	S\$11,062.25 Edit Estimates	S\$11,062.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TREEDOTS ENTERPRISE (PRIVATE LIMITED), Co. Reg. No.: 201724120K, Tel: +6596986909		
Vehicle Reg. No.:	GBH1552B	Date of Loss:	23/02/2018 22:00 - :59 [17 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D01069C01	Policy/Cover Note No.:	DMCV5N3010991800 (Comprehensive) Coverage: 06/02/2018 - 05/02/2019
		Excess:	S\$550.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/03/2018]		
Driver/Custodian:	LAU JIA CAI (25 / Male) , NRIC: S92147722, Tel: +6596986909 Email: JIACAI@THETREEDOTS.COM		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPIING (02/10/2018): < No subject >
- CHINA_TAIPIING (08/03/2018): Alert - Adj Mandate Approved (S\$54109.75) - GBH1552B - Claim Handler: Adeline Ch...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBH1552B (SNM18D01069C01)

OD

Feb 23 2018 10:00PM

[TREEDOTS ENTERPRISE (PRIVATE LIMITED)]

K Kim Hin Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports

1 per page ☒

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 19:39	Accident Statement	 Load HTM	☐
2	06/03/18 10:17	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 09:01	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ☒

No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
2	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
3	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
4	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
5	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
6	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
7	27/02/18 19:36	Accident Photo [Linked Accident Report Documents]	 Load JPG ☒	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/19 15:54	General View	 Load JPG ☒	☒
2	14/03/19 15:54	General View	 Load JPG ☒	☒
3	14/03/19 15:54	General View	 Load JPG ☒	☒
4	14/03/19 15:54	General View	 Load JPG ☒	☒
5	14/03/19 15:54	General View	 Load JPG ☒	☒
6	14/03/19 15:54	General View	 Load JPG ☒	☒
7	14/03/19 15:54	General View	 Load JPG ☒	☒
8	14/03/19 15:54	General View	 Load JPG ☒	☒
9	14/03/19 15:54	General View	 Load JPG ☒	☒
10	14/03/19 15:54	General View	 Load JPG ☒	☒
11	14/03/19 15:54	General View	 Load JPG ☒	☒
12	14/03/19 15:54	General View	 Load JPG ☒	☒
13	14/03/19 15:54	General View	 Load JPG ☒	☒
14	14/03/19 15:54	General View	 Load JPG ☒	☒
15	14/03/19 15:54	General View	 Load JPG ☒	☒
16	14/03/19 15:54	General View	 Load JPG ☒	☒
17	14/03/19 15:54	General View	 Load JPG ☒	☒
18	14/03/19 15:54	General View	 Load JPG ☒	☒
19	14/03/19 15:54	General View	 Load JPG ☒	☒
20	14/03/19 15:54	General View	 Load JPG ☒	☒
21	14/03/19 15:54	General View	 Load JPG ☒	☒
22	14/03/19 15:54	General View	 Load JPG ☒	☒
23	14/03/19 15:54	General View	 Load JPG ☐	☐

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
				☒
24	14/03/19 15:54	General View	Load JPG	☒
25	14/03/19 15:54	General View	Load JPG	☒
26	14/03/19 15:54	General View	Load JPG	☒
27	14/03/19 15:54	General View	Load JPG	☒
28	14/03/19 15:54	General View	Load JPG	☒
29	14/03/19 15:54	General View	Load JPG	☒
30	14/03/19 15:54	General View	Load JPG	☒
31	14/03/19 15:54	General View	Load JPG	☒
32	14/03/19 15:54	General View	Load JPG	☒
33	14/03/19 15:54	General View	Load JPG	☒
34	14/03/19 15:54	General View	Load JPG	☒
35	14/03/19 15:54	General View	Load JPG	☒
36	14/03/19 15:54	General View	Load JPG	☒
37	14/03/19 15:54	General View	Load JPG	☒
38	14/03/19 15:54	General View	Load JPG	☒
39	14/03/19 15:54	General View	Load JPG	☒
40	14/03/19 15:54	General View	Load JPG	☒
41	14/03/19 15:54	General View	Load JPG	☒
42	14/03/19 15:54	General View	Load JPG	☒
43	14/03/19 15:54	General View	Load JPG	☒
44	14/03/19 15:54	General View	Load JPG	☒
45	14/03/19 15:54	Odometer Reading	Load JPG	☒
46	14/03/19 15:54	Chassis Number	Load JPG	☒
47	14/03/19 16:11	Reinspection Photo	Load JPG	☒
48	14/03/19 16:11	Reinspection Photo	Load JPG	☒
49	14/03/19 16:11	Reinspection Photo	Load JPG	☒
50	14/03/19 16:11	Reinspection Photo	Load JPG	☒
51	14/03/19 16:11	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 16:20	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	27/02/18 16:21	Police Report [Linked Accident Report Documents]	Load TIF	
3	06/03/18 10:16	Certificate of Insurance	Load PDF	
4	06/03/18 10:16	Driver's NRIC	Load PDF	
5	06/03/18 10:16	Log card (If available)	Load PDF	
6	06/03/18 10:16	TRANSFER FEE	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 15:05	ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 19:39	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 19:36	Accident Photo	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
2	27/02/18 19:36	Accident Photo		Load JPG	☒
3	27/02/18 19:36	Accident Photo		Load JPG	☒
4	27/02/18 19:36	Accident Photo		Load JPG	☒
5	27/02/18 19:36	Accident Photo		Load JPG	☒
6	27/02/18 19:36	Accident Photo		Load JPG	☒
7	27/02/18 19:36	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	27/02/18 16:20	Sketch Plan		Load TIF	
2	27/02/18 16:21	Police Report		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118004369/KQD3E2

Date: 25/03/2019

REFERENCE

Insured/Claimant:	TREEDOTS ENTERPRISE (PRIVATE LIMITED)	Policy No:	DMCVSN3010991800
Date of Loss:	23/02/2018	Nature of Claim:	OD
		Claim No:	SNM18D01069C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH1552B	Engine No:	1KD2769200
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y10K209660
Reg. Date:	06/02/2018 (Man. Year: 2017)	Odometer:	644 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,200.50	8,922.25	46,278.25	83.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,490.00	2,140.00	2,350.00	52.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	59,690.50	11,062.25	48,628.25	81.47
- Excess (S\$)	0.00	550.00	-550.00	
(S\$)	59,690.50	10,512.25	49,178.25	82.39
+ GST 7.00/7.00% (S\$)	4,178.34	735.86	3,442.48	82.39
Nett Amount (S\$)	63,868.84	11,248.11	52,620.73	82.39

INSPECTION

Date of Assignment:	06/03/2018 Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	07/03/2018 Inspected At:	K Kim Hin Auto Pte Ltd (HQ)
		160 Sin Ming Drive #02-20, Sin Ming
		AutoCity
		Singapore 575722
Estimated Period of Repair:	14.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Mar 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH1552B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER (WCP)	Buckled / Cut	350.00 F	*350.00 F
2	1	*O/S FRONT BUMPER BRACKET (WCP)	Repair	110.00 F	*- F
3	1	*O/S FRONT BUMPER FOG COVER (WCP)	Serviceable	35.00 F	*- F
4	1	*O/S HEADLAMP ASSY (WCP)	Cracked	500.00 F	*500.00 F
5	1	*FRONT GRILLE (WCP)	Serviceable	320.00 F	*- F
6	1	*O/S FRONT CORNER PANEL (WCP)	Cracked	110.00 F	*110.00 F
7	1	*O/S FRONT CORNER PANEL BRACKET (WCP)	Repair	40.00 F	*- F
8	1	*FRONT WINDSCREEN GLASS (WCP)	Serviceable	480.00 F	*- F
9	1	*FRONT WINDSCREEN GLASS RUBBER (WCP)	Cut	115.00 F	*115.00 F
10	1	*O/S FRONT DOOR (WCP)	Bent	630.00 F	*630.00 F
11	1	*O/S FRONT DOOR GLASS (WCP)	Serviceable	175.00 F	*- F
12	1	*O/S FRONT DOOR GLASS RUN CHANNEL (WCP)	Serviceable	85.00 F	*- F
13	1	*O/S FRONT DOOR GLASS OUTER MOULDING (WCP)	Serviceable	55.00 F	*- F
14	1	*O/S FRONT DOOR GLASS REGULATOR (WCP)	Repair	100.00 F	*- F
15	1	*O/S FRONT DOOR GLASS REGULATOR MOTOR (WCP)	Repair	195.00 F	*- F
16	1	*O/S FRONT DOOR OUTER HANDLE (WCP)	Cut	75.00 F	*75.00 F
17	1	*O/S FRONT DOOR WEATHERSTRIP (WCP)	Serviceable	75.00 F	*- F
18	1	*O/S FRONT DOOR LOCK (WCP)	Repair	125.00 F	*- F
19	1	*O/S FRONT DOOR LOCK CATCH (WCP)	Repair	35.00 F	*- F
20	1	*O/S FRONT DOOR LOWER RUBBER LID (WCP)	Serviceable	55.00 F	*- F
21	1	*O/S FRONT DOOR LOWER INNER SEAL (WCP)	Serviceable	35.00 F	*- F
22	1	*O/S FRONT DOOR STEP GARNISH (WCP)	Dented / Cut	125.00 F	*125.00 F
23	1	*O/S FRONT DOOR FRAME (WCP)	Serviceable	380.00 F	*- F
24	1		Not Necessary	30.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
		*O/S FRONT DOOR FRAME TOYOTA D-4D EMBLEM (WCP)			
25	1	*O/S WINGMIRROR ASSY (WCP)	Cracked	85.00 F	*85.00 F
26	1	*O/S FRONT MUDGUARD (WCP)	Cut	165.00 F	*165.00 F
27	1	*O/S FRONT MUDFLAP (WCP)	Serviceable	85.00 F	*- F
28	1	*N/S REAR MUDGUARD-FRONT (WCP)	Bent	165.00 F	*165.00 F
29	1	*N/S REAR MUDGUARD-REAR (WCP)	Buckled	165.00 F	*165.00 F
30	1	*N/S REAR MUDFLAP (WCP)	Serviceable	85.00 F	*- F
31	1	*N/S REAR WHEEL BEARING-INNER (WCP)	Serviceable	45.00 F	*- F
32	1	*N/S REAR WHEEL BEARING-OUTER (WCP)	Serviceable	45.00 F	*- F
33	1	*N/S REAR WHEEL BEARING OIL SEAL-INNER (WCP)	Serviceable	35.00 F	*- F
34	1	*N/S REAR WHEEL BEARING OIL SEAL-OUTER (WCP)	Serviceable	35.00 F	*- F
35	1	*N/S REAR AXLE SHAFT (WCP)	Serviceable	695.00 F	*- F
36	2	*REAR SHOCK ABSORBER (LH/RH) (WCP)	Serviceable	100.00 F	*- F
37	1	*REAR AXLE HOUSING (WCP)	Serviceable	2,850.00 F	*- F
38	1	*O/S FRONT SHOCK ABSORBER (WCP)	Serviceable	60.00 F	*- F
39	1	*O/S FRONT UPPER ARM (WCP)	Serviceable	380.00 F	*- F
40	1	*O/S KNUCKLE ARM (WCP)	Serviceable	280.00 F	*- F
41	1	*O/S FRONT LOWER ARM (WCP)	Serviceable	225.00 F	*- F
42	1	*O/S FRONT LOWER ARM BALL JOINT (WCP)	Serviceable	85.00 F	*- F
43	1	*O/S FRONT WHEEL BEARING (WCP)	Not Necessary	85.00 F	*- F
44	1	*O/S FRONT BEARING HUB (WCP)	Serviceable	185.00 F	*- F
45	4	*FUEL INJECTOR (WCP)	Serviceable	1,920.00 F	*- F
46	1	*COMMON RAIL (WCP)	Serviceable	750.00 F	*- F
47	1	*AIR FILTER (WCP)	Serviceable	45.00 F	*- F
48	1	*AIR FLOW SENSOR (WCP)	Serviceable	120.00 F	*- F
49	1	*TURBO ASSY (WCP)	Serviceable	2,200.00 F	*- F
50	1	*TURBO INTER COOLER (WCP)	Serviceable	780.00 F	*- F
51	1	*EGR VALVE (WCP)	Serviceable	220.00 F	*- F
52	1	*EGR COOLER (WCP)	Serviceable	285.00 F	*- F
53	2	*ENGINE MOUNTING (LH/RH) (WCP)	Serviceable	120.00 F	*- F
54	1	*GEAR BOX MOUNTING (WCP)	Serviceable	60.00 F	*- F
55	1	*FRONT EXHAUST MUFFLER (WCP)	Serviceable	880.00 F	*- F
Report was unsubmitted during this print-out.					

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	1	*CENTRE EXHAUST MUFFLER (WCP)	Serviceable	650.00 F	*- F
57	2	*FRONT EXHAUST MUFFLER TEMPERATURE SENSOR (WCP)	Serviceable	450.00 F	*- F
58	1	*REAR FREEZER BOX	Bent / Cracked	32,000.00 F	*5,000.00 FS
59	1	*ERP BRACKET	Not Necessary	26.00 FS	*- FS
60	1	*O/S FRONT DOOR COMPANY REGISTRATION STICKER	Necessary	25.00 FS	*25.00 FS
61	1	*N/S REAR TYRE-OUTER	Cut	320.00 FS	*320.00 FS
62	1	*N/S REAR RIM-OUTER	Dented	280.00 FS	*280.00 FS
63	1	*O/S REAR TYRE-OUTER	Cut	320.00 FS	*320.00 FS
64	1	*O/S REAR RIM-OUTER	Dented	280.00 FS	*280.00 FS
65	1	*O/S FRONT TYRE	Serviceable	370.00 FS	*- FS
66	1	*O/S FRONT RIM	Serviceable	280.00 FS	*- FS
67	1	*ENGINE OIL	Necessary	88.00 FS	*88.00 FS
68	1	*POWER STEERING OIL	Not Necessary	65.00 FS	*- FS
69	1	*RADIATOR COOLANT	Not Necessary	48.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	52,672.00	8,798.00
+ Margin on L,N Items 5.00/5.00% (S\$)	2,528.50	124.25
Total Parts (S\$)	55,200.50	8,922.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	800.00	600.00
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	50.00	20.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	120.00	60.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE REPAIRING WORKS.	New	150.00	80.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACUUM AND RECHARGE GAS.	New	100.00	100.00
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	280.00	240.00
7	TO REMOVE DOORS FITTINGS.	New	120.00	60.00
8	TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS.	New	280.00	0.00
9	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	240.00	0.00
10	TO DISMANTLE AND CHECK REAR UNDER-CARRIAGES. TO REPLACE AFFECTED PORTIONS.	New	240.00	200.00
11	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	100.00	60.00
12	TO REMOVE AND RENEW EXHAUST SILENCER BOX.	New	280.00	0.00
13	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,000.00	720.00
14	TO REMOVE AND RENEW FUEL INJECTOR AND COMMON RAIL. TO REWIRING AND RE-SETTING PROGRAM.	New	380.00	0.00
15	TO REMOVE AND RENEW FRONT EXHAUST MUFFLER. TO REWIRING, RE-SETTING PROGRAM, REGENERATION DPF SYSTEM.	New	350.00	0.00
Gross Labour Cost (S\$)			4,490.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >