

ASS. REC. BY:

REF:

CS/MS618004384/Sqbn2

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

Maiman

From (Person):

Jocelyn Ng

of

MSLH

Date/Time: 07032018 939am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLQ 42Y

Insured:

at Workshop m/s

Sin Yew Hup

Tel:

67600819

of

Blk D4 Yew Tee Ind Est 393M

Policy No:

P28932966 MPQ

Claim No:

551360

Sum Insured:

Excess:

\$3500.00

Make of Veh:

D.O.A.

03032018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

07032018 951am

Person Contacted:

Edwin

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 42Y - X
08/3/18 @ 4.17pm	revert to Jocelyn Ng via Maiman.
17/3/18 @ 9.05am	Ming Shao informed C/A via Maiman.
14/3/18 @ 9.05am	Inform Yung Jian C/A of exs \$3500 by email.
14/5/18 @ 12.06pm	2nd revert to Jocelyn Ng via Maiman. (Supplementary).
17/5/18 @ 1.21pm	Ceng ong informed C/A of \$17960.67 via Maiman.

17/5

OD. MSIG Rev Excess: \$3500

REF: _____

Signature: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value: 115K *RS*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ424 Yr Regn: 2010, Aug 24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Cayennes (V8) c.c. 4806

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 150201 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP1ZZZ92ZBLA12335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/30 ZR22

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>3/3/18</u>		D.O.I. <u>7/3/18</u>

Survey held at Sin Yew Hup

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S, N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Sebastian finalised final fig @ 17960.67 (Red @ 4301.01, 1972.)</u>

RECEIVED 18 MAY 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) 18/5/18 THMGA ☐ : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: MEP-00

Lump Sum / I.B.I: (\$) 17960.67

Days Of Repair: 9

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

300
10

310

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. _____

☐ : Interview (\$ _____) Photos _____

☐ : Tech. Invs (\$ _____) Others _____

☐ : Weekend (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004384/Sqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 07-03-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLQ 42Y
Policy No.	P28932966MPQ	Coverage (\$)	0.00
Claim No.	551360	Excess (\$)	3,500.00
Assign From	MERIMEN (JOCELYN NG)	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/03/2018	Inspection Date	07/03/2018
Survey held at	SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 14 May 2018

Preliminary Advice

Vehicle No	: SLQ42Y	Accident Date	: 03/03/2018
Make	: PORSCHE CAYENNE	Policy No.	: P28932966MPQ
Assignment Date	: 07/03/2018	Excess	: S\$3,500.00
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 9.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,261.68	(ESTIMATE \$20,621.50 + SUPPLEMENTARY 1 \$935.00 + SUPPLEMENTARY 2 \$440.00 + SUPPLEMENTARY 3 \$110.00 + SUPPLEMENTARY 4 \$155.18)
Revised Amount	:S\$	17,960.67	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	17,960.67	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	72,151.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,849.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 08 Mar 2018

Preliminary Advice

Vehicle No	: SLQ42Y	Accident Date	: 03/03/2018
Make	: PORSCHE CAYENNE	Policy No.	: P28932966MPQ
Assignment Date	: 07/03/2018	Excess	: S\$3,500.00
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 9.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,621.50
Revised Amount	:S\$	12,424.50
Check Items (Estimated)	:S\$	7,557.00
Total	:S\$	19,981.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	72,151.00
Salvage Value	:S\$	
Margin for Repair	:S\$	42,849.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Mar 2018 Sendback Est	06 Mar 2018 16:09 S\$20,621.50	07 Mar 2018 09:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	THE STRAITS INTERNATIONAL PTE LTD, Co. Reg. No.: 201025898Z		
Vehicle Reg. No.:	SLQ42Y	Date of Loss:	03/03/2018 21:00 - :59
Claim Type:	OD / 551360	Policy/Cover Note No.:	P28932966MPQ (Comprehensive) Coverage: 04/04/2017 - 03/04/2018
		Excess:	\$43,500.00
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/03/2018]		
Driver/Custodian:	KEE KAH RONG, CYNTHIA (31 / Female), NRIC: S8627324A, Tel: +6591145706		
Adj Asg. Remarks:	Please revert, thank you		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Mar 2018 11:01	Clim Veh Model Changed	(200728) PORSCHE CAYENNE S.	[I] Jocelyn Ng Shin Bun
2	06 Mar 2018 11:01	Clim Created	Reg No: SLQ42Y. Policy No: P28932966MPQ. Acct Date: 2018/03/03. Claim Type: S C. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MSYH18030575	[I] Jocelyn Ng Shin Bun
3	06 Mar 2018 15:21	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[J] Edwin Yap Kiat Beng
4	06 Mar 2018 16:09	Clim Submitted	20621.50.	[R] Lim Jing Yee
5	06 Mar 2018 16:53	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert, thank you	[I] Jocelyn Ng Shin Bun
6	06 Mar 2018 16:53	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/07	[I] Jocelyn Ng Shin Bun
7	06 Mar 2018 16:53	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
8	07 Mar 2018 09:25	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	07 Mar 2018 09:37	Adj Assignment Cancelled	Car in, IHS unable to attend (ET-East side, AL-MC, DC-No survey till further instruct ion)	[I] Jocelyn Ng Shin Bun
10	07 Mar 2018 09:37	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
11	07 Mar 2018 09:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you	[I] Jocelyn Ng Shin Bun
12	07 Mar 2018 09:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/08	[I] Jocelyn Ng Shin Bun
13	07 Mar 2018 09:39	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
14	07 Mar 2018 09:50	Assignment 1st Accessed		[A] DENISE TAY KWEE CHENG
15	07 Mar 2018 14:37	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wai Keen	[A] CATHERINE CHONG KAI LING
16	08 Mar 2018 14:02	Adj Rpt Initiated		[A] SHIAU CHAN
17	08 Mar 2018 16:16	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/06	[A] SHIAU CHAN
18	08 Mar 2018 16:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/06	[A] SHIAU CHAN
19	08 Mar 2018 16:17	Adj Mandate Request	Cur.Req:19981.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	12 Mar 2018 09:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/06. Mandate Remarks: CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao
21	12 Mar 2018 09:25	Adj Mandate Set	Approved:12424.50:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao
22	14 Mar 2018 16:04	Clim Supp Created (S:691776)		[R] Lim Jing Yee
23	14 Mar 2018 16:09	Clim Submitted (S:691776)	935.00.	[R] Lim Jing Yee
24	14 Mar 2018 16:09	Adj Co Assigned (S:691776)	LKK Auto Consultants Pte Ltd (HQ):	[R] Merimen Administrator
25	14 Mar 2018 17:16	Supp Combined (S:691776)		[A] SHIAU CHAN
26	15 Mar 2018 15:54	Clim Supp Created (S:692111)		[R] Lim Jing Yee
27	15 Mar 2018 16:47	Clim Submitted (S:692111)	440.00.	[R] Lim Jing Yee
28	15 Mar 2018 16:47	Adj Co Assigned (S:692111)	LKK Auto Consultants Pte Ltd (HQ):	[R] Merimen Administrator
29	16 Mar 2018 09:01	Supp Combined (S:692111)		[A] SHIAU CHAN
30	06 Apr 2018 10:41	Clim Supp Created (S:698188)		[R] Lim Jing Yee
31	06 Apr 2018 10:43	Clim Submitted (S:698188)	110.00.	[R] Lim Jing Yee
32	06 Apr 2018 10:43	Adj Co Assigned (S:698188)	LKK Auto Consultants Pte Ltd (HQ):	[R] Merimen Administrator
33	10 Apr 2018 11:27	Supp Combined (S:698188)		[A] SHIAU CHAN
34	14 Apr 2018 09:30	Clim Supp Created (S:700327)		[R] Lim Jing Yee
35	14 Apr 2018 09:34	Clim Submitted (S:700327)	155.18.	[R] Lim Jing Yee
36	14 Apr 2018 09:34	Adj Co Assigned (S:700327)	LKK Auto Consultants Pte Ltd (HQ):	[R] Merimen Administrator

AUDIT TRAIL				
No.	On	Audit	Remarks	By
37	19 Apr 2018 17:41	Supp Combined (S:700327)		[A] SHIAU CHAN
38	14 May 2018 12:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/06	[A] SHIAU CHAN
39	14 May 2018 12:06	Adj Mandate Request	Cur.Req:17960.67:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
40	17 May 2018 13:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/06. Mandate Remarks: CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Keny Ong Thiam Beng
41	17 May 2018 13:21	Adj Mandate Set	Approved:17960.67:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Keny Ong Thiam Beng

Date From  Date To  Audit Type None  Go

ACTIVITY

[07/03/2018 09:27] Pauline Soh Li Ping:
Car in, IHS unable to attend (ET-East side, AL-MC, DC-No survey till further instruction)

Merimen Billing for this case - Transaction History							
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1740782	06/03/2018 15:21	Motor	Sin Yew Hup Auto Pte Ltd	Sin Yew Hup Auto Pte Ltd (HQ)	SLQ42Y		xx.xx
1743079	08/03/2018 14:02	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLQ42Y		10.70

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 12 March 2018 9:56 AM
To: sinyewhup@gmail.com
Cc: SUR
Subject: VEHICLE SLQ 42Y (DOA: 03/03/2018)

Dear Yong Jian,

As spoken with you.

As instructed by our client MSIG , please proceed to repair the insured vehicle **SLQ 42Y (Excess \$3,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	06 Mar 2018 11:01	Clim Veh Model Changed	(200728) PORSCHE CAYENNE S.		[I] Jocelyn Ng Shin Bun
2	06 Mar 2018 11:01	Clim Created	Reg No: SLQ42Y. Policy No: P28932966MPQ. Acct Date: 2018/03/03. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MSYH18030575		[I] Jocelyn Ng Shin Bun
3	06 Mar 2018 15:21	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.		[] Edwin Yap Kiat Beng
4	06 Mar 2018 16:09	Clim Submitted	20621.50.		[R] Lim Jing Yee
5	06 Mar 2018 16:53	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert, thank you		[I] Jocelyn Ng Shin Bun
6	06 Mar 2018 16:53	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/07		[I] Jocelyn Ng Shin Bun
7	06 Mar 2018 16:53	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Jocelyn Ng Shin Bun
8	07 Mar 2018 09:25	Assignment 1st Accessed			[A] Pauline Soh Li Ping
9	07 Mar 2018 09:37	Adj Assignment Cancelled	Car in, IHS unable to attend (ET-East side, AL-MC, DC-No survey till further instruction)		[I] Jocelyn Ng Shin Bun
10	07 Mar 2018 09:37	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment		[I] Jocelyn Ng Shin Bun
11	07 Mar 2018 09:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you		[I] Jocelyn Ng Shin Bun
12	07 Mar 2018 09:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/08		[I] Jocelyn Ng Shin Bun
13	07 Mar 2018 09:39	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.		[I] Jocelyn Ng Shin Bun
14	07 Mar 2018 09:50	Assignment 1st Accessed			[A] DENISE TAY KWEE CHENG
15	07 Mar 2018 14:37	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wai Keen		[A] CATHERINE CHONG KAI LING
16	08 Mar 2018 14:02	Adj Rpt Initiated			[A] SHIAU CHAN
17	08 Mar 2018 16:16	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/06		[A] SHIAU CHAN
18	08 Mar 2018 16:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/06		[A] SHIAU CHAN
19	08 Mar 2018 16:17	Adj Mandate Request	Cur.Req:19981.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
20	12 Mar 2018 09:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/06. Mandate Remarks: CHECK ITEMS TO BE VERIFIED AND CONFIRMED.		[I] Koh Ming Shao
21	12 Mar 2018 09:25	Adj Mandate Set	Approved:12424.50:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.		[I] Koh Ming Shao

ACTIVITY

[07/03/2018 09:27] Pauline Soh Li Ping:
Car in, IHS unable to attend (ET-East side, AL-MC, DC-No survey till further instruction)

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1740782	06/03/2018 15:21	Motor	Sin Yew Hup Auto Pte Ltd	Sin Yew Hup Auto Pte Ltd (HQ)	SLQ42Y		xx.xx
1743079	08/03/2018 14:02	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLQ42Y		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5898Z
Vehicle Details	
Vehicle No.:	SLQ42Y
Vehicle to be Exported:	No
Intended De-registration Date:	08 Mar 2018
Vehicle Make:	PORSCHE
Vehicle Model:	CAYENNE S (V8)
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	B02591
Chassis No.:	WP1ZZZ92ZBLA42335
Maximum Power Output:	294.0 kW (394 bhp)
Open Market Value:	\$102,508.00
Original Registration Date:	24 Aug 2010
First Registration Date:	24 Aug 2010
Transfer Count:	2
Actual ARF Paid:	\$102,508.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2020
PARF Rebate Amount:	\$61,504.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2020
COE Category:	B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$43,334.00
COE Rebate Amount:	\$10,647.00
Total Rebate Amount:	\$72,151.00

The information contained herein is correct as at 08 Mar 2018

OK

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Mar 2018)
Parts: M1-SUV PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/03/2018 16:09
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ CRK	0.00	0.00	*1,200.00 F
2	1		*FRONT BUMPER TOWING COVER RH ✓ MS	0.00	0.00	*75.00 F
3	1		*FRONT BUMPER LOWER CENTER GARNISH ? ✓ CRA	0.00	0.00	*60.00 F
4	1		*FRONT BUMPER LOWER LH GARNISH ✓ MS	0.00	0.00	*55.00 F
5	1		*FRONT BUMPER UNDERCOVER ✓ BT	0.00	0.00	*700.00 F
6	2		*FRONT BUMPER SIDE HOLDER ✓ CRK RH XNN	0.00	0.00	*160.00 F
7	1		*FRONT BUMPER INNER GARNISH LH ? ✓ CRA	0.00	0.00	*135.00 F
8	1		*FRONT BUMPER INNER QUARTER GARNISH ? ✓ CRA	0.00	0.00	*230.00 F
9	2		*FRONT BUMPER CENTER RETAINER ? ✓ Defen	0.00	0.00	*100.00 F
10	2		*FRONT BUMPER CENTER RETAINER BRACKET ? ✓ Defen	0.00	0.00	*100.00 F
11	2		*FRONT BUMPER CENTER INNER LOWER GARNISH ? ✓ DE	0.00	0.00	*400.00 F
12	1		*FRONT BUMPER INNER TOP GARNISH ? ✓ Defen	0.00	0.00	*75.00 F
13	2		*FRONT BUMPER OUTER SIDE RETAINER ? RH XNN LH CRA	0.00	0.00	*120.00 F
14	2		*FRONT BUMPER INNER SIDE RETAINER ? RH XNN LH CRA	0.00	0.00	*120.00 F
15	20		*FRONT BUMPER RIVET ✓ MS	0.00	0.00	*100.00 F XNN
16	2		*HEADLAMP LA CRK ✓ ✓ CRA	0.00	0.00	*6,000.00 F
17	1		*FRONT BUMPER DAYLIGHT LH ✓ SCR	0.00	0.00	*850.00 F
18	1		*FRONT BUMPER FOG LAMP LH ?	0.00	0.00	*110.00 F XNN
19	1		*HEADLAMP WASHER COVER LH ✓ MS	0.00	0.00	*75.00 F
20	1		*HEADLAMP WASHER NOZZLE LH ? ✓ PMG	0.00	0.00	*160.00 F
21	1		*HEADLAMP WASHER NOZZLE HEAD LH ? ✓ PMG	0.00	0.00	*70.00 F
22	1		*FRONT SUPPORT TOP PANEL ? ✓ CRA	0.00	0.00	*570.00 F
23	1		*FRONT SUPPORT TOP PANEL BRACKET ? ✓ CRA	0.00	0.00	*150.00 F
24	1		*FRONT BUMPER REINFORCEMENT ? XNN	0.00	0.00	*1,400.00 F
25	1		*FRONT FENDER LH ✓ BT	0.00	0.00	*1,200.00 F
26	1		*FRONT FENDER BRACKET A ? XNN	0.00	0.00	*40.00 F
27	1		*FRONT FENDER BRACKET B ? XNN	0.00	0.00	*30.00 F
28	1		*FRONT FENDER FENDER ARCH GARNISH LH ✓ SCR	0.00	0.00	*450.00 F
29	10		*FRONT FENDER FENDER ARCH GARNISH LH CLIP ✓ MS	0.00	0.00	*30.00 F XNN
30	1		*FRONT WHEEL RIM LH ✓ MS	0.00	0.00	*1,400.00 F R
31	1		*NUMBER PLATE ✓ CRK	0	0.00	*30.00 FS
32	1		*FRONT BUMPER SIDE INDICATOR LH ✓ SCR	0.00	0.00	*100.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	16,295.00
+ Margin on L,N Items 10.00% (\$\$)	1,626.50
Total Parts (\$\$)	17,921.50

Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/03/2018 16:09. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PUTTY AND SPRAY PAINT FRONT BONNET IN & OUT, FRONT BUMPER, FRONT FENDER LH, WHEELHOUSE LH	New	1,400.00
2	TO CHECK WHEEL ALIGNMENT	New	100.00
3	TO REMOVE AND REFIT FRONT BUMPER, FRONT FENDER LH, HEADLAMP, FRONT BUMPER REINFORCEMENT, FRONT WHEEL RIM AND DAMAGED PARTS, PANEL BEAT WHEELHOUSE LH	New	1,200.00
Gross Labour Cost (S\$)			2,700.00

Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/03/2018 16:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

9 days.

Sebastian.
7/3/18.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

90036121

Sebastianyeang@lkkauto.com

Excess: \$ 3500

Revert.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


12/3/18

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Mar 2018)
 Parts: M1-SUV PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/03/2018 16:09

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	17569 (8)	*FRONT BUMPER ✓ CRK	0.00	0.00	*1,200.00 F ✓
2	1	17569 (10)	*FRONT BUMPER TOWING COVER RH ✓ MS	0.00	0.00	*75.00 F ✓
3	1	05289 (5)	*FRONT BUMPER LOWER CENTER GARNISH ? ✓ CRK	0.00	0.00	*60.00 F ✓
4	1	17569 (15)	*FRONT BUMPER LOWER LH GARNISH ✓ MS	0.00	0.00	*55.00 F ✓
5	1	17569 (13)	*FRONT BUMPER UNDERCOVER ✓ BT	0.00	0.00	*700.00 F ✓
6	18	17569 (14)	*FRONT BUMPER SIDE HOLDER ✓ CRK RH X, LH ✓ CRK	0.00	0.00	*160.00 F 80.00 ✓
7	1	17569 (15)	*FRONT BUMPER INNER GARNISH LH ? ✓ CRK	0.00	0.00	*135.00 F ✓
8	1	17569 (16)	*FRONT BUMPER INNER QUARTER GARNISH ? ✓ CRK	0.00	0.00	*230.00 F ✓
9	2	17569 (18)	*FRONT BUMPER CENTER RETAINER ? ✓ 17819 (1)	0.00	0.00	*100.00 F ✓
10	2	17569 (18) (20)	*FRONT BUMPER CENTER RETAINER BRACKET ? ✓	0.00	0.00	*100.00 F ✓
11	21	17569 (21)	*FRONT BUMPER CENTER INNER LOWER GARNISH ? ✓ Defam	0.00	0.00	*400.00 F 260.00 ✓
12	1	17569 (25)	*FRONT BUMPER INNER TOP GARNISH ? ✓ sponge	0.00	0.00	*75.00 F ✓
13	12	17569 (23)	*FRONT BUMPER OUTER SIDE RETAINER ? RH X, LH ✓ CRK	0.00	0.00	*120.00 F 60.00 ✓
14	12	17569 (23)	*FRONT BUMPER INNER SIDE RETAINER ? RH X, LH ✓ CRK	0.00	0.00	*120.00 F 60.00 ✓
15	20		*FRONT BUMPER RIVET ✓ NCC	0.00	0.00	*100.00 F
16	2	17569 (1) (2)	*HEADLAMP LH CRK ✓ RH ? ✓ CRK	0.00	0.00	*6,000.00 F ✓
17	1	05289 (6)	*FRONT BUMPER DAYLIGHT LH ✓ SCR	0.00	0.00	*850.00 F ✓
18	1		*FRONT BUMPER FOG LAMP LH ?	0.00	0.00	*110.00 F
19	1	17569 (25)	*HEADLAMP WASHER COVER LH ✓ MS	0.00	0.00	*75.00 F ✓
20	1	17569 (26)	*HEADLAMP WASHER NOZZLE LH ? ✓ Orig	0.00	0.00	*160.00 F ✓
21	1	17569 (27)	*HEADLAMP WASHER NOZZLE HEAD LH ? ✓ Orig	0.00	0.00	*70.00 F ✓
22	1	17569 (28)	*FRONT SUPPORT TOP PANEL ? ✓ CRK	0.00	0.00	*570.00 F ✓
23	1	17569 (33)	*FRONT SUPPORT TOP PANEL BRACKET ? ✓ CRK	0.00	0.00	*150.00 F ✓
24	1		*FRONT BUMPER REINFORCEMENT ? X	0.00	0.00	*1,400.00 F
25	1	17569 (24)	*FRONT FENDER LH ✓ BT	0.00	0.00	*1,200.00 F ✓
26	1		*FRONT FENDER BRACKET A ? X	0.00	0.00	*40.00 F
27	1		*FRONT FENDER BRACKET B ? X	0.00	0.00	*30.00 F
28	1	17569 (30)	*FRONT FENDER FENDER ARCH GARNISH LH ✓ SCR	0.00	0.00	*450.00 F ✓
29	10		*FRONT FENDER FENDER ARCH GARNISH LH CLIP ✓ NCC	0.00	0.00	*30.00 F
30	1		*FRONT WHEEL RIM LH ✓ CRK	0.00	0.00	*1,400.00 F
31	1		*NUMBER PLATE ✓ CRK	0	0.00	*30.00 FS
32	1	17569 (6)	*FRONT BUMPER SIDE INDICATOR LH ✓ SCR	0.00	0.00	*100.00 F ✓

F=Franchise part, S=SpcNett.

Sub Total (S\$) ~~10,295.00~~
 + Margin on L,N Items 10.00% (S\$) 1,626.50
 Total Parts (S\$) 17,921.50

Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/03/2018 16:09. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Total Part 12,755.00 ✓

S.N. 30.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Mar 2018)
Parts: M1-SUV PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sin Yew Hup Auto Pte Ltd/SLQ42Y/14/03/2018 16:09
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	17734	*FRONT BUMPER CENTER INNER GRILLE ✓ Defor	0.00	0.00	*200.00 F ✓
2	1	17569	*HEADLAMP PROTECTOR CAP ✓ NR ✓ LH	0.00	0.00	*160.00 F ✓
3	1	17569	*HEADLAMP BRACKET LH ✓ Defor	0.00	0.00	*50.00 F ✓
4	1	17569	*HEADLAMP MOUNTING BRACKET LH ✓ Defor	0.00	0.00	*320.00 F ✓
5	1	17569	*FRONT SUPPORT PANEL TOP GARNISH ✓ Defor	0.00	0.00	*120.00 F ✓
Sub Total (S\$)						850.00 ✓
+ Margin on L,N Items 10.00% (S\$)						85.00
Total Parts (S\$)						935.00

F=Franchise part.

Sin Yew Hup Auto Pte Ltd/SLQ42Y/14/03/2018 16:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2018)

Parts: M1-SUV PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/SLQ42Y/15/03/2018 16:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	① 17969	*FRONT BUMPER FOG LAMP LH ✓	0.00	0.00	*400.00 ✓
F=Franchise part.						
Sub Total (S\$)						400.00 ✓
+ Margin on L,N Items 10.00% (S\$)						40.00
Total Parts (S\$)						440.00

Sin Yew Hup Auto Pte Ltd/SLQ42Y/15/03/2018 16:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Apr 2018)

Parts: M1-SUV PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/04/2018 10:43

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	05289 ①	*Front bumper moulding LH upper ✓ Defens	0.00	0.00	*50.00 F ✓
2	1	05289 ②	*Front bumper moulding LH lower ✓ Defens	0.00	0.00	*50.00 F ✓
Sub Total (S\$)						100.00 ✓
+ Margin on L,N Items 10.00% (S\$)						10.00
Total Parts (S\$)						110.00

F=Franchise part.

Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/04/2018 10:43. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Apr 2018)
 Parts: M1-SUV PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sin Yew Hup Auto Pte Ltd/SLQ42Y/14/04/2018 09:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*HEADLAMP LH BULB <i>V NEC</i>	0.00	0.00	*141.07 F
						Sub Total (S\$) 141.07 ✓
						+ Margin on L,N Items 10.00% (S\$) 14.11
						Total Parts (S\$) 155.18

Sin Yew Hup Auto Pte Ltd/SLQ42Y/14/04/2018 09:34. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Total Part 1 : 12,755.00 ✓
 Supp 1 : 850.00 ✓
 Supp 2 : 400.00 ✓
 Supp 3 : 100.00 ✓
 Supp 4 : 141.07 ✓
 14,246.07 ✓
 Markup 10% 1,424.60
 15,670.67 ✓
 S.N.I 30.00
 15,700.67 ✓
 Labour 2,060.00 ✓
 Repair Rim 200.00
 17,960.67 ✓

Total 17,960.67
 Excess 3,500.00
 14,460.67 ✓ before GST

Sebastian
 10/5/18

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO PUTTY AND SPRAY PAINT FRONT BONNET IN & OUT, FRONT BUMPER, FRONT FENDER LH, WHEELHOUSE LH	New	1,400.00
2	TO CHECK WHEEL ALIGNMENT	New	60 100.00
3	TO REMOVE AND REFIT FRONT BUMPER, FRONT FENDER LH, HEADLAMP, FRONT BUMPER REINFORCEMENT, FRONT WHEEL RIM AND DAMAGED PARTS, PANEL BEAT WHEELHOUSE LH	New	1,290.00
			1000
Gross Labour Cost (S\$)			2,700.00

Sin Yew Hup Auto Pte Ltd/SLQ42Y/06/03/2018 16:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

9 days.

Sebastian.
7/3/18.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

90036121

Sebastianyeang@lkkauto.com

Excess: \$ 3500

Revert.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rabul Ckk
13/08/18



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M

SIN YEW HUP AUTO PTE LTD
BLK.4 393M WOODLAND ROAD YEW TEE INDS EST
SINGAPORE 677981

TEL : 7600819 FAX : 7690221
ATTN : YONG JIAN

WIPAC
Dept Direct: 6417 9791 / 6743 9329



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blade: NWB (Nippon Wiper blade), Silver (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201803-17739
DATE : 31/03/2018
CUSTOMER ID : SIN016
VEH REG. NO. : ZZ92ZBLA42335
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 958 505 973 00 9B9	FRT BUMPER GRILLE MLDG (CENTRE)	U1	1	200.00	200.00

SUB-TOTAL : 200.00
ADD GST 7.00 % 14.00

E. & O.E TOTAL AMOUNT SGD : 214.00

[P] 31/03/2018 1:32:41PM

[E] 31/03/2018 11:27:35AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHONG



* AR 201803-17739 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9708 / 6745 9225



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9707

Wiper blade: NWB (Nippon Wiper blade), Seiper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SIN YEW HUP AUTO PTE LTD
BLK.4 393M WOODLAND ROAD YEW TEE INDS EST
SINGAPORE 677981

TEL : 7600819 FAX : 7690221
ATTN : YONG JIAN

TAX INVOICE : AR201804-05289
DATE : 10/04/2018
CUSTOMER ID : SIN016
VEH REG. NO. : ZZ92ZBLA42335
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	958 505 685 00 9B9	FRT LH UPPER BUMPER LAMINA	UI	1	50.00	50.00
2	958 505 877 00 9B9	FRT BUMPER LH GARNISH LOWER	UI	1	50.00	50.00
3	958 505 686 00 9B9	RH FRT UPPER BUMPER LAMINA	UI	1	50.00	50.00
4	958 505 878 00 9B9	FRT BUMPER GARNISH RH	UI	1	50.00	50.00
5	958 701 105 00/10 9B9	FRT NO PLATE BRACKET	UI	1	60.00	60.00
6	958 631 181 00	FRT BUMPER LAMP LH	UI	1	850.00	850.00

1,010.00

SUB-TOTAL : 1,116.00
ADD GST 7.00 % 77.70

E. & O.E

TOTAL AMOUNT SGD : 1,187.70

[P] 10/04/2018 11:01:47AM

[E] 10/04/2018 10:57:49AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive : CHONG



* AR201804-05289 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SIN YEW HUP AUTO PTE LTD

BLK 4 393M WOODLAND ROAD YEW TEE INDS EST

SINGAPORE 677981

TEL : 7600819 FAX : 7690221

ATTN : YONG JIAN

WIPER BLADES
Dept Direct: 6417 9791 / 6745 9929



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9795

Dept Direct: 6417 9793

Wiper blade: NNB (Nippon Wiper blade), Silper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201803-17569

DATE : 31/03/2018

CUSTOMER ID : SIN016

VEH REG. NO. : ZZ92ZBLA42335

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 3

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 958 631 177 01	HEAPLAMP LH	U1	1	3000.00	3,000.00
	SUPPLIER				
2. 958 631 178 01	RH HEAPLAMP	U1	1	3000.00	3,000.00
	SUPPLIER				
3. 958 631 237 00	HEAD LAMP PROTECTIVE CAP LH	U1	1	160.00	160.00
	SUPPLIER				
4. 958 631 194 02	LH LWR HEADLAMP BKT	U1	1	50.00	50.00
	SUPPLIER				
5. 958 631 519 00	LH HEADLAMP MOUNTING	U1	1	320.00	320.00
	SUPPLIER				
6. 958 631 101 00	FRT FENDER SIGNAL LH	U1	1	100.00	100.00
	SUPPLIER				
7. 955 631 163 00	FOG LAMP LH	U1	1	400.00	400.00
	SUPPLIER				
8. 958 505 221 31 G2L	FRT BUMPER	U1	1	1200.00	1,200.00
	SUPPLIER				
9. 958 505 155 00 G2L	FRT LH BUMPER CAP	U1	1	75.00	75.00
	SUPPLIER				
10. 958 505 156 00 G2L	RH FRT BUMPER CAP	U1	1	75.00	75.00
	SUPPLIER				
11. 958 701 105 00/10 9B9	FRT NO PLATE BRACKET	U1	1	60.00	60.00
	SUPPLIER				
12. 958 505 887 01 9B9	FRT LH SPOILER	U1	1	55.00	55.00
	SUPPLIER				
13. 958 505 061 00	FRT SPOILER UPPER PART	U1	1	700.00	700.00
	SUPPLIER				
14. 958 505 177 00	FRT BUMPER BKT LH	U1	1	80.00	80.00
	SUPPLIER				
15. 958 505 681 00	FRT LH BUMPER GRILLE	U1	1	135.00	135.00
	SUPPLIER				
16. 958 505 333 00 9B9	FRT LH BUMPER AIR GUIDE	U1	1	230.00	230.00
	SUPPLIER				

CONTINUE NEXT PAGE

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SIN YEW HUP AUTO PTE LTD
BLK.4 393M WOODLAND ROAD YEW TEE INDS EST
SINGAPORE 677981

TEL : 7600819 FAX : 7690221
ATTN : YONG JIAN

Arrange By _____ Driver _____
Dept Direct: 6417 9791 / 6745 5552



Wiper blade: NWB (Nippon Wiper blade), Skipper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201803-17569
DATE : 31/03/2018
CUSTOMER ID : SIN016
VEH REG. NO. : ZZ92ZBLA42335
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 3
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
17. 958 505 334 00 9B9	RH FRT BUMPER AIR GUIDE	U1	1	230.00	230.00
	SUPPLIER				
18. 958 505 829 00	BUMPER BRACKET R/L I SEE SAMPLE	U1	1	50.00	50.00
	SUPPLIER				
19. 958 505 245 00	FRT LH WATER DEFLECTOR	U1	1	50.00	50.00
	SUPPLIER				
20. 958 505 246 00	RH FRT WATER DEFLECTOR	U1	1	50.00	50.00
	SUPPLIER				
21. 958 505 550 01	FRT BUMPER FOAM	U1	1	75.00	75.00
	SUPPLIER				
22. 958 505 889 00	FRT HEADLAMP BKT LH	U1	1	60.00	60.00
	SUPPLIER				
23. 958 505 049 00	FRT LH BUMPER BRACKET	U1	1	60.00	60.00
	SUPPLIER				
24. 958 505 683 01	MOULDING	U1	1	200.00	200.00
	SUPPLIER				
25. 958 628 301 00 G2X	LH HEADLAMP WASH TRIM	U1	1	75.00	75.00
	SUPPLIER				
26. 958 628 180 00	NOZZLE PUMP R/L	U1	1	160.00	160.00
	SUPPLIER				
27. 958 628 185 00	LH WASHER JET BRACKET	U1	1	70.00	70.00
	2A11-F				
28. 958 505 594 01	FRT SUPPORT UPPER	U1	1	570.00	570.00
	SUPPLIER				
29. 958 503 031 02 GRV	FRT FENDER LH	U1	1	1200.00	1,200.00
	SUPPLIER				
30. 958 559 727 20 9B9	FRT FENDER WHEEL ARCH LH	U1	1	450.00	450.00
	SUPPLIER				
31. 958 556 806 01 01C	UPPER LOCK CARRIER TRIM	U1	1	120.00	120.00
	SUPPLIER				

CONTINUE NEXT PAGE
ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SIN YEW HUP AUTO PTE LTD
BLK.4 393M WOODLAND ROAD YEW TEE INDS EST
SINGAPORE 677981

TEL : 7600819 FAX : 7690221
ATTN : YONG JIAN

AM-SCPEET GLASS
Dept Direct: 6417 9795 / 6745 9229



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201803-17569
DATE : 31/03/2018
CUSTOMER ID : SIN016
VEH REG. NO. : ZZ92ZBLA42335
TERMS : 30 days
PO NO. :
PAGE NO. : Page 3 of 3
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
32. 958 504 731 00	FRT SUPPORT LOWER	UI	1	150.00	150.00
		SUPPLIER			

12,845.00

SUB-TOTAL : 13,210.00
ADD GST 7.00 % 924.70

E. & O.E TOTAL AMOUNT SGD : 14,134.70

[P] 31/03/2018 10:39:16AM

[E] 31/03/2018 9:31:24AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : CHONG



* AR201803-17569 *

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SIN YEW HUP AUTO PTE LTD
BLK.4 393M WOODLAND ROAD YEW TEE INDS EST
SINGAPORE 677981

TEL : 7600819 FAX : 7690221
ATTN : YONG JIAN

Arrange By _____ Driver _____
Dept Direct: 6417 9191 / 6745 6033



Dept Direct: 6395 9910

Dept Direct: 6309 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201803-17819
DATE : 31/03/2018
CUSTOMER ID : SIN016
VEH REG. NO. : ZZ92ZBLA42335
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 958 505 829 00	BUMPER BRACKET R/L I SEE SAMPLE	U1	1	50.00	50.00
		2B14-A			

SUB-TOTAL : 50.00
ADD GST 7.00 % 3.50

E. & O.E TOTAL AMOUNT SGD : 53.50

[P] 31/03/2018 1:34:09PM

[E] 31/03/2018 1:33:25PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : CHONG



* A R 2 0 1 8 0 3 - 1 7 8 1 9 *

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL



AUTOBACS VENTURE SINGAPORE PTE LTD
BUKIT BATOK STORE
TEL : 0740-5000
30 BUKIT BATOK EAST AVE 6 (S) 659761
CO REG NO 199500000H GST NO M2-8920436X
TAX INVOICE

14/04/2018 (Sat) 00:07 POS:0002
CashierNo 00000207:TAN CHY LUAN
SalesNo 00000100:LIM KOK PIN JOSEPH

0029 60140CB1 BIS XENL01105K 1
10585093000005 150.05

Subtotal	150.05
GST7%	9.89
Purchasing Item	1 item
Total	159.94
Cash	150.05
Change	9.89

For exchange of defective goods
Pls return item with receipt within
7 days of purchase in resellable
condition. item(s) exchange only
to same value or more.
Goods sold are not refundable.
*** Thank you! Pls come again! ***



0229

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/CT118004384/SQBN2

Date: 21/05/2018

REFERENCE

Insured/Claimant: THE STRAITS INTERNATIONAL PTE LTD

Policy No: P28932966MPQ

Date of Loss: 03/03/2018

Nature of Claim: OD

Claim No: 551360

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ42Y	Engine No:	B02591
Make & Model:	PORSCHE CAYENNE, S	Chassis No:	WP1ZZZ92ZBLA42335
Reg. Date:	24/08/2010 (Man. Year: 2010)	Odometer:	150201 km
Colour:	White		
Engine Capacity:	4806 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/30ZR22	Rear Tyre Size:	295/30ZR22
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,561.68	15,700.68	3,861.00	19.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	2,260.00	440.00	16.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,261.68	17,960.68	4,301.00	19.32
- Excess (S\$)	7,000.00	3,500.00	3,500.00	50.00
(S\$)	15,261.68	14,460.68	801.00	5.25
+ GST 7.00/7.00% (S\$)	1,068.32	1,012.25	56.07	5.25
Nett Amount (S\$)	16,330.00	15,472.93	857.07	5.25

INSPECTION

Date of Assignment: 07/03/2018 Present Location:

Date Inspected: 07/03/2018 Inspected At:

Sin Yew Hup Auto Pte Ltd (HQ)
Sin Yew Hup Auto Pte Ltd (HQ)
Blk D4 Woodlands Road 393M, Yew
Tee Industrial Estate
Singapore 677981

Estimated Period of Repair: 9.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents-Finalise amount: \$17,960.67

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 May 2018)	
Parts: M1-SUV	PORSCHE CAYENNE S (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SLQ42Y)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	1,200.00 F	*1,200.00 F
2	1		*FRONT BUMPER TOWING COVER RH (WCP)	Missing	75.00 F	*75.00 F
3	1		*FRONT BUMPER LOWER CENTER GARNISH (WCP)	Cracked	60.00 F	*60.00 F
4	1		*FRONT BUMPER LOWER LH GARNISH (WCP)	Missing	55.00 F	*55.00 F
5	1		*FRONT BUMPER UNDERCOVER (WCP)	Bent	700.00 F	*700.00 F
6	1		*FRONT BUMPER SIDE HOLDER (WCP)	N/s Cracked/O/s Not Necessary	160.00 F	*80.00 F
7	1		*FRONT BUMPER INNER GARNISH LH (WCP)	Cracked	135.00 F	*135.00 F
8	1		*FRONT BUMPER INNER QUARTER GARNISH (WCP)	Cracked	230.00 F	*230.00 F
9	2		*FRONT BUMPER CENTER RETAINER (WCP)	Deformed	100.00 F	*100.00 F
10	2		*FRONT BUMPER CENTER RETAINER BRACKET (WCP)	Deformed	100.00 F	*100.00 F
11	2		*FRONT BUMPER CENTER INNER LOWER GARNISH (WCP)	Deformed	400.00 F	*200.00 F
12	1		*FRONT BUMPER INNER TOP GARNISH (WCP)	Deformed	75.00 F	*75.00 F
13	1		*FRONT BUMPER OUTER SIDE RETAINER (WCP)	N/s Cracked/O/s Not Necessary	120.00 F	*60.00 F
14	1		*FRONT BUMPER INNER SIDE RETAINER (WCP)	N/s Cracked/O/s Not Necessary	120.00 F	*60.00 F
15	20		*FRONT BUMPER RIVET (WCP)	Not Necessary	100.00 F	*- F
16	2		*HEADLAMP (WCP)	Cracked	6,000.00 F	*6,000.00 F
17	1		*FRONT BUMPER DAYLIGHT LH (WCP)	Scratched	850.00 F	*850.00 F
18	1		*FRONT BUMPER FOG LAMP LH (WCP)	Not Necessary	110.00 F	*- F
19	1		*HEADLAMP WASHER COVER LH (WCP)	Missing	75.00 F	*75.00 F
20	1		*HEADLAMP WASHER NOZZLE LH (WCP)	Damaged	160.00 F	*160.00 F
21	1		*HEADLAMP WASHER NOZZLE HEAD LH (WCP)	Damaged	70.00 F	*70.00 F
22	1		*FRONT SUPPORT TOP PANEL (WCP)	Cracked	570.00 F	*570.00 F
23	1		*FRONT SUPPORT TOP PANEL BRACKET (WCP)	Cracked	150.00 F	*150.00 F
24	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,400.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		(WCP) *FRONT FENDER LH	Bent	1,200.00 F	*1,200.00 F
26	1		(WCP) *FRONT FENDER BRACKET A	Not Necessary	40.00 F	*- F
27	1		(WCP) *FRONT FENDER BRACKET B	Not Necessary	30.00 F	*- F
28	1		(WCP) *FRONT FENDER FENDER ARCH GARNISH LH	Scratched	450.00 F	*450.00 F
29	10		(WCP) *FRONT FENDER FENDER ARCH GARNISH LH CLIP	Not Necessary	30.00 F	*- F
30	1		(WCP) *FRONT WHEEL RIM LH	Repair	1,400.00 F	*- F
31	1		*NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
32	1		(WCP) *FRONT BUMPER SIDE INDICATOR LH	Scratched	100.00 F	*100.00 F
Supplementary #1						
33	1		(WCP) *FRONT BUMPER CENTER INNER GRILLE	Deformed	200.00 F	*200.00 F
34	1		LH (WCP) *HEADLAMP PROTECTOR CAP	Necessary	160.00 F	*160.00 F
35	1		(WCP) *HEADLAMP BRACKET LH	Deformed	50.00 F	*50.00 F
36	1		(WCP) *HEADLAMP MOUNTING BRACKET LH	Deformed	320.00 F	*320.00 F
37	1		(WCP) *FRONT SUPPORT PANEL TOP GARNISH	Deformed	120.00 F	*120.00 F
Supplementary #2						
38	1		(WCP) *FRONT BUMPER FOG LAMP LH	Cracked	400.00 F	*400.00 F
Supplementary #3						
39	1		(WCP) *Front bumper moulding LH upper	Deformed	50.00 F	*50.00 F
40	1		(WCP) *Front bumper moulding LH lower	Deformed	50.00 F	*50.00 F
Supplementary #4						
41	1		(WCP) *HEADLAMP LH BULB	Necessary	141.07 F	*141.07 F
F=Franchise part. S=SpcNett.						
Sub Total (\$\$)					17,786.07	14,276.07
+ Margin on L,N Items 10.00/10.00% (\$\$)					1,775.61	1,424.61
Total Parts (\$\$)					19,561.68	15,700.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY PAINT FRONT BONNET IN & OUT, FRONT BUMPER, FRONT FENDER LH, WHEELHOUSE LH	New	1,400.00	1,000.00
2	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
3	TO REMOVE AND REFIT FRONT BUMPER, FRONT FENDER LH, HEADLAMP, FRONT BUMPER REINFORCEMENT, FRONT WHEEL RIM AND DAMAGED PARTS, PANEL BEAT WHEELHOUSE LH	New	1,200.00	1,200.00
Gross Labour Cost (S\$)			2,700.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >