

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9549K - AIG

AAD1803-024

Not Authorized

- 8315.00

Vehicle No.:	SHD9459K - CANDY
Chassis No.:	KL1LA69RJBB078319
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	03.03.2018
Third Party Insurer :	AIG

		PART		LIST
1	1	Rear Bumper	\$	<i>R</i> 1,202.00 ✗
2	1	Rear Bumper Beam	\$	<i>R</i> 239.94 ✗
3	1	Rear Bumper Centre Absorber	\$	<i>Sm</i> 260.00 ✗
4	1	Rear Bumper Side Retainer RH	\$	<i>Sm</i> 68.76 ✗
5	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 ✗
6	1	Rear Bumper Reflectors RH	\$	<i>Sm</i> 119.74 ✗
7	1	Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74 ✓
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sm</i> 93.00
9	1	Rear End Panel Outer	\$	<i>R</i> 623.76
10	1	Rear End Panel Inner Trim	\$	<i>Sm</i> 263.84
11	1	Bootlid	\$	<i>R</i> 973.00
12	1	Bootlid Weatherstrip	\$	<i>Sm</i> 344.28
13	1	Bootlid Lock - Top	\$	<i>R</i> 466.56
14	1	Bootlid 'CHEVROLET' Badge	\$	<i>nn</i> 120.62
15	1	Bootlid Logo	\$	<i>nn</i> 138.84
16	1	Bootlid 'EPICA LT' Badge	\$	<i>nn</i> 119.84
17	1	Bootlid Reflector Centre	\$	<i>Sm</i> 217.97 ✗
18	1	Bootlid Reflector RH	\$	<i>Sm</i> 128.40
19	1	Bootlid Reflector LH	\$	<i>Sm</i> 128.40
20	1	Bootlid Hinge RH	\$	<i>R</i> 120.00
21	1	Bootlid Hinge LH	\$	<i>R</i> 120.00
22	1	Rear Tail Lamp RH	\$	<i>Sm</i> 479.30
23	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00
24	1	Rear Tail Lamp LH	\$	<i>Sm</i> 479.30
25	1	Rear Tail Lamp Panel LH	\$	<i>R</i> 359.00
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00
27	1	Rear Fender RH	\$	<i>R</i> 1,145.00
28	1	Rear Fender Inner Trim RH	\$	<i>Sm</i> 418.44
29	1	Rear Fender LH	\$	<i>R</i> 1,145.00
30	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 418.44

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-024

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9549K - AIG

TOTAL	\$	11,850.93
10%	\$	1,185.09
	\$	10,665.84

Special Nett

1	1Set	Licence Plate With Holder	\$	Sm	60.00	} X
2	1Set	Bootlid inner trim board Clip	\$	nn	40.00	
3	1Set	Rear Bumper Parking Sensor	\$	Sm	300.00	
4	1Set	Rear Bumper Fastener Clip	\$	nn	44.00	
5	1Set	Rear Fender Inner Trim Clip LH	\$	nn	30.00	
6	1Set	Rear Fender Inner Trim Clip RH	\$	nn	30.00	
7	1Set	Rear Bumper End Dust Cover Clip	\$	nn	30.00	
8	1	Rear Boot Sticker 'Trans-cab'	\$	nn	30.00	
9	1	Rear Boot Sticker '6555-3333'	\$	nn	30.00	
10	1	Rear Exhaust Mounting	\$	Sm	10.00	
11	2	Rear Windscreen Sealant	\$	nn	80.00	
12	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	
13	1	Spare Tyre	\$	Sm	180.00	
14	1	Spare Wheel Rim	\$	Sm	126.74	

TOTAL	\$	1,090.74
TOTAL PARTS	\$	11,756.58

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,700.00	100
To Check Electrical Lighting Concerned.	\$	170.00	15
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,800.00	200
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of end panel fittings and conduct water seepage test.	\$	nn 170.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-024

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9549K - AIG

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To transfer of boot fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
Towing fees	\$	<i>nn</i> 120.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
	\$	<u>7,410.00</u>
TOTAL	\$	<u>19,166.58</u>

Repair Days

~~10 Days~~
1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: