

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9997S -**AAD1803-014***Not Notarised
1/ Sep 8440d*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD9777S - CANDY
VF1ABL15AUC277235
RENAULT
LATITUDE
01.03.2018
Alh

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
3	1	BUMPER FOG LAMP GRILLE RH	\$	<i>DT</i> 207.22 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41 X
5	1	BUMPER RETAINER FRT RH	\$	<i>DT</i> 151.41 ✓
6	1	BUMPER SUPPORT FRT RH	\$	<i>Sn</i> 123.88 X
7	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
8	1	RADAIOR GRILLE	\$	<i>Sn</i> 1,707.78 X
9	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>nn</i> 225.36 X
10	1	RADAIOR GRILLE FRAME	\$	<i>CM</i> 1,353.75 ✓
11	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90 X
12	1	FRAME FULL SUPPORT BRACKET	\$	<i>n</i> 89.79 X
13	1	BONNET	\$	<i>R</i> 1,941.63 X
14	1	HEADLAMP RH	\$	<i>CM</i> 1,184.43 ✓
15	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
16	1	FENDER PANEL FRT RH	\$	<i>Bu</i> 783.83 ✓
17	1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
18	1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
19	1	DOOR MIRROR RH	\$	<i>Sn</i> 1,483.40
20	1	DOOR MIRROR GLASS RH	\$	<i>Sn</i> 148.20
21	1	DOOR MIRROR BACK COVER RH	\$	<i>Sn</i> 218.46
22	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
23	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
24	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
TOTAL			\$	16,723.24
10%			\$	1,672.32
			\$	15,050.92

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
2	1SET	WHEELARCH CLIP RH	\$	<i>nn</i> 66.00 X
3	1	TOW COVER FRT	\$	<i>Sn</i> 14.50 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-014

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9997S -

4	1	CAP HUB RH FRT	\$	<i>pn</i>	35.00	} X
5	1	RIM RH FRT	\$	<i>pn</i>	385.00	
6	1	TYRE RH FRT	\$	<i>pn</i>	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP RH	\$	<i>nn</i>	9.80	
8	1SET	BUMEPR RETAINER FRT CLIP RH	\$	<i>nn</i>	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00	
10	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00	

TOTAL	\$	1,028.80
TOTAL PARTS	\$	16,079.72

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *50d*

To Check Electrical Lighting Concerned.

\$ 170.00 *2d*

Putty and spray painting of the affected portion.

\$ 3,000.00 *48d*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Towing Fees

\$ *nn* 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 *3d*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

TOTAL	\$	6,820.00
Over All Total	\$	22,899.72

(PARTS BY PARTS) Repair Days**10 Days***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: