

ASS. REC. BY:

REF:

CS/FWD18004395/Arber

Special Instruction:

Surveyor: Adrian
~~Norman~~ASSIGNMENT (Office)From (Person): Clara Li

of

FWDDate/Time: 07/03/2018 1:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 1747Z

Insured:

at Workshop m/s

Progressive

Tel:

6741 5336

of

Bik 3022A Ubi Rd 1 #D1-45

Policy No:

PNPV2017 - 00005796

Claim No:

1201800002524

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

D.O.A.

03032018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

07/03/2018 1:57pm

Person Contacted:

Pei WenVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLF 1747Z - X</u>
	<u>Sent pei, thru Norman</u>
	<u>Authorise repair; Inform Pei Wen thru phone and email</u>

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 112K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF 1747Z Yr Regn: 2016 / Sept.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan X-Trail c.c. 1997
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 17624 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN 1JANT32Z0002386
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim
 Tyre Size: F: 225/60R18
 R: 225/60R18
 BS: BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 07/03/18
 Survey held at Progressive (ubi)
 Des. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD FWD.

Unfirm \$11,087.00, 5 days
Red: \$3140, 22/.

RECEIVED 23 APR 2018

Date/Time. File Pass to?

☐

: Preli. Report

☒

: Final Report

1) typist

Date/Time. File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Report Format: 00Lump Sum / I.B.I. (\$) 11087.0025010010260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD18004395/Arb

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 07-03-2018



Code : FWD

1. Policy Particulars - OWN DAMAGE

Insured Veh.		Veh. Inspected	SLF 1747Z
Policy No.	PNPV2017-00005796	Coverage (\$)	0.00
Claim No.	1201800002924	Excess (\$)	500.00
Assign From	MERIMEN (CLARA LI)	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/03/2018	Inspection Date	07/03/2018
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018 Sendback Est	07 Mar 2018 12:45 S\$14,102.00	07 Mar 2018 13:23 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	CHOI KAM WAH, ID: S26972618, Tel: +6591119226, Email: WAH124@YAHOO.COM		
Vehicle Reg. No.:	SLF1747Z	Date of Loss:	03/03/2018 16:00 - :59
Claim Type:	OD / 1201800002924	Policy/Cover Note No.:	PNPV2017-00005796 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/03/2018]		
Driver/Custodian:	CHOI KAM WAH (59 / Male), NRIC: S2697261B, Tel: +6591119226		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 08 Mar 2018

Preliminary Advice

Vehicle No	: SLF1747Z	Accident Date	: 03/03/2018
Make	: NISSAN X-TRAIL	Policy No.	: PNPV2017-00005796
Assignment Date	: 07/03/2018	Excess	: S\$500.00
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 5.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,102.00
Revised Amount	:S\$	4,151.00
Check Items (Estimated)	:S\$	6,791.00
Total	:S\$	10,942.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	66,898.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,102.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

SLF1747Z (1201800002924)

OD

Mar 3 2018 4:00PM

[CHOI KAM WAH]

Progressive Automotive Pte Ltd

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 08/03/2018 11:31 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$10942.00) - SLF1747Z - Claim Handler: Clara Li Zi Rong

Approved:10942.00.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, March 08, 2018 12:49 PM
To: 'peiwen@progauto.com.sg'
Cc: SUR
Subject: SLF 1747Z FWD DOA : 03.03.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLF 1747Z (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 20 Apr 2018

Preliminary Advice

Vehicle No	: SLF1747Z	Accident Date	: 03/03/2018
Make	: NISSAN X-TRAIL	Policy No.	: PNPV2017-00005796
Assignment Date	: 07/03/2018	Excess	: S\$500.00
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 5.00
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,227.00	(Include Supplementary \$125.00)
Revised Amount	:S\$	11,087.00	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	11,087.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	66,898.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,102.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7261B

Vehicle Details

Vehicle No.: SLF1747Z
Vehicle to be Exported: No
Intended De-registration Date: 08 Mar 2018
Vehicle Make: NISSAN
Vehicle Model: X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour: Orange
Manufacturing Year: 2016
Engine No.: MR20890168B
Chassis No.: JN1JANT32Z0002386
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$23,227.00
Original Registration Date: 16 Aug 2016
First Registration Date: 16 Aug 2016
Transfer Count: 0
Actual ARF Paid: \$24,518.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 Aug 2026
PARF Rebate Amount: \$18,388.00

Intended COE Rebate Details

COE Expiry Date: 15 Aug 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$57,508.00
COE Rebate Amount: \$48,510.00
Total Rebate Amount: \$66,898.00

The information contained herein is correct as at 08 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2018 16:28
Date Of Accident	03/03/2018 16:20
Exact Location Of Accident	PIE TOWARDS JURONG NEAR PAYA LEBAR FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF1747Z
Insured/Policyholder	
Name Of Registered Owner	CHOI KAM WAH
NRIC No	S2697261B
Email Address	WAH124@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91119226
Alternative Phone No	OFFICE-91119226

Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL-2.0 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00005796
Cover Note Number	16/08/2017 - 15/08/2018

Driver

Name of Driver	CHOI KAM WAH
NRIC No	S2697261B
Date Of Birth	24/01/1959
Occupation	INDOOR
Date Of Driving Pass	04/05/2000
Driving Experience	17 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91119226
Fax Number	
Contact Number	OFFICE-91119226
Email Address	WAH124@YAHOO.COM

Address

BLK 324 UBI AVENUE 1
#12-555

Postcode

400324

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own
Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by
ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1

NAME: : YEUNG YUN OI

GENDER: : FEMALE

Passenger 2

NAME: : CHOI HIU YAN

GENDER: : FEMALE

Passenger 3

NAME: : CHOI JUN AN

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SFW4947A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

CHIN YIEN JUN

NRIC/Passport Number

S9220917B

Contact Number

Address.

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

- the class of representations of $\mathcal{A}$ from $\mathcal{B}$ to $\mathcal{A}$ is nonempty, then $\mathcal{A}$ is a subalgebra of $\mathcal{B}$. In particular, if $\mathcal{A}$ is a subalgebra of $\mathcal{B}$, then $\mathcal{A}$ is a subalgebra of $\mathcal{B}$.

For the case of the homogeneous theorem, we will use the following lemma. For any $\alpha \in \mathbb{R}$, let $\mathcal{H}_\alpha$ denote the space of functions $f: \mathbb{R}^d \rightarrow \mathbb{R}$ satisfying $\Delta f = \alpha f$. A function f is called *homogeneous* if $f \in \mathcal{H}_\alpha$ for some $\alpha \in \mathbb{R}$. The next lemma is due to

Content under the Personal Data Protection Act (PDPA)

$$f(x) = \frac{1}{2} \left(\frac{1}{x} + \frac{1}{x^2} \right) \quad \text{for } x \in \mathbb{R} \setminus \{0\}$$

- On the other hand, the *Journal of the American Academy of Child and Adolescent Psychiatry* (JACCAP) is a peer-reviewed journal that publishes research, clinical reports, and reviews in the field of child and adolescent psychiatry. The JACCAP is published by the American Academy of Child and Adolescent Psychiatry (AACAP) and is one of the leading journals in the field. The JACCAP is published quarterly and is available in both print and online formats. The JACCAP is a peer-reviewed journal that publishes research, clinical reports, and reviews in the field of child and adolescent psychiatry. The JACCAP is published by the American Academy of Child and Adolescent Psychiatry (AACAP) and is one of the leading journals in the field. The JACCAP is published quarterly and is available in both print and online formats.

[illegible]

1. $\frac{1}{2} \frac{d}{dt} \int_{\mathbb{R}^n} |u|^2 dx = \int_{\mathbb{R}^n} u \Delta u dx = - \int_{\mathbb{R}^n} |\nabla u|^2 dx \leq 0$

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 103–110

[illegible]

Received 12 May 2004
 Received revised 10 June 2004
 Accepted 12 June 2004

2. The number of the *Journal of Applied Behavior Analysis* is 19.

Sketch Plan #2

SKETCH PLAN



Vehicle No.

A-51718470

B - SPIN 4444A

Legend



Vehicle



Figure

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

Please be advised that your insurer may have a 14 day clause whereby the claim against your policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Author's Signature:

Date & Time:

Owner's Signature: _____

(I cannot not not the solution for you)

Date & Time:

Reporting Centre Personnel's Signature: _____

Number.

NĂIQU/FA No. _____



PROGRESSIVE AUTOMOTIVE PTE LTD.

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0318-6402
Policy No:	PNPV2017-00005796	Date of Loss:	03/03/2018
Vehicle Reg. No.:	SLF1747Z	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOI KAM WAH	Contact No:	+6591119226
Driver:	CHOI KAM WAH		

Make/Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Vehicle Reg. Date:	16/08/2016
Vehicle Colour:	BROWN		
Engine No:	MR20890168B	Chassis No:	JN1JANT32Z0002386
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair **7**
(day)

Description of Accident/Loss: STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Remarks: VEHICLE IS IN WORKSHOP

Present Location: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	11,957.00
Miscellaneous Items	55.00
Labour	1,090.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (\$\$)	14,102.00
+ GST 7.00% (\$\$)	987.14
Nett Amount (\$\$)	15,089.14

This claim is handled by: **NG PEI WEN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 07 Mar 2018)**Parts:** N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET <i>Dented.</i>	0.00	0.00	/*650.00 F ✓
2	1	NA	*BONNET LOCK <i>the one</i>	0.00	0.00	X *90.00 F X
3	1	NA	*BONNET RUBBER - INNER - LH	0.00	0.00	/*25.00 F+
4	1	NA	*BONNET RUBBER - INNER - RH	0.00	0.00	/*25.00 F+
5	1	NA	*BONNET RUBBER - OUTER - LH	0.00	0.00	/*25.00 F+
6	1	NA	*BONNET RUBBER - OUTER - RH	0.00	0.00	/*25.00 F+
7	1	NA	*BONNET HINGE - RH <i>the one</i>	0.00	0.00	X *50.00 F ?
8	1	NA	*BONNET HINGE - LH <i>? Bent</i>	0.00	0.00	/*50.00 F ?
9	12	NA	*BONNET INSULATOR CLIPS <i>the one</i>	0.00	0.00	/*24.00 F-
10	1	NA	*FRONT BUMPER <i>Deformed</i>	0.00	0.00	/*450.00 F-
11	1	NA	*FRONT BUMPER SIDE HOLDER - RH	0.00	0.00	/*20.00 F-
12	1	NA	*FRONT BUMPER SIDE HOLDER - LH	0.00	0.00	/*20.00 F-
13	10	NA	*FRONT BUMPER CLIPS <i>the one</i>	0.00	0.00	/*20.00 F-
14	1	NA	*FRONT BUMPER REINFORCEMENT <i>? Bent</i>	0.00	0.00	/*350.00 F ?
15	1	NA	*FRONT BUMPER FOG LAMP COVER - LH	0.00	0.00	X *75.00 F+
16	1	NA	*FRONT BUMPER FOG LAMP COVER - RH	0.00	0.00	X *75.00 F+
17	1	NA	*FRONT BUMPER FOG LAMP - LH	0.00	0.00	X *250.00 F+
18	1	NA	*FRONT BUMPER FOG LAMP - RH	0.00	0.00	X *250.00 F+
19	1	NA	*FRONT BUMPER BRACKET - LH	0.00	0.00	/*58.00 F ?
20	1	NA	*FRONT BUMPER BRACKET - RH	0.00	0.00	/*58.00 F ?
21	1	NA	*FRONT BUMPER FOAM <i>can be</i>	0.00	0.00	/*175.00 F ✓
22	1	NA	*FRONT BUMPER TOWING COVER - LH <i>the one</i>	0.00	0.00	X *20.00 F+
23	1	NA	*FRONT BUMPER LOWER GARNISH; BLACK <i>the one</i>	0.00	0.00	/*270.00 F+
24	1	NA	*FRONT BUMPER LOWER CHROME <i>the one</i>	0.00	0.00	/*125.00 F+
25	1	NA	*GRILLE W/CHROME ASSY - CENTRE <i>can be</i>	0.00	0.00	/*380.00 F ✓
26	1	NA	*GRILLE LOGO <i>the one</i>	0.00	0.00	/*55.00 F-
27	6	NA	*GRILLE CLIP <i>the one</i>	0.00	0.00	/*12.00 F-
28	1	NA	*HEAD LAMP UNIT - LH (HID) <i>? the one</i>	0.00	0.00	/*1,950.00 F ?
29	1	NA	*HEAD LAMP UNIT - RH (HID) <i>? the one</i>	0.00	0.00	/*1,950.00 F ?
30	1	NA	*HEAD LAMP LOWER RETAINER - LH <i>? the one</i>	0.00	0.00	/*25.00 F ?
31	1	NA	*HEAD LAMP LOWER RETAINER - RH <i>? the one</i>	0.00	0.00	/*25.00 F ?
32	1	NA	*TOP PANEL <i>the one</i>	0.00	0.00	X *190.00 F+
33	2	NA	*HEAD LAMP PANEL - LH; RH <i>the one</i>	0.00	0.00	/*150.00 F+
34	1	NA	*LOWER MEMBER <i>the one</i>	0.00	0.00	/*260.00 F+
35	1	NA	*BRACE PANEL <i>the one</i>	0.00	0.00	/*50.00 F ✓
36	1	NA	*HORN - LH <i>? the one</i>	0.00	0.00	X *95.00 F ?
37	1	NA	*HORN - RH <i>? the one</i>	0.00	0.00	X *95.00 F ?
38	1	NA	*AIRCON CONDENSER <i>Dented</i>	0.00	0.00	/*750.00 F ✓
39	1	NA	*AIRCON/RADIATOR FAN MOTOR; COWLING & BLADE ASSY <i>? the one</i>	0.00	0.00	/*750.00 F ?
40	1	NA	*AIRCON DISCHARGE PIPE <i>the one</i>	0.00	0.00	X *230.00 F+
41	1	NA	*AIRCON LIQUID TUBE <i>the one</i>	0.00	0.00	X *130.00 F+
42	1	NA	*RADIATOR <i>? Dented</i>	0.00	0.00	/*795.00 F ?
43	1	NA	*WIPER TANK ASSY <i>the one</i>	0.00	0.00	X *240.00 F+
44	1	NA	*RADIATOR SPARE TANK <i>the one</i>	0.00	0.00	X *85.00 F+

Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1	NA	*RADIATOR TOP HOSE <i>3 new</i>	0.00	0.00	X *35.00 F +
46	1	NA	*RADIATOR BOTTOM HOSE	0.00	0.00	X *45.00 F +
47	1	NA	*OIL COOLER ? <i>Replaced</i>	0.00	0.00	/ *480.00 F ?
48	1	NA	*POWER STEERING RETURN HOSE - NO PRICE <i>NEW</i>	0.00	0.00	X *-F ?
Total Parts (S\$)						11,957.00

F=Franchise part.

Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COOLANT <i>Nu</i>	20.00 ✓
2	1	FRONT NUMBER PLATE W/CASING <i>Bert</i>	35.00 ✓
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00 700 ✓
Labour Items			
2	TO KNOCK OUT DENTS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	880.00 660 ✓
3	TO CHECK WIRING	New	50.00 30 ✓
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00 ✓
5	TO RESET CHECK LIGHT	New	60.00 ?
Gross Labour Cost (S\$)			2,090.00

Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
P/P 07/03/18
05 days.



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0318-6402
Policy No:	PNPV2017-00005796	Date of Loss:	03/03/2018
Vehicle Reg. No.:	SLF1747Z	Driveable?	
Driver Age/Info:	59 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHOI KAM WAH	Contact No:	+6591119226
Driver:	CHOI KAM WAH		

Make/Model:	NISSAN X-TRAIL, 2.0 CVT (A)	Vehicle Reg. Date:	16/08/2016
Vehicle Colour:	BROWN		
Engine No:	MR20890168B	Chassis No:	JN1JANT32Z0002386
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Description of Accident/Loss	STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)
------------------------------	--

Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)
-------------------	-------------------------------------

COST OF CLAIMS	Amount
Parts	125.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	125.00
+ GST 7.00% (S\$)	8.75
Nett Amount (S\$)	133.75
+ Previous Estimates (S\$)	15,089.14
Claim Total (S\$)	15,222.89

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 29 Mar 2018)
Parts: N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLF1747Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*AIRCON SIDE GARNISH - LH/RH <i>Detached</i>	0.00	0.00	*90.00 F ✓
2	1		*AIRCON TEMPERATURE SENSOR <i>Damaged</i>	0.00	0.00	*35.00 F ✓
Total Parts (\$)						125.00

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

SUPP 125.00

PARTS 949.00

SN 55.00

LABS. 1490.00

11087.00

00 6402

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Progressive Automotive Pte Ltd/SLF1747Z/16/04/2018 10:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Janice Lee (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, April 06, 2018 4:31 PM
To: SUR
Cc: 'Wayne Lim'; msho@progauto.com.sg; peiwen@progauto.com.sg
Subject: FW: SLF1747Z - TO FINALIZE
Attachments: FINALIZE REPORT .pdf; SUPPLIER'S BILL .pdf

CS/FWD18004395/Arb

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [mailto:ray@progauto.com.sg]
Sent: Friday, 6 April 2018 4:15 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: 'Wayne Lim' <wayne@progauto.com.sg>; msho@progauto.com.sg; 'Peiwen PROGAUTO' <peiwen@progauto.com.sg>; siewwei@progauto.com.sg
Subject: SLF1747Z - TO FINALIZE

Hi Adrian/ Veron,

Please refer to finalize

Supp	\$125.00
Parts	\$9417.00
Sn	\$55.00
Lab	\$1490.00
Total	\$11087.00

✓
✓
✓
✓
✓
✓
R.S.

Thank you

Best regard,

Ray

Progressive Automotive Pte Ltd

Tel: 6741-5336 Fax: 6741-7208

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Mar 2018)

Parts: N/A NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET <i>Deletd</i>	0.00	0.00	*650.00 F ✓
2	1	NA	*BONNET LOCK <i>Not Nec</i>	0.00	0.00	*90.00 F ✓
3	1	NA	*BONNET RUBBER - INNER - LH <i>2</i>	0.00	0.00	*25.00 F ✓
4	1	NA	*BONNET RUBBER - INNER - RH <i>1400 Not Nec</i>	0.00	0.00	*25.00 F ✓
5	1	NA	*BONNET RUBBER - OUTER - LH <i>1400 Not Nec</i>	0.00	0.00	*25.00 F ✓
6	1	NA	*BONNET RUBBER - OUTER - RH <i>1400 Not Nec</i>	0.00	0.00	*25.00 F ✓
7	1	NA	*BONNET HINGE - RH <i>2</i>	0.00	0.00	*50.00 F ✓
8	1	NA	*BONNET HINGE - LH <i>Best</i>	0.00	0.00	*50.00 F ✓
9	12	NA	*BONNET INSULATOR CLIPS <i>Not Nec</i>	0.00	0.00	*24.00 F ✓
10	1	NA	*FRONT BUMPER <i>Reformed</i>	0.00	0.00	*450.00 F ✓
11	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>2</i>	0.00	0.00	*20.00 F ✓
12	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>2</i>	0.00	0.00	*20.00 F ✓
13	10	NA	*FRONT BUMPER CLIPS <i>Not Nec</i>	0.00	0.00	*20.00 F ✓
14	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	*350.00 F ✓
15	1	NA	*FRONT BUMPER FOG LAMP COVER - LH <i>2 Not a</i>	0.00	0.00	*75.00 F ✓
16	1	NA	*FRONT BUMPER FOG LAMP COVER - RH <i>2</i>	0.00	0.00	*75.00 F ✓
17	1	NA	*FRONT BUMPER FOG LAMP - LH <i>2 Not a</i>	0.00	0.00	*250.00 F ✓
18	1	NA	*FRONT BUMPER FOG LAMP - RH <i>2</i>	0.00	0.00	*250.00 F ✓
19	1	NA	*FRONT BUMPER BRACKET - LH <i>Best</i>	0.00	0.00	*58.00 F ✓
20	1	NA	*FRONT BUMPER BRACKET - RH <i>Best</i>	0.00	0.00	*58.00 F ✓
21	1	NA	*FRONT BUMPER FOAM <i>Not Nec</i>	0.00	0.00	*175.00 F ✓
22	1	NA	*FRONT BUMPER TOWING COVER - LH <i>Not a</i>	0.00	0.00	*20.00 F ✓
23	1	NA	*FRONT BUMPER LOWER GARNISH; BLACK <i>Deletd</i>	0.00	0.00	*270.00 F ✓
24	1	NA	*FRONT BUMPER LOWER CHROME <i>Not a</i>	0.00	0.00	*125.00 F ✓
25	1	NA	*GRILLE W/CHROME ASSY - CENTRE <i>Not a</i>	0.00	0.00	*380.00 F ✓
26	1	NA	*GRILLE LOGO <i>Not a</i>	0.00	0.00	*55.00 F ✓
27	6	NA	*GRILLE CLIP <i>Not a</i>	0.00	0.00	*12.00 F ✓
28	1	NA	*HEAD LAMP UNIT - LH (HID) <i>Not a</i>	0.00	0.00	*1,950.00 F ✓
29	1	NA	*HEAD LAMP UNIT - RH (HID) <i>Not a</i>	0.00	0.00	*1,950.00 F ✓
30	1	NA	*HEAD LAMP LOWER RETAINER - LH <i>Not a</i>	0.00	0.00	*25.00 F ✓
31	1	NA	*HEAD LAMP LOWER RETAINER - RH <i>Not a</i>	0.00	0.00	*25.00 F ✓
32	1	NA	*TOP PANEL <i>Not a</i>	0.00	0.00	*190.00 F ✓
33	2	NA	*HEAD LAMP PANEL - LH; RH <i>Not a</i>	0.00	0.00	*150.00 F ✓
34	1	NA	*LOWER MEMBER <i>Not a</i>	0.00	0.00	*200.00 F ✓
35	1	NA	*BRACE PANEL <i>Best</i>	0.00	0.00	*50.00 F ✓
36	1	NA	*HORN - LH <i>Not a</i>	0.00	0.00	*95.00 F ✓
37	1	NA	*HORN - RH <i>Not a</i>	0.00	0.00	*95.00 F ✓
38	1	NA	*AIRCON CONDENSER <i>Deletd</i>	0.00	0.00	*750.00 F ✓
39	1	NA	*AIRCON/RADIATOR FAN MOTOR; COWLING & BLADE ASSY <i>Deletd</i>	0.00	0.00	*750.00 F ✓
40	1	NA	*AIRCON DISCHARGE PIPE <i>Not a</i>	0.00	0.00	*230.00 F ✓
41	1	NA	*AIRCON LIQUID TUBE <i>Not a</i>	0.00	0.00	*130.00 F ✓
42	1	NA	*RADIATOR <i>Deletd</i>	0.00	0.00	*795.00 F ✓
43	1	NA	*WIPER TANK ASSY <i>Not a</i>	0.00	0.00	*240.00 F ✓
44	1	NA	*RADIATOR SPARE TANK <i>Not a</i>	0.00	0.00	*65.00 F ✓

Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3/7/2018

Estimate Report

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1	NA	*RADIATOR TOP HOSE <i>7mm</i>	0.00	0.00	35.00 F
46	1	NA	*RADIATOR BOTTOM HOSE	0.00	0.00	45.00 F
47	1	NA	*OIL COOLER <i>Devised</i>	0.00	0.00	480.00 F
48	1	NA	*POWER STEERING RETURN HOSE - NO PRICE ?	0.00	0.00	F ?

F=Franchise part.

Total Parts (S\$)

11,957.00 *9417*

Progressive Automotive Pte Ltd/SLF1747Z/07/03/2018 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>Mer</i>	20.00 //
2	1	FRONT NUMBER PLATE W/CASING <i>Bent</i>	35.00 //
Sub Total (S\$)			55.00 //

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00 700 //
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	880.00 660 //
3	TO CHECK WIRING	New	50.00 30 //
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00 //
5	TO RESET CHECK LIGHT	New	60.00 ?
Gross Labour Cost (S\$)			2,090.00 1490

Progressive Automotive Pte Ltd/SLF17472/07/03/2018 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw affixor and the support dolly system to provide accurate re-alignment and speedy repairs.

Adrian Ling
R/p 07/03/18
05 days.
Not Authorized.
Excess \$500



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

WINDSCREEN GLASS
Dept Direct: 6417 0791 / 6745 0939



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9795

====Email: jaeauto@pacificnet.sg====
PROGRESSIVE AUTOMOTIVE PTE LTD
VEH REG NO: ML4P1820 Co Reg No.: 199307741M
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

Wiper blade HWS (Nissan Wiper blade) Silver (Mazda Wiper blade)

Spark plug: Bosch (Made in Germany) AR201803-06210

TAX INVOICE
DATE : 10/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

00 6402

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	N27722-3RA0A T32	TEMP.SENSOR	MO SUPPLIER	1	35.00	35.00 /-

SUB-TOTAL : 35.00
ADD GST 7.00 % 2.45

E. & O.E TOTAL AMOUNT SGD : 37.45

[P] 10/03/2018 10:31:27AM


[E] 10/03/2018 10:31:02AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



* AR201803-06210 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610 Dept Direct: 6305 9611 Dept Direct: 6417 9792



Dept Direct: 6417 9791 Dept Direct: 6417 9795 Dept Direct: 6417 9796 Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Stripes (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

DD 6402

TAX INVOICE : AR201803-05478
DATE : 09/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1.	N65401-4CLOA/4BA0A T32	HINGE ASSY - HOOD , LH	PA PL3-D1-06B	1	50.00	50.00 ✓
2.	N65846-40F00 YL ALL	CLIP HOOD INSULATOR	PA PL3-A1-12A	12	2.00	24.00 ✓
3.	N62022-4CB0H T32 X-TRAIL	FRT BUMPER	PA PL4-D1-02	1	450.00	450.00 ✓
4.	N01553-09611 YL B15 N16 J31 C11 G11	CLIP BUMPER TOP 01553-10501	PA PL3-A1-12A	16	2.00	32.00 ✓
5.	N21558-4BB0A T32	AIR GUIDE RH	PA PL3-B1-09C	1	45.00	45.00 ✓
6.	N21559-4BB0A T32	AIR GUIDE LH	PA PL3-B1-09D	1	45.00	45.00 ✓
7.	N62310-4CE1B/0B T32	GRILLE ASSY	PA PL3-C1-100	1	380.00	380.00 ✓

SUB-TOTAL : 1,026.00
ADD GST 7.00 % 71.82

E. & O.E TOTAL AMOUNT SGD : 1,097.82

[P] 09/03/2018 11:40:13AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 09/03/2018 10:40:46AM

JAE Auto Pte. Ltd.

Sales Executive: GUAN

This is computer generated document.

No signature is required.



* A R 2 0 1 8 0 3 - 0 5 4 7 8 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

00 6402

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6746 9930



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9793

Dept Direct: 6417 9793

Dept Direct: 6417 9793

Dept Direct: 6417 9793

Wiper blade: HWB (Hopen Wiper Blade, Silver / Made in Korea).

Spark plug: NGK (NGK Spark Plug, Made in Japan).

TAX INVOICE : AR201803-06183
DATE : 10/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1/ NF510M-4CCMA T32	HOOD	MO SUPPLIER	1	650.00	650.00

SUB-TOTAL : 650.00
ADD GST 7.00 % 45.50

E. & O.E TOTAL AMOUNT SGD : 695.50

[P] 10/03/2018 10:30:28AM

[E] 10/03/2018 10:19:15AM

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : GUAN



* AR201803-06183 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

THIRDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9933



Dept Direct: 6305 9010

Dept Direct: 6305 9011

Dept Direct: 6417 9722



Dept Direct: 6417 9794

Dept Direct: 6417 9755

Dept Direct: 6417 9755

Dept Direct: 6417 9759

Wiper blade: NPB (Nippon Wiper Blade), Silper (Made in Korea),
Ferch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY
ATTN: WENDY

00 6402

TAX INVOICE : AR201803-05539
DATE : 09/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1	N65810-4CL1A T32	SEAL - HOOD	CC CC9-B-01B5	1	25.00	25.00 ✓
2	N65810-4CL1B T32	SEAL - HOOD	CC CC9-B-01B3	1	25.00	25.00 ✓

SUB-TOTAL : 50.00
ADD GST 7.00 % 3.50

E. & O E TOTAL AMOUNT SGD : 53.50

[P] 09/03/2018 11:26:56AM

[E] 09/03/2018 11:19:50AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: GUAN

This is computer generated document.

No signature is required.



* A R 2 0 1 8 0 3 - 0 5 5 3 9 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 301B UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 0743 9530



Dept Direct: 6395 0618



Dept Direct: 6395 9011




Dept Direct: 6417 9792



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Wipac (Made in Japan)

TAX INVOICE AR201803-05481

DATE : 09/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

00 6402

SO STOCKID	DESCRIPTION	Std Loc	QTY	U/PRICE	AMOUNT
N62030-4CLOA	ARMATURE ASSY - FRT	MO	1	450.00	450.00
	BUMPER				RETURN X
T32		2B16			
2. N62090-4CE0A	ABSORBER - ENERGY, FRT	MO	1	175.00	175.00 ✓
	BUMPER				
T32		3N1			
3. N21481-4CE0A	MOTOR	MO	1	750.00	750.00 ✓
		SUPPLIER			
T32		MO			
4. N21410-4BB0A/B	RADIATOR (N21410-4BE0A)	MO	1	795.00	795.00 ✓
		SUPPLIER			
T32		MO			
5. N65810-4CL1C	SEAL - HOOD	MO	2	25.00	50.00 ✓
		SUPPLIER			

SUB-TOTAL : 2,220.00
ADD GST 7.00 % 155.40

E. & O.E TOTAL AMOUNT SGD : 2,375.40

[P] 09/03/2018 12:00:54PM

[E] 09/03/2018 10:45:53AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



* AR201803-05481 *

Goods Received in Good Order

Signature / Co Stamp / Date

This is computer generated document.

No signature is required.

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 9839



Wiper blade: NWB (Nippon Wiper blades), Silipor (Made in Korea).
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

TAX INVOICE : AR201803-05472
DATE : 09/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

00 6402

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U PRICE	AMOUNT
1	N2610M-1CCMA T32	HOOD	CC CC9-O-07A	1	650.00	650.00 Refund X
2	N26010-4CA5C/6D T32	HEAD LAMP RH HID	CC CC9-N-09C	1	1950.00	1,950.00 ✓
3	N26060-4CA5C/6D T32	HEAD LAMP LH	CC CC9-M-09C	1	1950.00	1,950.00 ✓
4	N62222-4CL0A T32	FRT BRACKET RH	CC CC9-B-03B1	1	20.00	20.00 ✓
5	N62223-4CL0A T32	FRT BRACKET LH	CC CC9-B-03B2	1	20.00	20.00 ✓
6	N62660-4CF0B T32	LOWER COVER	CC CC9-A-02B	1	270.00	270.00 Refund X
7	N62072-4BA0A T32	MLD - FRT BUMPER	CC CC9-C-06B	1	125.00	125.00 ✓

CONTINUE NEXT PAGE

[P] 09/03/2018 11:11:26AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 09/03/2018 10:38:26AM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9933



Dept Direct: 6305 9410

Dept Direct: 6305 9511

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9798

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY
ATTN: WENDY

TAX INVOICE : AR201803-05472
DATE : 09/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

00 6402

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
8	N62890-4BA0A T32	EMBLEM	CC CC9-C-04B	1	55.00	55.00 ✓
9	N62550-4CB0A T32	STAY ASSY - HOOD LOCK	CC CC9-B-01A3	1	50.00	50.00 ✓
10	N21606-4BA0A T32	OIL COOLER	CC CC9-C-09C	1	480.00	480.00 ✓
11	N62210-4CL0A/1A T32	STAY - FRT BUMPER, RH	CC CC9-B-01A1	1	58.00	58.00 ✓
12	N62211-4CL0A/1A T32	STAY - FRT BUMPER, LH	CC CC9-B-01A2	1	58.00	58.00 ✓

SUB-TOTAL : 5,686.00
ADD GST 7.00 % 398.02

E & O F TOTAL AMOUNT SGD : 6,084.02

[P] 09/03/2018 11:11:26AM

[E] 09/03/2018 10:38:26AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: GUAN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

PROGRESSIVE AUTOMOTIVE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY

ATTN : WENDY

REFER AR201803-05481

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 9033



Dept Direct: 6417 9754

Dept Direct: 6417 9755

Dept Direct: 6417 9756

Dept Direct: 6417 9753

Wiper blades: NWB (Nippon Wiper blade), Sliiper (Made in Korea).

Forch Made in Germany

Spark plug: Hanco, Bosch, NGK (Made in Japan)

TAX INVOICE : AR201803-06728

DATE : 12/03/2018

CUSTOMER ID : PRO005

VEH REG. NO. : SLH1747Z

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. N62030-4CL0A	ARMATURE ASSY - FRT BUMPER	MO	1	350.00	350.00
T32		2B16			

SUB-TOTAL : 350.00

ADD GST 7.00 % 24.50

E. & O.E TOTAL AMOUNT SGD : 374.50

[P] 12/03/2018 11:22:53AM

[E] 12/03/2018 11:22:24AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



* AR201803-06728 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-518201-3 CO. REG. NO.: 189307741M

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

00 6402

WINDSCREEN GLASS
Dept Direct: 6417 8791 / 6745 9932



Dept Direct: 6385 8810

Dept Direct: 6385 8811

Dept Direct: 6417 8792



Dept Direct: 6417 8794

Dept Direct: 6417 9285

Dept Direct: 6417 8790

Dept Direct: 6417 8793

Wiper blade: FWB (Nippon Wiper blade), Saliper (Made in Korea).

Spark plug: HIRATA (Hirata Spark Plug) Made in Japan

TAX INVOICE : ARC201803-05697
DATE : 09/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	N92100-5HA0A/4EB0A T32	AIR CONDENSER	MO SUPPLIER	1	750.00	750.00

SUB-TOTAL : 750.00
ADD GST 7.00 % 52.50

E. & O.E

TOTAL AMOUNT SGD : 802.50

[P] 09/03/2018 1:51:35PM

[E] 09/03/2018 1:51:04PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



* AR 201803-05697 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

[Signature]

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450618 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 728672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERSCREEN GLASS
Dept Direct: 6417 0781 / 6745 9930



Dept Direct: 6305 9618



Dept Direct: 6417 9735



Dept Direct: 6417 9735



Dept Direct: 6417 9750



Dept Direct: 6417 9750

Wiper blade: NWB (Nippon Wiper blade), Sliiper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE AUTOMOTIVE PTE LTD
BLOCK 3022A #01-45/46
UBI ROAD 1
BUTTON 92712711
SINGAPORE 408716
TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY
ATTN : WENDY

TAX INVOICE : AR201803-06332
DATE : 10/03/2018
CUSTOMER ID : PRO005
VEH REG. NO. : SLH1747Z
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

BY TODAY

00 6402

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	N62254-4CE0A T32	GRILLE - FRT BUMPER	CC CC9-E-04B	1	145.00	145.00

SUB-TOTAL : 145.00
ADD GST 7.00 % 10.15

E. & O.E TOTAL AMOUNT SGD : 155.15

[P] 10/03/2018 12:31:59PM

[E] 10/03/2018 12:27:14PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: GUAN

This is computer generated document.

No signature is required.



AR201803-06332

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Mar 2018 Sendback Est	07 Mar 2018 12:45 \$14,102.00	07 Mar 2018 13:23 Edit Adj Rpt	\$11,087.00 Edit Estimates	\$11,087.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	29 Mar 2018 09:53	16 Apr 2018 10:13 \$125.00	29 Mar 2018 15:22			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHOI KAM WAH , ID: S2697261B, Tel: +6591119226, Email: WAH124@YAHOO.COM									
Vehicle Reg. No.: SLF1747Z		Date of Loss: 03/03/2018 16:00 - :59 [18 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 1201800002924		Policy/Cover Note No.: PNPV2017-00005796 (Comprehensive)							
		Excess: \$500.00							
Repairer: Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/03/2018]									
Driver/Custodian: CHOI KAM WAH (59 / Male) , NRIC: S2697261B, Tel: +6591119226									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (20/04/2018): Alert - Adj Mandate Approved (\$11087.00) - SLF1747Z - Claim Handler: Clara Li Z... - FWD_SG (08/03/2018): Alert - Adj Mandate Approved (\$10942.00) - SLF1747Z - Claim Handler: Clara Li Z...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLF1747Z (1201800002924)

OD

Mar 3 2018 4:00PM

[CHOI KAM WAH]

Progressive Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser		
Video		1 per page 1 ☒		
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	05/03/18 16:49	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
Assessment Reports		1 per page 1 ☒		
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 12:45	Repairer Estimates	Load HTM	☐
2	16/04/18 10:13	Repairer Estimates Suppl. #1	Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 10:32	Adjuster Immediate Advice	Load HTM	☐
2	20/04/18 15:06	Adjuster Immediate Advice	Load HTM	☐
Photos/Images		3 per page 3 ☒		
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 12:45	1	Load JPG	☒
2	07/03/18 12:45	2	Load JPG	☒
3	07/03/18 12:45	3	Load JPG	☒
4	07/03/18 12:45	4	Load JPG	☒
5	07/03/18 12:45	5	Load JPG	☒
6	07/03/18 12:45	6	Load JPG	☒
7	07/03/18 12:45	7	Load JPG	☒
8	07/03/18 12:45	8	Load JPG	☒
9	07/03/18 12:45	9	Load JPG	☒
10	07/03/18 12:45	10	Load JPG	☒
11	07/03/18 12:45	11	Load JPG	☒
12	07/03/18 12:45	12	Load JPG	☒
13	07/03/18 12:45	13	Load JPG	☒
14	07/03/18 12:45	14	Load JPG	☒
15	07/03/18 12:45	15	Load JPG	☒
16	07/03/18 12:45	16	Load JPG	☒
17	07/03/18 12:45	17	Load JPG	☒
18	07/03/18 12:45	18	Load JPG	☒
19	07/03/18 12:45	19	Load JPG	☒
20	07/03/18 12:45	20	Load JPG	☒
21	07/03/18 12:45	21	Load JPG	☒
22	07/03/18 12:45	22	Load JPG	☒
23	07/03/18 12:45	23	Load JPG	☒
24	07/03/18 12:45	24	Load JPG	☒
25	07/03/18 12:45	25	Load JPG	☒
26	07/03/18 12:45	26	Load JPG	☒
27	07/03/18 12:45	27	Load JPG	☒
28	07/03/18 12:45	28	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
29	07/03/18 12:45	29	 Load JPG	☒
30	07/03/18 12:45	30	 Load JPG	☒
31	07/03/18 12:45	31	 Load JPG	☒
32	07/03/18 12:45	32	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 09:30	General View	 Load JPG	☒
2	19/04/18 09:30	General View	 Load JPG	☒
3	19/04/18 09:30	General View	 Load JPG	☒
4	19/04/18 09:30	General View	 Load JPG	☒
5	19/04/18 09:30	General View	 Load JPG	☒
6	19/04/18 09:30	General View	 Load JPG	☒
7	19/04/18 09:30	General View	 Load JPG	☒
8	19/04/18 09:30	General View	 Load JPG	☒
9	19/04/18 09:30	General View	 Load JPG	☒
10	19/04/18 09:30	General View	 Load JPG	☒
11	19/04/18 09:30	General View	 Load JPG	☒
12	19/04/18 09:30	General View	 Load JPG	☒
13	19/04/18 09:30	General View	 Load JPG	☒
14	19/04/18 09:30	General View	 Load JPG	☒
15	19/04/18 09:30	General View	 Load JPG	☒
16	19/04/18 09:30	General View	 Load JPG	☒
17	19/04/18 09:30	General View	 Load JPG	☒
18	19/04/18 09:30	General View	 Load JPG	☒
19	19/04/18 09:30	General View	 Load JPG	☒
20	19/04/18 09:30	General View	 Load JPG	☒
21	19/04/18 09:30	General View	 Load JPG	☒
22	19/04/18 09:30	General View	 Load JPG	☒
23	19/04/18 09:30	General View	 Load JPG	☒
24	19/04/18 09:30	General View	 Load JPG	☒
25	19/04/18 09:30	General View	 Load JPG	☒
26	19/04/18 09:30	General View	 Load JPG	☒
27	19/04/18 09:30	General View	 Load JPG	☒
28	19/04/18 09:30	General View	 Load JPG	☒
29	19/04/18 09:30	General View	 Load JPG	☒
30	19/04/18 09:30	General View	 Load JPG	☒
31	19/04/18 09:30	General View	 Load JPG	☒
32	19/04/18 09:30	General View	 Load JPG	☒
33	19/04/18 09:30	General View	 Load JPG	☒
34	19/04/18 09:30	General View	 Load JPG	☒
35	19/04/18 09:30	General View	 Load JPG	☒
36	19/04/18 09:30	General View	 Load JPG	☒
37	19/04/18 09:30	General View	 Load JPG	☒
38	19/04/18 09:30	General View	 Load JPG	☒
39	19/04/18 09:30	General View	 Load JPG	☒
40	19/04/18 09:30	General View	 Load JPG	☒
41	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
42	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
43	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
44	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
45	19/04/18 09:31	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
46	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
47	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
48	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
49	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
50	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
51	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
52	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
53	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
54	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
55	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
56	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
57	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
58	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
59	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
60	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
61	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
62	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
63	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
64	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
65	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
66	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
67	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
68	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
69	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
70	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
71	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
72	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
73	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
74	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
75	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
76	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
77	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
78	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
79	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
80	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
81	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
82	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
83	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
84	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
85	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
86	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
87	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
88	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
89	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
90	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
91	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
92	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
93	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
94	19/04/18 09:31	Reinspection Photo	 Load JPG	☒
95	19/04/18 09:31	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
96	19/04/18 09:31	Reinspection Photo	Load JPG	☒
97	19/04/18 09:31	Reinspection Photo	Load JPG	☒
98	19/04/18 09:31	Reinspection Photo	Load JPG	☒
99	19/04/18 09:31	Reinspection Photo	Load JPG	☒
100	19/04/18 09:31	Reinspection Photo	Load JPG	☒
101	19/04/18 09:31	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Automotive Pte Ltd (HQ)	Thumbnail	Print
1	07/03/18 12:45	E-filed GIA report	Load PDF	
2	07/03/18 12:45	Certificate of Insurance	Load TIF	
3	07/03/18 12:45	Claimant's NRIC & LICENSE	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/03/18 10:38	SLF 1747Z ESTIMATE	Load PDF	
2	08/03/18 11:12	Certificate of Insurance	Load PDF	
3	08/03/18 11:12	SLF 9674Y ESTIMATE	Load PDF	
4	08/03/18 11:12	Singapore Accident Statement	Load PDF	
5	08/03/18 11:12	Insured's NRIC & DL	Load PDF	
6	20/04/18 14:55	SLF 1747Z SUPPLEMENTARY ESTIMATE	Load PDF	
7	26/04/18 15:09	Parts Invoice	Load PDF	

Linked Accident Report Documents

Video			View	View In Browser	
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	05/03/18 16:49	Video - Accident		Load MP4	
Assessment Reports			1 per page		
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	05/03/18 16:49	Accident Statement		Load HTM	
Photos/Images			3 per page		
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	05/03/18 16:41	Accident Photo		Load JPG	
2	05/03/18 16:41	Accident Photo		Load JPG	
3	05/03/18 16:41	Accident Photo		Load JPG	
4	05/03/18 16:41	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Progressive Automotive Pte Ltd (HQ)		Thumbnail	Print
1	05/03/18 16:42	Sketch Plan		Load JPG	
2	05/03/18 16:42	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18004395/ARBE2

Date: 26/04/2018

REFERENCE

Insured/Claimant: CHOI KAM WAH Policy No: PNPV2017-00005796
Date of Loss: 03/03/2018 Nature of Claim: OD Claim No: 1201800002924

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF1747Z
Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20890168B
Reg. Date: 16/08/2016 (Man. Year: 2016) Chassis No: JN1JANT32Z0002386
Colour: Brown Odometer: 17624 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$112,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,082.00	9,542.00	2,540.00	21.02
Miscellaneous Items	55.00	55.00	0.00	0.00
Labour	1,090.00	790.00	300.00	27.52
Paintwork Labour	1,000.00	700.00	300.00	30.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,227.00	11,087.00	3,140.00	22.07
- Excess (\$\$)	0.00	500.00	-500.00	
(\$\$)	14,227.00	10,587.00	3,640.00	25.59
+ GST 7.00/7.00% (\$\$)	995.89	741.09	254.80	25.59
Nett Amount (\$\$)	15,222.89	11,328.09	3,894.80	25.59

INSPECTION

Date of Assignment: 07/03/2018 Present Location: Progressive Automotive Pte Ltd (HQ)
Date Inspected: 07/03/2018 Inspected At: Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Apr 2018)	
Parts:	N/A	NISSAN X-TRAIL 2.0 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF1747Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET	Dented	650.00 F	*650.00 F
2	1	NA	*BONNET LOCK	Not Necessary	90.00 F	*- F
3	1	NA	*BONNET RUBBER - INNER - LH	Necessary	25.00 F	*25.00 F
4	1	NA	*BONNET RUBBER - INNER - RH	Necessary	25.00 F	*25.00 F
5	1	NA	*BONNET RUBBER - OUTER - LH	Necessary	25.00 F	*25.00 F
6	1	NA	*BONNET RUBBER - OUTER - RH	Necessary	25.00 F	*25.00 F
7	1	NA	*BONNET HINGE - RH	Not Necessary	50.00 F	*- F
8	1	NA	*BONNET HINGE - LH	Bent	50.00 F	*50.00 F
9	12	NA	*BONNET INSULATOR CLIPS	Necessary	24.00 F	*24.00 F
10	1	NA	*FRONT BUMPER	Deformed	450.00 F	*450.00 F
11	1	NA	*FRONT BUMPER SIDE HOLDER - RH	Necessary	20.00 F	*20.00 F
12	1	NA	*FRONT BUMPER SIDE HOLDER - LH	Necessary	20.00 F	*20.00 F
13	10	NA	*FRONT BUMPER CLIPS	Necessary	20.00 F	*20.00 F
14	1	NA	*FRONT BUMPER REINFORCEMENT	Bent	350.00 F	*350.00 F
15	1	NA	*FRONT BUMPER FOG LAMP COVER - LH	Not Necessary	75.00 F	*- F
16	1	NA	*FRONT BUMPER FOG LAMP COVER - RH	Not Necessary	75.00 F	*- F
17	1	NA	*FRONT BUMPER FOG LAMP - LH	Not Necessary	250.00 F	*- F
18	1	NA	*FRONT BUMPER FOG LAMP - RH	Not Necessary	250.00 F	*- F
19	1	NA	*FRONT BUMPER BRACKET - LH	Bent	58.00 F	*58.00 F
20	1	NA	*FRONT BUMPER BRACKET - RH	Bent	58.00 F	*58.00 F
21	1	NA	*FRONT BUMPER FOAM	Cracked	175.00 F	*175.00 F
22	1	NA	*FRONT BUMPER TOWING COVER - LH	Not Necessary	20.00 F	*- F
23	1	NA	*FRONT BUMPER LOWER GARNISH; BLACK	Deformed	270.00 F	*145.00 F
24	1	NA	*FRONT BUMPER LOWER CHROME	Cracked	125.00 F	*125.00 F
25	1	NA	*GRILLE W/CHROME ASSY - CENTRE	Cracked	380.00 F	*380.00 F
26	1	NA	*GRILLE LOGO	Necessary	55.00 F	*55.00 F
27	6	NA	*GRILLE CLIP	Necessary	12.00 F	*12.00 F
28	1	NA	*HEAD LAMP UNIT - LH (HID)	Cracked	1,950.00 F	*1,950.00 F
29	1	NA	*HEAD LAMP UNIT - RH (HID)	Cracked	1,950.00 F	*1,950.00 F
30	1	NA	*HEAD LAMP LOWER RETAINER - LH	Not Necessary	25.00 F	*- F
31	1	NA	*HEAD LAMP LOWER RETAINER - RH	Not Necessary	25.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1	NA	*TOP PANEL	Repair	190.00 F	*- F
33	2	NA	*HEAD LAMP PANEL - LH; RH	Repair	150.00 F	*- F
34	1	NA	*LOWER MEMBER	Repair	260.00 F	*- F
35	1	NA	*BRACE PANEL	Bent	50.00 F	*50.00 F
36	1	NA	*HORN - LH	Not Necessary	95.00 F	*- F
37	1	NA	*HORN - RH	Not Necessary	95.00 F	*- F
38	1	NA	*AIRCON CONDENSER	Dented	750.00 F	*750.00 F
39	1	NA	*AIRCON/RADIATOR FAN MOTOR; COWLING & BLADE ASSY	Damaged	750.00 F	*750.00 F
40	1	NA	*AIRCON DISCHARGE PIPE	Not Necessary	230.00 F	*- F
41	1	NA	*AIRCON LIQUID TUBE	Not Necessary	130.00 F	*- F
42	1	NA	*RADIATOR	Dented	795.00 F	*795.00 F
43	1	NA	*WIPER TANK ASSY	Not Necessary	240.00 F	*- F
44	1	NA	*RADIATOR SPARE TANK	Not Necessary	85.00 F	*- F
45	1	NA	*RADIATOR TOP HOSE	Not Necessary	35.00 F	*- F
46	1	NA	*RADIATOR BOTTOM HOSE	Not Necessary	45.00 F	*- F
47	1	NA	*OIL COOLER	Dented	480.00 F	*480.00 F
48	1	NA	*POWER STEERING RETURN HOSE - NO PRICE	Not Necessary	0.00 F	*- F
Supplementary #1						
49	2		*AIRCON SIDE GARNISH - LH/RH	Deformed	90.00 F	*90.00 F
50	1		*AIRCON TEMPERATURE SENSOR	Damaged	35.00 F	*35.00 F

F=Franchise part.

Total Parts (S\$) 12,082.00 9,542.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	20.00	20.00
2	1	FRONT NUMBER PLATE W/CASING (BENT)	35.00	35.00
Sub Total (S\$)			55.00	55.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00	700.00
Labour Items				
2	TO KNOCK OUT DENTS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	880.00	660.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
5	TO RESET CHECK LIGHT	New	60.00	0.00
Gross Labour Cost (S\$)			2,090.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >