

FIRST AUTOWORKS

Repair Estimate

Date : 06/03/2018

Reference:

To Whom It May Concern

Make: OPEL
ASTRA

Dear Sir,

*Not Delivered
like
to repair to be done
7/3/18
327.*

RE: VEHICLE .: SLM 5250B
CHASSIS NO.: W0LBE8EA4H8042287
ENGINE NO.: B1163377GT2X0966

Name of insured .: Azmi Bin Saat
Date of accident.: 03/03/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

| No. | Qty | Part Description | Price (SGD) |
|---------------------|-----|----------------------------|-------------------|
| 1 | 1 | FRT BUMPER FASCIA | 1,800.00 <i>X</i> |
| 2 | 1 | FRT BUMPER BRACKET RH | 50.00 <i>---</i> |
| 3 | 1 | FRT BUMPER (BOLT) SET | 30.00 <i>---</i> |
| 4 | 1 | HEAD LAMP RH | 950.00 <i>X</i> |
| 5 | 1 | HEAD LAMP RH BRACKET | 150.00 <i>X</i> |
| 6 | 1 | FOG LAMP COVER RH | 250.00 <i>X</i> |
| 7 | 1 | FRT FENDER RH | 650.00 <i>---</i> |
| 8 | 1 | FRT FENDER BRACKET | 50.00 <i>?</i> |
| 9 | 1 | FRT FENDER RH WHEEL LINNER | 150.00 <i>?</i> |
| Parts Total: | | | 4,080.00 |
| Less 10%: | | | 408.00 |
| Total : | | | 3,672.00 |

Labour

| No. | Labour Description | Price (SGD) |
|-----------------------|---|---------------------|
| 1 | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. | 2500.00 <i>650</i> |
| 2 | Carry out spray painting on accident affected area. (frt Lh fender & Frt bumper other affected area) | 1800.00 <i>1100</i> |
| 3 | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair | 160.00 <i>30</i> |
| 4 | To conduct 4 wheel alignment | 160.00 <i>X</i> |
| Labour Total : | | 4,620.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicoon Building, Singapore 415003 - Tel: 6844 1985 Fax: 6844 5185

Other


| <u>No.</u> | <u>Qty</u> | <u>Other Description</u> | <u>Price (SGD)</u> |
|------------|------------|--------------------------|--------------------|
| 1 | 1 | Rim | 400.00 X |
| 2 | 1 | Tyre | 250.00 X |

Other Total : 650.00

Total : \$8,942.00
Gst (7%) : \$625.94
GRAND TOTAL: \$9,567.94

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor
Ronnie Tan
DID: 6844 1985 Fax:6844 5185