

ASS. REC. BY:

REF: CS/GA118004398/Urbna

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Rachel Tan

of

GAI

Date/Time: 07/03/2018 2:28pm

Estimated Cost:

Bill to:

OD / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 4774B

Insured: SJK 7852K

at Workshop m/s Trans Eurocars

Tel: 6395 8685

of 5 ubi close

Policy No:

Claim No: CLMOMVP000000597

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 02/03/2018

CA / REV / REP. / REV 24 HRS 'wpi'

07-03-2018 @ 2:30pm

H.O.D. Endorsement:

Date/Time: 07/03/2018 3pm

Person Contacted:

Jess

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 4774B - x
	SJK 7852K - (07 / ALH 11017800 / Gpb392) D.A: 30/08/2011
	Perant thru email

Mercurus

GAI

ASSIGNMENT

From _____ Date 9/3/18

Estimated Cost: _____

DD: TP WS TP RES / OD RES / EVA / INV / MV

Tow/used Vehicle No: SLT 4774B

at Workshop/mile: Trans Eurokars

at: Subi close

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

Client's Record: 2:30pm Owner exiting

Make of ver: Jess

Ver No: SLT4774B Page: 10 17

Type: Car M/Cycle Bus/Van/Truck Taxi Prime Mover

Truck T/A and: (A)

Make: Mazda 5 Year: 1998

Color: blue

So Reading: 13204

Eng No: _____

Chassis: YM6CW1071H0126168

Gen Cont: Good Fair Poor Burnt

Steering: OK Jammed Leaked Burnt or

Brake: OK Jammed Leaked Burnt or

Mod: Nil SRIM STD 4 Rim or

Tyre Size: F

R 205/55-16

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Ball or Market value: _____

DAC Accident Report: 2 Consistent?: Yes or No

CP Seen: 2 Consistent?: Yes or No

Est Repairs: 8 days Res: Yes or No

Wm Sum: 1.31 % S/Vail: Yes or No

CA / REV / REP / 24 HRS / wp

Date: _____ Person Contacted: _____ Vehicle IN / OUT

BS / DUN / EXNOVA / G / PS LIZA MID OHTSL FR SUM

YOYO / YOKO or

Front	7	Back	7
REs	--	REs	--
LBs	--	LBs	--
DD	<u>2/3/18</u>	DD	<u>9/3/18</u>

Survey report: _____

Des of Damages: Ree

The UIC / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

26/4/18 Confirmed final g of 10414.69 with collection.

led: \$ 9575.27, 48%.

RECEIVED 03 MAY 2018

Date Time File Pass of: typist

Prelim Report

Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: _____

Report Format: TP

10,414.69

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004398/Urb

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 07-03-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 7852K	Veh. Inspected	SLT 4774B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/03/2018	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Our Ref: CS/GAI18004398/Urb

The Motor Claims Department
GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF SLT 4774B .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02/03/2018 at the premises of M/s TRANS EUROKARS PTE LTD and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 19,989.96</u> .
Revised Estimate Amount	: <u>S\$ 10,414.69</u> .
“Check” Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear portion..



Yours faithfully
MARCUS
Automotive Assessor

Catherine Chong (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Wednesday, 7 March, 2018 2:28 PM
To: LKK Assignments
Subject: RE: YOUR REF: SJK7852K / OUR REF: SLT4774B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)
Attachments: 2919_001.pdf

Dear LKK

Please accept assignment to conduct TP PRI on a without prejudice basis, thank you.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]
Sent: Wednesday, March 7, 2018 9:13 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg; admin-d@lkkauto.com
Subject: RE: YOUR REF: SJK7852K / OUR REF: SLT4774B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Hi Rachel,

We choose LKK AUTO CONSULTANTS for this case.

Kindly do the necessary arrangements.

Regards.

Jess Francis Carlos
Insurance Claims Executive
Trans Eurokars Pte Ltd
5 Ubi Close
Singapore 408605
Tel no.: 63958784

From: Eric Pau
Sent: Wednesday, 7 March 2018 9:08 AM
To: Jess Francis <jess.francis@eurokars.com.sg>
Subject: FW: YOUR REF: SJK7852K / OUR REF: SLT4774B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

FYI

Best Regards,

Eric Pau
Insurance Claims Officer

TRANS EUOKARS PTE LTD
5 Ubi Close, Singapore 408605

D: (65) 6395 8685 H: (65) 9618 5991
E: eric.pau@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

Sent: Tuesday, March 6, 2018 6:29 PM

To: Eric Pau <eric.pau@eurokars.com.sg>

Subject: RE: YOUR REF: SJK7852K / OUR REF: SLT4774B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Without Prejudice

Dear Eric

Has this been attended to? If not, We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: eric.pau@eurokars.com.sg [<mailto:eric.pau@eurokars.com.sg>]

Sent: Monday, March 05, 2018 5:51 PM

To: Ng, Sharon <Sharon.Ng@sg.gaig.com>; jess.francis@eurokars.com.sg

Cc: ronald.yap@eurokars.com.sg; vion.lim@eurokars.com.sg; catherinechua@eurokars.com.sg

Subject: YOUR REF: SJK7852K / OUR REF: SLT4774B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

YOUR REF: SJK7852K / OUR REF: SLT4774B THIRD PARTY CLAIM (REQUESTING FOR SURVEY AND A DIRECT SETTLEMENT)

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Liaise with Jess for survey arrangement.

Best Regards,

Eric Pau

Insurance Claims Officer

TRANS EUROKARS PTE LTD
5 Ubi Close, Singapore 408605
D: (65) 6395 8685 H: (65) 9618 5991
E: eric.pau@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]
Sent: Monday, March 5, 2018 6:00 PM
To: Eric Pau <eric.pau@eurokars.com.sg>
Subject: Attached Image

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0451H

Vehicle Details

Vehicle No.: SLT4774B

Vehicle to be Exported: No

Intended De-registration Date: 09 Mar 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA5 WAGON 2.0 AT
EU6

Primary Colour: Blue

Manufacturing Year: 2017

Engine No.: PE10520690

Chassis No.: JM6CW1071H0126168

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$17,222.00

Original Registration Date: 30 Oct 2017

First Registration Date: 30 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$17,222.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Oct 2027

PARF Rebate Amount: \$12,916.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2027

COE Category: E - Open - all except
motorcycle

COE Period(Years): 10

QP Paid: \$49,012.00

COE Rebate Amount: \$47,233.00

Total Rebate Amount: \$60,149.00

The information contained herein is correct as at 09 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/03/2018 08:47
Date Of Accident 02/03/2018 17:45
Exact Location Of Accident BKE
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT4774B

Insured/Policyholder
Name Of Registered Owner TAN CHUEN HUN
NRIC No S7180451H
Email Address CHUENHUN.TAN@YAHOO.COM
Mobile Phone No (LOCAL) +65-92975977
Alternative Phone No OTHERS-92975977

Vehicle Particulars
Manufacturer MAZDA
Model MAZDA 5
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company
Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 1700077952
Cover Note Number

Driver
Name of Driver TAN CHUEN HUN
NRIC No S7180451H
Date Of Birth 16/05/1971
Occupation INDOOR
Date Of Driving Pass 12/03/1999
Driving Experience 18 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-92975977
Fax Number
Contact Number OTHERS-92975977
EMail Address CHUENHUN.TAN@YAHOO.COM

Address 63 ROSEWOOD DRIVE
 #04-10
 Postcode 737874
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 *

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4

Passenger 1 NAME: : WENDY YONG WEI LAN
 GENDER: : FEMALE
 Passenger 2 NAME: : NAOMI TAN MENG CHION
 GENDER: : FEMALE
 Passenger 3 NAME: : NATRICIA TAN MENG HWI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJK7852K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver AW QIAN WEN, SIMONE
 NRIC/Passport Number S8822140J
 Contact Number 91090660

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

GREAT AMERICAN INSURANCE COMPANY

2



SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Polichholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts any allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involving in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) Investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Signature
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policy holder) / Date & Time

Signature
Witnessed by Reporting Centre Personnel

MAR 31 2019

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on BKE AND in ~~lane~~

I was driving on BKE on 2 March 2018 around 1745, at lane 1
toward woodland.

The car in front stop. I also stop and about 10 second.

The car behind hit my car at rear. It was rainy heavily
no one injure

0

other passenger 4
my wife Wendy yong wei len 90568036

Daughter Naomi To Meng Chien
 Xitricia To Meng Hui

Declaration

I/We declare the foregoing particulars are true in every respect.

D
MAR 31 2018

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policy holder) / Date & Time Witnessed by Reporting Centre Personnel

APPROXIMATE ON W/M 9: @ 2:30



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



GREAT AMERICAN INSURANCE COMPANY 3 Temasek Ave., #16-01 Centennial Tower Singapore 039190 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Tan Chuen Hun ADDRESS : 63 Rosewood Drive #04-10 Singapore 737874 TEL : 92975977	WIP : 10698 EXCESS : DATE: 5-Mar-18 <i>g day</i> <i>Not Authorized</i> <i>Make</i> <i>Take photo before parting</i> <i>9/3/18</i>
VEH NO :	SLT4774B	DATE IN :	CONTACT PERSON :
CHASSIS NO :	JM6CW1071H0126168	MILEAGE :	JESS 6395 7874
MODEL :	MAZDA5	DATE REG.:	THIRD PARTY CLAIM
		30-Oct-17	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES		
1	REAR BUMPER	1	MC513-50-221EBB	7-3	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-211C	sep	\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	hand	\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	neu	\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	neu	\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371	11	\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E	11	\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361	11	\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E	cre	\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC	22	\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	neu	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	neu	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	neu	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	neu	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	neu	\$ 8.80
16	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	neu	\$ 6.60
17	PANEL, REAR END	1	MCG15-70-750B	n	\$ 491.10
18	TAILGATE	1	MCGY3-62-02XF	S. by 22	\$ 1,559.00
19	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	neu	\$ 22.80
20	WEATHERSTRIP, TAILGATE	1	MC513-62-761C	11	\$ 169.00
21	TRIM LOWER, TAILGATE	1	MC513-68-960B	11	\$ 411.40
22	TAPE PROTECTOR, TAILGATE	2	MBR5S-56-994	neu	\$ 14.40
23	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864	neu	\$ 14.00
24	LOCK, TAILGATE	1	MC513-62-310A	22	\$ 244.00
25	GARNISH, TAILGATE	1	MC513-50-810F13	11	\$ 459.40
26	CLIP, GARNISH	3	MEG21-51-SJ3	neu	\$ 16.20
27	SEAL, TAILGATE	4	MGJ6A-50-818	neu	\$ 10.00
28	MAZDA, EMBLEM	1	MCGY0-51-711	neu	\$ 43.10
29	S, EMBLEM	1	MCGY0-51-721	neu	\$ 34.50
30	SKYACTIV, EMBLEM	1	MC597-51-771	neu	\$ 76.10

31	MOULD, REAR WINDSCREEN	1	MCS13-50-611	<i>nu</i>	\$ -	57.60	/	
32	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	<i>nu</i>	\$ -	5.20	/	
33	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	<i>nu</i>	\$ -	6.80	/	
34	FASTENER, REAR WINDSCREEN	2	MC273-50-896	<i>nu</i>	\$ -	15.60	/	
35	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	<i>nu</i>	\$ -	48.40	/	
36	PIN STUD, REAR WINDSCREEN	1	MG21E-63-938B	<i>nu</i>	\$ -	10.50	/	
37	PROTECTOR, REAR SPOILER	2	MC514-51-979B	<i>nu</i>	\$ -	10.40	/	
38	PROTECTOR, REAR SPOILER	2	MC514-51-982B	<i>nu</i>	\$ -	22.80	/	
39	PROTECTOR, REAR SPOILER	2	MC514-51-972B	<i>nu</i>	\$ -	26.80	/	
40	CLIP, REAR SPOILER	3	MC514-51-958A	<i>nu</i>	\$ -	21.90	/	
41	CLIP, REAR SPOILER	1	MC525-51-958A	<i>nu</i>	\$ -	8.20	/	
42	LAMP(LHS), TAILLAMP	1	MC513-51-160D	<i>11</i>	\$	573.00	/	
43	LAMP(RHS), TAILLAMP	1	MC513-51-150D	<i>11</i>	\$	573.00	/	
44	GROMMET, TAILLAMP	2	MEA02-51-146A	<i>nu</i>	\$ -	6.00	/	
45	GROMMET, TAILLAMP	2	MEA01-51-146B	<i>nu</i>	\$ -	5.40	/	
46	FASTENER, TAILLAMP	2	MGJ6A-51-14Y	<i>nu</i>	\$ -	29.80	/	
47	FASTENER, TAILLAMP	4	MB01W-51-142B	<i>nu</i>	\$ -	12.00	/	
48	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	<i>nu</i>	\$ -	90.80	/	
49	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	<i>nu</i>	\$ -	90.80	/	
50	LHS TAILLAMP	1	MC513-51-3G0G	<i>nu</i>	\$	370.00	/	
51	TRIM, BOOT END	1	MC513-68-89XD	<i>11</i>	\$	76.50	/	
52	BEZEL, LOCK	1	MC513-68-894A	<i>11</i>	\$	13.00	/	
53	TRAY BOOT END	1	MC235-68-8MXD00	<i>11</i>	\$	342.50	/	
					TOTAL PARTS	\$	7,344.40	
					LESS 10%	\$	734.44	
					TOTAL PARTS COST	\$	6,609.96	

Labour Description

1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>660</i>	<i>1650</i>	\$	4,620.00	
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, TAILGATE AND REAR SPARE TYRE FLOOR PANEL.	<i>630</i>	<i>2205</i>	\$	3,780.00	
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		<i>nu</i>	\$	350.00	
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		<i>1500</i>	\$	250.00	
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		<i>300</i>	\$	660.00	
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.		<i>NETT</i>	\$	560.00	
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	<i>nu</i>	<i>NETT</i>	\$	120.00	

8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	200	\$ 660.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
10		TO SUPPLY EXHAUST TIP MUFFLER.	11 X	NETT \$ 150.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	Sub	NETT \$ 70.00 ✓
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
14		TO SUPPLY BRILA PREMIUM COATING.	20 30	NETT \$ 800.00 ✓
15	MZ-BR-SUNDRI	SUNDRIES.	30	NETT \$ 100.00 ✓

TOTAL LABOUR	\$ -	\$ 13,380.00
TOTAL PARTS	\$ -	\$ 6,609.96
TOTAL	\$ -	\$ 19,989.96
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



GREAT AMERICAN INSURANCE COMPANY		NAME : Mr Tan Chuen Hun		WIP : 10698	
3 Temasek Ave.,		ADDRESS : 63 Rosewood Drive		EXCESS :	
#16-01 Centennial Tower		#04-10		DATE: 5-Mar-18	
Singapore 039190		Singapore 737874			
ATTN. : MOTOR CLAIMS		TEL : 92975977			
FAX :					
VEH NO :	SLT4774B	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6CW1071H0126168	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	30-Oct-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	\$ 915.40	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C	\$ 45.30	\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	\$ 45.30	\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	\$ 5.40	\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	\$ 5.40	\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371		\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E		\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361		\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E	\$ 50.40	\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC	\$ 148.00	\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.00	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 21.60	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-ES1	\$ 8.80	\$ 8.80
16	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ 6.60	\$ 6.60
17	PANEL, REAR END	1	MCG15-70-750B		\$ 491.10
18	TAILGATE	1	MCGY3-62-02XF	\$ 1,559.00	\$ 1,559.00
19	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	\$ 22.80	\$ 22.80
20	WEATHERSTRIP, TAILGATE	1	MC513-62-761C		\$ 169.00
21	TRIM LOWER, TAILGATE	1	MC513-68-960B		\$ 411.40
22	TAPE PROTECTOR, TAILGATE	2	MBR55-56-994	\$ 14.40	\$ 14.40
23	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864	\$ 14.00	\$ 14.00
24	LOCK, TAILGATE	1	MC513-62-310A	\$ 244.00	\$ 244.00
25	GARNISH, TAILGATE	1	MC513-50-810F13		\$ 459.40
26	CLIP, GARNISH	3	MEG21-51-SJ3	\$ 16.20	\$ 16.20
27	SEAL, TAILGATE	4	MGJ6A-50-818	\$ 10.00	\$ 10.00
28	MAZDA, EMBLEM	1	MCGY0-51-711	\$ 43.10	\$ 43.10
29	S, EMBLEM	1	MCGY0-51-721	\$ 34.50	\$ 34.50
30	SKYACTIV, EMBLEM	1	MC597-51-771	\$ 76.10	\$ 76.10
31	MOULD, REAR WINDSCREEN	1	MC513-50-611	\$ 57.60	\$ 57.60

32	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	\$ 5.20	\$ 5.20
33	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	\$ 6.80	\$ 6.80
34	FASTENER, REAR WINDSCREEN	2	MC273-50-896	\$ 15.60	\$ 15.60
35	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	\$ 48.40	\$ 48.40
36	PIN STUD, REAR WINDSCREEN	1	MG21E-63-938B	\$ 10.50	\$ 10.50
37	PROTECTOR, REAR SPOILER	2	MC514-51-979B	\$ 10.40	\$ 10.40
38	PROTECTOR, REAR SPOILER	2	MC514-51-982B	\$ 22.80	\$ 22.80
39	PROTECTOR, REAR SPOILER	2	MC514-51-972B	\$ 26.80	\$ 26.80
40	CLIP, REAR SPOILER	3	MC514-51-958A	\$ 21.90	\$ 21.90
41	CLIP, REAR SPOILER	1	MC525-51-958A	\$ 8.20	\$ 8.20
42	LAMP(LHS), TAILLAMP	1	MC513-51-160D		\$ 573.00
43	LAMP(RHS), TAILLAMP	1	MC513-51-150D		\$ 573.00
44	GROMMET, TAILLAMP	2	MEA02-51-146A	\$ 6.00	\$ 6.00
45	GROMMET, TAILLAMP	2	MEA01-51-146B	\$ 5.40	\$ 5.40
46	FASTENER, TAILLAMP	2	MGJ6A-51-14Y	\$ 29.80	\$ 29.80
47	FASTENER, TAILLAMP	4	MB01W-51-142B	\$ 12.00	\$ 12.00
48	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	\$ 90.80	\$ 90.80
49	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	\$ 90.80	\$ 90.80
50	LHS TAILLAMP	1	MC513-51-3G0G	\$ 370.00	\$ 370.00
51	TRIM, BOOT END	1	MC513-68-89XD		\$ 76.50
52	BEZEL, LOCK	1	MC513-68-894A		\$ 13.00
53	TRAY BOOT END	1	MC235-68-8MXD00		\$ 342.50
TOTAL PARTS				\$ 4,144.10	\$ 7,344.40
LESS 10%				\$ 414.41	\$ 734.44
TOTAL PARTS COST				\$ 3,729.69	\$ 6,609.96

Labour Description

1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,650.00	\$ 4,620.00
2		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, TAILGATE AND REAR SPARE TYRE FLOOR PANEL.	\$ 2,205.00	\$ 3,780.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 300.00	\$ 660.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	\$ 560.00	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$ 120.00	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 200.00	\$ 660.00
9	MZ-BR-REVTEN	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00

10		TO SUPPLY EXHAUST TIP MUFFLER.		\$ 150.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	\$ 70.00	\$ 70.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
14		TO SUPPLY BRILA PREMIUM COATING. ADD	\$ 800.00	\$ 800.00
15	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 6,685.00 \$ 13,380.00
			TOTAL PARTS	\$ 3,729.69 \$ 6,609.96
			TOTAL	\$ 10,414.69 \$ 19,989.96
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 10,414.69
			GST 7%	\$ 729.03 \$ -
			GRAND TOTAL	\$ 11,143.72 \$ -

net

REMARKS:

8 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



mazda

CODE:

c0003 CS-WSHOP

CUSTOMER:
ADDRESS:

Mr Tan Chuen Hun
63 Rosewood Drive
#04-10

TEL NO:

Singapore 737874
Mobile: 92975977

MODEL:

MAZDA5 SKYACTIVE

CHASSIS NO:

JM6CW1071H0126168

ENGINE NO:

PE10520690

DESCRIPTION:

General mechanical

TAX INVOICE

GST Reg No:M90364005A

Mazda

PAGE NO : 1

INVOICE NO: L 29241536

DEPT/POS ID: L / 12

DATE IN 15/11/2017

DATE PRINTED: 15/11/2017

JOB NO : 44777

CSO/OP CODE: John Lim

REGN NO : SLT4774B

REGN DATE : 30/10/2017

MILEAGE : 648

REQUISITION NO: JOHNLIM

CODE	DESCRIPTION	AMOUNT
SUB	BRILA PREMIUM BODY COATING	976.00
NOTES	SLT4774B / 123917 / INVOICE NO.81008324 / JOHNLIM 1)APPLY BRILA PREMIUM BODY COATING - DONE 2)CHECK BP9.0 DVR CAMERA CANT VIEW BACK CAMERA - REFER PETER LIM, RECONNECT BACK CAMERA. - TESTED WORKING	0.00
	Parts	0.00
	Surcharge	0.00
	Labour	976.00
	Menus	0.00
	Net	976.00
	G.S.T. 7%	68.32
	Total	1,044.32
	Paid	0.00
	Amount Due	1,044.32

COPY DOCUMENT

WORKSHOP COPY

All major repaired parts stated above are covered under a 6 months or 10,000 km warranty, whichever comes first. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handlings.


TRANS EUROKARS PTE LTD

Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER
NO:

Customer Signature

Authorised Signature



zoom-zoom

Corporate Head Office : Trans Eurokars Pte Ltd, Eurokars Centre 12 Sungai Kadut Ave Singapore 729648
Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

Showroom & Service Centre : 5 Ubi Close Singapore 408605
Sales Tel : 6395 8888 Service Tel : 6395 8899
Sales Fax : 6848 1700 Service Fax : 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel : 6803 6118 Service Tel : 6803 6128
Sales Fax : 6476 7073 Service Fax : 6476 7417



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18004398/Urbn2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 10-05-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 7852K	Veh. Inspected	SLT 4774B
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000000597	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6CW1071H0126168	Colour	BLUE
Odometer	13204	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOYO	7 mm
L/H Front Tyre	205/55 R16	TOYO	7 mm
R/H Rear Tyre	205/55 R16	TOYO	7 mm
L/H Rear Tyre	205/55 R16	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/03/2018	Inspection Date	09/03/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4774B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	915.40	915.40
1	RETAINER (LHS),REAR BUMPER	BENT	45.30	45.30
1	RETAINER (RHS),REAR BUMPER	BENT	45.30	45.30
1	BRACKET (LHS),REAR BUMPER	NECESSARY	5.40	5.40
1	BRACKET (RHS),REAR BUMPER	NECESSARY	5.40	5.40
1	GUARD (LHS),REFLECTOR	NOT NECESSARY	20.50	-
1	REFLECTOR LHS	NOT NECESSARY	50.40	-
1	GUARD (RHS),REFLECTOR	NOT NECESSARY	20.50	-
1	REFLECTOR RHS	CRACKED	50.40	50.40
1	REAR REINFORCEMENT	DENTED	148.00	148.00
2	FASTENER,REAR BUMPER	NECESSARY	6.00	6.00
4	RIVET,REAR BUMPER	NECESSARY	21.60	21.60
1	GROMMET,REAR BUMPER	NECESSARY	2.80	2.80
4	GROMMET,REAR BUMPER	NECESSARY	10.00	10.00
2	GROMMET,REAR BUMPER	NECESSARY	8.80	8.80
2	TAPE PROTECTOR,REAR BUMPER	NECESSARY	6.60	6.60
1	PANEL,REAR END	TO REPAIR SEE LABOUR	491.10	-
1	TAILGATE	BADLY DENTED	1,559.00	1,559.00
2	VALVE ONEWAY,TAILGATE	NECESSARY	22.80	22.80
1	WEATHERSTRIP,TAILGATE	NOT NECESSARY	169.00	-
1	TRIM LOWER,TAILGATE	NOT NECESSARY	411.40	-
2	TAPE PROTECTOR,TAILGATE	NECESSARY	14.40	14.40
2	TAPE PROTECTOR,TAILGATE	NECESSARY	14.00	14.00
1	LOCK,TAILGATE	DENTED	244.00	244.00
1	GARNISH,TAILGATE	NOT NECESSARY	459.40	-
3	CLIP,GARNISH	NECESSARY	16.20	16.20
4	SEAL,TAILGATE	NECESSARY	10.00	10.00
1	MAZDA,EMBLEM	NECESSARY	43.10	43.10
1	5,EMBLEM	NECESSARY	34.50	34.50
1	SKYACTIV,EMBLEM	NECESSARY	76.10	76.10
1	MOULD,REAR WINDSCREEN	NECESSARY	57.60	57.60
2	FASTENER,REAR WINDSCREEN	NECESSARY	5.20	5.20
1	SPACER,REAR WINDSCREEN	NECESSARY	6.80	6.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FASTENER, REAR WINDSCREEN	NECESSARY	15.60	15.60
4	SPACER, REAR WINDSCREEN	NECESSARY	48.40	48.40
1	PIN STUD, REAR WINDSCREEN	NECESSARY	10.50	10.50
2	PROTECTOR, REAR SPOILER	NECESSARY	10.40	10.40
2	PROTECTOR, REAR SPOILER	NECESSARY	22.80	22.80
2	PROTECTOR, REAR SPOILER	NECESSARY	26.80	26.80
3	CLIP, REAR SPOILER	NECESSARY	21.90	21.90
1	CLIP, REAR SPOILER	NECESSARY	8.20	8.20
1	LAMP (LHS), TAILLAMP	NOT NECESSARY	573.00	-
1	LAMP (RHS), TAILLAMP	NOT NECESSARY	573.00	-
2	GROMMET, TAILLAMP	NECESSARY	6.00	6.00
2	GROMMET, TAILLAMP	NECESSARY	5.40	5.40
2	FASTENER, TAILLAMP	NECESSARY	29.80	29.80
4	FASTENER, TAILLAMP	NECESSARY	12.00	12.00
1	GASKET (LHS), TAILGATE LAMP	NECESSARY	90.80	90.80
1	GASKET (RHS), TAILGATE LAMP	NECESSARY	90.80	90.80
1	LHS TAILLAMP	CRACKED	370.00	370.00
1	TRIM, BOOT END	NOT NECESSARY	76.50	-
1	BEZEL, LOCK	NOT NECESSARY	13.00	-
1	TRAY BOOT END	NOT NECESSARY	342.50	-
	LESS 10% DISCOUNT		-734.44	-414.41
			6,609.96	3,729.69
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	NUMBER PLATE (SN)	BENT	70.00	70.00
1	EXHAUST TIP MUFFLER (SN)	NOT NECESSARY	150.00	-
1	BRILA PREMIUM COATING (SN)	NECESSARY	800.00	800.00
1	WINDSCREEN GLASS (SN)	NECESSARY	120.00	120.00
			1,240.00	1,020.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF PANEL, REAR END.		4,620.00	1,650.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, TAILGATE AND REAR SPARE TYRE FLOOR PANEL.		3,780.00	2,205.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GAVE WAY TO THE REPAIR ON THE REAR SECTION.		660.00	300.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS.		560.00	560.00
	TO TRANSFER REVERSE CAMERA.		660.00	200.00
	TO TRANSFER REVERSE SENSORS.		660.00	330.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			12,140.00	5,665.00
	GRAND TOTAL		19,989.96	10,414.69
RECOMMENDED COST OF REPAIRS				10,414.69

Report Ref No. CS/GAI18004398/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.