

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD334X -**AAD1803-042**

Not Notified
Merry Bepain 83845.1P

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD334X - JHOW

VF1ABL15AUC282687

RENAULT

LATITUDE

05.03.2018

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	1,108.46	} X
2	1	BUMPER LOWER REAR	\$	768.84	
3	1	BUMPER BRACKET CTR REAR	\$	113.47	
4	1	BUMEP R BRACKET SIDE RH REAR	\$	135.97	
5	1	BUMEP R RETAINER RH REAR	\$	44.99	
6	1	BUMPER REFLECTOR RH	\$	43.61	
7	1	BUMEP R BRACKET SIDE LH REAR	\$	135.97	
8	1	BUMEP R RETAINER LH REAR	\$	44.99	
9	1	ROCKER PANEL OUTER RH	\$	987.49	
10	1	FENDER PANEL REAR RH	\$	3,299.13	
11	1	FENDER PANEL INNER TRIM REAR	\$	671.45	} X
12	1	WHEELARCH REAR RH	\$	543.47	
13	1	TAILLAMP RH	\$	552.55	
14	1	TAILLAMP PANEL RH	\$	986.70	
15	1	EXHAUST REAR	\$	7,489.05	
16	1	EXHAUST CAP REAR	\$	230.49	
17	1	DOOR PANEL REAR RH	\$	2,844.66	
18	1	DOOR GUIDE REAR RH	\$	176.82	
19	1	DOOR HINGE UPPER RH	\$	274.50	
20	1	DOOR HINGE LOWER RH	\$	300.55	
21	1	DOOR CHECK REAR RH	\$	203.06	} X
22	1	DOOR LOCK REAR RH	\$	908.75	
23	1	DOOR GRAB HANDLE REAR RH	\$	210.96	
24	1	DOOR HANDLE OUTER REAR RH	\$	126.49	
25	1	DOOR HANDLE CAP REAR RH	\$	35.52	
26	1	DOOR HANDLE SEAL REAR RH	\$	7.89	
27	1	DOOR HANDLE COVER REAR RH	\$	13.22	
28	1	DOOR HANDLE MODULE REAR RH	\$	133.60	
29	1	DOOR FINISHER REAR RH	\$	423.10	
30	1	DOOR WHEATHESTRIIP REAR RH	\$	410.66	
31	1	DOOR SEAL REAR RH	\$	162.02	}
32	1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
33	1	DOOR MOULDING REAR RH	\$	176.82	
34	1	DOOR PANEL FRT RH	\$	2,844.66	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-042

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD334X -

TOTAL	\$	26,744.60
10%	\$	2,674.46
	\$	24,070.14

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00	
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00	
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
8	1	EXHAUST MOUNTING REAR	\$	nn	17.82	
9	1	TAILLAMP CLIP RH	\$	nn	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00	
11	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
12	1	WINDSCREEN MOULDING	\$	nn	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
14	1	CAP HUB RH RR	\$	Sn	35.00	
15	1	RIM RH RR	\$	Sn	385.00	
16	1	TYRE RH RR	\$	Sn	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	600
18	1	DOOR STICKER "Classic"	\$	nn	30.00	150
19	1	DOOR STICKER "6555-3333"	\$	nn	80.00	600

TOTAL	\$	2,225.82
TOTAL PARTS	\$	26,295.96

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	600
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	400
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-042

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD334X -

To repair and realign rear exhaust pipe.	\$	~ 170.00 X
Towing Fees	\$	~ 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 60
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X

TOTAL	\$	7,710.00
Over All Total	\$	34,005.96

(PARTS BY PARTS)**Repair Days**~~10 Days~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: