

22/03/2012

ASS. REC. BY:

REF:

CS/MSG18003913/Tlvb-1

Special Instruction:

Survivor:

merimen

## ASSIGNMENT (Office)

From (Person): Joslin Lim of MSLH Date/Time: 07/03/2018 3:56pm

Estimated Cost: Bill to:

① / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 2595H Insured:

at Workshop m/s Vin's Motor Tel: 6453 2121

of 160 Sin Ming Drw #03-03

Policy No: A80430752 AVW Claim No: 550704

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 25022018

(Client's Record)

CA / REV / REP. / REV 24 HRS 08/03/2018 H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SKN 2595H - CS/MSG18003913/Tlvbs2 DOA: 250218
	Vin's Automotive able to repair with \$11K
9/3/18	Revert by merimen
13/3/18	Race approved \$11000
13/3/18	@ 139pm Informed Raymond c/A on LS repair \$11000 ex \$500



## Survey Department Check List (Case Handler)

Reference No.: CS/MSG/800 3913/TIV6-1  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 28/6/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/201.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18003913/T1vb-1		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 07-03-2018		
		Code : MSG		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.	Veh. Inspected		SKN 2595H	
Policy No. A80430752AVW	Coverage (\$)		0.00	
Claim No. 550704	Excess (\$)		500.00	
Assign From MERIMEN (JOSLIN LIM)	Assign Date		07/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date 25/02/2018	Inspection Date		08/03/2018	
Survey held at	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTO CITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018 14:21 <a href="#">Sendback Est</a>	07 Mar 2018 15:04 <b>\$21,505.60</b>	07 Mar 2018 15:56 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
<b>Insured:</b> Lim Eng Nguk, ID: S0127414G, Tel: +6598570072									
<b>Vehicle Reg. No.:</b> SKN2595H		<b>Date of Loss:</b> 25/02/2018 18:00 - :59							
<b>Claim Type:</b> OD / 550704		<b>Policy/Cover Note No.:</b> A80430752AVW (Comprehensive) Coverage: 27/05/2017 - 26/05/2018							
		<b>Excess:</b> S\$500.00							
<b>Repairer:</b> Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121									
<b>Handling Insurer:</b> MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]									
<b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/03/2018]									
<b>Driver/Custodian:</b> Lim Eng Nguk (70), NRIC: S0127414G, Tel: +6598570072									
<b>Adj Asg. Remarks:</b> Owner change workshop to Vin's Automotive. Vin's Automotive able to repair with \$11K before excess. Please survey and revert.									
<b>ASSOCIATED MAIL RECEIVED</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Compose Case Mail</a> </div>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <div style="float: right;"> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Received Message

This mail is associated with :

**SKN2595H (550704)**

OD

Feb 25 2018 6:00PM

[Lim Eng Nguk]

Vin's Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on **13/03/2018 12:44 PM**.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$11000.00) - SKN2595H - Claim Handler: Joslin Lim

Approved:11000.00:Approved lump sum repair at \$11000 before excess \$500

### DOCUMENTS SUMMARY

There are no documents.



**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joslin Lim	Date: 09 Mar 2018
<b><u>Preliminary Advice</u></b>	

Vehicle No	: SKN2595H	Accident Date	: 25/02/2018
Make	: VOLKSWAGEN JETTA	Policy No.	: A80430752AVW
Assignment Date	: 07/03/2018	Excess	: S\$500.00
Date of Inspection	: 08/03/2018	Est. Duration of Repair	: 14.00
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion. The chassis frame affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,505.60
Revised Amount	:S\$	18,909.60
Check Items (Estimated)	:S\$	2,266.00
Total	:S\$	21,175.60
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	47,467.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,533.00

**Remarks**

( X ) The vehicle is economical for repair.

( X ) Repairer able to undertake the repair at Lump Sum \$11,000/-

**LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR**

1. I, [Name] [NRIC] Lim Eng Nguk Sol27446 the owner/ authorized driver of vehicle [Registration No.] SKN2595H ["Vehicle"] do hereby authorize the [Workshop] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out repair and I note that [Workshop] will not be furnishing a detailed breakdown of parts or prices for such lump sum repair.
4. I am confirm that I will hold MSIG Insurance (Singapore) Pte Ltd harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. \*To be applicable where people authorized driver.  
I confirm that I have the authority from the owner of the Vehicle to authorize the Lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:

Lim Eng Nguk

Signature of policyholder/ authorized driver\* and company stamp (if applicable)

Date:

[Signature]



Name and signature of workshop personnel including workshop stamp

Date:

\*authorized driver to either the named driver as per motor insurance policy or in case of commercial vehicles, permitted drivers who are permitted to drive the insured vehicle.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/02/2018 16:56
Date Of Accident	25/02/2018 18:20
Exact Location Of Accident	169 JLN JRG KECHIL SHERWOOD CONDO NR TO THE EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN2595H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM ENG NGUK
NRIC No	S0127414G
Email Address	LIMENGNGUK@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98570072
Alternative Phone No	OFFICE-98570072

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA A6 1.4 TSI DSG 90KW TL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 80430752 AVW
Cover Note Number	

### Driver

Name of Driver	LIM ENG NGUK
NRIC No	S0127414G
Date Of Birth	13/06/1947
Occupation	INDOOR
Date Of Driving Pass	23/08/1977
Driving Experience	40 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98570072
Fax Number	(LOCAL) +65-98570072
Contact Number	OFFICE-98570072
EEmail Address	LIMENGNGUK@YAHOO.COM.SG

Address	71 CHUN TIN ROAD
Postcode	599647
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT TIMAH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 1 TOH YI DRIVE , POSTCODE: 590001 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4689999 - FAX NO: 64623782
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

FOR MORE DETALIS PLEASE REFER TO POLICE REPORT & SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

*Lim Eng Ngak*


Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

*Wong*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was exiting the basement carpark of Shenwood Condominium on Sunday, 25 Feb, at 6:15pm, I saw a pylon in the middle of the driveway. The pylon had not been there before. ~~I was~~ In order to avoid the pylon, I swerved and I hit the wall of the driveway. (Please refer to in-car camera footage for the details.) The weather at that time was fair and visibility was clear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*Lim Eng Nguk*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*Mur*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**

**POLICE REPORT (NP299)**

Police Station Of Origin  
Bukit Timah NPP  
1 Toh Yi Drive #01-139 SINGAPORE 591501  
Tel No 1800-4689999



D/20180225/2066

1 of 2

Report No. D/20180225/2066

Date/Time Report Made 25/02/2018 19:34		Vide Report No. D/20180225/0139		Station Diary No. 20	
Name Of Informant LIM ENG NGUK		Address 71 CHUN TIN ROAD SINGAPORE 599647			
ID Type / ID No. NRIC NO / S0127414G		Contact No. Home/Office		Mobile 98570072	
Nationality SINGAPORE CITIZEN		Email Address			
Occupation Retiree		Sex Female	Age 70	Date of Birth 13/06/1947	Race Chinese
Institution/School Name		Language			
Date/Time Of Incident 25/02/2018 18:20		Location Of Incident 169 JALAN JURONG KECHIL SHERWOOD CONDOMINIUM SINGAPORE 598669 NEAR TO THE EXIT			

**Brief details.**

On the above mentioned date, time and location, I was driving my vehicle bearing registration plate no SKN2995H and heading out. While exiting, near to the bend area, I spotted a cone placed in the middle of the road near to the exit point. As I was confused and panicked, I tried to maneuver around it but I lose control and my vehicle front hit onto the wall. I wish to state that I was not injured but the airbag were deployed. I exited my vehicle and the security called for the police assistance.

Signature Of Officer Recording The Report: D / Sgt 2 SHONG SHENG GUAN	Signature Of Informant: <i>Lim Eng Nguk</i>
Signature Of Interpreter: Not applicable	Date/Time: 25/02/2018 19:34
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp MUHAMMAD HAFEZ BIN ZULKEFLI Contact No.. 67740000	Classification Of Case:
Authentication Stamp	



**SINGAPORE  
POLICE FORCE**



D/20180225/2066

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20180225/2066

I am lodging this report for record purposes.

Signature Of Officer Recording The Report: D / Sgt 2 SHONG SHENG GUAN	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 25/02/2018 19:34
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Insp MUHAMMAD HAFEZ BIN ZULKEFLI Contact No. 67740000	Classification Of Case:
Authentication Stamp	



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7414G
Vehicle Details	
Vehicle No.:	SKN2595H
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	CAXE14304
Chassis No.:	WVWZZZ16ZEM026514
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,691.00
Original Registration Date:	27 May 2014
First Registration Date:	27 May 2014
Transfer Count:	0
Actual ARF Paid:	\$8,691.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2024
PARF Rebate Amount:	\$6,518.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10

QP Paid:	\$65,689.00
COE Rebate Amount:	\$40,949.00
Total Rebate Amount:	\$47,467.00

The information contained herein is correct as at 01 Mar 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7414G
Vehicle Details	
Vehicle No.:	SKN2595H
Vehicle to be Exported:	No
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1622G5
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	CAXE14304
Chassis No.:	WVWZZZ16ZEM026514
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,691.00
Original Registration Date:	27 May 2014
First Registration Date:	27 May 2014
Transfer Count:	0
Actual ARF Paid:	\$8,691.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2024
PARF Rebate Amount:	\$6,518.00
Intended COE Rebate Details	

COE Expiry Date:	26 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,689.00
COE Rebate Amount:	\$40,843.00
Total Rebate Amount:	\$47,361.00

The information contained herein is correct as at 06 Mar 2018

OK

# VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : OD/032018/3531

Tax Invoice:

Accident date: 25/02/2018

Your Ref : SKN2595H

Date : 07/03/2018

## Motor Claim Department

### MSIG INSURANCE (SINGAPORE) PTE LTD

No.4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

### ESTIMATE COST OF REPAIRS TO VOLKSWAGEN JETTA SKN2595H

1 pc Front bonnet	\$ 700.00	bt✓
1 pc Front bonnet rubber	\$ 30.00	re✓
1 pc Front bonnet insulator clips @ \$3.00	\$ 30.00	re✓
1 pc Front bonnet lock	\$ 140.00	bt✓
1 pc Front headlamp @ \$410.00	\$ 820.00	ao✓
1 pc Front headlamp panel @ \$40.00	\$ 80.00	bt✓
1 pc Front grille	\$ 280.00	ao✓
1 pc Front grille logo	\$ 20.00	re✓
1 pc Front fender @ \$340.00	\$ 680.00	bt✓
1 pc Front fender inner fabric @ \$110.00	\$ 220.00	re✓
1 pc Front fender inner fabric clips @ \$3.00	\$ 60.00	re✓
1 pc Front bumper	\$ 700.00	ao✓
1 pc Front bumper reinforcement	\$ 380.00	bt✓
1 pc Front bumper sponge	\$ 80.00	ao✓
1 pc Front bumper side retainer @ \$30.00	\$ 60.00	re✓
1 pc Front bumper fog lamp cover @ \$60.00	\$ 60.00	re✓
1 pc Front bumper lower spoiler	\$ 140.00	ao✓
1 pc Front bumper center grille	\$ 170.00	ao✓
1 pc Front bumper under cover	\$ 130.00	ao✓
1 pc Front support panel	\$ 640.00	ao✓
1 pc Front brace panel	\$ 40.00	bt✓
1 pc Front radiator	\$ 380.00	?
1 pc Front radiator lower hose	\$ 90.00	?
1 pc Front radiator fan assy	\$ 530.00	?
1 pc Front radiator lower member	\$ 110.00	?
1 pc Front air condenser	\$ 590.00	bt✓
1 pc Front air cond fan assy	\$ 380.00	?
1 pc Front inter cooler	\$ 290.00	?
1 pc Front air cleaner	\$ 280.00	?
1 pc Front no. plate	\$ 40.00	re✓
1 pc Front windscreen glass	\$ 580.00	ao✓
Balance c/f	\$ 8,730.00	

**VIN'S MOTOR PTE LTD**

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722 Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our ref: OD/032018/3531

Page 2

Balance	\$ 8,730.00
1 pc Front windscreen moulding	\$ 60.00 <i>net</i>
1 pc Front windscreen gum	\$ 60.00 <i>net</i>
1 pc Front windscreen ERP bracket	\$ 26.00 <i>net</i>
1 pc Front steering air bag	\$ 1,900.00 <i>net</i>
1 pc Front steering air bag coin spring	\$ 120.00 <i>net</i>
1 pc Front LH air bag	\$ 2,100.00 <i>net</i>
1 pc Front dashboard	\$ 2,400.00 <i>net</i>
1 pc Front air bag ECU	\$ 980.00 <i>net</i>
1 pc Front safety belt @ \$510.00	\$ 1,020.00 <i>net</i>
	<u>\$ 17,396.00</u>
Add: 10%	\$ 1,739.60
Balance c/f	<u>\$ 19,135.60</u>

To towing	\$ 80.00 <i>Go</i>
To remove and refix front glass	\$ 120.00 <i>✓</i>
To remove and refix front and rear bearing	\$ 120.00 <i>X</i>
To refill air cond gas	\$ 120.00 <i>100</i>
To remove and refix front dashboard	\$ 180.00 <i>✓</i>
To check wheel alignment	\$ 90.00 <i>80</i>
To repair front damage	\$ 780.00 <i>700</i>
To spray painting	\$ 880.00 <i>800</i>
	<u>\$ 21,505.60</u>

**VIN'S MOTOR PTE LTD**


**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Taufer 97495749  
Ex \$500  
Ravart.  
8/3/18 R1630  
14 days  
Lumpsum  
Resurvey after repair  
Resurvey check items.  
surc lkkauto.com

*possible to save?*  
*12/3/18*

**VIN'S MOTOR PTE LTD**

130 Sin Ming Drive, Sin Ming AutoCity, #03-03 Singapore 575722 Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : OD/032018/3531  
 Accident date: 25/02/2018  
 Your Ref : SKN2595H

Tax Invoice:

Date : 07/03/2018

**Motor Claim Department****MSIG INSURANCE (SINGAPORE) PTE LTD**

No.4 Shenton Way  
 #21-01 SGX Centre 2  
 Singapore 068807

**ESTIMATE COST OF REPAIRS TO VOLKSWAGEN JETTA SKN2595H**

1 pc Front bonnet	\$ 700.00	bt✓
1 pc Front bonnet rubber	\$ 30.00	re✓
1 pc Front bonnet insulator clips @ \$3.00	\$ 30.00	re✓
1 pc Front bonnet lock	\$ 140.00	bt✓
1 pc Front headlamp @ \$410.00	\$ 820.00	ao✓
1 pc Front headlamp panel @ \$40.00	\$ 80.00	bt✓
1 pc Front grille	\$ 280.00	ao✓
1 pc Front grille logo	\$ 20.00	uer✓
1 pc Front fender @ \$340.00	\$ 680.00	bt✓
1 pc Front fender inner fabric @ \$110.00	\$ 220.00	re✓
1 pc Front fender inner fabric clips @ \$3.00	\$ 60.00	uer✓
1 pc Front bumper	\$ 700.00	de✓
1 pc Front bumper reinforcement	\$ 380.00	bt✓
1 pc Front bumper sponge	\$ 80.00	ao✓
1 pc Front bumper side retainer @ \$30.00	\$ 60.00	re✓
1 pc Front bumper fog lamp cover @ \$60.00	\$ 60.00	m✓
1 pc Front bumper lower spoiler	\$ 140.00	de✓
1 pc Front bumper center grille	\$ 170.00	de✓
1 pc Front bumper under cover	\$ 130.00	ole✓
1 pc Front support panel	\$ 640.00	re✓
1 pc Front brace panel	\$ 40.00	bt✓
1 pc Front radiator / bt	\$ 380.00	? bt✓
1 pc Front radiator lower hose	\$ 90.00	R✓
1 pc Front radiator fan assy at✓	\$ 530.00	? ant✓
1 pc Front radiator lower member	\$ 110.00	R✓
1 pc Front air condenser	\$ 590.00	bt✓
1 pc Front air cond fan assy at✓	\$ 380.00	? ant✓
1 pc Front inter cooler bt✓	\$ 290.00	? ant✓
1 pc Front air cleaner at✓	\$ 280.00	? aa✓
1 pc Front no. plate	\$ 40.00	m✓
1 pc Front windscreen glass	\$ 580.00	ao✓
Balance c/f	\$ 8,730.00	



## VIN'S MOTOR PTE LTD

180 Sin Ming Drive, Sin Ming AutoCity #15-15, Singapore 576722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our ref: OD/032018/3531

Page 2

Balance	\$ 8,730.00
1 pc Front windscreen moulding	\$ 60.00 <i>net</i>
1 pc Front windscreen gum	\$ 60.00 <i>net</i>
1 pc Front windscreen ERP bracket	\$ 26.00 <i>net</i>
1 pc Front steering air bag	\$ 1,900.00 <i>net</i>
1 pc Front steering air bag coin spring	\$ 120.00 <i>net</i>
1 pc Front LH air bag	\$ 2,100.00 <i>net</i>
1 pc Front dashboard	\$ 2,400.00 <i>net</i>
1 pc Front air bag ECU	\$ 980.00 <i>net</i>
1 pc Front safety belt @ \$510.00	\$ 1,020.00 <i>net</i>
	<u>\$ 17,396.00</u>
Add: 10%	\$ 1,739.60
Balance c/f	<u>\$ 19,135.60</u>

To towing  
 To remove and refix front glass  
 To remove and refix front and rear bearing  
 To refill air cond gas  
 To remove and refix front dashboard  
 To check wheel alignment  
 To repair front damage  
 To spray painting

\$ 80.00	<i>Go</i>
\$ 120.00	<i>✓</i>
\$ 120.00	<i>X net</i>
\$ 120.00	<i>net</i>
\$ 180.00	<i>✓</i>
\$ 90.00	<i>80</i>
\$ 780.00	<i>700</i>
\$ 880.00	<i>800</i>
<u>\$ 21,505.60</u>	

VIN'S MOTOR PTE LTD



Tanjin 97495749  
 Ex \$500

Revert.

8/3/18 R1630

14 days

Lumpsum

Resumey after repair  
 Repair check items.

sure 11/11/2018

**Veron Chen (LKKAUTO)**

---

**From:** Admin @ VAuG <admin@vinsautogroup.com.sg>  
**Sent:** Wednesday, 7 March 2018 3:44 PM  
**To:** SUR; katherine\_wong@sg.msig-asia.com  
**Subject:** SKN2595H Letter of Authorization  
**Attachments:** 20180307152748.pdf

Good afternoon,

Please check the attachment for the letter of authorization.

Thanks!

Best Regards

Raymond Teo

--



Sin Ming AutoCity  
160 Sin Ming Drive #03-03  
Singapore 575722  
Tel: 64532121 (4 lines)  
Fax: 64599795  
Website: [www.vinsautogroup.com.sg](http://www.vinsautogroup.com.sg)  
Email: [admin@vinsautogroup.com.sg](mailto:admin@vinsautogroup.com.sg)

Follow us on :



\*\* w.e.f 15th May 2017, we have shifted location! \*\*  
\*\* w.e.f 20th November 2017, we have changed our email address! \*\*

LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR

1. I, [Name] [NRIC] Lim Eng Nguk S0127446 the owner/ authorized driver of vehicle [Registration No.] SKN2595H ["Vehicle"] do hereby authorize the [Workshop] to repair the Vehicle on a lump sum basis instead of part by part.
2. The [Workshop] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out repair and I note that [Workshop] will not be furnishing a detailed breakdown of parts or prices for such lump sum repair.
4. I am confirm that I will hold MSIG Insurance (Singapore) Pte Ltd harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
5. \*To be applicable where people authorized driver.  
I confirm that I have the authority from the owner of the Vehicle to authorize the Lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:

Lim Eng Nguk

Signature of policyholder/ authorized driver\* and company stamp (if applicable)

Date:

[Signature]



Name and signature of workshop personnel including workshop stamp

Date:

\*authorized driver to either the named driver as per motor insurance policy or in case of commercial vehicles, permitted drivers who are permitted to drive the insured vehicle.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018 14:21 <a href="#">Sendback Est</a>	07 Mar 2018 15:04 <b>S\$21,505.60</b>	07 Mar 2018 15:56 <a href="#">Edit Adj Rpt</a>	<b>S\$11,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$11,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>Lim Eng Nguk</b> , ID: S0127414G, Tel: +6598570072									
Vehicle Reg. No.: <b>SKN2595H</b>		Date of Loss: 25/02/2018 18:00 - :59 [44 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>OD / 550704</b>		Policy/Cover Note No.: A80430752AVW (Comprehensive) Coverage: 27/05/2017 - 26/05/2018							
		Excess: S\$500.00							
Repairer: <b>Vin's Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Joslin Lim</b> - 6643 1327]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 06/04/2018]									
Driver/Custodian: Lim Eng Nguk (70), NRIC: S0127414G, Tel: +6598570072									
Adj Asg. Remarks: Owner change workshop to Vin's Automotive. Vin's Automotive able to repair with \$11K before excess. Please survey and revert.									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>MSIG_SG (28/06/2018): Re: SKN2595H - DOA: 25/02/18 - Our Ref: 550704</li> <li>MSIG_SG (24/05/2018): Re: SKN2595H - DOA: 25/02/18 - OUR REF: 550704</li> <li>MSIG_SG (13/03/2018): Alert - Adj Mandate Approved (S\$11000.00) - SKN2595H - Claim Handler: Joslin Lim</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

SKN2595H (550704)

OD

Feb 25 2018 6:00PM





[Lim Eng Nguk]

Vin's Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

### Assessment Reports

1 per page
☒































































































No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/03/18 15:04	<b>Repairer Estimates</b>	 Load HTM	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/03/18 15:52	<b>Accident Statement</b> From: OD - Reg. No: SKN2595H, Claimant: LIM ENG NGUK	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 13:58	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>
2	09/03/18 14:04	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>

### Photos/Images

3 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	09/03/18 12:28	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports				
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
30	09/03/18 12:28	General View	 Load JPG	
31	09/03/18 12:28	General View	 Load JPG	
32	09/03/18 12:28	General View	 Load JPG	
33	09/03/18 12:28	General View	 Load JPG	
34	09/03/18 12:28	General View	 Load JPG	
35	09/03/18 12:28	General View	 Load JPG	
36	09/03/18 12:28	General View	 Load JPG	
37	09/03/18 12:28	General View	 Load JPG	
38	09/03/18 12:28	General View	 Load JPG	
39	09/03/18 12:28	General View	 Load JPG	
40	09/03/18 12:28	General View	 Load JPG	
41	09/03/18 12:28	General View	 Load JPG	
42	09/03/18 12:28	General View	 Load JPG	
43	09/03/18 12:28	General View	 Load JPG	
44	09/03/18 12:28	General View	 Load JPG	
45	09/03/18 12:28	General View	 Load JPG	
46	09/03/18 12:28	General View	 Load JPG	
47	09/03/18 12:28	General View	 Load JPG	
48	09/03/18 12:28	General View	 Load JPG	
49	09/03/18 12:28	General View	 Load JPG	
50	09/03/18 12:28	General View	 Load JPG	
51	09/03/18 12:28	General View	 Load JPG	
52	09/03/18 12:28	General View	 Load JPG	
53	09/03/18 12:28	General View	 Load JPG	
54	09/03/18 12:28	General View	 Load JPG	
55	09/03/18 12:28	General View	 Load JPG	
56	09/03/18 12:28	General View	 Load JPG	
57	09/03/18 12:28	General View	 Load JPG	
58	09/03/18 12:28	General View	 Load JPG	
59	09/03/18 12:28	General View	 Load JPG	
60	09/03/18 12:28	General View	 Load JPG	
61	09/03/18 12:28	General View	 Load JPG	
62	09/03/18 12:28	General View	 Load JPG	
63	09/03/18 12:28	General View	 Load JPG	
64	09/03/18 12:28	General View	 Load JPG	
65	28/06/18 15:07	Reinspection Photo	 Load JPG	
66	28/06/18 15:07	Reinspection Photo	 Load JPG	
67	28/06/18 15:07	Reinspection Photo	 Load JPG	
68	28/06/18 15:07	Reinspection Photo	 Load JPG	
69	28/06/18 15:07	Reinspection Photo	 Load JPG	
70	28/06/18 15:07	Reinspection Photo	 Load JPG	
71	28/06/18 15:07	Reinspection Photo	 Load JPG	
72	28/06/18 15:07	Reinspection Photo	 Load JPG	
73	28/06/18 15:07	Reinspection Photo	 Load JPG	
74	28/06/18 15:07	Reinspection Photo	 Load JPG	
75	28/06/18 15:07	Reinspection Photo	 Load JPG	
76	28/06/18 15:07	Reinspection Photo	 Load JPG	
77	28/06/18 15:07	Reinspection Photo	Load JPG	

Assessment Reports				✓
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
78	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
79	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
80	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
81	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
82	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
83	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
84	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
85	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
86	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
87	28/06/18 15:07	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/03/18 15:52	Vins Automotive able to repair within \$11K From: OD - Reg. No: SKN2595H, Claimant: LIM ENG NGUK	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/03/18 12:31	MARK ESTIMATE	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG18003913/T1VBS2-1  
**Date:** 29/06/2018

## REFERENCE

Insured/Claimant:	Lim Eng Nguk	Policy No:	A80430752AVW	
Date of Loss:	25/02/2018	Nature of Claim:	OD	Claim No: 550704

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SKN2595H</b>		
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Engine No:	CAXE14304
Reg. Date:	27/05/2014 (Man. Year: 2014)	Chassis No:	WVWZZZ16ZEM026514
Colour:	Beige	Odometer:	41221 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,135.60	18,915.60	220.00	1.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	2,040.00	330.00	13.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,505.60</b>	<b>20,955.60</b>	<b>550.00</b>	<b>2.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>11,000.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>(S\$)</b>	21,005.60	10,500.00	10,505.60	50.01
<b>+ GST 7.00/7.00% (S\$)</b>	1,470.39	735.00	735.39	50.01
<b>Nett Amount (S\$)</b>	<b>22,475.99</b>	<b>11,235.00</b>	<b>11,240.99</b>	<b>50.01</b>

## INSPECTION

Date of Assignment:	07/03/2018	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	08/03/2018	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	14.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2018)
<b>Parts:</b>	143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKN2595H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Front bonnet</b> (WCP)	Bent	700.00 F	*700.00 F
2	1		<b>*Front bonnet rubber</b> (WCP)	Necessary	30.00 F	*30.00 F
3	10		<b>*Front bonnet insulator clips @ \$3.00</b> (WCP)	Necessary	30.00 F	*30.00 F
4	1		<b>*Front bonnet lock</b> (WCP)	Bent	140.00 F	*140.00 F
5	2		<b>*Front headlamp @ \$410.00</b> (WCP)	Cracked	820.00 F	*820.00 F
6	2		<b>*Front headlamp panel @ \$40.00</b> (WCP)	Bent	80.00 F	*80.00 F
7	1		<b>*Front grille</b> (WCP)	Cracked	280.00 F	*280.00 F
8	1		<b>*Front grille logo</b> (WCP)	Necessary	20.00 F	*20.00 F
9	2		<b>*Front fender @ \$340.00</b> (WCP)	Bent	680.00 F	*680.00 F
10	2		<b>*Front fender inner fabric @ \$110.00</b> (WCP)	Necessary	220.00 F	*220.00 F
11	20		<b>*Front fender inner fabric clips @ \$3.00</b> (WCP)	Necessary	60.00 F	*60.00 F
12	1		<b>*Front bumper</b> (WCP)	Deformed	700.00 F	*700.00 F
13	1		<b>*Front bumper reinforcement</b> (WCP)	Bent	380.00 F	*380.00 F
14	1		<b>*Front bumper sponge</b> (WCP)	Cracked	80.00 F	*80.00 F
15	2		<b>*Front bumper side retainer @ \$30.00</b> (WCP)	Necessary	60.00 F	*60.00 F
16	1		<b>*Front bumper fog lamp cover @ \$60.00</b> (WCP)	Missing	60.00 F	*60.00 F
17	1		<b>*Front bumper lower spoiler</b> (WCP)	Deformed	140.00 F	*140.00 F
18	1		<b>*Front bumper center grille</b> (WCP)	Deformed	170.00 F	*170.00 F
19	1		<b>*Front bumper under cover</b> (WCP)	Deformed	130.00 F	*130.00 F
20	1		<b>*Front support panel</b> (WCP)	Necessary	640.00 F	*640.00 F
21	1		<b>*Front brace panel</b> (WCP)	Bent	40.00 F	*40.00 F
22	1		<b>*Front radiator</b> (WCP)	Bent	380.00 F	*380.00 F
23	1		<b>*Front radiator lower hose</b> (WCP)	Not Necessary	90.00 F	*- F
24	1		<b>*Front radiator fan assy</b> (WCP)	Cut	530.00 F	*530.00 F
25	1		<b>*Front radiator lower member</b> (WCP)	Not Necessary	110.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		<b>*Front air condenser</b> (WCP)	Bent	590.00 F	*590.00 F
27	1		<b>*Front air cond fan assy</b> (WCP)	Cut	380.00 F	*380.00 F
28	1		<b>*Front inter cooler</b> (WCP)	Bent	290.00 F	*290.00 F
29	1		<b>*Front air cleaner</b> (WCP)	Cracked	280.00 F	*280.00 F
30	1		<b>*Front no. plate</b> (WCP)	Missing	40.00 F	*40.00 F
31	1		<b>*Front windscreen glass</b> (WCP)	Cracked	580.00 F	*580.00 F
32	1		<b>*Front windscreen moulding</b> (WCP)	Necessary	60.00 F	*60.00 F
33	1		<b>*Front windscreen gum</b> (WCP)	Necessary	60.00 F	*60.00 F
34	1		<b>*Front windscreen ERP bracket</b> (WCP)	Necessary	26.00 F	*26.00 F
35	1		<b>*Front steering air bag</b> (WCP)	Activated	1,900.00 F	*1,900.00 F
36	1		<b>*Front steering air bag coin spring</b> (WCP)	Activated	120.00 F	*120.00 F
37	1		<b>*Front LH air bag</b> (WCP)	Activated	2,100.00 F	*2,100.00 F
38	1		<b>*Front dashboard</b> (WCP)	Deformed	2,400.00 F	*2,400.00 F
39	1		<b>*Front air bag ECU</b> (WCP)	Activated	980.00 F	*980.00 F
40	2		<b>*Front safety belt @ \$510.00</b> (WCP)	Jammed	1,020.00 F	*1,020.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>17,396.00</b>	<b>17,196.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	1,739.60	1,719.60
<b>Total Parts (\$\$)</b>	<b>19,135.60</b>	<b>18,915.60</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To towing	New	80.00	60.00
2	To remove and refix front glass	New	120.00	120.00
3	To remove and refix front and rear bearing	New	120.00	0.00
4	To refill air cond gas	New	120.00	100.00
5	To remove and refix front dashboard	New	180.00	180.00
6	To check wheel alignment	New	90.00	80.00
7	To repair front damage	New	780.00	700.00
8	To spray painting	New	880.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,370.00</b>	<b>2,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >