

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : OD/032018/3531
 Accident date: 25/02/2018
 Your Ref : SKN2595H

Tax Invoice:
 Date : 07/03/2018

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
 No.4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

ESTIMATE COST OF REPAIRS TO VOLKSWAGEN JETTA SKN2595H

1 pc Front bonnet	\$ 700.00	bt ✓
1 pc Front bonnet rubber	\$ 30.00	re ✓
1 pc Front bonnet insulator clips @ \$3.00	\$ 30.00	re ✓
1 pc Front bonnet lock	\$ 140.00	bt ✓
1 pc Front headlamp @ \$410.00	\$ 820.00	cr ✓
1 pc Front headlamp panel @ \$40.00	\$ 80.00	bt ✓
1 pc Front grille	\$ 280.00	cr ✓
1 pc Front grille logo	\$ 20.00	re ✓
1 pc Front fender @ \$340.00	\$ 680.00	bt ✓
1 pc Front fender inner fabric @ \$110.00	\$ 220.00	re ✓
1 pc Front fender inner fabric clips @ \$3.00	\$ 60.00	cr ✓
1 pc Front bumper	\$ 700.00	bt ✓
1 pc Front bumper reinforcement	\$ 380.00	bt ✓
1 pc Front bumper sponge	\$ 80.00	cr ✓
1 pc Front bumper side retainer @ \$30.00	\$ 60.00	re ✓
1 pc Front bumper fog lamp cover @ \$60.00	\$ 60.00	re ✓
1 pc Front bumper lower spoiler	\$ 140.00	bt ✓
1 pc Front bumper center grille	\$ 170.00	bt ✓
1 pc Front bumper under cover	\$ 130.00	bt ✓
1 pc Front support panel	\$ 640.00	cr ✓
1 pc Front brace panel	\$ 40.00	bt ✓
1 pc Front radiator	\$ 380.00	?
1 pc Front radiator lower hose	\$ 90.00	?
1 pc Front radiator fan assy	\$ 530.00	?
1 pc Front radiator lower member	\$ 110.00	?
1 pc Front air condenser	\$ 590.00	bt ✓
1 pc Front air cond fan assy	\$ 380.00	?
1 pc Front inter cooler	\$ 290.00	?
1 pc Front air cleaner	\$ 280.00	?
1 pc Front no. plate	\$ 40.00	re ✓
1 pc Front windscreen glass	\$ 580.00	cr ✓
Balance c/f	\$ 8,730.00	

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795


Our ref: OD/032018/3531

Page 2

Balance	\$ 8,730.00
1 pc Front windscreen moulding	\$ 60.00 <i>net</i>
1 pc Front windscreen gum	\$ 60.00 <i>net</i>
1 pc Front windscreen ERP bracket	\$ 26.00 <i>net</i>
1 pc Front steering air bag	\$ 1,900.00 <i>net</i>
1 pc Front steering air bag coin spring	\$ 120.00 <i>net</i>
1 pc Front LH air bag	\$ 2,100.00 <i>net</i>
1 pc Front dashboard	\$ 2,400.00 <i>net</i>
1 pc Front air bag ECU	\$ 980.00 <i>net</i>
1 pc Front safety belt @ \$510.00	\$ 1,020.00 <i>net</i>
	<u>\$ 17,396.00</u>
Add: 10%	\$ 1,739.60
Balance c/f	<u>\$ 19,135.60</u>

To towing	\$ 80.00 <i>Go</i>
To remove and refix front glass	\$ 120.00 ✓
To remove and refix front and rear bearing	\$ 120.00 X
To refill air cond gas	\$ 120.00/00
To remove and refix front dashboard	\$ 180.00 ✓
To check wheel alignment	\$ 90.00 80
To repair front damage	\$ 780.00 700
To spray painting	\$ 880.00 800
	<u>\$ 21,505.60</u>

VIN'S MOTOR PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanjin 97495749
Ex \$500

Revert.

8/3/18 21630

14 days

Lumpsum

Resurvey after repair
Resurvey check items.

surc 11/11/2018