



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M

5 Benoi Place Singapore 629926

Tel: 6861 0908 Fax: 6515 2948

Date: 07.03.2018

India International Insurance Pte Ltd

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SKQ9126S TOYOTA CAMRY 2014

To Supply

1) 1pc	rear bumper	\$	573.70 ²⁰
2) 1pc	rear bumper reinforcement	\$	382.70 [?]
3) 1set	rear bumper clip	\$	30.00 ^{new}
Sub total parts		\$	986.40
Less: 25% discount		\$	(246.60)
		\$	739.80

To supply S.Nett Parts

1) 1set	reverse sensor	\$	230.00 200 ^{new}
----------	----------------	----	--------------------------------------

L/charges

1)	To remove & replace reverse sensor	\$	50.00 [/]
2)	To repair rear boot lid, knock rear end panel. Remove rear bumper, rear bumper reinforcement, replace the above parts	\$	350.00 300
3)	To putty & respray painting rear bumper, rear end panel & rear boot lid. To polish	\$	600.00 400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Sub total L/charges \$ 1,000.00
Estimated Total \$ 1,969.80

RASUL
Hp 90010068
3 days
45
07/03/18 @ 1430
Resurvey after repair