

## Print Sent Message

This mail is associated with :

**\*SLK2566X (C0471938)**

**[SHB7583H]**

TP

GRAB RENTALS PTE LTD

Mar 2 2018 7:00PM

[TRANS-CAB SERVICES PTE LTD]

Esteem Performance Pte Ltd - Sin Ming

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **21/03/2018 17:03 PM**.  
**To** AXA\_SG; AXA\_CynthiaLoh  
**CC** admin-a@lkkauto.com; vicalpeh@lkkauto.com; ashersng@lkkauto.com  
**Subject** Re: C0471938/P1680520

Dear Cynthia,

ACCIDENT INVOLVING VEHICLES SHB 7583H / SLK 2566X / OTHERS ON 02/03/2018

We refer to the above matter.

Please be informed that a copy of TP video footage was forwarded via accellion as requested.

Based on the footage, TP vehicle collided to the front vehicle prior to being rear-ended by Insured vehicle.

Kindly confirm if we still follow BOLA 28 where Insured is liable to the damages to the front and rear of TP vehicle.

Thank you.

Vic Alpeh  
LKK Auto Consultants Pte Ltd  
Tel: 6841 2096

<-- Original Message -->

From: AXA\_SG  
To: LKK\_HQ; sur@lkkauto.com; assignments@lkkauto.com  
Sent On: 06/03/2018 02:42 PM  
Subject: C0471938/P1680520



AXA INSURANCE PTE LTD  
8 Shenfon Way, #24-01 AXA Tower  
Singapore 068811  
Customer Centre #B1-01  
☎ (65) 6880 4888  
☎ (65) 6338 2522  
🌐 www.axa.com.sg  
GST Reg No.: 199903512M  
Co. Reg No.: 199903512M

Dear LKK Auto Consultants Pte Ltd,

Prior accident - ID reported only rear-ended TP,SLK2566X.  
Please assist to obtain TP's CCTV.

Thanks & Regards,  
Cynthia Loh

