



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/250, 580536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLK 2566 X

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>35,868.21</u>
	Plus/Less 25%	\$	<u>8,972.05</u>
	<b>Total of Cost / List</b>	\$	<u><u>26,916.16</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) <b>Special Nett Items</b>	\$	<u>290.00</u>
	<b>Total Parts Cost</b>	\$	<u><u>27,206.16</u></u>
	<b>Labour</b>	\$	<u><u>5,790.00</u></u>
	<b>Total</b>	\$	<u><u>32,996.16</u></u>

*35,788.21*  
*8,947.05*  
*26,841.16*  
*Not Authorized*  
*1.13.1*  
*Resurvey By paint*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*390.00*  
*27,231.16*  
*33,021.16*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 7/13/18 at 1 pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 14 days day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Sc Date: 7/13/18



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLK 2566 X  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU903539892

Submit By : Carmen Lim  
 Year Manufacture : 2016  
 Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	/
2	Front number plate garnish	1	\$45.00		/
3	Bonnet	1	\$812.40		/
4	Bonnet lock	1	\$130.00		/
5	Bonnet hinge LH	1	\$57.80		/
6	Bonnet hinge RH	1	\$57.80		/
7	Bonnet heat insulator	1	\$440.12		X
8	Bonnet heat insulator clip	10	\$35.00		/
9	Front support panel centre	1	\$338.50		/
10	Front support panel LH	1	\$213.50		/
11	Front support panel RH	1	\$213.50		/
12	Headlamp panel LH	1	\$89.20		/
13	Headlamp panel RH	1	\$89.20		/
14	Support panel lower	1	\$387.95		?
15	Front support panel top garnish	1	\$285.40		/
16	Front support panel top garnish clip	10	\$35.00		/
17	Air duct	1	\$195.40		/
18	Air duct - inlet	1	\$109.75		/
19	Brace panel	1	\$105.20		/
20	Condenser	1	\$1,544.70		/
21	Radiator	1	\$1,841.80		/
22	Radiator fan motor RH	1	\$455.70		?
23	Radiator fan motor LH	1	\$491.79		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLK 2566 X  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU903539892

Submit By : Carmen Lim  
 Year Manufacture : 2016  
 Engine No. :

**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	\$197.80		?
25	Radiator fan blade RH	1	\$219.80		?
26	Radiator fan cowling	1	\$287.67		?
27	Radiator top hose	<i>Per</i> 1	\$49.80		—
28	Radiator bottom hose	1	\$46.95		?
29	Radiator spare tank	1	\$186.70		?
30	Radiator top garnish	1	\$54.24		?
31	Intake manifold	1	\$892.74		?
32	Headlamp LH	<i>my car</i> 1	\$2,531.60		—
33	Headlamp RH	<i>car</i> 1	\$2,531.60		—
34	Front bumper	<i>Per car</i> 1	\$450.80		—
35	Front bumper clip	<i>Per</i> 10	\$40.00		—
36	Front bumper reinforcement - upper	<i>P</i> 1	\$711.50		?
37	Front bumper reinforcement - lower	1	\$245.30		?
38	Front bumper side retainer RH	<i>Dis</i> 1	\$107.20		—
39	Front bumper side retainer LH	<i>Dis</i> 1	\$107.20		—
40	Front bumper upper grille	<i>car</i> 1	\$321.90		—
41	Front bumper lower grille	<i>car</i> 1	\$148.60		—
42	Front bumper emblem	<i>Per</i> 1	\$87.10		—
43	Front bumper tow cover RH	<i>Per</i> 1	\$25.70		—
44	Front bumper tow cover LH	1	\$25.70		?
45	Front bumper sponge - upper	<i>car</i> 1	\$89.81		—
46	Front bumper sponge - lower	1	\$135.70		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spare Parts**

Vehicle No. : SLK 2566 X  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FU903539892

Submit By : Carmen Lim  
 Year Manufacture : 2016  
 Engine No. : \_\_\_\_\_  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp LH	1	\$910.70		?
48	Fog lamp RH	1	\$910.70		?
49	Engine under cover	1	\$198.30		?
50	Engine under cover clip	10	\$35.00		?
51	Washer tank	1	\$195.60		?
52	Washer tank motor	1	\$196.74		X
53	RH front fender	1	\$868.70		✓
54	RH front fender undershield	1	\$185.64		X
55	RH front fender undershield clip	10	\$25.00		X
56	RHF fender wording "HYBRID"	1	\$44.17		✓
57	LH front fender	1	\$868.70		X
58	LH front fender undershield	1	\$195.60		✓
59	LH front fender undershield clip	10	\$25.00		X
60	LHF fender wording "HYBRID"	1	\$44.17		X
61	Rear windscreen moulding	1	\$97.70		✓
62	Rear windscreen sealant	1	\$50.00		400ml
63	Rear number plate	1	\$45.00	S.N	✓
64	Reverse sensor	1	\$200.00	S.N	✓
65	Rear bumper	1	\$497.50		✓
66	Rear bumper clip	10	\$40.00		✓
67	Rear bumper side retainer LH	1	\$112.70		✓
68	Rear bumper side retainer RH	1	\$112.70		X
69	Rear bumper reinforcement	1	\$398.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.