

Spare Parts

Vehicle No. : SLK 2566 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU903539892

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Rear bumper lower garnish centre <i>B₁</i>	1	\$582.60		✓
71	Rear bumper lower garnish LH <i>m11</i>	1	\$149.70		✓
72	Rear bumper lower garnish RH	1	\$149.70		?
73	Rear bumper tow cover <i>m11</i>	1	\$31.70		✓
74	Rear bumper under cover <i>m11</i>	1	\$355.20		✓
75	Rear bumper under cover LH	1	\$187.60		?
76	Rear bumper under cover RH	1	\$187.60		?
77	Rear bumper under cover clip	4	\$14.00		?
78	Tail door <i>B₂</i>	1	\$1,122.50		✓
79	Tail door lock	1	\$487.70		?
80	Tail door emblem <i>m₂</i>	1	\$61.70		✓
81	Wording "PRIUS" <i>m₂</i>	1	\$51.90		✓
82	Wording "HYBRID" <i>m₂</i>	1	\$55.47		✓
83	Tail door hinge LH <i>R</i>	1	\$87.60		X
84	Tail door hinge RH <i>R</i>	1	\$87.60		X
85	Tail door plate garnish <i>R</i>	1	\$782.50		?
86	Tail door inner trim <i>B₂</i>	1	\$278.90		✓
87	Tail door inner trim clip <i>m₂</i>	10	\$28.00		X
88	Taildoor spoiler <i>B₂</i>	1	\$1,567.83		X
89	Tail end panel <i>B₁</i>	1	\$596.60		✓
90	Tail end panel garnish <i>D-11</i>	1	\$151.60		✓
91	Tail end panel garnish clip <i>m₂</i>	10	\$35.00		✓
92	Boot weatherstrip <i>D-11/Ad</i>	1	\$353.10		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLK 2566 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKKB3FU903539892

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Spare tyre well panel	1	\$793.15		?
94	Spare tyre board	1	\$566.79		?
95	Tail lamp LH - UPPER	1	\$498.75		?
96	Tail lamp RH - UPPER	1	\$498.75		X
97	Tail lamp LH - LOWER	1	\$511.60		?
98	Tail lamp RH - LOWER	1	\$511.60		X
99	Taildoor glass sealant	1	\$50.00		4000
100	Tail door spoiler	1	\$1,567.83		?
101					
102					
103					
104					
105					
106					
107					
108					
109					
110					
111					
112					
113					
114					
115					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLK 2566 X Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,REAR BUMPER,TAILDOOR, END PANEL,SPARE TYRE WELL PANEL,RH UPPER PILLAR)	\$2,400.00	1600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,REAR BUMPER,TAILDOOR, END PANEL,SPARE TYRE WELL PANEL,RH UPPER PILLAR)	\$2,200.00	2000
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$300.00	150
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

