

Kh



ESTEEM PERFORMANCE

ESTEEM PERFORMANCE PTE LTD

Blk 5039 Ang Mo Kio, Ind Park 2 #01-251/259, 559536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLK 2566 X

Parts (a) Cost / List Price Items	\$	35,888.21
Plus/Less 25%	\$	8,972.05
Total of Cost / List	\$	26,916.16
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	290.00
Total Parts Cost	\$	27,206.16
Labour	\$	5,790.00
Total	\$	32,996.16

Finalized

23980.10

Not Authorized

5995.03

1.31

Resurvey B4 paint

17985.07

370

18355.07

4330

22630.18

22685.07

22408.47

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kennerh

Company

LICK

Survey conducted on

7/13/18

at

1 pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair :

14 days

day(s)

(c) Resurvey

Required / Not Required

(d) Excess

:\$ _____

(e) Signature of surveyor

Le

Date:

7/13/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLK 2566 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU903539892

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S.N	✓
2	Front number plate garnish	1	\$45.00	✓	✓
3	Bonnet	1	\$812.40	✓	✓
4	Bonnet lock	1	\$130.00	✓	✓
5	Bonnet hinge LH	1	\$57.80	✓	✓
6	Bonnet hinge RH	1	\$57.80	✓	✓
7	Bonnet heat insulator	1	\$440.12		X
8	Bonnet heat insulator clip	10	\$35.00	✓	✓
9	Front support panel centre	1	\$338.50	✓	✓
10	Front support panel LH	1	\$213.50	✓	✓
11	Front support panel RH	1	\$213.50	✓	✓
12	Headlamp panel LH	1	\$89.20	✓	✓
13	Headlamp panel RH	1	\$89.20	✓	✓
14	Support panel lower	1	\$387.95	✓	✓
15	Front support panel top garnish	1	\$285.40	✓	✓
16	Front support panel top garnish clip	10	\$35.00	✓	✓
17	Air duct	1	\$195.40	✓	✓
18	Air duct - inlet	1	\$109.75	✓	✓
19	Brace panel	1	\$105.20	✓	✓
20	Condenser	1	\$1,544.70	✓	✓
21	Radiator	1	\$1,841.80	✓	✓
22	Radiator fan motor RH	1	\$455.70		X
23	Radiator fan motor LH	1	\$491.79		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
 Company Reg No. 200005485N / GST No. 20-0005485-N

6349

6387-10

SN 45

Spare Parts

Vehicle No. : _____
 Make & Model : SLK 2566 X
 Chassis No : TOYOTA PRIUS
JTDKKB3FU903639892

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH <i>h</i>	1	\$197.80		X
25	Radiator fan blade RH <i>n/i</i>	1	\$219.80	✓	Z
26	Radiator fan cowling <i>cm</i>	1	\$287.67	✓	Z
27	Radiator top hose <i>Per</i>	1	\$49.80	✓	-
28	Radiator bottom hose <i>h</i>	1	\$46.95		X
29	Radiator spare tank <i>R4 fan</i>	1	\$186.70	✓	X
30	Radiator top garnish <i>cm h</i>	1	\$54.24	✓	X
31	Intake manifold <i>n/d/c</i>	1	\$892.74	✓	Z
32	Headlamp LH <i>mg cm</i>	1	\$2,531.60	✓	-
33	Headlamp RH <i>cm</i>	1	\$2,531.60	✓	-
34	Front bumper <i>Ry cm</i>	1	\$450.80	✓	-
35	Front bumper clip <i>h</i>	10	\$40.00	✓	-
36	Front bumper reinforcement - upper <i>R</i>	1	\$711.50	✓ 696.40	Z
37	Front bumper reinforcement - lower <i>r</i>	1	\$245.30		X
38	Front bumper side retainer RH <i>DII</i>	1	\$107.20	✓	-
39	Front bumper side retainer LH <i>Diy</i>	1	\$107.20	✓	-
40	Front bumper upper grille <i>301-90 cm</i>	1	\$321.90	✓	-
41	Front bumper lower grille <i>cm</i>	1	\$148.60	✓	-
42	Front bumper emblem <i>h</i>	1	\$87.10	✓	-
43	Front bumper tow cover RH <i>r/d</i>	1	\$25.70	✓	-
44	Front bumper tow cover LH <i>h</i>	1	\$25.70		X
45	Front bumper sponge - upper <i>cm</i>	1	\$89.81	✓	-
46	Front bumper sponge - lower <i>h</i>	1	\$135.70		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

8517-92 8843-96

Spare Parts

Vehicle No. : _____
 Make & Model : SLK 2566 X
 Chassis No. : TOYOTA PRIUS
JTDKB3FU903539892

Submit By : _____
 Year Manufacture : Garmen Lim
 Engine No. : _____
2016

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp LH	1	\$910.70		X
48	Fog lamp RH	1	\$910.70		X
49	Engine under cover	1	\$198.30		X
50	Engine under cover clip	10	\$35.00		X
51	Washer tank	1	\$195.60		X
52	Washer tank motor	1	\$196.74		X
53	RH front fender	1	\$868.70		✓
54	RH front fender undershield	1	\$185.64		X
55	RH front fender undershield clip	10	\$25.00		X
56	RHF fender wording "HYBRID"	1	\$44.17		✓
57	LH front fender	1	\$868.70		X
58	LH front fender undershield	1	\$195.60		X
59	LH front fender undershield clip	10	\$25.00		X
60	LHF fender wording "HYBRID"	1	\$44.17		X
61	Rear windscreen moulding	1	\$97.70		✓
62	Rear windscreen sealant	1	\$50.00		4 asn
63	Rear number plate	1	\$45.00	S.N	✓
64	Reverse sensor	1	\$200.00	S.N	✓
65	Rear bumper	1	\$497.50		✓
66	Rear bumper clip	10	\$40.00		✓
67	Rear bumper side retainer LH	1	\$112.70		✓
68	Rear bumper side retainer RH	1	\$112.70		X
69	Rear bumper reinforcement	1	\$398.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2089.67 ✓
 28X (S.N).

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLK 2566 X

TOYOTA PRIUS
 JTDKKB3FU903539892

Submit By :
 Year Manufacture :
 Engine No. :
Cost / List

Carmen Lim
 2016

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Rear bumper lower garnish centre <i>B₁</i>	1	\$582.60		✓
71	Rear bumper lower garnish LH <i>miy</i>	1	\$149.70		✓
72	Rear bumper lower garnish RH <i>cmf</i>	1	\$149.70	✓	✓
73	Rear bumper tow cover <i>miy</i>	1	\$31.70		✓
74	Rear bumper under cover <i>miy</i>	1	\$355.20		✓
75	Rear bumper under cover LH <i>sn</i>	1	\$187.60		✓
76	Rear bumper under cover RH <i>sn</i>	1	\$187.60		✓
77	Rear bumper under cover clip <i>nn</i>	4	\$14.00		✓
78	Tail door <i>B₂</i>	1	\$1,122.50		✓
79	Tail door lock <i>R</i>	1	\$487.70		✓
80	Tail door emblem <i>nn</i>	1	\$61.70		✓
81	Wording "PRIUS" <i>nn</i>	1	\$51.90		✓
82	Wording "HYBRID" <i>nn</i>	1	\$55.47		✓
83	Tail door hinge LH <i>R</i>	1	\$87.60		X
84	Tail door hinge RH <i>R</i>	1	\$87.60		X
85	Tail door plate garnish <i>R</i>	1	\$782.50		✓
86	Tail door inner trim <i>sn</i>	1	\$278.90		X
87	Tail door inner trim clip <i>nn</i>	10	\$28.00		X
88	Taildoor spoiler <i>sn</i>	1	\$1,567.83		X
89	Tail end panel <i>B₁</i>	1	\$596.60		✓
90	Tail end panel garnish <i>diy</i>	1	\$151.60		✓
91	Tail end panel garnish clip <i>nn</i>	10	\$35.00		✓
92	Boot weatherstrip <i>diy/nd</i>	1	\$353.10		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

3696-77 ✓

Spare Parts

Vehicle No. : SLK 2566 X
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU903639892

Submit By : Carmen Lim
 Year Manufacture : 2016
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Spare tyre well panel	1	\$793.15		X
94	Spare tyre board	1	\$566.79		X
95	Tail lamp LH - UPPER	1	\$498.75		X
96	Tail lamp RH - UPPER	1	\$498.75		X
97	Tail lamp LH - LOWER	1	\$511.60		X
98	Tail lamp RH - LOWER	1	\$511.60		X
99	Taildoor glass sealant	1	\$50.00	✓	4000
100	Tail door spoiler	1	\$1,567.83		X
101					
102					
103					
104					
105					
106					
107					
108					
109					
110					
111					
112					
113					
114					
115					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

40 (S-N).

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :
Make & Model :
Chassis No :

SLK 2566 X

TOYOTA PRIUS

JTDKB3FU903539892

Submit By :
Year Manufacture :
Engine No. :
Cost / List

CARMEN LIM

2016

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp ballast RH <i>CM</i>	1	\$725.60		✓
2	Washer tank neck <i>nd</i>	1	\$72.80		✓
3	Front bumper top rubber <i>Tn</i>	1	\$42.70		✓
4	Aircon pipe (condensor to cooling coil) <i>nd</i>	1	\$597.80		✓
5	Water pump <i>Tm</i>	1	\$678.40		✓
6	Air cleaner air duct <i>nd</i>	1	\$178.40		✓
7	Vaccum sensor <i>CM</i>	1	\$297.40		✓
8	Air resonator <i>CM</i>	1	\$45.70		✓
9	Air resonator hose <i>nd</i>	1	\$81.40		✓
10	Spare tank water hose adapter <i>nd</i>	1	\$17.20		✓
11	Intake manifold hose <i>pu</i>	1	\$121.70		✓
12	Radiator Air guide RH <i>CM</i>	1	\$78.70		✓
13	Bonnet cable <i>Tn</i>	1	\$54.80		✓
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

2992.60 ✓



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-261/269, 560536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLK 2566 X Submit By : Carmen Lim
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RH UPPER PILLAR)	\$2,400.00	1600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, RH UPPER PILLAR)	\$2,200.00	2000
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$300.00	150
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

