

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SJY2496P
Chassis No : JHMF1630AS200037
Model : CIVIC 1.8L VTI-S AUTO
Owner's Name : KUAH ENG CHUAN
Ins Policy No :
Date of Accident :

Document No. : SQT18001163
Date : 19. Mar 2018
Customer No. : WZF002
Svc Advisor :
Engine No : R18A15000206
Date | Time : 19. Mar 2018 5:10:57 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	DIRECT SETTLEMENT (J/NO: 70160 OWNER:KUAH ENG CHUAN OWNER INSURER:AVIVA ACC DATE:05/03/2018 SURVEYED BY:ADRAIN(LKK) DATE:08/03/2018 TP INSURER:FIRST CAPITAL TP VEH::SHB3562U Supplementary Part & labours						
66100-SNA-U02ZZ	PANELREAR <i>Dented.</i>	1	314.50	25	235.87	16.51	252.38
				Sum Item	<u>235.87</u>	<u>16.51</u>	<u>252.38</u>
BOJSE	BODY JOINT SEALANT. <i>replaced</i>	1	200.00		200.00	14.00	214.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	60.00		60.00	4.20	64.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	1500.00		1500.00	105.00	1605.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1400.00		1400.00	98.00	1498.00
				Sum Labor	<u>3280.00</u>	<u>229.60</u>	<u>3,509.60</u>

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 3,515.87 246.11 3,761.98
Total (Inclusive of GST) 3,761.98

Adrian S.
20/03/18.

Printed on 19/3/2018 5:44:53 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMF1630AS200037
License No: SJY2496P
Mileage: 147303
Engine No: R18A15000206

Document No: SVO18015743
Printed By: FSCHUI
Order Date: 19. March 2018
Order Time: 8:45:28 AM
Service Advisor: STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 70160 OWNER:KUAH ENG CHUAN OWNER INSURER:AVIVA ACC DATE:05/03/2018 SURVEYED BY:ADRAIN(LKK) DATE:08/03/2018 REF NO: TP INSURER:FIRST CAPITAL TP VEH::SHB3562U						
84640-SNA-A01ZA	LININGRR.PANEL	1	61.80	25	46.35	3.24	49.59
75701-SNB-003	EMBLEMRR (H)	1	28.90	25	21.67	1.52	23.19
75725-SNA-K01	EMBLEMRR (I-VTEC)	1	34.70	25	26.02	1.82	27.84
75722-SNB-J01	EMBLEMRR (CIVIC)	1	31.40	25	23.55	1.65	25.20
04715-SNB-010ZZ	FACE,REAR BUMPER	1	715.70	25	536.77	37.57	574.34
71598-SNA-A01	SPACERL RR BPR SIDE	1	15.30	25	11.47	0.80	12.27
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	15.30	25	11.47	0.80	12.27
66100-SNA-U02ZZ	PANELREAR	1	314.50	25	235.87	16.51	252.38
91503-SZ3-003	CLIP ABUMPER <i>mc</i>	4	3.90	25	11.70	0.82	12.52 <i>47</i>
	SUM PARTS:				924.87	64.73	989.60
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BOJSE	0672 BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	60.00		60.00	4.20	64.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	80.00		80.00	5.60	85.60
BP05R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,190.00		2,190.00	153.30	2,343.30
BKTRR	EXT-YJ REMOVE & RENEW TRUNK LID & RR BUMPER.TO STRG RR EN	1	2,300.00		2,300.00	161.00	2,461.00
	SUM LABOUR:				4,740.00	331.80	5,071.80
	TOTAL SGD				5,664.87	396.53	6,061.40

Total Payable (SGD)**6,061.40**

GST Amount is calculated from individual line(s)