

Not Authored
1-B1, 1/1 Lyp B?
12 days

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 02 March 2018

Third Party Insurer:

AXA

Vehicle No: SLH2589X

Third Party Veh No:

YP6477M

Model: TOYOTA AQUA HYBRID 1.5

Date of Accident:

28/02/18

Chassis: NHP10-2565643

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	By Shatterd	\$820.00
1	REAR TAILGATE WINDSCREEN	Shatterd	\$918.00
1	REAR TAILGATE SPOILER	Warp	\$1,346.15
1	REAR TAILGATE SPOILER 3D BRAKE LED LAMP	CM	\$257.80
1	REAR TAILGATE WIPER ARM		\$48.21
1	REAR TAILGATE WIPER ARM COVER	Rel	\$18.50
1	REAR TAILGATE WIPER ARM RUBBER SEAL	Re	\$15.20
1	REAR TAILGATE WIPER BLADE		\$48.60
1	REAR TAILGATE WIPER MOTOR		\$650.10
1	REAR TAILGATE WIPER MOTOR COVER	D.V	\$25.70
3	REAR TAILGATE WIPER MOTOR COVER CLIP	\$7.21	\$21.63
2	REAR TAILGATE DAMPER LH + RH	\$218.40	\$436.80
1	REAR TAILGATE OUTER GARNISH	Warp	\$201.60
2	REAR TAILGATE NUMBER PLATE LAMP LH + RH	\$42.10	\$84.20
1	REAR TAILGATE OUTER LOCK HANDLE SWITCH		\$133.59
2	REAR TAILGATE HINGES LH + RH	\$48.90	\$97.80
1	REAR TAILGATE INNER LOCK HANDLE		\$36.70
1	REAR TAILGATE INNER UPHOLSTERY BOARD		\$428.60
6	REAR TAILGATE INNER UPHOLSTERY BOARD CLIP	\$7.21	\$43.26
1	REAR TAILGATE LOGO EMBLEM	Re	\$45.90
1	REAR TAILGATE AQUA EMBLEM	Re	\$48.60
1	REAR TAILGATE HYBRID SYNERGY DRIVE	Re	\$70.50
1	REAR TAILGATE MECHANISM LOCK	Th	\$452.71
1	REAR TAILGATE WEATHERSTRIP	D.V / Re	\$291.80
2	REAR TAILLAMP LH + RH	\$528.80	CM \$1,057.60
2	REAR TAILLAMP LOWER BRACKET LH + RH	\$42.57	Re \$85.14
2	REAR TAILLAMP INNER PANEL LH + RH	\$142.70	\$285.40
4	REAR TAILLAMP CLIP LH + RH	\$7.21	Re \$28.84
1	REAR BUMPER	Re	\$408.31
2	REAR BUMPER SIDE RETAINER LH + RH	\$68.28	D.V \$136.56
8	REAR BUMPER CLIP	\$5.78	Re \$46.24
1	REAR BUMPER LOWER UNDER COVER		\$139.10
1	REAR BUMPER REINFORCEMENT		\$278.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 02 March 2018

Third Party Insurer: AXA

Vehicle No: SLH2589X

Third Party Veh No: YP6477M

Model: TOYOTA AQUA HYBRID 1.5

Date of Accident: 28/02/18

Chassis: NHP10-2565643

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
2	REAR BUMPER REINFORCEMENT BRACKET LH + RH	\$115.70	\$231.40	7
1	REAR END PANEL		<i>RM</i> \$629.80	✓
1	REAR END PANEL INNER TOP GARNISH		<i>RM</i> \$191.40	✓
4	REAR END PANEL INNER TOP GARNISH CLIP	\$6.21	<i>RM</i> \$24.84	✓
1	REAR END PANEL TAILGATE ANTENNA SENSOR		\$144.20	7
1	REAR END PANEL LOCK STRIKER		\$38.90	7
1	REAR FENDER LH		<i>RM</i> \$629.70	✓
1	REAR FENDER PETROL LID COVER LH		<i>RM</i> \$128.60	X
1	REAR FENDER INNER TRIM BOARD LH		\$628.01	7
12	REAR FENDER INNER TRIM BOARD CLIP LH	\$7.39	\$88.68	7
1	REAR FENDER INNER TOP GARNISH LH		\$256.10	7
4	REAR FENDER INNER TOP GARNISH CLIP LH	\$7.21	\$28.84	7
1	REAR FENDER INNER PANEL		<i>RM</i> \$423.51	X
1	REAR FENDER INNER AIR VENT		\$124.50	7
1	REAR FENDER INNER TRIM BOARD RH		\$628.61	7
12	REAR FENDER INNER TRIM BOARD CLIP RH	\$8.51	\$102.12	7
1	REAR FENDER INNER TOP GARNISH RH		\$255.70	7
4	REAR FENDER INNER TOP GARNISH CLIP RH	\$7.21	\$28.84	7
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD		\$488.61	7
1	SPARE TYRE RETAINER LOCK		\$42.10	7
SUB TOTAL			\$14,122.00	
Less 25%			-\$3,530.50	
PARTS TOTAL			\$10,591.50	

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$	
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER		<i>RM</i> \$100.00	405m
1	REAR TAILGATE NUMBER PLATE WITH CASING		<i>RM</i> \$50.00	455m
1	REAR BUMPER REVERSE SENSOR		<i>RM</i> \$280.00	2005m
S/N TOTAL			\$430.00	

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 02 March 2018

Third Party Insurer:

AXA

Vehicle No: SLH2589X

Third Party Veh No:

YP6477M

Model: TOYOTA AQUA HYBRID 1.5

Date of Accident:

28/02/18

Chassis: NHP10-2565643

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,600.00	1400
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,400.00	1200
TO TUFF KOTE / ANTI-RUST	\$60.00	✓
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$60.00	500
TO REMOVE AND REINSTALL REAR WINDSCREEN PERFORM AND WATER LEAK TEST	\$150.00	1200
TO MOUNT VEHICLE ONTO 3D COMPUTERISE CAR 'O' LINER TO CALIBRATE SUB CHASSIS FRAME & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$280.00	7
TO DISMANTLE & REINSTALL INTERIOR CARPET, FRONT/ REAR SEAT ASSY WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$250.00	1200

LABOUR TOTAL	\$3,800.00
--------------	------------

WINSON	TOTAL	\$14,821.50
--------	--------------	--------------------